

EX90 MODEL YEAR 2025
Candidate List Substances Table

We hereby inform that almost all product areas contain lead (CAS No 7439-92-1), primarily as alloying elements in steel, aluminium and copper.

Released: 2024 week 35.

Localisation	Partnames	Substance/s
Electric Power Supply / Instruments - [cleaner]	PUMP, WIPER ARM, REAR WIPER, WIPER APPARATUS, WASHER FLUID RESERVOIR, DUAL PUMP, LEVEL SENSOR	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], C,C'-azodi(formamide) [123-77-3]
Electric Power Supply / Instruments - [miscellaneous]	PUMP, TELESCOPE, DUAL PUMP, WASHER FLUID RESERVOIR	Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Frame / Springs / Damping / Wheels - [spring, hydraulic / gas / air spring]	VALVE BLOCK, AIR HOSE, AIR SUPPLY UNIT, AIR TANK, CONNECTOR, HOSE COUPLING	Lead [7439-92-1], Lead-monoxide [1317-36-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Electric Power Supply / Instruments - [vehicle control system]	SWITCH PANEL, USB - C CHARGER, SWITCH, CONTROL PANEL POWER SEAT, MSM, SWITCH WINDOW LIFT, CUT-OFF SWITCH, STALK MODULE, CONTROL UNIT DOOR, CONTROL UNIT, ECU, ECU POWER SEAT REAR	Lead [7439-92-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], TBBA [79-94-7], Melamine [108-78-1], 4,4'-Isopropylidenediphenol [80-05-7]
Body, Interior / Exterior - [upholstery]	SHIM, B-PILLAR PANEL, DAWN, DOOR PANEL, DAWN/CHARCOAL, C-PILLAR PANEL, CHARCOAL, SILL MOULDING, TRIM MOULDING, TURNED BIRC, LIGHT ASH, TRIM MOULDING ALUMINIUM, GRAB HANDLE CHARCOAL, GRAB HANDLE CARDAMOM, GRAB HANDLE DAWN, MICROSWITCH, CARDAMOM, CLIP HOUSING	Lead [7439-92-1], Melamine [108-78-1], C,C'-azodi(formamide) [123-77-3], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Bumetrizole [3896-11-5]
Body, Interior / Exterior - [interior equipment]	USB - C CHARGER, EC REAR VIEW MIRROR, RETAINER, PANEL AIR OUTLET, AIR OUTLET, CUP HOLDER, WOOD, LED MODULE	Lead-monoxide [1317-36-8], Lead [7439-92-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Tris(nonylphenyl)phosphite [26523-78-4]
Wheel Suspension / Steering - [axle member / link arm / suspension]	CONTROL ARM, BUSHING, BUSHING SUBFRAME, LOWER LINK ARM CPL, SUBFRAME REAR	Imidazolidine-2-thione [96-45-7], Lead [7439-92-1]
Electric Power Supply / Instruments - [protection]	ACCELEROMETER, LEVEL SENSOR, LEVEL SENSOR REAR, LEVEL SENSOR FRONT RH, CONTROL UNIT	Lead [7439-92-1], Lead-monoxide [1317-36-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Diboron-trioxide [1303-86-2]

Electric Power Supply / Instruments - [support systems]	SENSOR, THERMAL UNIT, EXT743, DRIVER MONITORING CAMERA, CAMERA, RADAR, FAN, LIDAR, CONTROL UNIT, EXT744, EXT745, EXT746	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Lead-titanium-trioxide [12060-00-3], Melamine [108-78-1], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Dodecamethylcyclohexasiloxane [540-97-6], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], N,N-Dimethylacetamide [127-19-5], Cobalt(II) nitrate hexahydrate [10026-22-9], TBBA [79-94-7], 1-Methyl-2-pyrrolidone [872-50-4]
Electric Power Supply / Instruments - [antenna]	ANTENNA AMPLIFIER, CARD READER, ETC ANTENNA, ETC	Lead-monoxide [1317-36-8], Lead [7439-92-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead titanium zirconium oxide [12626-81-2], Diboron-trioxide [1303-86-2], 1-Propanol, 2,3-dibromo- [96-13-9]
Body, Interior / Exterior - [lock / handle]	LOCK, OUTER HANDLE, SIX POINT SOCKET SCREW, BRACKET, EXT743, EXT739, ACTUATOR, DOOR LOCK, EXT745	Hexahydromethylphthalic-anhydride [25550-51-0], Lead [7439-92-1], Melamine [108-78-1], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 1-Methyl-2-pyrrolidone [872-50-4], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1], Phenol, dimethyl-, phosphate (3:1) [25155-23-1], 2-Methylimidazole [693-98-1], C,C'-azodi(formamide) [123-77-3]
Body, Interior / Exterior - [airbag]	ACCELEROMETER, FRONT SENSOR, AIRBAG, INFLATABLE KNEE BOLSTER, AIRBAG MODULE, AIRBAG PASSENGER, DAWN, CONTROL UNIT	Lead-monoxide [1317-36-8], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], Lead [7439-92-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2]
Engine - [cooling system]	VALVE, HOSE, HOSE LOWER, FAN, GROMMET, PUMP, TEMPERATURE SENSOR, CLIP	Lead [7439-92-1], Lead-monoxide [1317-36-8], 2-Methylimidazole [693-98-1], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Dodecamethylcyclohexasiloxane [540-97-6], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Diboron-trioxide [1303-86-2], Bumetizole [3896-11-5]
Electric Power Supply / Instruments - [radio equipment]	LOUDSPEAKER, TWEETER, MIDRANGE, MICROPHONE, AUDIO MODULE, CENTRE LOUDSPEAKER, WOOFER	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7]
Frame / Springs / Damping / Wheels - [anti-roll bar]	LINK FRONT ANTI-ROLL BAR, LINK ANTI-ROLL BAR	Diboron-trioxide [1303-86-2], Imidazolidine-2-thione [96-45-7]
Brake - [wheel brake]	BRAKE CALIPER, WEAR SENSOR, BRAKE CALIPER FRONT, AIR VENTING NIPPLE	Imidazolidine-2-thione [96-45-7], Lead [7439-92-1], Cobalt(II) nitrate hexahydrate [10026-22-9], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]

Electric Power Supply / Instruments - [cable system high voltage]	CHARGE CABLE, ACTUATOR, CABLE HARNESS, FLANGE NUT, CHARGE CABLE CORD	Octamethylcyclotetrasiloxane [556-67-2], Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Phenol, dimethyl-, phosphate (3:1) [25155-23-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Melamine [108-78-1], Cobalt-dinitrate [10141-05-6]
Electric Power Supply / Instruments - [battery and mounting parts]	TOLERANCE COMPENSATOR, BATTERY, FILTER, RELAY, CONTACTOR, SERVICE LID, RBMS, BMS, CONNECTOR PLATE, CABLE HARNESS, SERVICE LID HV BATTERY, FLANGE NUT	Lead [7439-92-1], Octamethylcyclotetrasiloxane [556-67-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Dodecamethylcyclohexasiloxane [540-97-6], Decamethylcyclopentasiloxane [541-02-6], Cobalt-dinitrate [10141-05-6]
Frame / Springs / Damping / Wheels - [rim]	SENSOR, SPARE WHEEL 20", KEY, WHEEL BOLT, ADHESIVE BALANCE WEIGHT	1,2-Dimethoxyethane [110-71-4], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], 2-Methylimidazole [693-98-1], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [glass, window / windscreen / roof]	REAR SCREEN, GLASS LAMINATED, QUARTER GLASS HARDENED, QUARTER GLASS LAMINATED, SEALING	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Bumetizole [3896-11-5], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [air conditioning]	ELECTRIC HEATER, PRESSURE HOSE, PIPE ASSEMBLY, GAS HOSE, CHILLER, BRACKET, SENSOR, AIR CONDITIONING, PIPE AC, BOTTLE, EXPANSION VALVE, SENSOR PRESSURE TEMP, BRACKET SUBFRAME, TEMPERATURE SENSOR, DAWN, EL COMPRESSOR, ELECTRIC HEATER COOLANT, WATER COOLED CONDENSER, AIR INLET HOUSING, DISTRIBUTION HOUSING, GROMMET, STEPPING MOTOR, SUN SENSOR, CLIMATE UNIT, FAN, AIR DUCT, REFRIGERATOR COMPRESSOR, REFRIGERATOR BOX, POWER UNIT, SENSOR INTERIOR, CONTROL UNIT, HUMIDITY SENSOR, FLANGE SCREW, AIR CLEANER, CHANNEL SENSOR, VALVE	Lead-titanium-trioxide [12060-00-3], Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], 2-Methylimidazole [693-98-1], Decamethylcyclopentasiloxane [541-02-6], Dodecamethylcyclohexasiloxane [540-97-6], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Bumetizole [3896-11-5], Imidazolidine-2-thione [96-45-7], Melamine [108-78-1], Octamethylcyclotetrasiloxane [556-67-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], TBBA [79-94-7], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Hexahydromethylphthalic-anhydride [25550-51-0], 4,4'-Isopropylidenediphenol [80-05-7], Cobalt-dichloride [7646-79-9]
Body, Interior / Exterior - [seat belt / other restraining systems]	HEIGHT ADJUSTMENT, SEAT BELT	Lead [7439-92-1], Cobalt(II) nitrate hexahydrate [10026-22-9], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Silicic acid, lead salt [11120-22-2], Melamine [108-78-1]
Body, Interior / Exterior - [tool / jack]	COMPRESSOR, BOTTLE, REPAIR KIT	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1], Decamethylcyclopentasiloxane [541-02-6], Dodecamethylcyclohexasiloxane [540-97-6], Octamethylcyclotetrasiloxane [556-67-2]
Body, Interior / Exterior - [tank hatch]	MODULE	Lead [7439-92-1]
Body, Interior / Exterior - [side door]	CARRIER PLATE, MOTOR WINDOW REGULATOR, DOOR MODULE LH FRT, DOOR MODULE LH REAR, DOOR MODULE RH FRT, DOOR MODULE RH REAR	Lead [7439-92-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]

Electric Power Supply / Instruments - [lighting]	CONTROL UNIT HCM, REAR LAMP, HEADLAMP, DIRECTION INDICATOR	Lead [7439-92-1], Diboron-trioxide [1303-86-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 4,4'-Isopropylidenediphenol [80-05-7]
Body, Interior / Exterior - [trunk lid / tailgate complete]	SPINDLE DRIVE, ANTIFLUTTER	Lead [7439-92-1], Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Electric Power Supply / Instruments - [cable system]	FUSE MODULE, FUSE BOX ASSY, CABLE HARNESS BUMPER, CABLE HARNESS, CABLE FLOOR, CABLE, ADAPTER HARNESS, FLANGE NUT, FLANGE SCREW	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1], Dodecamethylcyclohexasiloxane [540-97-6], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Glycols, polyethylene, mono(p-(1,1,3,3-tetramethylbutyl)phenyl) ether [9002-93-1], Bumetrizole [3896-11-5], Cobalt-dinitrate [10141-05-6], Cobalt-dichloride [7646-79-9]
Engine - [accelerator control]	ACCELERATOR PEDAL	Lead [7439-92-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
Wheel Suspension / Steering [steering gear / wheel / shaft / column]	CONTROL UNIT, STEERING COLUMN, SEALING FLOOR, STEERING GEAR, STEERING WHEEL, CHARCOAL/D	Lead [7439-92-1], Phenol, dimethyl-, phosphate (3:1) [25155-23-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7]
Body, Interior / Exterior - [recovery / towing unit]	HARNESS, TOWING HOOK	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1], Imidazolidine-2-thione [96-45-7]
Power Transmission - [electrical axis drive]	INNER HOUSING, OUTER HOUSING, BRACKET, ELECTRIC MOTOR, SERVICE KIT, TRANSMISSION HOUSE, O-RING, INVERTER, BALANCING PLATE, REAR AXLE, TWIN DISC CLUTCH, ACTUATOR, GASKET, HOUSING, CONNECTOR, LID, FRONT AXLE, TRANSMISSION HOUSING, OIL PUMP, FLANGE SCREW	Lead [7439-92-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], N,N-Dimethylacetamide [127-19-5], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Lead-titanium-trioxide [12060-00-3], Dodecamethylcyclohexasiloxane [540-97-6], Cobalt-dichloride [7646-79-9]
Body, Interior / Exterior - [floor / frame section / wheel housing / firewall]	LOAD CARRIER, WELD SEALANT CURING, ADHESIVE, FLANGE SCREW	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt-dichloride [7646-79-9]
Frame / Springs / Damping / Wheels - [shock absorber]	TOPMOUNT, SHOCK ABSORBER REAR, SHOCK ABSORBER FRONT	Lead [7439-92-1]
Body, Interior / Exterior - [instrument / radio panel]	LAMP, CONCEALING PANEL, CASSETTE, DECOR, TURNED BIRCH, LIGHT ASH, ALUMINIUM, ACTUATOR, GLOVE BOX, HINGE PIN	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2]
Electric Power Supply / Instruments - [Lighting Interior areas]	LAMP, LIGHT GUIDE, SENSOR, OVERHEAD CONSOLE, READING LAMP, LED MODULE	Lead [7439-92-1], Lead titanium zirconium oxide [12626-81-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]

Electric Power Supply / Instruments - [vehicle computational units / gateway modules]	CONTROL UNIT, GATEWAY MODULE	Lead [7439-92-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], TBBA [79-94-7], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], Melamine [108-78-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 1-Methyl-2-pyrrolidone [872-50-4]
Body, Interior / Exterior - [outside / exterior trim]	RAILS, EMBLEM, LID, REFLEX, SEALING	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead [7439-92-1], Dicyclohexyl-phthalate [84-61-7]
Electric Power Supply / Instruments - [infotainment system]	DISPLAY, GRAPHIC HEAD UP DISPLAY, CAMERA	Lead [7439-92-1], TBBA [79-94-7], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Boric acid [10043-35-3], Lead-titanium-trioxide [12060-00-3], Melamine [108-78-1], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Dibutylbis(pentane-2,4-dionato-O,O')tin [22673-194]
Electric Power Supply / Instruments - [horn]	HORN	Lead [7439-92-1], Diboron-trioxide [1303-86-2]
Electric Power Supply / Instruments - [communication, mobile telephone]	BATTERY, CONTROL UNIT, WIRELESS CHARGE SYSTEM	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], 1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4], TBBA [79-94-7]
Body, Interior / Exterior - [front fender]	FRONT FENDER, FENDER CARRIER, ANTIFLUTTER	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Brake - [brake control]	BRAKE PEDAL, PEDAL UNIT	Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [spring, leaf spring]	AIR SPRING REAR, SHOCK ABSORBER FRONT, TOPMOUNT, AIR SPRING FRONT, PRESSURE RETAIN VALVE	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Body, Interior / Exterior - [miscellaneous]	BREATHER PLUG, TRANSPORT PROTECTION	Bumetrizole [3896-11-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Body, Interior / Exterior - [seats]	SEAT, UNDERCARRIAGE, HARDBACK, DAWN, HEAD REST, WHITE, CHARCOAL, CARDAMOM, LUMBAR SUPPORT, HEATER, FRAMEWORK, OUTER SECTION REAR, ECU, LUMBAR SUPPORT 4-WAY, HEADREST, VENTILATION	Lead [7439-92-1], Lead-monoxide [1317-36-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], C,C'-azodi(formamide) [123-77-3], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Imidazolidine-2-thione [96-45-7], Melamine [108-78-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7]

Electric Power Supply / Instruments - [automatic monitoring / control]	UWB ANTENNA, CONTROL UNIT, RAIN SENSOR, SIREN, RFK SET, TRM	Lead [7439-92-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead titanium zirconium oxide [12626-81-2], 1,2-Dimethoxyethane [110-71-4], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], TBBA [79-94-7]
Electric Power Supply / Instruments - [electric drive system, high voltage]	CURRENT SENSOR, CONTROL UNIT, CELL VOLTAGE TEMP NODE, DETECTION UNIT, FLANGE NUT	Lead [7439-92-1], Lead-monoxide [1317-36-8], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Dodecamethylcyclohexasiloxane [540-97-6], Cobalt-dinitrate [10141-05-6]
Body, Interior / Exterior - [outside mirrors]	HOSE, NOZZLE, GLASS, REAR VIEW MIRROR OUTER, CAMERA, REAR VIEW MIRROR, MOTOR UNIT, DIRECTION INDICATOR	Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1], Phenol, dimethyl-, phosphate (3:1) [25155-23-1], Lead-monoxide [1317-36-8], Bumetrizole [3896-11-5]
Body, Interior / Exterior - [roof]	GLASS COVER, GLASS ROOF, BRACKET, ANTENNA, WELD SEALANT CURING, ADHESIVE	Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead [7439-92-1], Bumetrizole [3896-11-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], C,C'-azodi(formamide) [123-77-3], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Electric Power Supply / Instruments - [electrical distribution box / fuse box]	CONTROL UNIT, BRACKET	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
Brake - [brake line with connections]	BRAKE PIPE, FILLER PIPE, BRAKE PIPE FRONT, BRAKE PIPE REAR, BRAKE PIPE LEFT REAR, RETAINER	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bumetrizole [3896-11-5]
Body, Interior / Exterior - [exterior equipment]	BRACKET, SPOILER, EXT739, EXT743, STOP LAMP, ACTIVE SPOILER SHUTTER	Bumetrizole [3896-11-5], Lead [7439-92-1], Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Diboron-trioxide [1303-86-2], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9]
Body, Interior / Exterior - [bumper with mounting / damping]	OUTER CASING, EXT740, LID, E, CLIP	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1], Bumetrizole [3896-11-5]
Body, Interior / Exterior - [bonnet / cover with assembly parts]	COVER, SIDE PANEL	Lead [7439-92-1], Bumetrizole [3896-11-5]
Engine - [cold zone / batterybox]	NVH WALL	Lead [7439-92-1]

Electric Power Supply / Instruments - [electric drive system]	VOLTAGE CONVERTER, ONBOARD CHARGER	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Decamethylcyclopentasiloxane [541-02-6], Boric acid [10043-35-3], Lead-titanium-trioxide [12060-00-3]
Brake - [brake, anti lock (anti-skid)]	HYDRAULIC UNIT, LID, SENSOR	Lead [7439-92-1], Lead titanium zirconium oxide [12626-81-2], Boric acid [10043-35-3], Cobalt(II) nitrate hexahydrate [10026-22-9], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], TBBA [79-94-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Body, Interior / Exterior - [climate unit]	CONTROL UNIT	Lead [7439-92-1], Lead titanium zirconium oxide [12626-81-2]
Body, Interior / Exterior - [lid, cover plate]	COVER PANEL	Tris(nonylphenyl)phosphite [26523-78-4], Diboron-trioxide [1303-86-2]
Electric Power Supply / Instruments - [media, navigation and communication]	PRINTED CIRCUIT BOARD, CONTROL UNIT	Lead-monoxide [1317-36-8], Lead [7439-92-1], Diboron-trioxide [1303-86-2], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 4,4'-Isopropylidenediphenol [80-05-7], Lead-titanium-trioxide [12060-00-3], Melamine [108-78-1]
Body, Interior / Exterior - [instruction / information plates]	NUMBER PLATE HOLDER, SIX POINT SOCKET SCREW	Lead [7439-92-1], 1-Methyl-2-pyrrolidone [872-50-4]
Body, Interior / Exterior - [body side]	WELD SEALANT CURING, ADHESIVE	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Body, Interior / Exterior - [sealings]	EXPANDING TAPE	C,C'-azodi(formamide) [123-77-3]
Body, Interior / Exterior - [hood cover]	HOOD, ANTIFLUTTER	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]