

**V60CC MODEL YEAR 2025
Candidate List Substances Table**

We hereby inform that almost all product areas contain lead (CAS No 7439-92-1), primarily as alloying elements in steel, aluminium and copper.

Released: 2024 week 35.

Localisation	Partnames	Substance/s
Engine - [cooling system]	PUMP, TWO-WAY VALVE, VALVE, HOSE TEMP SENSOR, HOSE OUTLET, TWIN CLIP, WATER PUMP, COOLER, CONDENSER, SET, COMPLETE COOLER, PRESSURE SENSOR, RADIATOR, CHARGE AIR COOLER, TEMPERATURE SENSOR, THREE-WAY VALVE, BRACKET, CLAMP BRACKET, HOSE, RETAINER, HEATER HOSE, PIPE, EL WATER PUMP, HOSE MODULE, THERMOSTAT HOUSING, GASKET, O-RING, NIPPLE, PLASTIC PIPE, SIX POINT SOCKET SCREW, INLET PIPE, COVER, THERMOSTAT, SEALING RING, SEALING, MODULE WATER PUMP, BRACKET TEMP SENSOR, STRIKER PLATE	TBBA [79-94-7], Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Decamethylcyclotrasiloxane [541-02-6], Melamine [108-78-1], Dodecamethylcyclohexasiloxane [540-97-6], Lead titanium zirconium oxide [12626-81-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 1-Methyl-2-pyrrolidone [872-50-4], Silicic acid, lead salt [11120-22-2], 4,4'-Isopropylidenediphenol [80-05-7], Octamethylcyclotetrasiloxane [556-67-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead(II,IV)-oxide [1314-41-6], C,C'-azodi(formamide) [123-77-3]
Electric Power Supply / Instruments - [automatic monitoring / control]	CONTROL UNIT, SIREN, RAIN SENSOR, REMOTE KEY, TRM, SENSOR	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead [7439-92-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4], Lead(II,IV)-oxide [1314-41-6], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], 1,2-Dimethoxyethane [110-71-4], Lead-titanium-trioxide [12060-00-3], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead titanium zirconium oxide [12626-81-2], TBBA [79-94-7]
Body, Interior / Exterior - [lock / handle]	DOOR LOCK, LOCK, LOCK CYLINDER SET, OUTER HANDLE, WIRE, EXT743, EXT745, EXT746, EXT744, KEY	Lead [7439-92-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Bumetizole [3896-11-5], Melamine [108-78-1], Hexahydromethylphthalic-anhydride [25550-51-0], 2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol [3864-99-1]
Wheel Suspension / Steering [steering gear / wheel / shaft / column]	STEERING WHEEL, STEERING WHEEL RIM, STEERING COLUMN LOCK, STEERING GEAR, SEALING FLOOR, STEERING WHEEL HARNESS, COVER PLUG, CHARCOAL SO, BLOND, STEERING COLUMN	Dicyclohexyl-phthalate [84-61-7], Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead-monoxide [1317-36-8], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], TBBA [79-94-7], Diboron-trioxide [1303-86-2]

Electric Power Supply / Instruments - [radio equipment]	MICROPHONE, LOUDSPEAKER, SPEAKER MIDRANGE, AUDIO MODULE, WOOFER, SUBWOOFER, TWEETER, CENTRE LOUDSPEAKER	Diboron-trioxide [1303-86-2], Lead [7439-92-1], N,N-Dimethylacetamide [127-19-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], Melamine [108-78-1], TBBA [79-94-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Cobalt(II) nitrate hexahydrate [10026-22-9], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
Electric Power Supply / Instruments - [vehicle control system]	HARDWARE, SWITCH PANEL, STALK MODULE, CONTROL UNIT DOOR, BUTTON, ECU, SWITCH, COMBI INSTRUMENT, CUT-OFF SWITCH, USB POWER OUTLET, CONTROL PANEL POWER SEAT, SWITCH DOOR, SWITCH WINDOW LIFT, SWITCH MODULE, SWITCH STEERING WHEEL	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Boric acid [10043-35-3], 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride [19438-60-9], TBBA [79-94-7], 4,4'-Isopropylidenediphenol [80-05-7], Lead titanium zirconium oxide [12626-81-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Lead-titanium-trioxide [12060-00-3]
Body, Interior / Exterior - [air conditioning]	CLIMATE UNIT, FUEL OPERATED HEATER, IONIZER, SUN SENSOR, DISTRIBUTION HOUSING, SENSOR, FAN, EVAPORATOR HOUSING, SENSOR INTERIOR, HUMIDITY SENSOR, PROTECTIVE CAP, VALVE, SENSOR KIT, DEFROSTER, STEPPING MOTOR, CONTROL UNIT, SOLENOID CLUTCH, PIPE ASSEMBLY, AC-COMPRESSOR, DRAINAGE HOSE, AIR CLEANER, AIR INLET, VALVE CAP, CONTROL VALVE, CHANNEL SENSOR, FUEL PUMP	Lead [7439-92-1], TBBA [79-94-7], 2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol [3864-99-1], Bumetrizole [3896-11-5], Refractory ceramic fibres [142844-00-6], 2-Methylimidazole [693-98-1], Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Diboron-trioxide [1303-86-2], Melamine [108-78-1], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Octamethylcyclotetrasiloxane [556-67-2], Cobalt(II) nitrate hexahydrate [10026-22-9], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Electric Power Supply / Instruments - [support systems]	SENSOR, CONTROL UNIT, CAMERA, BOX, RADAR, EXT743, EXT746	Lead-monoxide [1317-36-8], Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], 2-Methylimidazole [693-98-1], Dicyclohexyl-phthalate [84-61-7], Lead-titanium-trioxide [12060-00-3], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Lead titanium zirconium oxide [12626-81-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 1-Propanol, 2,3-dibromo- [96-13-9]
Engine - [fan]	FAN	1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Lead [7439-92-1], TBBA [79-94-7], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [glass, window / windscreen / roof]	WINDSCREEN, QUARTER GLASS LAMINATED, REAR SCREEN, QUARTER GLASS HARDENED, GLASS HARDENED	Lead [7439-92-1], Bumetrizole [3896-11-5], Diboron-trioxide [1303-86-2]

Electric Power Supply / Instruments - [lighting]	OVERHEAD CONSOLE LENS, CONTROL UNIT HCM, HEADLAMP, READING LAMP, LIGHTING, LAMP LED, REAR LAMP REAR DOOR, REAR LAMP, FOG LIGHT, LED MODULE	Lead [7439-92-1], TBBA [79-94-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Melamine [108-78-1], Dicyclohexyl-phthalate [84-61-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Bumetrizole [3896-11-5], Octamethylcyclotetrasiloxane [556-67-2], Lead-titanium-trioxide [12060-00-3]
Power Transmission - [front axle / rear axle / drive shaft]	AOC, DRIVE SHAFT, BRACKET, FEEDER PUMP KIT, VIBRATION DAMPER, REAR AXLE, PUMP UNIT, FINAL DRIVE, BEARING ANCHORAGE, FLANGE SCREW	Lead [7439-92-1], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Melamine [108-78-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Cobalt-dichloride [7646-79-9]
Body, Interior / Exterior - [upholstery]	DOOR PANEL, SWITCH, LOCK BUTTON, LOCK BUTTON LED, ARM REST, LUGGAGE COVER, LAMP LED, SIDE PANEL, CLIP HOUSING	C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1], Bumetrizole [3896-11-5], TBBA [79-94-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], N,N-Dimethylacetamide [127-19-5]
Body, Interior / Exterior - [seats]	HEAD RESTRAINT, UPHOLSTERY, SIDE BOLSTER, HARDBACK, UNDERCARRIAGE, ARM REST, ENGINE TILT, ENGINE, HEATING PAD SEAT, VENTILATION, LUMBAR SUPPORT, LOCK, CHARCOAL SOLID, STS SENSOR, FRAMEWORK, MESSAGE UNIT, BACKREST FRAME, LUMBAR SUPPORT 4-WAY, HEATER, MESSAGE PUMP, SIX POINT SOCKET SCREW, CABLE HARNESS, FRAME, FAN, COVER, AMBER, COULISSE, HATCH, CHARCOAL/BLOND, SLATE, BLOND	C,C'-azodi(formamide) [123-77-3], Melamine [108-78-1], Lead [7439-92-1], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], TBBA [79-94-7], Boric acid [10043-35-3], Imidazolidine-2-thione [96-45-7], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], 1-Methyl-2-pyrrolidone [872-50-4], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3], Bumetrizole [3896-11-5], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Glutaral [111-30-8], N,N-Dimethylacetamide [127-19-5]
Body, Interior / Exterior - [front fender]	SHIM	Lead [7439-92-1]
Engine - [control systems]	TEMP AND PRESSURE SENSOR, AIR TEMP SENSOR, CONTROL UNIT, MASS AIR FLOW SENSOR, PRESSURE SENSOR	Lead [7439-92-1], Hexahydromethylphthalic-anhydride [25550-51-0], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Silicic acid, lead salt [11120-22-2], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3], Dicyclohexyl-phthalate [84-61-7]

Body, Interior / Exterior - [outside mirrors]	REAR VIEW MIRROR OUTER, REAR VIEW MIRROR, CAMERA, GLASS, MOTOR UNIT	Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1], TBBA [79-94-7], Lead titanium zirconium oxide [12626-81-2], Dicyclohexyl-phthalate [84-61-7], Lead-monoxide [1317-36-8], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 2-Methylimidazole [693-98-1], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Cobalt-dinitrate [10141-05-6]
Body, Interior / Exterior - [interior equipment]	JALUSIE, ARM REST, EC REAR VIEW MIRROR, RETAINER, LIGHTING, DAMPER, SUN VISOR, BLOND, HINGE, LED MODULE, CUP HOLDER	C,C'-azodi(formamide) [123-77-3], Tris(nonylphenyl)phosphite [26523-78-4], Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Cobalt sulphate [10124-43-3], TBBA [79-94-7], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7]
Brake - [brake, anti lock (anti-skid)]	HYDRAULIC UNIT, SENSOR	Lead [7439-92-1], Lead titanium zirconium oxide [12626-81-2], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1], Boric acid [10043-35-3], Cobalt(II) nitrate hexahydrate [10026-22-9]
Electric Power Supply / Instruments - [battery and mounting parts]	BMS, BATTERY, SWITCH, BATTERY 48V, 48V BATTERY	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead titanium zirconium oxide [12626-81-2], 1,3-Propanesultone [1120-71-4], Octamethylcyclotetrasiloxane [556-67-2], 1-Propanol, 2,3-dibromo- [96-13-9], Lead-titanium-trioxide [12060-00-3], 1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1]
Engine - [selective catalytic reduction]	CONTROL UNIT, PUMP MODULE, SENSOR, FILLER CAP, BRACKET, CLIP, TANK, CONTROL MODULE	Lead [7439-92-1], Nonylphenol [25154-52-3], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Bumetrizole [3896-11-5], Dodecamethylcyclohexasiloxane [540-97-6], Decamethylcyclopentasiloxane [541-02-6], TBBA [79-94-7], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead titanium zirconium oxide [12626-81-2], Octamethylcyclotetrasiloxane [556-67-2], Silicic acid, lead salt [11120-22-2]
Electric Power Supply / Instruments - [cleaner]	WIPER ARM, REAR WIPER MOTOR, WASHER FLUID RESERVOIR, WIPER APPARATUS, FILLER PIPE, SEALING, WIPER ARM DS, WIPER ARM PS, PUMP, DUAL PUMP	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Cobalt(II) nitrate hexahydrate [10026-22-9], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2]

Power Transmission - [gear lever carrier / gear selector controls]	GEAR LEVER CARRIER, BRACKET, GEAR LEVER KNOB, GEAR SHIFT CABLE, HOUSING	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 4,4'-Isopropylidenediphenol [80-05-7], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
Electric Power Supply / Instruments - [antenna]	BLUETOOTH ANTENNA, ANTENNA AMPLIFIER, MAM ANTENNA MODULE, ANTENNA, WAVE TRAP, GROUND SIDE COIL	Lead [7439-92-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], Lead titanium zirconium oxide [12626-81-2], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 1-Propanol, 2,3-dibromo- [96-13-9], Melamine [108-78-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1]
Brake - [brake line with connections]	BRAKE PIPE, BRAKE PIPE FRONT, RETAINER, BRAKE PIPE REAR	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bumetrizole [3896-11-5]
Engine - [inlet / exhaust systems]	EXHAUST SYSTEM, THROTTLE, INTAKE MANIFOLD, HEAT SHIELD PLATE	Lead-monoxide [1317-36-8], Lead [7439-92-1], Diboron-trioxide [1303-86-2], 4,4'-Isopropylidenediphenol [80-05-7], Boric acid [10043-35-3], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
Engine - [engine / engine mounting]	ENGINE MOUNT, TORQUE ROD, ENGINE, TORQUE LINK BRACKET, ENGINE BRACKET	Lead [7439-92-1], Bis(4-chlorophenyl) sulfon [80-07-9], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9]
Body, Interior / Exterior - [outside / exterior trim]	EMBLEM	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
Body, Interior / Exterior - [bonnet / cover with assembly parts]	HOOD LOCK, HOOD LOCK CONTROL, END FOAM, HOOD RELEASE CABLE, COVER	Lead [7439-92-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Imidazolidine-2-thione [96-45-7]
Body, Interior / Exterior - [side door]	SIDE DOOR, CARRIER PLATE, WINDOW LIFT	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]

Electric Power Supply / Instruments - [vehicle computational units / gateway modules]	CONTROL UNIT	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8]
Power Transmission - [gearbox]	TORQUE CONVERTER, AUTOMATIC GEARBOX, CONTROL UNIT, VALVE BODY, CABLE HARNESS, CONNECTOR, SERVO COVER, CONTROL SYSTEM, OIL PUMP	Lead [7439-92-1], Lead-monoxide [1317-36-8], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], Diboron-trioxide [1303-86-2], Nonylphenol [25154-52-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7], 1-Methyl-2-pyrrolidone [872-50-4], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3]
Electric Power Supply / Instruments - [mobile data services]	CONTROL UNIT, BOX	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methylimidazole [693-98-1], Melamine [108-78-1]
Electric Power Supply / Instruments - [cable system]	CABLE HARNESS, CABLE, CABLE HARNESS WEM, CABLE FLOOR, FUSE BOX, CABLE DUCT, FLANGE NUT, FUSE BOX ASSY, BRACKET, CABLE PAC, CABLE TELE, CABLE INFOTAINMENT, PRINTED CIRCUIT BOARD	Lead [7439-92-1], Tris(nonylphenyl)phosphite [26523-78-4], 6,6'-Di-tert-butyl-2,2'-methylene-di-p-cresol [119-47-1], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], TBBA [79-94-7], Dicyclohexyl-phthalate [84-61-7], Cobalt-dinitrate [10141-05-6], Paraffin oils, chloro [85422-92-0], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], 4,4'-Isopropylidenediphenol [80-05-7]
Body, Interior / Exterior - [instrument / radio panel]	IONIZER, INSTRUMENT PANEL, LAMP LED, PANEL NOZZLE, CONCEALING PANEL, HINGE PIN, GLOVE BOX	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
Electric Power Supply / Instruments - [electric drive system]	VOLTAGE CONVERTER, STARTER MOTOR ALTERNATOR, PULLEY, SEALING, STARTER MOTOR, COOLANT PIPE, SENSOR, BRACKET	Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], 2-Methylimidazole [693-98-1], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Dicyclohexyl-phthalate [84-61-7], N,N-Dimethylacetamide [127-19-5]
Body, Interior / Exterior - [roof]	PANORAMA ROOF, GLASS PANEL, FRAME, WELD SEALANT CURING, ADHESIVE ROOF HATCH, MOTOR	Lead [7439-92-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Tris(nonylphenyl)phosphite [26523-78-4], 6,6'-Di-tert-butyl-2,2'-methylene-di-p-cresol [119-47-1], C,C'-azodi(formamide) [123-77-3], Lead-monoxide [1317-36-8]

Electric Power Supply / Instruments - [communication, mobile telephone]	CONTROL UNIT, WIRELESS CHARGE SYSTEM, BATTERY, PRINTED CIRCUIT BOARD	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Engine - [fuel / EVAP system]	FUEL PUMP MODULE, FILTER, PURGE VALVE, LEAK DETECTION PUMP, PURGE VALVE ASSY, FILLER PIPE, PEM, HOSE, CANISTER, FUEL PRESSURE SENSOR, FUEL FILTER, FUEL TANK, TANK WELDED, HIGH PRESSURE PUMP, FUEL DISTRIBUTION PIPE, INJECTOR, FUEL PUMP, DELIVERY PIPE, INJECTION VALVE	Lead-monoxide [1317-36-8], Lead [7439-92-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], TBBA [79-94-7], Cobalt-dinitrate [10141-05-6], C,C'-azodi(formamide) [123-77-3]
Body, Interior / Exterior - [exterior equipment]	SPOILER, ACTIVE GRILLE SHUTTER, EXT746, ACTIVE SPOILER SHUTTER	Lead [7439-92-1], C,C'-azodi(formamide) [123-77-3], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [airbag]	SIDE AIR BAG, CONTROL UNIT SRS, AIRBAG MODULE, CONTROL UNIT, ACCELEROMETER SENSOR, INFLATABLE CURTAIN	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead-monoxide [1317-36-8], Lead [7439-92-1], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9]
Body, Interior / Exterior - [seat belt / other restraining systems]	HEIGHT ADJUSTMENT, BELT CATCH, BELT CATCH REAR, SEAT BELT, BELT	Lead [7439-92-1], TBBA [79-94-7], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead-monoxide [1317-36-8]
Body, Interior / Exterior - [miscellaneous]	ABSORBER, TRANSPORT PROTECTION, SEALANT REPAIR, SEALING, SOUND INSULATION	Tris(nonylphenyl)phosphite [26523-78-4], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Dibutylbis(pentane-2,4-dionato-O,O')tin [22673-19-4], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [trunk lid / tailgate complete]	TAILGATE, SPINDLE DRIVE, ANTIFLUTTER	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1], Bumetizole [3896-11-5]
Body, Interior / Exterior - [floor / frame section / wheel housing / firewall]	FRONT SIDE MEMBER, WHEEL HOUSING, ADHESIVE, TOP COVER, REINFORCEMENT, TOP COVER PANEL REAR, BATTERY BOX, FLOOR PANEL	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]

Electric Power Supply / Instruments - [infotainment system]	CONTROL UNIT, GRAPHIC HEAD UP DISPLAY, DISPLAY, PRINTED CIRCUIT BOARD, USB HUB	Lead-monoxide [1317-36-8], Lead [7439-92-1], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 4,4'-Isopropylidenediphenol [80-05-7], Diboron-trioxide [1303-86-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], TBBA [79-94-7], Melamine [108-78-1], Lead-titanium-trioxide [12060-00-3], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonfluoro-, potassium salt (1:1) [29420-49-3], Boric acid [10043-35-3], Lead titanium zirconium oxide [12626-81-2]
Wheel Suspension / Steering [axle member / link arm / suspension]	LOWER LINK ARM, UPPER LINK ARM	Imidazolidine-2-thione [96-45-7], Lead [7439-92-1]
Brake - [wheel brake]	BRAKE CALIPER, HOUSING, AIR VENTING NIPPLE, EPB, BLEEDER VALVE, BRAKE LINING	Lead [7439-92-1], 2-Methylimidazole [693-98-1], Tris(nonylphenyl)phosphite [26523-78-4], Hexahydromethylphthalic-anhydride [25550-51-0], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Dicyclohexyl-phthalate [84-61-7]
Electric Power Supply / Instruments - [protection]	SENSOR REAR, SENSOR FRONT	Lead [7439-92-1], TBBA [79-94-7]
Body, Interior / Exterior - [recovery / towing unit]	TRM, HARNESS, TOWING HOOK	Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7]
Electric Power Supply / Instruments - [electrical distribution box / fuse box]	CEM, ATTACHMENT, PRINTED CIRCUIT BOARD	Lead-monoxide [1317-36-8], Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3]
Power Transmission - [final drive]	BRACKET, PT-UNIT	Lead [7439-92-1]
Engine - [emission equipment]	LAMBDA SOND, STAY, PRESSURE SENSOR, VALVE, COOLER	Diboron-trioxide [1303-86-2], Lead [7439-92-1], TBBA [79-94-7], Lead-monoxide [1317-36-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Brake - [brake control]	PEDAL UNIT, SENSOR	Lead [7439-92-1]
Body, Interior / Exterior - [body side]	WELD SEALANT CURING, ADHESIVE, REINFORCEMENT	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Electric Power Supply / Instruments - [horn]	HORN	Lead-monoxide [1317-36-8], Lead [7439-92-1]

Body, Interior / Exterior - [instruction / information plates]	SIX POINT SOCKET SCREW, DECAL SRS	1-Methyl-2-pyrrolidone [872-50-4], 2-ethylhexyl 10-ethyl-4,4-dioctyl-7-oxo-8-oxa-3,5-dithia-4-stannatetradecanoate [15571-58-1]
Frame / Springs / Damping / Wheels - [rim]	KEY, WHEEL BOLT, ADHESIVE BALANCE WEIGHT	Lead [7439-92-1], 2-Methylimidazole [693-98-1]
Engine - [miscellaneous / help device installation]	BRACKET, TENSIONER, SPLASH PROTECTION	Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [anti-roll bar]	LINK FRONT ANTI-ROLL BAR, LINK ANTI-ROLL BAR, ANTI-ROLL BAR FRONT, ANTI-ROLL BAR REAR	Imidazolidine-2-thione [96-45-7], 2-Methylimidazole [693-98-1]
Body, Interior / Exterior - [hood cover]	ANTIFLUTTER, HOOD, HINGE, HINGE RELEASER	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [protective shields / flaps]	CLIP, HEAT SHIELD PLATE	Bumetrizole [3896-11-5], C,C'-azodi(formamide) [123-77-3]
Electric Power Supply / Instruments - [alternator]	REGULATOR LIN, ALTERNATOR 210A	Lead [7439-92-1]
Engine - [intercooler / connection]	CHARGE AIR PIPE, CHARGE AIR COOLER	Lead [7439-92-1]
Electric Power Supply / Instruments - [starting system]	STARTER MOTOR	Lead [7439-92-1], Ethylenediamine [107-15-3], Diboron-trioxide [1303-86-2]
Electric Power Supply / Instruments - [cable components]	RECEPTACLE HOUSING, CABLE DUCT	Lead [7439-92-1]
Brake - [master cylinder / brake booster]	LID, SHELL, BRAKE FLUID RESERVOIR, ACTUATION UNIT, MASTER CYLINDER	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1], TBBA [79-94-7]
Engine - [accelerator control]	ACCELERATOR PEDAL	Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-monoxide [1317-36-8]

Body, Interior / Exterior - [tank hatch]	PLASTIC MODULE	Lead [7439-92-1]
Engine - [air cleaner]	BOX, BELLOWS, SEALING, RESONATOR, HOSE MODULE	Lead [7439-92-1], Bumetrizole [3896-11-5], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Electric Power Supply / Instruments - [cable system high voltage]	CHARGE CABLE CORD	Lead [7439-92-1], Melamine [108-78-1], Octamethylcyclotetrasiloxane [556-67-2], Lead-monoxide [1317-36-8]
Engine - [cold zone / batterybox]	NVH PANEL	Lead [7439-92-1]
Engine - [supercharging]	SLEEVE, PIPE COMPRESSOR, TURBO CHARGER, OIL DRAINING PIPE, COMPRESSOR, O-RING, STAY COMPRESSOR, SUPERCHARGER, THROTTLE, VACUUM RESERVOIR, VACUUM REGULATOR, BYPASS HOUSING, COMPRESSOR PIPE, BRACKET, MP TURBO, INLET PIPE	Lead [7439-92-1], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], N,N-Dimethylacetamide [127-19-5], Melamine [108-78-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Lead-monoxide [1317-36-8], Dicyclohexyl-phthalate [84-61-7]
Engine - [transmission]	TENSIONER, CAMSHAFT, IDLER PULLEY, SOLENOID, GASKET, BALANCE SHAFT, BELT PROTECTOR, HOUSING, BELT COVER, VVT-UNIT, VVT ACTUATOR, SLEEVE	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Engine - [lubricating and oil system]	OIL SUMP, SUCTION LINE, OIL PUMP, PISTON COOLING JET, GASKET, VALVE, INLET PIPE, PISTON COOLING VALVE, WINDAGE TRAY, OIL LEVEL SENSOR, OIL FILTER, PLUG, OIL PRESSURE SENSOR	Lead [7439-92-1], Bis(4-chlorophenyl) sulfon [80-07-9], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Engine - [cylinder block / head]	CYLINDER HEAD, BEDPLATE, ENGINE BRACKET, VACUUM PUMP, CYLINDER BLOCK, TOP COVER, GUIDE SLEEVE, BEARING HOUSE CAM SHAFT, CAP, CAM SHAFT COVER, PROTECTING CASING, CAMSHAFT CAP, HOUSING, CAM SHAFT HOUSING, LOCATING PIN	Lead [7439-92-1]
Engine - [distributor]	CRANKSHAFT POS SENSOR, CAMSHAFT POSITION SENSOR, BRACKET, KNOCK SENSOR	Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2]
Engine - [crank mechanism]	DUAL MASS FLYWHEEL, NIPPLE, NON-RETURN VALVE	Lead [7439-92-1]
Engine - [ignition / spark plug]	GLOW PLUG, IGNITION COIL, SPARK PLUG, CONTROL UNIT	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8]