

**V90CC MODEL YEAR 2025
Candidate List Substances Table**

We hereby inform that almost all product areas contain lead (CAS No 7439-92-1), primarily as alloying elements in steel, aluminium and copper.

Released: 2024 week 35.

Localisation	Partnames	Substance/s
Engine - [cooling system]	PUMP, TWO-WAY VALVE, VALVE, HOSE TEMP SENSOR, HOSE OUTLET, HOSE MODULE, TWIN CLIP, WATER PUMP, COOLER, SET, CONDENSER, COMPLETE COOLER, PRESSURE SENSOR, RADIATOR, CHARGE AIR COOLER, TEMPERATURE SENSOR, THREE-WAY VALVE, BRACKET, CLAMP BRACKET, HOSE, RETAINER, HEATER HOSE, PIPE, HOSE HEATER, HOSE INLET, THERMOSTAT HOUSING, GASKET, O-RING, NIPPLE, PLASTIC PIPE, SIX POINT SOCKET SCREW, INLET PIPE, COVER, THERMOSTAT, SEALING RING, SEALING, MODULE WATER PUMP, BRACKET TEMP SENSOR, STRIKER PLATE	TBBA [79-94-7], Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Decamethylcyclopentasiloxane [541-02-6], Melamine [108-78-1], Dodecamethylcyclohexasiloxane [540-97-6], Lead titanium zirconium oxide [12626-81-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 1-Methyl-2-pyrrolidone [872-50-4], Silicic acid, lead salt [11120-22-2], 4,4'-Isopropylidenediphenol [80-05-7], Octamethylcyclotetrasiloxane [556-67-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead(II,IV)-oxide [1314-41-6], C,C'-azodi(formamide) [123-77-3]
Body, Interior / Exterior - [lock / handle]	DOOR LOCK, LOCK WITH ANTI THEFT COVE, LOCK, OUTER HANDLE, HANDLE, EXT746, EXT739, EXT745, LOCK CYLINDER SET, KEY, BRACKET OUTER HANDLE, LOCK CYLINDER, WIRE	Lead [7439-92-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Melamine [108-78-1], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Hexahydromethylphthalic-anhydride [25550-51-0], Bumetrizole [3896-11-5]
Wheel Suspension / Steering [steering gear / wheel / shaft / column]	STEERING WHEEL, STEERING WHEEL RIM, STEERING COLUMN LOCK, STEERING GEAR, SEALING FLOOR, STEERING WHEEL HARNESS, STEERING COLUMN	Dicyclohexyl-phthalate [84-61-7], Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead-monoxide [1317-36-8], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], TBBA [79-94-7], Diboron-trioxide [1303-86-2]
Electric Power Supply / Instruments - [radio equipment]	MICROPHONE, SPEAKER MIDRANGE, AUDIO MODULE, BRACKET, SUBWOOFER, WOOFER, TWEETER, LOUDSPEAKER, CENTRE LOUDSPEAKER	Diboron-trioxide [1303-86-2], Lead [7439-92-1], N,N-Dimethylacetamide [127-19-5], Lead monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], Melamine [108-78-1], TBBA [79-94-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Cobalt(II) nitrate hexahydrate [10026-22-9], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]

Body, Interior / Exterior - [air conditioning]	CLIMATE UNIT, FUEL OPERATED HEATER, IONIZER, SUN SENSOR, DISTRIBUTION HOUSING, SENSOR, FAN, EVAPORATOR HOUSING, SENSOR INTERIOR, HUMIDITY SENSOR, PROTECTIVE CAP, VALVE, SENSOR KIT, DEFROSTER, STEPPING MOTOR, NOZZLE CHARCOAL SOLID, NOZZLE BLOND, CONTROL UNIT, PIPE ASSEMBLY, DRAINAGE HOSE, AIR CLEANER, AIR INLET, VALVE CAP, CHANNEL SENSOR, CONTROL VALVE, MAGNET CLUTCH, AC-COMPRESSOR, FUEL PUMP	Lead [7439-92-1], TBBA [79-94-7], 2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol [3864-99-1], Bumetrizole [3896-11-5], Refractory ceramic fibres [142844-00-6], 2-Methylimidazole [693-98-1], Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Diboron-trioxide [1303-86-2], Melamine [108-78-1], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Octamethylcyclotetrasiloxane [556-67-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 4,4'-Isopropylidenediphenol [80-05-7], Tris(nonylphenyl)phosphite [26523-78-4]
Engine - [fan]	FAN, FAN LOW	1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Lead [7439-92-1], TBBA [79-94-7], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [seats]	FRAMEWORK, HEAD RESTRAINT, UPHOLSTERY, HARDBACK, UNDERCARRIAGE, ARM REST, ENGINE TILT, ENGINE, HEATING PAD SEAT, VENTILATION, LUMBAR SUPPORT, LOCK, CHARCOAL SOLID, STS SENSOR, MASSAGE UNIT, BACKREST FRAME, LUMBAR SUPPORT 4-WAY, HEATER, MASSAGE PUMP, SIX POINT SOCKET SCREW, CABLE HARNESS, SIDE BOLSTER, FRAME, FAN, COVER, AMBER, COULISSE, HATCH, CHARCOAL/BLOND, SLATE, BLOND	Paraffin oils, chloro [85422-92-0], C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], N,N-Dimethylacetamide [127-19-5], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], TBBA [79-94-7], Melamine [108-78-1], Boric acid [10043-35-3], Imidazolidine-2-thione [96-45-7], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], 1-Methyl-2-pyrrolidone [872-50-4], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3], Bumetrizole [3896-11-5], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Glutaral [111-30-8]
Body, Interior / Exterior - [upholstery]	DOOR PANEL, SILL MOULDING, WAISTRAIL, SIDE PANEL, LAMP LED, LIGHTING, SILL FRONT, GUIDE RAIL, FLOOR HATCH, PANEL, TRUNK FLOOR SUPPORT, CLIP HOUSING, HEADLINING, BELT GUIDE, LUGGAGE COVER, B-PILLAR PANEL, BLOND, C-PILLAR PANEL, CHARCOAL, A-PILLAR PANEL	C,C'-azodi(formamide) [123-77-3], Diboron-trioxide [1303-86-2], Lead [7439-92-1], TBBA [79-94-7], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], Bumetrizole [3896-11-5], Melamine [108-78-1]
Body, Interior / Exterior - [interior equipment]	PADDING, ARM REST, JALUSIE, CUP HOLDER, EC REAR VIEW MIRROR, RETAINER, COURTESY HANDLE, LIGHTING, AIR OUTLET, DAMPER, HINGE, SIDE PANEL, LED MODULE, FRAMEWORK, SUN VISOR, CHARCOAL, BLOND	C,C'-azodi(formamide) [123-77-3], Tris(nonylphenyl)phosphite [26523-78-4], Lead [7439-92-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Cobalt sulphate [10124-43-3], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Cobalt-dinitrate [10141-05-6], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]

Power Transmission - [front axle / rear axle / drive shaft]	AOC, PUMP UNIT, DRIVE SHAFT, BRACKET, VIBRATION DAMPER, REAR AXLE, FINAL DRIVE, BEARING ANCHORAGE, FLANGE SCREW	Lead [7439-92-1], Decamethylcyclotetrasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Cobalt-dichloride [7646-79-9]
Electric Power Supply / Instruments - [vehicle control system]	SWITCH PANEL, CONTROL UNIT DOOR, BUTTON, ECU, STALK MODULE, HARDWARE, SWITCH, LOCK BUTTON, LOCK BUTTON LED, COMBI INSTRUMENT, CUT-OFF SWITCH, USB POWER OUTLET, SWITCH WINDOW LIFT, GEAR SHIFT PADDLE, CONTROL PANEL POWER SEAT, SWITCH DOOR, SWITCH MODULE, SWITCH STEERING WHEEL	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], TBBA [79-94-7], 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride [19438-60-9], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Boric acid [10043-35-3], 4,4'-Isopropylidenediphenol [80-05-7], Lead-titanium-trioxide [12060-00-3]
Electric Power Supply / Instruments - [infotainment system]	DISPLAY, GRAPHIC HEAD UP DISPLAY, CONTROL UNIT, PRINTED CIRCUIT BOARD, USB HUB	Boric acid [10043-35-3], Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], TBBA [79-94-7], Melamine [108-78-1], Lead-titanium-trioxide [12060-00-3], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) [29420-49-3], Silicic acid, lead salt [11120-22-2]
Body, Interior / Exterior - [front fender]	SHIM, ANTIFLUTTER, FRONT FENDER	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Engine - [control systems]	TEMP AND PRESSURE SENSOR, AIR TEMP SENSOR, CONTROL UNIT, MASS AIR FLOW SENSOR, PRESSURE SENSOR	Lead [7439-92-1], Hexahydromethylphthalic-anhydride [25550-51-0], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Silicic acid, lead salt [11120-22-2], Lead titanium zirconium oxide [12626-81-2]
Electric Power Supply / Instruments - [support systems]	SENSOR, CONTROL UNIT, CAMERA, RADAR, EXT743, EXT746	Lead [7439-92-1], Lead-monoxide [1317-36-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Diboron-trioxide [1303-86-2], 2-Methylimidazole [693-98-1], TBBA [79-94-7], Dicyclohexyl-phthalate [84-61-7], Lead-titanium-trioxide [12060-00-3], Decamethylcyclotetrasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Lead titanium zirconium oxide [12626-81-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 1-Propanol, 2,3-dibromo- [96-13-9]
Brake - [brake, anti lock (anti-skid)]	HYDRAULIC UNIT, SENSOR	Lead [7439-92-1], Lead titanium zirconium oxide [12626-81-2], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1], Boric acid [10043-35-3], Cobalt(II) nitrate hexahydrate [10026-22-9]

<p>Electric Power Supply / Instruments - [battery and mounting parts]</p>	<p>BMS, BATTERY, SWITCH, BATTERY 48V, 48V BATTERY</p>	<p>Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead titanium zirconium oxide [12626-81-2], 1,3-Propanesultone [1120-71-4], Octamethylcyclotetrasiloxane [556-67-2], 1-Propanol, 2,3-dibromo- [96-13-9], Lead-titanium-trioxide [12060-00-3], 1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1]</p>
<p>Electric Power Supply / Instruments - [lighting]</p>	<p>CONTROL UNIT HCM, HEADLAMP, OVERHEAD CONSOLE LENS, READING LAMP, LAMP LED, LIGHTING, LIGHTNING INSTRUMENT PANEL, LED MODULE, STOP LAMP, REAR LAMP</p>	<p>Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], TBBA [79-94-7], 1-Methyl-2-pyrrolidone [872-50-4], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Dicyclohexyl-phthalate [84-61-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Bumetizole [3896-11-5], Octamethylcyclotetrasiloxane [556-67-2], Silicic acid, lead salt [11120-22-2], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Melamine [108-78-1], Lead-titanium-trioxide [12060-00-3]</p>
<p>Engine - [selective catalytic reduction]</p>	<p>CONTROL UNIT, PUMP MODULE, SENSOR, FILLER CAP, BRACKET, CLIP, TANK, CONTROL MODULE</p>	<p>Lead [7439-92-1], Nonylphenol [25154-52-3], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Bumetizole [3896-11-5], Dodecamethylcyclohexasiloxane [540-97-6], Decamethylcyclopentasiloxane [541-02-6], TBBA [79-94-7], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead titanium zirconium oxide [12626-81-2], Octamethylcyclotetrasiloxane [556-67-2], Silicic acid, lead salt [11120-22-2]</p>
<p>Electric Power Supply / Instruments - [cable system]</p>	<p>CABLE, CABLE HARNESS, CABLE FLOOR, CABLE HARNESS WEM, FUSE BOX, CABLE DUCT, BRACKET, FLANGE NUT, DISCONNECTOR POWER, FUSE BOX ASSY, CABLE PAC, PRINTED CIRCUIT BOARD, CABLE INFOTAINMENT</p>	<p>Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Tris(nonylphenyl)phosphite [26523-78-4], TBBA [79-94-7], Dicyclohexyl-phthalate [84-61-7], Cobalt-dinitrate [10141-05-6], Diboron-trioxide [1303-86-2], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Paraffin oils, chloro [85422-92-0], 4,4'-Isopropylidenediphenol [80-05-7]</p>
<p>Electric Power Supply / Instruments - [automatic monitoring / control]</p>	<p>SIREN, RAIN SENSOR, REMOTE KEY, TRM, SENSOR, CONTROL UNIT</p>	<p>Lead-monoxide [1317-36-8], Lead [7439-92-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4], Diboron-trioxide [1303-86-2], Lead(II,IV)-oxide [1314-41-6], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], 1,2-Dimethoxyethane [110-71-4], Lead-titanium-trioxide [12060-00-3], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead titanium zirconium oxide [12626-81-2], TBBA [79-94-7]</p>

Power Transmission - [gear lever carrier / gear selector controls]	GEAR LEVER CARRIER	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
Brake - [brake line with connections]	BRAKE PIPE, BRAKE PIPE FRONT, RETAINER, BRAKE PIPE REAR	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bumetizole [3896-11-5]
Engine - [engine / engine mounting]	ENGINE MOUNT, TORQUE ROD, ENGINE, TORQUE LINK BRACKET, ENGINE BRACKET	Lead [7439-92-1], Bis(4-chlorophenyl) sulfon [80-07-9], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9]
Body, Interior / Exterior - [outside / exterior trim]	EMBLEM	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
Body, Interior / Exterior - [bonnet / cover with assembly parts]	HOOD LOCK, COVER, FOAM, HOOD RELEASE CABLE, HOOD LOCK CONTROL	Lead [7439-92-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], C,C'-azodi(formamide) [123-77-3], Imidazolidine-2-thione [96-45-7]
Electric Power Supply / Instruments - [vehicle computational units / gateway modules]	CONTROL UNIT	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8]
Power Transmission - [gearbox]	TORQUE CONVERTER, AUTOMATIC GEARBOX, CONTROL UNIT, VALVE BODY, CABLE HARNESS, CONNECTOR	Lead [7439-92-1], Lead-monoxide [1317-36-8], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], Diboron-trioxide [1303-86-2], Nonylphenol [25154-52-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7], 1-Methyl-2-pyrrolidone [872-50-4], Lead titanium zirconium oxide [12626-81-2]
Body, Interior / Exterior - [glass, window / windscreen / roof]	WINDSCREEN, GLASS HARDENED, GLASS LAMINATED, REAR SCREEN, QUARTER GLASS HARDENED, QUARTER GLASS LAMINATED	Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [side door]	SIDE DOOR, WINDOW LIFT, HEMMING ADHESIVE, CARRIER PLATE, BODY MOUNTED SEALING, DOOR MOUNTED SEALING	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1], Imidazolidine-2-thione [96-45-7], C,C'-azodi(formamide) [123-77-3]

Body, Interior / Exterior - [recovery / towing unit]	TOWING HOOK, TRM, HARNESS	Lead [7439-92-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7]
Electric Power Supply / Instruments - [mobile data services]	CONTROL UNIT	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1]
Electric Power Supply / Instruments - [electric drive system]	VOLTAGE CONVERTER, STARTER MOTOR ALTERNATOR, PULLEY, SEALING, STARTER MOTOR, COOLANT PIPE, SENSOR, BRACKET	Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], 2-Methylimidazole [693-98-1], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Dicyclohexyl-phthalate [84-61-7], N,N-Dimethylacetamide [127-19-5]
Body, Interior / Exterior - [roof]	PANORAMA ROOF, GLASS PANEL, FRAME, WELD SEALANT CURING, ADHESIVE ROOF HATCH, MOTOR	Lead [7439-92-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Tris(nonylphenyl)phosphite [26523-78-4], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], C,C'-azodi(formamide) [123-77-3], Lead-monoxide [1317-36-8]
Electric Power Supply / Instruments - [communication, mobile telephone]	CONTROL UNIT, WIRELESS CHARGE SYSTEM, BATTERY, PRINTED CIRCUIT BOARD	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Engine - [fuel / EVAP system]	FUEL PUMP MODULE, FILTER, PURGE VALVE, LEAK DETECTION PUMP, PURGE VALVE ASSY, FILLER PIPE, PEM, HOSE, CANISTER, FUEL PRESSURE SENSOR, FUEL FILTER, FUEL TANK, TANK WELDED, HIGH PRESSURE PUMP, FUEL DISTRIBUTION PIPE, INJECTOR, FUEL PUMP, DELIVERY PIPE, INJECTION VALVE	Lead-monoxide [1317-36-8], Lead [7439-92-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], TBBA [79-94-7], Cobalt-dinitrate [10141-05-6], C,C'-azodi(formamide) [123-77-3]
Body, Interior / Exterior - [airbag]	SIDE AIR BAG, AIRBAG MODULE, CONTROL UNIT, ACCELEROMETER SENSOR, PRESSURE SENSOR	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [seat belt / other restraining systems]	HEIGHT ADJUSTMENT, BELT CATCH, SEAT BELT, BELT, LOAD NET, BELT CATCH REAR	Lead [7439-92-1], TBBA [79-94-7], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt sulphate [10124-43-3], Lead-monoxide [1317-36-8], Cobalt(II) nitrate hexahydrate [10026-22-9], Cobalt-dinitrate [10141-05-6], Melamine [108-78-1]

Electric Power Supply / Instruments - [cleaner]	WIPER UNIT, WASHER FLUID RESERVOIR, REAR WIPER, HEADLAMP WIPER, PUMP, DUAL PUMP, LEVEL SENSOR, WIPER ARM	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], C,C'-azodi(formamide) [123-77-3], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [floor / frame section / wheel housing / firewall]	BUMPER BEAM, FRONT SIDE MEMBER, WHEEL HOUSING, WELD SEALANT CURING, ADHESIVE, TOP COVER, REINFORCEMENT, SIDE MEMBER UPPER INNER, BRACE INNER, BRACE OUTER, FLOOR PANEL, BATTERY TRAY, CRASH BOX	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Engine - [emission equipment]	COOLER, LAMBDA SOND, PRESSURE SENSOR, VALVE	Lead [7439-92-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Lead-monoxide [1317-36-8], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Engine - [intercooler / connection]	CHARGE AIR COOLER, CHARGE AIR HOSE, CHARGE AIR PIPE, RESONATOR	Lead [7439-92-1], Boric acid [10043-35-3]
Body, Interior / Exterior - [trunk lid / tailgate complete]	REAR DOOR, SPINDLE DRIVE	Lead [7439-92-1], TBBA [79-94-7], Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8]
Wheel Suspension / Steering - [axle member / link arm / suspension]	LOWER LINK ARM, SUBFRAME FRONT, UPPER LINK ARM	Imidazolidine-2-thione [96-45-7], Cobalt-dichloride [7646-79-9], Lead [7439-92-1]
Engine - [inlet / exhaust systems]	TAILPIPE, THROTTLE, EXHAUST SYSTEM, INTAKE MANIFOLD, HEAT SHIELD PLATE	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 4,4'-Isopropylidenediphenol [80-05-7], Boric acid [10043-35-3], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
Body, Interior / Exterior - [outside mirrors]	REAR VIEW MIRROR OUTER, CAMERA, REAR VIEW MIRROR, MOTOR UNIT, DIRECTION INDICATOR, TEMPERATURE SENSOR, GLASS, REAR VIEW MIRROR CASING	Lead [7439-92-1], Lead-monoxide [1317-36-8], Octamethylcyclotetrasiloxane [556-67-2], Diboron-trioxide [1303-86-2], Dicyclohexyl-phthalate [84-61-7], 2-Methylimidazole [693-98-1], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Lead titanium zirconium oxide [12626-81-2], TBBA [79-94-7], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Lead-titanium-trioxide [12060-00-3], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Melamine [108-78-1], Tris(nonylphenyl)phosphite [26523-78-4]

Brake - [wheel brake]	BRAKE CALIPER, HOUSING, AIR VENTING NIPPLE, EPB, BLEEDER VALVE	Lead [7439-92-1], 2-Methylimidazole [693-98-1], Tris(nonylphenyl)phosphite [26523-78-4], Hexahydromethylphthalic-anhydride [25550-51-0]
Electric Power Supply / Instruments - [protection]	SENSOR REAR, CONTROL UNIT, SENSOR FRONT, ACCELEROMETER FRONT	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], TBBA [79-94-7]
Electric Power Supply / Instruments - [electrical distribution box / fuse box]	CEM, ATTACHMENT, PRINTED CIRCUIT BOARD	Lead-monoxide [1317-36-8], Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3]
Body, Interior / Exterior - [instrument / radio panel]	LAMP LED, GLOVE BOX, CONCEALING PANEL, STORAGE BOX, HINGE PIN	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], TBBA [79-94-7], Lead [7439-92-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8]
Power Transmission - [final drive]	BRACKET, PT-UNIT	Lead [7439-92-1]
Brake - [brake control]	PEDAL UNIT, SENSOR	Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [spring, leaf spring]	RESEVOIR, HOSE COUPLING, VALVE BLOCK, AIR SPRING REAR, TOPMOUNT, COMPRESSOR	Lead [7439-92-1], Decamethylcyclopentasiloxane [541-02-6], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Tris(nonylphenyl)phosphite [26523-78-4]
Body, Interior / Exterior - [miscellaneous]	SEALING, TRANSPORT PROTECTION, SEALANT REPAIR, SOUND INSULATION	C,C'-azodi(formamide) [123-77-3], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Dibutylbis(pentane-2,4-dionato-O,O')tin [22673-19-4], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [body side]	WELD SEALANT CURING, ADHESIVE	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Electric Power Supply / Instruments - [horn]	HORN	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8]
Body, Interior / Exterior - [instruction / information plates]	SIX POINT SOCKET SCREW, NUMBER PLATE HOLDER, DECAL SRS	1-Methyl-2-pyrrolidone [872-50-4], Imidazolidine-2-thione [96-45-7], 2-ethylhexyl 10-ethyl-4,4-dioctyl-7-oxo-8-oxa-3,5-dithia-4-stannatetradecanoate [15571-58-1]
Frame / Springs / Damping / Wheels - [rim]	KEY, WHEEL BOLT, ADHESIVE BALANCE WEIGHT	Lead [7439-92-1], 2-Methylimidazole [693-98-1]

Engine - [miscellaneous / help device installation]	BRACKET, TENSIONER, SPLASH PROTECTION	Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [anti-roll bar]	LINK FRONT ANTI-ROLL BAR, LINK ANTI-ROLL BAR, ANTI-ROLL BAR REAR, ANTI-ROLL BAR FRONT	Imidazolidine-2-thione [96-45-7], 2-Methylimidazole [693-98-1]
Body, Interior / Exterior - [hood cover]	ANTIFLUTTER, FOAM, HOOD	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], C,C'-azodi(formamide) [123-77-3], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Body, Interior / Exterior - [protective shields / flaps]	CLIP	Bumetrizole [3896-11-5]
Electric Power Supply / Instruments - [antenna]	ANTENNA AMPLIFIER, ETC ON BOARD UNIT, ANTENNA, ETC MODULE	TBBA [79-94-7], Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead titanium zirconium oxide [12626-81-2], 1-Propanol, 2,3-dibromo- [96-13-9], Melamine [108-78-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1]
Body, Interior / Exterior - [tank hatch]	ACTUATOR, PLASTIC MODULE	Lead [7439-92-1]
Brake - [master cylinder / brake booster]	LID	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Body, Interior / Exterior - [exterior equipment]	ACTIVE GRILLE SHUTTER, ACTIVE SPOILER SHUTTER	Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Electric Power Supply / Instruments - [starting system]	STARTER MOTOR	Lead [7439-92-1]
Engine - [accelerator control]	ACCELERATOR PEDAL	Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-monoxide [1317-36-8]
Frame / Springs / Damping / Wheels - [shock absorber]	SHOCK ABSORBER FRONT, TOPMOUNT, SHOCK ABSORBER	Lead [7439-92-1]
Electric Power Supply / Instruments - [cable system high voltage]	CHARGE CABLE CORD	Lead [7439-92-1], Melamine [108-78-1], Octamethylcyclotetrasiloxane [556-67-2], Lead-monoxide [1317-36-8]

Engine - [cold zone / batterybox]	NVH PANEL	Lead [7439-92-1]
Engine - [air cleaner]	BELLOWS, SEALING, RESONATOR, HOSE MODULE	Bumetrizole [3896-11-5], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]
Engine - [supercharging]	SLEEVE, PIPE COMPRESSOR, TURBO CHARGER, OIL DRAINING PIPE, COMPRESSOR, O-RING, STAY COMPRESSOR, SUPERCHARGER, THROTTLE, VACUUM RESERVOIR, VACUUM REGULATOR, BYPASS HOUSING, COMPRESSOR PIPE, BRACKET, MP TURBO, INLET PIPE	Lead [7439-92-1], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], N,N-Dimethylacetamide [127-19-5], Melamine [108-78-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[1.2.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Lead-monoxide [1317-36-8], Dicyclohexyl-phthalate [84-61-7]
Engine - [transmission]	TENSIONER, CAMSHAFT, IDLER PULLEY, SOLENOID, GASKET, BALANCE SHAFT, BELT PROTECTOR, HOUSING, BELT COVER, VVT-UNIT, VVT ACTUATOR, SLEEVE	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Engine - [lubricating and oil system]	OIL SUMP, SUCTION LINE, OIL PUMP, PISTON COOLING JET, GASKET, VALVE, INLET PIPE, PISTON COOLING VALVE, WINDAGE TRAY, OIL LEVEL SENSOR, OIL FILTER, PLUG, OIL PRESSURE SENSOR	Lead [7439-92-1], Bis(4-chlorophenyl) sulfon [80-07-9], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Engine - [cylinder block / head]	CYLINDER HEAD, BEDPLATE, ENGINE BRACKET, VACUUM PUMP, CYLINDER BLOCK, TOP COVER, GUIDE SLEEVE, BEARING HOUSE CAM SHAFT, CAP, CAM SHAFT COVER, PROTECTING CASING, CAMSHAFT CAP, HOUSING, CAM SHAFT HOUSING, LOCATING PIN	Lead [7439-92-1]
Engine - [distributor]	CRANKSHAFT POS SENSOR, CAMSHAFT POSITION SENSOR, BRACKET, KNOCK SENSOR	Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2]
Engine - [crank mechanism]	DUAL MASS FLYWHEEL, NIPPLE, NON-RETURN VALVE	Lead [7439-92-1]
Engine - [ignition / spark plug]	GLOW PLUG, IGNITION COIL, SPARK PLUG, CONTROL UNIT	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8]