

V90CC MODEL YEAR 2024
Candidate List Substances Table

We hereby inform that almost all product areas contain lead (CAS No 7439-92-1), primarily as alloying elements in steel, aluminium and copper.

Released: 2023 week 41.

Localisation	Partnames	Substance/s
Engine - [cooling system]	PUMP, TWO-WAY VALVE, VALVE, HOSE TEMP SENSOR, HOSE OUTLET, HOSE MODULE, TWIN CLIP, WATER PUMP, COOLER, SET, CONDENSER, COMPLETE COOLER, PRESSURE SENSOR, RADIATOR, CHARGE AIR COOLER, TEMPERATURE SENSOR, THREE-WAY VALVE, BRACKET, CLAMP BRACKET, HOSE, RETAINER, HEATER HOSE, PIPE, HOSE HEATER, HOSE INLET, OUTLET HOSE, THERMOSTAT HOUSING, O-RING, NIPPLE, PLASTIC PIPE, GASKET, INLET PIPE, COVER, SIX POINT SOCKET SCREW, MODULE WATER PUMP, BRACKET TEMP SENSOR, STRIKER PLATE	TBBA [79-94-7], Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Decamethylcyclotrasiloxane [541-02-6], Melamine [108-78-1], Lead titanium zirconium oxide [12626-81-2], 1-Methyl-2-pyrrolidone [872-50-4], Silicic acid, lead salt [11120-22-2], 4,4'-Isopropylidenediphenol [80-05-7], Octamethylcyclotetrasiloxane [556-67-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead(II,IV)-oxide [1314-41-6], C,C'-azodi(formamide) [123-77-3]
Body, Interior / Exterior - [lock / handle]	DOOR LOCK, LOCK WITH ANTI THEFT COVE, LOCK, OUTER HANDLE, HANDLE, LOCK CYLINDER SET, KEY, BRACKET OUTER HANDLE, LOCK CYLINDER	Lead [7439-92-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Melamine [108-78-1], Hexahydromethylphthalic-anhydride [25550-51-0], 1,3,5-Tris(oxiranymethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9]
Wheel Suspension / Steering [steering gear / wheel / shaft / column]	STEERING WHEEL, STEERING WHEEL RIM, STEERING COLUMN LOCK, STEERING GEAR, STEERING WHEEL HARNESS, STEERING COLUMN	Dicyclohexyl-phthalate [84-61-7], Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2]
Electric Power Supply / Instruments - [radio equipment]	MICROPHONE, SPEAKER MIDRANGE, AUDIO MODULE, BRACKET, SUBWOOFER, WOOFER, LOUDSPEAKER, CENTRE LOUDSPEAKER	Diboron-trioxide [1303-86-2], Lead [7439-92-1], N,N-Dimethylacetamide [127-19-5], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], Melamine [108-78-1], TBBA [79-94-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Cobalt(II) nitrate hexahydrate [10026-22-9], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Body, Interior / Exterior - [air conditioning]	CLIMATE UNIT, FUEL OPERATED HEATER, IONIZER, SUN SENSOR, SENSOR, PROTECTIVE CAP, VALVE, HUMIDITY SENSOR, SENSOR KIT, DEFROSTER, STEPPING MOTOR, FAN, CONTROL UNIT, PIPE ASSEMBLY, AIR CLEANER, AIR INLET, VALVE CAP, CHANNEL SENSOR, CONTROL VALVE, MAGNET CLUTCH, AC-COMPRESSOR, SENSOR INTERIOR, FUEL PUMP	Lead [7439-92-1], TBBA [79-94-7], 2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol [3864-99-1], Refractory ceramic fibres [142844-00-6], 2-Methylimidazole [693-98-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Melamine [108-78-1], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7], Tris(nonylphenyl)phosphite [26523-78-4], Octamethylcyclotetrasiloxane [556-67-2]

Engine - [fan]	FAN, FAN LOW	1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Lead [7439-92-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8]
Body, Interior / Exterior - [seats]	FRAMEWORK, HEAD RESTRAINT, UPHOLSTERY, HARDBACK, UNDERCARRIAGE, ARM REST, ENGINE TILT, ENGINE, HEATING PAD SEAT, VENTILATION, LUMBAR SUPPORT, STS SENSOR, MASSAGE UNIT, BACKREST FRAME, SIDE BOLSTER, HEATER, CABLE HARNESS, SIX POINT SOCKET SCREW, FRAME, FAN, LUMBAR SUPPORT 4-WAY	Paraffin oils, chloro [85422-92-0], C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], N,N-Dimethylacetamide [127-19-5], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], TBBA [79-94-7], Melamine [108-78-1], Boric acid [10043-35-3], Imidazolidine-2-thione [96-45-7], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], Diboron-trioxide [1303-86-2], 1-Methyl-2-pyrrolidone [872-50-4], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3], Glutaral [111-30-8]
Body, Interior / Exterior - [upholstery]	DOOR PANEL, SILL MOULDING, WAISTRAIL, SIDE PANEL, LAMP LED, LIGHTING, SILL FRONT, GUIDE RAIL, FLOOR HATCH, PANEL, TRUNK FLOOR SUPPORT, HEADLINING, BELT GUIDE	C,C'-azodi(formamide) [123-77-3], Diboron-trioxide [1303-86-2], Lead [7439-92-1], TBBA [79-94-7], Melamine [108-78-1]
Body, Interior / Exterior - [interior equipment]	PADDING, ARM REST, JALUSIE, CUP HOLDER, EC REAR VIEW MIRROR, COURTESY HANDLE, DAMPER, HINGE, SIDE PANEL, LIGHTING, LED MODULE, FRAMEWORK	C,C'-azodi(formamide) [123-77-3], Tris(nonylphenyl)phosphite [26523-78-4], Lead [7439-92-1], TBBA [79-94-7], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Cobalt sulphate [10124-43-3], Cobalt-dinitrate [10141-05-6], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Power Transmission - [front axle / rear axle / drive shaft]	AOC, PUMP UNIT, DRIVE SHAFT, BRACKET, VIBRATION DAMPER, REAR AXLE, FINAL DRIVE, BEARING ANCHORAGE, FLANGE SCREW	Lead [7439-92-1], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Cobalt-dichloride [7646-79-9]
Electric Power Supply / Instruments - [vehicle control system]	SWITCH PANEL, CONTROL UNIT DOOR, BUTTON, ECU, STALK MODULE, HARDWARE, SWITCH, LOCK BUTTON, LOCK BUTTON LED, COMBI INSTRUMENT, CUT-OFF SWITCH, USB POWER OUTLET, SWITCH WINDOW LIFT, GEAR SHIFT PADDLE, CONTROL PANEL POWER SEAT, SWITCH DOOR, SWITCH MODULE, SWITCH STEERING WHEEL	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], TBBA [79-94-7], 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride [19438-60-9], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Boric acid [10043-35-3], 4,4'-Isopropylidenediphenol [80-05-7], Lead-titanium-trioxide [12060-00-3]
Electric Power Supply / Instruments - [infotainment system]	DISPLAY, GRAPHIC HEAD UP DISPLAY, CONTROL UNIT, USB HUB, PRINTED CIRCUIT BOARD	Boric acid [10043-35-3], Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], TBBA [79-94-7], Melamine [108-78-1], Lead-titanium-trioxide [12060-00-3], 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) [29420-49-3], Silicic acid, lead salt [11120-22-2]

Body, Interior / Exterior - [front fender]	SHIM, ANTIFLUTTER, FRONT FENDER	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Engine - [control systems]	TEMP AND PRESSURE SENSOR, AIR TEMP SENSOR, CONTROL UNIT, MASS AIR FLOW SENSOR, PRESSURE SENSOR	Lead [7439-92-1], Hexahydromethylphthalic-anhydride [25550-51-0], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Silicic acid, lead salt [11120-22-2], Lead titanium zirconium oxide [12626-81-2]
Electric Power Supply / Instruments - [support systems]	SENSOR, CONTROL UNIT, CAMERA, RADAR	Lead [7439-92-1], Lead-monoxide [1317-36-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Diboron-trioxide [1303-86-2], 2-Methylimidazole [693-98-1], TBBA [79-94-7], Dicyclohexyl-phthalate [84-61-7], Lead-titanium-trioxide [12060-00-3], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Lead titanium zirconium oxide [12626-81-2], 1-Propanol, 2,3-dibromo- [96-13-9]
Brake - [brake, anti lock (anti-skid)]	HYDRAULIC UNIT, SENSOR	Lead [7439-92-1], Lead titanium zirconium oxide [12626-81-2], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
Electric Power Supply / Instruments - [battery and mounting parts]	BMS, BATTERY, SWITCH, BATTERY 48V, 48V BATTERY	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead titanium zirconium oxide [12626-81-2], 1,3-Propanesultone [1120-71-4], Octamethylcyclotetrasiloxane [556-67-2], 1-Propanol, 2,3-dibromo- [96-13-9], Lead-titanium-trioxide [12060-00-3], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1]
Electric Power Supply / Instruments - [lighting]	CONTROL UNIT HCM, HEADLAMP, OVERHEAD CONSOLE LENS, READING LAMP, LAMP LED, LIGHTING, LIGHTNING INSTRUMENT PANEL, LED MODULE, STOP LAMP, REAR LAMP, FOG LIGHT	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], TBBA [79-94-7], 1-Methyl-2-pyrrolidone [872-50-4], Dicyclohexyl-phthalate [84-61-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Octamethylcyclotetrasiloxane [556-67-2], Silicic acid, lead salt [11120-22-2], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Melamine [108-78-1], Lead-titanium-trioxide [12060-00-3]
Engine - [selective catalytic reduction]	CONTROL UNIT, PUMP MODULE, SENSOR, BRACKET, TANK, CONTROL MODULE	Lead [7439-92-1], Nonylphenol [25154-52-3], Lead-titanium-trioxide [12060-00-3], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Decamethylcyclopentasiloxane [541-02-6], Dodecamethylcyclohexasiloxane [540-97-6], TBBA [79-94-7], Lead titanium zirconium oxide [12626-81-2], Octamethylcyclotetrasiloxane [556-67-2], Silicic acid, lead salt [11120-22-2]

Electric Power Supply / Instruments - [cable system]	CABLE, CABLE HARNESS, CABLE FLOOR, CABLE HARNESS WEM, CABLE DUCT, BRACKET, FLANGE NUT, DISCONNECTOR POWER, FUSE BOX ASSY, CABLE PAC, FUSE BOX, PRINTED CIRCUIT BOARD, CABLE INFOTAINMENT	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Tris(nonylphenyl)phosphite [26523-78-4], TBBA [79-94-7], Dicyclohexyl-phthalate [84-61-7], Cobalt-dinitrate [10141-05-6], Diboron-trioxide [1303-86-2], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Paraffin oils, chloro [85422-92-0], 4,4'-Isopropylidenediphenol [80-05-7]
Electric Power Supply / Instruments - [automatic monitoring / control]	SIREN, RAIN SENSOR, CONTROL UNIT, REMOTE KEY, TRM, SENSOR	Lead-monoxide [1317-36-8], Lead [7439-92-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Diboron-trioxide [1303-86-2], Lead(II,IV)-oxide [1314-41-6], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead titanium zirconium oxide [12626-81-2], 1,2-Dimethoxyethane [110-71-4], Lead-titanium-trioxide [12060-00-3], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], TBBA [79-94-7]
Power Transmission - [gear lever carrier / gear selector controls]	GEAR LEVER CARRIER	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
Brake - [brake line with connections]	BRAKE PIPE, BRAKE PIPE FRONT, BRAKE PIPE REAR	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Engine - [engine / engine mounting]	ENGINE MOUNT, TORQUE ROD, TORQUE LINK BRACKET, ENGINE BRACKET	Lead [7439-92-1]
Body, Interior / Exterior - [bonnet / cover with assembly parts]	HOOD LOCK, COVER, FOAM, HOOD RELEASE CABLE, HOOD LOCK CONTROL	Lead [7439-92-1], C,C'-azodi(formamide) [123-77-3], Imidazolidine-2-thione [96-45-7]
Electric Power Supply / Instruments - [vehicle computational units / gateway modules]	CONTROL UNIT	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8]
Power Transmission - [gearbox]	TORQUE CONVERTER, AUTOMATIC GEARBOX, CONTROL UNIT, VALVE BODY, CABLE HARNESS, CONNECTOR	Lead [7439-92-1], Lead-monoxide [1317-36-8], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], Diboron-trioxide [1303-86-2], Nonylphenol [25154-52-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7], 1-Methyl-2-pyrrolidone [872-50-4], Lead titanium zirconium oxide [12626-81-2]
Body, Interior / Exterior - [glass, window / windscreen / roof]	WINDSCREEN, GLASS HARDENED, GLASS LAMINATED, REAR SCREEN, QUARTER GLASS HARDENED, QUARTER GLASS LAMINATED	Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [side door]	SIDE DOOR, WINDOW LIFT, HEMMING ADHESIVE, CARRIER PLATE, BODY MOUNTED SEALING, DOOR MOUNTED SEALING	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1], Imidazolidine-2-thione [96-45-7], C,C'-azodi(formamide) [123-77-3]

Body, Interior / Exterior - [recovery / towing unit]	TOWING HOOK, TRM, HARNESS	Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7]
Electric Power Supply / Instruments - [mobile data services]	CONTROL UNIT	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1]
Electric Power Supply / Instruments - [electric drive system]	VOLTAGE CONVERTER, STARTER MOTOR ALTERNATOR, COOLANT PIPE, SENSOR, STARTER MOTOR, BRACKET	Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Dicyclohexyl-phthalate [84-61-7], N,N-Dimethylacetamide [127-19-5]
Body, Interior / Exterior - [roof]	PANORAMA ROOF, GLASS PANEL, WELD SEALANT CURING, ADHESIVE ROOF HATCH, MOTOR	Lead [7439-92-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Tris(nonylphenyl)phosphite [26523-78-4], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], C,C'-azodi(formamide) [123-77-3], Lead-monoxide [1317-36-8]
Electric Power Supply / Instruments - [communication, mobile telephone]	CONTROL UNIT, WIRELESS CHARGE SYSTEM, BATTERY, PRINTED CIRCUIT BOARD	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Engine - [fuel / EVAP system]	FUEL PUMP MODULE, PURGE VALVE, LEAK DETECTION PUMP, PURGE VALVE ASSY, CANISTER, FUEL PRESSURE SENSOR, HOSE, FUEL FILTER, FUEL TANK, TANK WELDED, HIGH PRESSURE PUMP, FUEL DISTRIBUTION PIPE, INJECTOR, FUEL PUMP, DELIVERY PIPE, INJECTION VALVE	Lead-monoxide [1317-36-8], Lead [7439-92-1], Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], TBBA [79-94-7], Cobalt-dinitrate [10141-05-6], C,C'-azodi(formamide) [123-77-3]
Body, Interior / Exterior - [seat belt / other restraining systems]	HEIGHT ADJUSTMENT, BELT CATCH, SEAT BELT, BELT, LOAD NET, BELT CATCH REAR	Lead [7439-92-1], TBBA [79-94-7], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt sulphate [10124-43-3], Lead-monoxide [1317-36-8], Melamine [108-78-1], Cobalt-dinitrate [10141-05-6]
Electric Power Supply / Instruments - [cleaner]	WIPER UNIT, WASHER FLUID RESERVOIR, REAR WIPER, HEADLAMP WIPER, PUMP, DUAL PUMP, WIPER ARM	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [floor / frame section / wheel housing / firewall]	BUMPER BEAM, FRONT SIDE MEMBER, WHEEL HOUSING, WELD SEALANT CURING, ADHESIVE, TOP COVER, REINFORCEMENT, SIDE MEMBER UPPER INNER, BRACE INNER, BRACE OUTER, CRASH BOX REINFORCEMENT, FLOOR PANEL, BATTERY TRAY, CRASH BOX	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]

Engine - [emission equipment]	COOLER, LAMBDA SOND, PRESSURE SENSOR, VALVE, TEMPERATURE SENSOR EGT, TEMPERATURE SENSOR	Lead [7439-92-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Lead-monoxide [1317-36-8], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
Engine - [intercooler / connection]	CHARGE AIR COOLER, CHARGE AIR HOSE, CHARGE AIR PIPE, RESONATOR	Lead [7439-92-1], Boric acid [10043-35-3]
Body, Interior / Exterior - [trunk lid / tailgate complete]	REAR DOOR, SPINDLE DRIVE	Lead [7439-92-1], TBBA [79-94-7], Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8]
Wheel Suspension / Steering - [axle member / link arm / suspension]	LOWER LINK ARM, SUBFRAME FRONT, UPPER LINK ARM	Imidazolidine-2-thione [96-45-7], Cobalt-dichloride [7646-79-9], Lead [7439-92-1]
Engine - [inlet / exhaust systems]	TAILPIPE, THROTTLE, EXHAUST SYSTEM, HEAT SHIELD PLATE, INTAKE MANIFOLD	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 4,4'-Isopropylidenediphenol [80-05-7], Boric acid [10043-35-3], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
Body, Interior / Exterior - [outside mirrors]	REAR VIEW MIRROR OUTER, CAMERA, REAR VIEW MIRROR, MOTOR UNIT, DIRECTION INDICATOR, TEMPERATURE SENSOR, GLASS, REAR VIEW MIRROR CASING	Lead [7439-92-1], Lead-monoxide [1317-36-8], Octamethylcyclotetrasiloxane [556-67-2], Diboron-trioxide [1303-86-2], Dicyclohexyl-phthalate [84-61-7], 2-Methylimidazole [693-98-1], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Lead titanium zirconium oxide [12626-81-2], TBBA [79-94-7], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Melamine [108-78-1], Tris(nonylphenyl)phosphite [26523-78-4]
Brake - [wheel brake]	BRAKE CALIPER, HOUSING, AIR VENTING NIPPLE, EPB, BLEEDER VALVE	Lead [7439-92-1], 2-Methylimidazole [693-98-1], Tris(nonylphenyl)phosphite [26523-78-4], Hexahydromethylphthalic-anhydride [25550-51-0]
Electric Power Supply / Instruments - [protection]	SENSOR REAR, CONTROL UNIT, SENSOR FRONT, ACCELEROMETER FRONT	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], TBBA [79-94-7]
Body, Interior / Exterior - [airbag]	AIRBAG MODULE, CONTROL UNIT, ACCELEROMETER SENSOR	4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7], Lead-monoxide [1317-36-8]
Electric Power Supply / Instruments - [electrical distribution box / fuse box]	CEM, ATTACHMENT	Lead-monoxide [1317-36-8], Lead [7439-92-1], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [instruction / information plates]	DECAL SRS, NUMBER PLATE HOLDER, SIX POINT SOCKET SCREW	2-ethylhexyl 10-ethyl-4,4-dioctyl-7-oxo-8-oxa-3,5-dithia-4-stannatetradecanoate [15571-58-1], Imidazolidine-2-thione [96-45-7], 1-Methyl-2-pyrrolidone [872-50-4]

Body, Interior / Exterior - [instrument / radio panel]	LAMP LED, STORAGE BOX, HINGE PIN, CONCEALING PANEL, GLOVE BOX	TBBA [79-94-7], Lead [7439-92-1]
Power Transmission - [final drive]	BRACKET, PT-UNIT	Lead [7439-92-1]
Body, Interior / Exterior - [body side]	WELD SEALANT CURING, ADHESIVE	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Frame / Springs / Damping / Wheels - [rim]	KEY, WHEEL BOLT, ADHESIVE BALANCE WEIGHT	Lead [7439-92-1], 2-Methylimidazole [693-98-1]
Frame / Springs / Damping / Wheels - [anti-roll bar]	LINK FRONT ANTI-ROLL BAR, LINK ANTI-ROLL BAR, ANTI-ROLL BAR REAR, ANTI-ROLL BAR FRONT	Imidazolidine-2-thione [96-45-7], 2-Methylimidazole [693-98-1]
Body, Interior / Exterior - [miscellaneous]	TRANSPORT PROTECTION, SEALANT REPAIR, SEALING, SOUND INSULATION	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Dibutylbis(pentane-2,4-dionato-O,O')tin [22673-19-4], C,C'-azodi(formamide) [123-77-3], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [hood cover]	ANTIFLUTTER, FOAM, HOOD	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], C,C'-azodi(formamide) [123-77-3]
Brake - [brake control]	SENSOR, PEDAL UNIT	Lead [7439-92-1]
Electric Power Supply / Instruments - [antenna]	ANTENNA AMPLIFIER, ETC ON BOARD UNIT, ANTENNA, ETC MODULE	TBBA [79-94-7], Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead titanium zirconium oxide [12626-81-2], 1-Propanol, 2,3-dibromo- [96-13-9], Melamine [108-78-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1]
Body, Interior / Exterior - [tank hatch]	ACTUATOR, PLASTIC MODULE	Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [spring, leaf spring]	RESEVOIR, HOSE COUPLING, VALVE BLOCK, AIR SPRING REAR, TOPMOUNT, COMPRESSOR	Lead [7439-92-1], Decamethylcyclopentasiloxane [541-02-6], Tris(nonylphenyl)phosphite [26523-78-4]
Electric Power Supply / Instruments - [horn]	HORN	Lead [7439-92-1], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [exterior equipment]	ACTIVE GRILLE SHUTTER, ACTIVE SPOILER SHUTTER	Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Electric Power Supply / Instruments - [starting system]	STARTER MOTOR	Lead [7439-92-1]

Engine - [accelerator control]	ACCELERATOR PEDAL	Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-monoxide [1317-36-8]
Engine - [miscellaneous / help device installation]	SPLASH PROTECTION, BRACKET, TENSIONER, GUIDE SLEEVE	Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [shock absorber]	SHOCK ABSORBER FRONT, TOPMOUNT, SHOCK ABSORBER, SHOCK ABSORBER REAR	Lead [7439-92-1]
Electric Power Supply / Instruments - [cable system high voltage]	CHARGE CABLE CORD	Lead [7439-92-1], Melamine [108-78-1], Octamethylcyclotetrasiloxane [556-67-2], Lead-monoxide [1317-36-8]
Engine - [cold zone / batterybox]	NVH PANEL	Lead [7439-92-1]
Engine - [supercharging]	SLEEVE, PIPE COMPRESSOR, TURBO CHARGER, OIL DRAINING PIPE, COMPRESSOR, O-RING, STAY COMPRESSOR, SUPERCHARGER, THROTTLE, VACUUM RESERVOIR, VACUUM REGULATOR, BYPASS HOUSING, COMPRESSOR PIPE, BRACKET, MP TURBO, INLET PIPE	Lead [7439-92-1], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], N,N-Dimethylacetamide [127-19-5], Melamine [108-78-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Lead-monoxide [1317-36-8], Dicyclohexyl-phthalate [84-61-7]
Engine - [transmission]	TENSIONER, CAMSHAFT, IDLER PULLEY, HOUSING, SOLENOID, GASKET, BALANCE SHAFT, BELT PROTECTOR, BELT COVER, VVT ACTUATOR, SLEEVE	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Engine - [lubricating and oil system]	OIL SUMP, SUCTION LINE, OIL PUMP, PISTON COOLING JET, GASKET, VALVE, INLET PIPE, PISTON COOLING VALVE, WINDAGE TRAY, OIL LEVEL SENSOR, OIL FILTER, PLUG, OIL PRESSURE SENSOR	Lead [7439-92-1], Bis(4-chlorophenyl) sulfon [80-07-9], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7], Diboron-trioxide [1303-86-2]
Engine - [cylinder block / head]	CYLINDER HEAD, BEDPLATE, ENGINE BRACKET, VACUUM PUMP, CYLINDER BLOCK, TOP COVER, GUIDE SLEEVE, BEARING HOUSE CAM SHAFT, CAP, CAM SHAFT COVER, PROTECTING CASING, CAMSHAFT CAP, HOUSING, CAM SHAFT HOUSING, LOCATING PIN	Lead [7439-92-1]
Engine - [distributor]	CRANKSHAFT POS SENSOR, CAMSHAFT POSITION SENSOR, BRACKET, KNOCK SENSOR	Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2]
Engine - [crank mechanism]	DUAL MASS FLYWHEEL, NIPPLE, NON-RETURN VALVE	Lead [7439-92-1]
Engine - [ignition / spark plug]	GLOW PLUG, IGNITION COIL, SPARK PLUG, CONTROL UNIT	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8]
Engine - [air cleaner]	RESONATOR, HOSE MODULE	Lead [7439-92-1]