

C40 MODEL YEAR 2026
Candidate List Substances Table

Released: 2025 week 35.

We hereby inform that almost all product areas contain lead (CAS No 7439-92-1), primarily as alloying elements in steel, aluminium and copper.

Localisation	Partnames	Substance/s
Wheel Suspension / Steering - [axle member / link arm / suspension]	HUB, TRIPLESQUARE SOCKET SCREW, BUSHING, SUBFRAME	O,O,O-Triphenyl phosphorothioate [597-82-0], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Wheel Suspension / Steering - [front suspension]	HUB, TRIPLESQUARE SOCKET SCREW	O,O,O-Triphenyl phosphorothioate [597-82-0], Diboron-trioxide [1303-86-2]
Electric Power Supply / Instruments - [support systems]	SENSOR, CONTROL UNIT, CAMERA, RADAR, EXT743, EXT747, EXT746, EXT744, EXT745, EXT748	Lead-monoxide [1317-36-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Dodecamethylcyclotetrasiloxane [540-97-6], Diboron-trioxide [1303-86-2], 2-Methylimidazole [693-98-1], Dicyclohexyl-phthalate [84-61-7], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Lead-titanium-trioxide [12060-00-3], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], TBBA [79-94-7], Lead titanium zirconium oxide [12626-81-2], Lead [7439-92-1]
Electric Power Supply / Instruments - [radio equipment]	MICROPHONE, SOUND MODULE, AUDIO MODULE, TWEETER, SUBWOOFER, WOOFER	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Triphenyl-phosphate [115-86-6], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Cobalt(II) nitrate hexahydrate [10026-22-9], Imidazolidine-2-thione [96-45-7], Lead [7439-92-1]
Body, Interior / Exterior - [upholstery]	DOOR PANEL, CLIP HOUSING, SHIM	Triphenyl-phosphate [115-86-6], C,C'-azodi(formamide) [123-77-3], Bumetrizole [3896-11-5], Lead [7439-92-1]
Body, Interior / Exterior - [side door]	CARRIER, BELT MOULDING	O,O,O-Triphenyl phosphorothioate [597-82-0], Bumetrizole [3896-11-5], Lead [7439-92-1]
Body, Interior / Exterior - [lock / handle]	OUTER HANDLE, LOCK, EXT743, EXT745, EXT746, EXT744, WIRE, LOCK CYLINDER SET, DOOR LOCK, KEY	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Hexahydromethylphthalic-anhydride [25550-51-0], Triphenyl-phosphate [115-86-6], Melamine [108-78-1], Diboron-trioxide [1303-86-2], Bumetrizole [3896-11-5], Lead [7439-92-1]

Body, Interior / Exterior - [seats]	HEAD RESTRAINT, UPHOLSTERY, ARM REST, FOG, LUMBAR SUPPORT, REAR SEAT, FRONT SEAT, FRONT SEAT CUSHION EXTENS, FRONT SEAT BACKREST, UNDERCARRIAGE, SIX POINT SOCKET SCREW, COVER, CHARCOAL SOLID, HATCH, BACKREST FRAME, ENGINE, LATCH BEZEL, CHARCOAL SOLI, CABLE HARNESS, ECU, FRAMEWORK	Triphenyl-phosphate [115-86-6], C,C'-azodi(formamide) [123-77-3], Melamine [108-78-1], Hexahydromethylphthalic-anhydride [25550-51-0], Phenol, dimethyl-, phosphate (3:1) [25155-23-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 1-Methyl-2-pyrrolidone [872-50-4], Bumetrizole [3896-11-5], O,O,O-Triphenyl phosphorothioate [597-82-0], Sodium borate, decahydrate [1303-96-4], Acrylamide [79-06-1], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], N,N-Dimethylacetamide [127-19-5], Lead [7439-92-1]
Body, Interior / Exterior - [air conditioning]	AIR INLET, CHILLER BRACKET, IONIZER, SUN SENSOR, WATER CONDENSER, PIPE ASSEMBLY, CHILLER, CLIMATE UNIT, BLOCK WATER CONDENSER, ELECTRICAL HEATER, EL COMPRESSOR, BLOCK, HUMIDITY SENSOR, CONTROL UNIT FAN, RUBBER BUSHING, SENSOR PRESSURE TEMP, PRESSURE HOSE, MAIN BRACKET, BLOCK BRACKET, HARNESS, KIT RETAINER HOSE, SENSOR, SENSOR EVAPORATOR, SENSOR HEX, SENSOR AQS, TXV, SHUT-OFF VALVE, CHANNEL SENSOR, VALVE	Lead-monoxide [1317-36-8], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Bumetrizole [3896-11-5], Lead titanium zirconium oxide [12626-81-2], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Dodecamethylcyclohexasiloxane [540-97-6], Diboron-trioxide [1303-86-2], C,C'-azodi(formamide) [123-77-3], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7], Lead [7439-92-1]
Electric Power Supply / Instruments - [vehicle control system]	ECU, CONTROL UNIT DOOR, ECU MODULE SEAT HEATING, SWITCH DOOR, CONTROL PANEL 12W, SWITCH, SWITCH PANEL, CUT-OFF SWITCH, USB POWER OUTLET, STALK MODULE, COMBI INSTRUMENT, HARDWARE, SWITCH WINDOW LIFT, LOCK BUTTON, BUTTON, SWITCH CRUISE CONTROL	Lead titanium zirconium oxide [12626-81-2], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], TBBA [79-94-7], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7], Triphenyl-phosphate [115-86-6], Boric acid [10043-35-3], Lead-titanium-trioxide [12060-00-3], Lead [7439-92-1]
Brake - [brake control]	BRAKE LIGHT SWITCH	Triphenyl-phosphate [115-86-6], Lead [7439-92-1]
Electric Power Supply / Instruments - [lighting]	READING LAMP, HEADLAMP, REAR LAMP, OVERHEAD CONSOLE LENS, CONTROL UNIT HCM, LIGHTING, LAMP LED, LED MODULE, FOG LIGHT	Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Diboron-trioxide [1303-86-2], Dicyclohexyl-phthalate [84-61-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], TBBA [79-94-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1], Lead-titanium-trioxide [12060-00-3], Lead [7439-92-1]
Body, Interior / Exterior - [instrument / radio panel]	DECOR WOOD, LIGHTNING INSTRUMENT PANEL, PANEL NOZZLE, FRAME, LED MODULE, DIM COOLING, DECOR SPINNAKER, DECOR DIAMOND CUT, INSTRUMENT PANEL, HINGE PIN, GLOVE BOX	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Tris(nonylphenyl)phosphite [26523-78-4], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1]

Engine - [cooling system]	FAN, HOSE, COOLING MODULE, CONDENSER, 4WAY VALVE, ELECTRIC WATER PUMP, HOSE RADIATOR QC, VALVE, COOLER, SET, PLUG, THREE-WAY VALVE, RETURN PIPE, TEMPERATURE SENSOR, BRACKET	O,O,O-Triphenyl phosphorothioate [597-82-0], TBBA [79-94-7], Melamine [108-78-1], Lead-monoxide [1317-36-8], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [outside / exterior trim]	EMBLEM	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
Body, Interior / Exterior - [outside mirrors]	REAR VIEW MIRROR, CAMERA, REAR VIEW MIRROR OUTER, MOTOR UNIT, GLASS	Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-Methylimidazole [693-98-1], Dicyclohexyl-phthalate [84-61-7], Lead-monoxide [1317-36-8], TBBA [79-94-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Cobalt-dinitrate [10141-05-6], Lead [7439-92-1]
Electric Power Supply / Instruments - [cable system high voltage]	CHARGE CABLE CORD, CHARGE CABLE, CABLE HARNESS, CABLE CHARGE POINT HV, CABLE HARNESS ENGINE, CABLE HARNESS HV, ADAPTER, BRACKET, STRAIN RELIEF, CABLE DUCT, CHANNEL	Octamethylcyclotetrasiloxane [556-67-2], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Melamine [108-78-1], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Lead [7439-92-1]
Wheel Suspension / Steering - [steering gear / wheel / shaft / column]	SEALING FLOOR LHD, SEALING FLOOR RHD, STEERING COLUMN LOCK, STEERING COLUMN MANUAL, STEERING GEAR, COVER PLUG, CHARCOAL SO, STEERING WHEEL	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], O,O,O-Triphenyl phosphorothioate [597-82-0], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Dodecamethylcyclohexasiloxane [540-97-6], Diboron-trioxide [1303-86-2], TBBA [79-94-7], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead [7439-92-1]
Electric Power Supply / Instruments - [mobile data services]	CONTROL UNIT	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1], Lead [7439-92-1]
Electric Power Supply / Instruments - [communication, mobile telephone]	CONTROL UNIT, BATTERY, WIRELESS CHARGE SYSTEM	Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Body, Interior / Exterior - [interior equipment]	ARM REST, EC REAR VIEW MIRROR, DAWN, AIR OUTLET, CUP HOLDER, REAR BRACKET, BRACKET	C,C'-azodi(formamide) [123-77-3], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Cobalt sulphate [10124-43-3], TBBA [79-94-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Tris(nonylphenyl)phosphite [26523-78-4], Lead [7439-92-1]

Body, Interior / Exterior - [glass, window / windscreen / roof]	REAR SCREEN, QUARTER GLASS DOOR HARDENED, WINDSCREEN	Diboron-trioxide [1303-86-2], Bumetrizole [3896-11-5]
Body, Interior / Exterior - [exterior equipment]	STOP LAMP, ACTIVE GRILLE SHUTTER, ACTIVE SPOILER SHUTTER	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead [7439-92-1]
Electric Power Supply / Instruments - [cleaner]	WIPER APPARATUS, SEALING, WASHER FLUID RESERVOIR, WASHER PUMP, LEVEL SENSOR, PUMP, WIPER ARM	Lead-monoxide [1317-36-8], O,O,O-Triphenyl phosphorothioate [597-82-0], Diboron- trioxide [1303-86-2], TBBA [79-94-7], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1]
Body, Interior / Exterior - [seat belt / other restraining systems]	SEAT BELT, BELT, HEIGHT ADJUSTMENT, BELT CATCH	Triphenyl-phosphate [115-86-6], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt(II) nitrate hexahydrate [10026-22-9], Cobalt-dinitrate [10141-05-6], TBBA [79-94- 7], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead-monoxide [1317-36-8], Melamine [108-78-1], Decamethyltetrasiloxane [141-62-8], Lead [7439-92-1]
Electric Power Supply / Instruments - [automatic monitoring / control]	RAIN SENSOR, SIREN, SENSOR, REMOTE KEY, CONTROL UNIT, TRM	Lead-monoxide [1317-36-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead titanium zirconium oxide [12626-81-2], 1,2-Dimethoxyethane [110-71-4], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], Lead [7439-92-1]
Body, Interior / Exterior - [trunk lid / tailgate complete]	TAILGATE, ANTIFLUTTER, SPINDLE DRIVE	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Methyl-1-(4-methylthiophenyl)-2- morpholinopropan-1-one [71868-10-5], Melamine [108-78-1], Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [rim]	ADHESIVE BALANCE WEIGHT, WHEEL 7, 5X19X50, 5, WHEEL 8, 5X19X56, VALVE, KEY, WHEEL BOLT	Diboron-trioxide [1303-86-2], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], 2-Methylimidazole [693-98-1], Lead [7439-92-1]
Electric Power Supply / Instruments - [battery and mounting parts]	HOUSING, PLUG, BUSBAR, BATTERY MODULE, CURRENT SENSOR, SERVICE LID, BARRIER RIGHT, BARRIER LEFT, BATTERY DISCONNECT UNIT, LID, RAIL INLET, RAIL, SWITCH, CONNECTOR, TEMP SENSOR, BATTERY, BMS	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Dodecamethylcyclotetrasiloxane [540-97-6], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556- 67-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 2-Methyl-1-(4- methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Triphenyl-phosphate [115-86- 6], Alkanes, C14-17, chloro [85535-85-9], Lead [7439-92-1]
Engine - [control systems]	CONTROL UNIT	Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Lead [7439-92-1]

Electric Power Supply / Instruments - [antenna]	ANTENNA AMPLIFIER, ETC MODULE, WAVE TRAP, GROUND SIDE COIL, ETC ON BOARD UNIT, ANTENNA	Lead-monoxide [1317-36-8], Melamine [108-78-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2], 4,4'-Isopropylidenediphenol [80-05-7], Hexahydromethylphthalic-anhydride [25550-51-0], Lead titanium zirconium oxide [12626-81-2], 1-Propanol, 2,3-dibromo- [96-13-9], Lead [7439-92-1]
Brake - [wheel brake]	BRAKE CALIPER, HOUSING, EPB, AIR VENTING NIPPLE, BLEEDER VALVE	O,O,O-Triphenyl phosphorothioate [597-82-0], 2-Methylimidazole [693-98-1], Diboron-trioxide [1303-86-2], Tris(nonylphenyl)phosphite [26523-78-4], Hexahydromethylphthalic-anhydride [25550-51-0], Lead [7439-92-1]
Electric Power Supply / Instruments - [vehicle computational units / gateway modules]	CONTROL UNIT	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Power Transmission - [electrical axis drive]	O-RING, SEALING, SEALING RING, DRIVE SHAFT SEAL, INVERTER, GASKET, DRIVE SHAFT, ELECTRIC MOTOR, REAR AXLE, FRONT AXLE, FLANGE SCREW, INNER HOUSING, OUTER HOUSING, BRACKET, TRANSMISSION HOUSE	Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Triphenyl-phosphate [115-86-6], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead-monoxide [1317-36-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], Sodium borate, pentahydrate [12179-04-3], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], N,N-Dimethylacetamide [127-19-5], Melamine [108-78-1], Cobalt-dichloride [7646-79-9], Lead [7439-92-1]
Electric Power Supply / Instruments - [electric drive system]	FUSE, VOLTAGE CONVERTER, ONBOARD CHARGER, INVERTER TRANSDUCER, BRACKET	Melamine [108-78-1], Lead-monoxide [1317-36-8], N,N-Dimethylacetamide [127-19-5], 1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2], Terphenyl, hydrogenated [61788-32-7], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Triphenyl-phosphate [115-86-6], 2-Methylimidazole [693-98-1], Lead [7439-92-1]
Electric Power Supply / Instruments - [cable system]	CABLE IP, CABLE FLOOR, CABLE HARNESS, CABLE, BRACKET, FUSE BOX HOUSING, CABLE HARNESS TAILGATE, BRACKET CJB	Triphenyl-phosphate [115-86-6], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Bumetrizole [3896-11-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]

Body, Interior / Exterior - [airbag]	CONTROL UNIT, AIRBAG MODULE, ACCELEROMETER SENSOR, AIRBAG	Lead-monoxide [1317-36-8], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Refractory ceramic fibres [142844-00-6], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]
Body, Interior / Exterior - [hood cover]	HOOD, ANTIFLUTTER	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Power Transmission - [gear lever carrier / gear selector controls]	GEAR LEVER CARRIER	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead [7439-92-1]
Body, Interior / Exterior - [roof]	GLASS ROOF	Bumetrizole [3896-11-5]
Brake - [brake line with connections]	BRAKE PIPE, BRAKE PIPE FRONT, BRAKE PIPE ENGINE COMPART, BRAKE PIPE REAR, RETAINER	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bumetrizole [3896-11-5], Lead [7439-92-1]
Electric Power Supply / Instruments - [infotainment system]	PRINTED CIRCUIT BOARD, DISPLAY, USB HUB	Lead-monoxide [1317-36-8], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 4,4'-Isopropylidenediphenol [80-05-7], Diboron-trioxide [1303-86-2], Melamine [108-78-1], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Boric acid [10043-35-3], Triphenyl-phosphate [115-86-6], Lead [7439-92-1]
Electric Power Supply / Instruments - [electric drive system, high voltage]	BATTERY CONTROL UNIT, CELL VOLTAGE TEMP NODE	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Dodecamethylcyclotetrasiloxane [540-97-6], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Lead-monoxide [1317-36-8], Melamine [108-78-1], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Brake - [brake, anti lock (anti-skid)]	HYDRAULIC UNIT MKC1, SENSOR	Lead titanium zirconium oxide [12626-81-2], TBBA [79-94-7], Boric acid [10043-35-3], O,O,O-Triphenyl phosphorothioate [597-82-0], Cobalt(II) nitrate hexahydrate [10026-22-9], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Electric Power Supply / Instruments - [electrical distribution box / fuse box]	CEM	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [tool / jack]	JACK, COMPRESSOR, BOTTLE	Ethylenediamine [107-15-3], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]

Body, Interior / Exterior - [floor / frame section / wheel housing / firewall]	WELD SEALANT CURING, WELD NUT, CARRIER	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Boric acid [10043-35-3], Lead [7439-92-1]
Electric Power Supply / Instruments - [horn]	HORN	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [bonnet / cover with assembly parts]	HOOD LOCK, COVER	4-Nonylphenol, branched [84852-15-3], Lead [7439-92-1]
Body, Interior / Exterior - [climate unit]	CONTROL UNIT	Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Electric Power Supply / Instruments - [protection]	LEVEL SENSOR FRONT, LEVEL SENSOR REAR, SENSOR	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead-monoxide [1317-36-8], Lead [7439-92-1]
Body, Interior / Exterior - [miscellaneous]	TRANSPORT PROTECTION, SEALANT REPAIR	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Dibutylbis(pentane-2,4-dionato-O,O')tin [22673-19-4]
Electric Power Supply / Instruments - [cable components]	BRACKET, DISCONNECTOR POWER, DIODE, FUSE BOX, BOTTOM PART, CHANNEL, FUSE BOX HOUSING, FRAME ASSY, STRAIN RELIEF, CABLE DUCT, RECEPTACLE HOUSING, ADAPTER PLATE	TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Brake - [master cylinder / brake booster]	LID	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Frame / Springs / Damping / Wheels - [anti-roll bar]	LINK ANTI-ROLL BAR	Imidazolidine-2-thione [96-45-7]
Body, Interior / Exterior - [instruction / information plates]	NUMBER PLATE HOLDER	Lead [7439-92-1]
Body, Interior / Exterior - [recovery / towing unit]	TOWING HOOK, HARNESS	Lead [7439-92-1]
Engine - [engine / engine mounting]	BRACKET ENGINE MOUNT, TORQUE ROD LOWER, ENGINE MOUNT	Lead [7439-92-1]