

ES90 MODEL YEAR 2026
Candidate List Substances Table

Released: 2025 week 35.

We hereby inform that almost all product areas contain lead (CAS No 7439-92-1), primarily as alloying elements in steel, aluminium and copper.

Localisation	Partnames	Substance/s
Frame / Springs / Damping / Wheels - [spring, hydraulic / gas / air spring]	VALVE BLOCK, AIR SUPPLY UNIT, CONNECTOR, AIR HOSE, AIR TANK, HOSE COUPLING	Lead-monoxide [1317-36-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead [7439-92-1]
Electric Power Supply / Instruments - [vehicle control system]	USB - C CHARGER, SWITCH, CUT-OFF SWITCH, CONTROL UNIT DOOR, ECU, STALK MODULE, SWITCH WINDOW LIFT, CONTROL PANEL POWER SEAT, MSM, SWITCH PANEL	Lead-monoxide [1317-36-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], TBBA [79-94-7], Lead [7439-92-1]
Wheel Suspension / Steering - [axle member / link arm / suspension]	CONTROL ARM, HUB, BUSHING, BUSHING SUBFRAME, LOWER LINK ARM CPL, SUBFRAME REAR	Imidazolidine-2-thione [96-45-7], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead [7439-92-1]
Electric Power Supply / Instruments - [protection]	ACCELEROMETER, CONTROL UNIT, LEVEL SENSOR, LEVEL SENSOR REAR, LEVEL SENSOR FRONT RH	Lead-monoxide [1317-36-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Electric Power Supply / Instruments - [support systems]	SENSOR, EXT743, DRIVER MONITORING CAMERA, CAMERA, RADAR, FAN, CONTROL UNIT, THERMAL UNIT, LIDAR, EXT744, EXT745, EXT746	Dodecamethylcyclotetrasiloxane [540-97-6], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Lead-titanium-trioxide [12060-00-3], Melamine [108-78-1], Cobalt(II) nitrate hexahydrate [10026-22-9], TBBA [79-94-7], 1-Methyl-2-pyrrolidone [872-50-4], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], N,N-Dimethylacetamide [127-19-5], Lead [7439-92-1]
Electric Power Supply / Instruments - [antenna]	ANTENNA AMPLIFIER, CARD READER, ETC ANTENNA, ETC	Lead-monoxide [1317-36-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead titanium zirconium oxide [12626-81-2], Diboron-trioxide [1303-86-2], 1-Propanol, 2,3-dibromo- [96-13-9], Melamine [108-78-1], Lead [7439-92-1]

Body, Interior / Exterior - [lock / handle]	LOCK, SIX POINT SOCKET SCREW, OUTER HANDLE, SOFT CLOSING REAR RH, SOFT CLOSING REAR LH, ACTUATOR SOFT CLOSING, BRACKET, EXT739, EXT743, EXT747, EXT745, EXT746, EXT749	Hexahydromethylphthalic-anhydride [25550-51-0], Triphenyl-phosphate [115-86-6], Melamine [108-78-1], 1-Methyl-2-pyrrolidone [872-50-4], Diboron-trioxide [1303-86-2], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead-monoxide [1317-36-8], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Bumetrizole [3896-11-5], 2-Methylimidazole [693-98-1], C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1]
Body, Interior / Exterior - [airbag]	ACCELEROMETER, FRONT SENSOR, INFLATABLE CURTAIN, AIRBAG MODULE, DAWN, INFLATABLE KNEE BOLSTER, AIRBAG, CONTROL UNIT, AIRBAG PASSENGER	Lead-monoxide [1317-36-8], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7], Lead [7439-92-1]
Body, Interior / Exterior - [seats]	LOUDSPEAKER, TRIM MOULDING, STRIKER, LOCK, CHARCOAL, DAWN, HARDBACK, COVER, VENTILATION, HEATER FRONT CUSHION, HEATER, HEATER REAR CUSHION, UPHOLSTERY, UPHOLSTERY CARDAMOM, UPHOLSTERY MULBERRY, CARDAMOM, MULBERRY, UPHOLSTERY DAWN, FOG, ARM REST CHARCOAL BROWN, ARM REST CARDAMOM BROWN, ARM REST DAWN LIGHT ASH, ARM REST, ARM REST FOG MELANGE, ARM REST MULBERRY, UNDERCARRIAGE, ARMREST, HEAD REST, CUSHION, WHITE, HEADREST AUDIO, HEADREST, FRONT HEADREST, CUP HOLDER, LUMBAR SUPPORT, LUMBAR SUPPORT 4-WAY, COVER DAWN, LATCH BEZEL, ARMREST MULBERRY	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead-monoxide [1317-36-8], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Bumetrizole [3896-11-5], C,C'-azodi(formamide) [123-77-3], Melamine [108-78-1], Diboron-trioxide [1303-86-2], Triphenyl-phosphate [115-86-6], O,O,O-Triphenyl phosphorothioate [597-82-0], Imidazolidine-2-thione [96-45-7], Lead [7439-92-1]
Electric Power Supply / Instruments - [radio equipment]	LOUDSPEAKER, TWEETER, MIDRANGE, AUDIO MODULE, CENTRE LOUDSPEAKER, WOOFER, MICROPHONE	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2], 4,4'-Isopropylidenediphenol [80-05-7], Lead-monoxide [1317-36-8], Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [anti-roll bar]	LINK FRONT ANTI-ROLL BAR, LINK ANTI-ROLL BAR	Diboron-trioxide [1303-86-2], Imidazolidine-2-thione [96-45-7]
Electric Power Supply / Instruments - [cable system high voltage]	CHARGE CABLE, CABLE HARNESS, FLANGE NUT, CHARGE CABLE CORD, ACTUATOR	Octamethylcyclotetrasiloxane [556-67-2], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Cobalt-dinitrate [10141-05-6], Lead [7439-92-1]

Frame / Springs / Damping / Wheels - [rim]	SENSOR, WHEEL 8, 5X21X38, 5, WHEEL 9X21X44, SPARE WHEEL 20", ADHESIVE BALANCE WEIGHT, VALVE, KEY, WHEEL BOLT	1,2-Dimethoxyethane [110-71-4], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], 2-Methylimidazole [693-98-1], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Wheel Suspension / Steering - [front suspension]	HUB	O,O,O-Triphenyl phosphorothioate [597-82-0]
Electric Power Supply / Instruments - [cable system]	FUSE MODULE, CABLE, CABLE FLOOR, CABLE HARNESS, FLANGE SCREW, FUSE BOX ASSY	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Dodecamethylcyclohexasiloxane [540-97-6], Bumetrizole [3896-11-5], Cobalt-dichloride [7646-79-9], Lead [7439-92-1]
Engine - [accelerator control]	ACCELERATOR PEDAL	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-Methylimidazole [693-98-1], Lead [7439-92-1]
Body, Interior / Exterior - [air conditioning]	GAS HOSE, CHILLER, SENSOR, BOTTLE, EXPANSION VALVE, SENSOR PRESSURE TEMP, WATER COOLED CONDENSER, AIR INLET HOUSING, GROMMET, STEPPING MOTOR, SUN SENSOR, FAN, TEMPERATURE SENSOR, EL COMPRESSOR, BRACKET, PRESSURE HOSE, PIPE ASSEMBLY, ELECTRIC HEATER COOLANT, CLIMATE UNIT, HUMIDITY SENSOR, DISTRIBUTION HOUSING, FLANGE SCREW, AIR CLEANER, PIPE, SENSOR INTERIOR, CHANNEL SENSOR	Decamethylcyclopentasiloxane [541-02-6], Dodecamethylcyclohexasiloxane [540-97-6], Lead-monoxide [1317-36-8], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Melamine [108-78-1], Diboron-trioxide [1303-86-2], Bumetrizole [3896-11-5], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], TBBA [79-94-7], Octamethylcyclotetrasiloxane [556-67-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Cobalt-dichloride [7646-79-9], Lead [7439-92-1]
Electric Power Supply / Instruments - [infotainment system]	DISPLAY, GRAPHIC HEAD UP DISPLAY, CAMERA	TBBA [79-94-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Dibutylbis(pentane-2,4-dionato-O,O')tin [22673-19-4], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], Melamine [108-78-1], Boric acid [10043-35-3], Triphenyl-phosphate [115-86-6], Silicic acid, lead salt [11120-22-2], Lead [7439-92-1]
Electric Power Supply / Instruments - [communication, mobile telephone]	BATTERY, WIRELESS CHARGE SYSTEM, CONTROL UNIT, PRINTED CIRCUIT BOARD	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], 1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4], Triphenyl-phosphate [115-86-6], 2-Ethoxyethanol [110-80-5], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], TBBA [79-94-7], Lead [7439-92-1]
Electric Power Supply / Instruments - [miscellaneous]	TELESCOPE, WASHER FLUID RESERVOIR 5, WASHER FLUID RESERVOIR, DUAL PUMP, WASHER NOZZLE, PUMP, WASHER HOSE	Lead-titanium-trioxide [12060-00-3], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead [7439-92-1]

Power Transmission - [electrical axis drive]	O-RING, SEALING, DRIVE SHAFT SEAL, ELECTRIC MOTOR, SEALING RING, REAR AXLE, INVERTER, FRONT AXLE, FLANGE SCREW, OUTER HOUSING, BRACKET, TRANSMISSION HOUSE, INNER HOUSING	Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Triphenyl-phosphate [115-86-6], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead-titanium-trioxide [12060-00-3], Melamine [108-78-1], 4-tert-Butylphenol [98-54-4], Nonylphenol [25154-52-3], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt-dichloride [7646-79-9], Lead [7439-92-1]
Body, Interior / Exterior - [outside / exterior trim]	EMBLEM, LID	Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Dicyclohexyl-phthalate [84-61-7], Lead [7439-92-1]
Body, Interior / Exterior - [roof]	BRACKET, ANTENNA, GLASS ROOF, BOX	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead-monoxide [1317-36-8], Bumetrizole [3896-11-5], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [bumper with mounting / damping]	CLIP	Bumetrizole [3896-11-5]
Engine - [cooling system]	PUMP, VALVE, GROMMET, FAN, CLIP, HOSE, TEMPERATURE SENSOR	Lead-monoxide [1317-36-8], Octamethylcyclotetrasiloxane [556-67-2], Dodecamethylcyclohexasiloxane [540-97-6], Decamethylcyclopentasiloxane [541-02-6], Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bumetrizole [3896-11-5], Lead [7439-92-1]
Body, Interior / Exterior - [climate unit]	CONTROL UNIT	Lead titanium zirconium oxide [12626-81-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1]
Electric Power Supply / Instruments - [automatic monitoring / control]	CONTROL UNIT, UWB ANTENNA, RAIN SENSOR, SIREN, RFK SET	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-titanium-trioxide [12060-00-3], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead titanium zirconium oxide [12626-81-2], 1,2-Dimethoxyethane [110-71-4], TBBA [79-94-7], Lead [7439-92-1]
Electric Power Supply / Instruments - [electrical distribution box / fuse box]	CONTROL UNIT, BRACKET	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1]

Body, Interior / Exterior - [outside mirrors]	CAMERA, REAR VIEW MIRROR OUTER, REAR VIEW MIRROR, REAR VIEW MIRROR FRAME, GLASS REAR VIEW MIRROR LH, GLASS REAR VIEW MIRROR RH, HOSE, NOZZLE, DIRECTION INDICATOR, GLASS	Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Lead-monoxide [1317-36-8], N,N-Dimethylacetamide [127-19-5], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1]
Body, Interior / Exterior - [lid, cover plate]	LIDAR COVER, GLASS	Tris(nonylphenyl)phosphite [26523-78-4], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [instrument / radio panel]	LAMP, DECOR, TURNED BIRCH, LIGHT ASH, CONCEALING PANEL, PANEL NOZZLE, GLOVE BOX MODULE, PANEL NOZZLE HOUSING, CASSETTE, INSTRUMENT PANEL, ACTUATOR, HINGE PIN	Lead-monoxide [1317-36-8], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Phenol, dimethyl-, phosphate (3:1) [25155-23-1], Lead [7439-92-1]
Electric Power Supply / Instruments - [Lighting Interior areas]	LAMP, SENSOR, OVERHEAD CONSOLE, READING LAMP	Lead-monoxide [1317-36-8], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Lead titanium zirconium oxide [12626-81-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead [7439-92-1]
Electric Power Supply / Instruments - [lighting]	STOP LAMP, REAR BUMPER LAMP LH, REAR BUMPER LAMP RH, HEADLAMP, DAY RUNNING LAMP, CONTROL UNIT HCM, REAR BODY LAMP ECE, COVER, REAR TRUNK LAMP ECE, UPPER LAMP LH, UPPER LAMP RH, MODULE	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Bumetizole [3896-11-5], Lead titanium zirconium oxide [12626-81-2], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-titanium-trioxide [12060-00-3], C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1]
Brake - [brake, anti lock (anti-skid)]	HYDRAULIC UNIT, LID, SENSOR	Lead-titanium-trioxide [12060-00-3], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead titanium zirconium oxide [12626-81-2], TBBA [79-94-7], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]
Wheel Suspension / Steering - [steering gear / wheel / shaft / column]	SEALING FLOOR, STEERING GEAR, STEERING COLUMN, CONTROL UNIT, STEERING WHEEL, CHARCOAL/D	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Diboron-trioxide [1303-86-2], Triphenyl-phosphate [115-86-6], TBBA [79-94-7], O,O,O-Triphenyl phosphorothioate [597-82-0], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 6,6'-Di-tert-butyl-2,2'-methylene-di-p-cresol [119-47-1], Phosphorothioic acid, O,O,O-triphenyl esters, tert-Bu derivs. [192268-65-8], Lead [7439-92-1]

Body, Interior / Exterior - [upholstery]	TRIM MOULDING, TURNED BIRC, LIGHT ASH, INNER DOOR OPENER, DOOR PANEL, CHARCOAL/DAWN, CHARC/CARDAMOM, CHARC/DAWN, LED MODULE, FOAM SEAL, CLIP HOUSING	Lead-monoxide [1317-36-8], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Melamine [108-78-1], C,C'-azodi(formamide) [123-77-3], Bumetrizole [3896-11-5], Lead [7439-92-1]
Electric Power Supply / Instruments - [media, navigation and communication]	PRINTED CIRCUIT BOARD, CONTROL UNIT	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 4,4'-Isopropylidenediphenol [80-05-7], Lead-titanium-trioxide [12060-00-3], Melamine [108-78-1], Lead [7439-92-1]
Body, Interior / Exterior - [body side]	WELD SEALANT CURING	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Body, Interior / Exterior - [floor / frame section / wheel housing / firewall]	WELD SEALANT CURING, FLANGE SCREW	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt-dichloride [7646-79-9]
Electric Power Supply / Instruments - [horn]	HORN	Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [seat belt / other restraining systems]	SEAT BELT, HEIGHT ADJUSTMENT	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Melamine [108-78-1], Triphenyl-phosphate [115-86-6], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Body, Interior / Exterior - [sealings]	EXPANDING SEALING	C,C'-azodi(formamide) [123-77-3], Dicyclohexyl-phthalate [84-61-7]
Body, Interior / Exterior - [front fender]	SPACER, ANTIFLUTTER	Dicyclohexyl-phthalate [84-61-7], C,C'-azodi(formamide) [123-77-3], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Brake - [wheel brake]	BRAKE CALIPER, BRAKE CALIPER 19", MOTOR UNIT, AIR VENTING NIPPLE	O,O,O-Triphenyl phosphorothioate [597-82-0], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]
Electric Power Supply / Instruments - [battery and mounting parts]	FUSE, CABLE HARNESS, BATTERY MODULE, PLATE, CONNECTOR PLATE, SERVICE LID HV BATTERY, TOLERANCE COMPENSATOR, BATTERY, RELAY, BMS, RBMS	Melamine [108-78-1], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) [29420-49-3], Dodecamethylcyclohexasiloxane [540-97-6], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1]

Electric Power Supply / Instruments - [cleaner]	WIPER APPARATUS, DUAL PUMP, WASHER FLUID RESERVOIR 5, PUMP, BLADE PS, WIPER ARM	Lead-monoxide [1317-36-8], O,O,O-Triphenyl phosphorothioate [597-82-0], Cobalt(II) nitrate hexahydrate [10026-22-9], Diboron-trioxide [1303-86-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1]
Body, Interior / Exterior - [tool / jack]	REPAIR KIT, COMPRESSOR, BOTTLE	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]
Body, Interior / Exterior - [interior equipment]	CUP HOLDER, AIR OUTLET, LED MODULE, EC REAR VIEW MIRROR	Lead-monoxide [1317-36-8], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead [7439-92-1]
Body, Interior / Exterior - [glass, window / windscreen / roof]	WINDSCREEN	Bumetizole [3896-11-5]
Body, Interior / Exterior - [side door]	GLASS RUN SEAL	C,C'-azodi(formamide) [123-77-3]
Body, Interior / Exterior - [bonnet / cover with assembly parts]	COVER, SEALING	C,C'-azodi(formamide) [123-77-3]
Electric Power Supply / Instruments - [vehicle computational units / gateway modules]	GATEWAY MODULE, CONTROL UNIT	Melamine [108-78-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 1-Methyl-2-pyrrolidone [872-50-4], Lead [7439-92-1]
Electric Power Supply / Instruments - [electric drive system, high voltage]	CONTROL UNIT, CELL VOLTAGE TEMP NODE, DETECTION UNIT, CURRENT SENSOR	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], Lead [7439-92-1]
Electric Power Supply / Instruments - [electric drive system]	ONBOARD CHARGER, VOLTAGE CONVERTER, CHARGE POINT	Lead-monoxide [1317-36-8], Decamethylcyclopentasiloxane [541-02-6], Boric acid [10043-35-3], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7], 2-Methylimidazole [693-98-1], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Dodecamethylcyclohexasiloxane [540-97-6], Cobalt chloride [7791-13-1], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Electric Power Supply / Instruments - [cable components]	RECEPTACLE HOUSING, TAB HOUSING	Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Dodecamethylcyclohexasiloxane [540-97-6]

Frame / Springs / Damping / Wheels - [spring, leaf spring]	AIR SPRING, TOPMOUNT, PRESSURE RETAIN VALVE, SHOCK ABSORBER, HOSE COUPLING	1-Methyl-2-pyrrolidone [872-50-4], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead [7439-92-1]
Body, Interior / Exterior - [miscellaneous]	TRANSPORT PROTECTION	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Body, Interior / Exterior - [trunk lid / tailgate complete]	ANTIFLUTTER, SPINDLE DRIVE	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Body, Interior / Exterior - [hood cover]	ANTIFLUTTER, TWO STEP GAS SPRING	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Brake - [brake line with connections]	RETAINER, BRAKE PIPE BUNDLE, BRAKE HOSE HECU LH	Bumetrizole [3896-11-5], Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [shock absorber]	TOPMOUNT, TOP MOUNT, SHOCK ABSORBER, SHOCK ABSORBER REAR	Lead [7439-92-1]
Engine - [cold zone / batterybox]	NVH WALL	Lead [7439-92-1]
Brake - [brake control]	BRAKE PEDAL	Lead [7439-92-1]
Body, Interior / Exterior - [exterior equipment]	ACTIVE SPOILER	Lead [7439-92-1]