

EX90 MODEL YEAR 2026
Candidate List Substances Table

We hereby inform that almost all product areas contain lead (CAS No 7439-92-1), primarily as alloying elements in steel, aluminium and copper.

Released: 2025 week 35.

Localisation	Partnames	Substance/s
Frame / Springs / Damping / Wheels - [spring, hydraulic / gas / air spring]	VALVE BLOCK, AIR SUPPLY UNIT, AIR HOSE, AIR TANK, CONNECTOR, HOSE COUPLING	Lead-monoxide [1317-36-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead [7439-92-1]
Electric Power Supply / Instruments - [vehicle control system]	SWITCH PANEL, USB - C CHARGER, SWITCH, CUT-OFF SWITCH, STALK MODULE, CONTROL UNIT DOOR, CONTROL UNIT, MSM, ECU, SWITCH WINDOW LIFT, CONTROL PANEL POWER SEAT	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], TBBA [79-94-7], Melamine [108-78-1], 4,4'-Isopropylidenediphenol [80-05-7], Lead [7439-92-1]
Wheel Suspension / Steering - [axle member / link arm / suspension]	CONTROL ARM, HUB, TRIPLESQUARE SOCKET SCREW, BUSHING, BUSHING SUBFRAME, LOWER LINK ARM CPL, SUBFRAME REAR, REAR SUBFRAME	Imidazolidine-2-thione [96-45-7], O,O,O-Triphenyl phosphorothioate [597-82-0], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Electric Power Supply / Instruments - [protection]	ACCELEROMETER, CONTROL UNIT, LEVEL SENSOR, LEVEL SENSOR REAR, LEVEL SENSOR FRONT RH	Lead-monoxide [1317-36-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Electric Power Supply / Instruments - [support systems]	SENSOR, THERMAL UNIT, EXT743, DRIVER MONITORING CAMERA, CAMERA, RADAR, FAN, CONTROL UNIT, LIDAR, EXT744, EXT745, EXT746	Dodecamethylcyclotetrasiloxane [540-97-6], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Lead-titanium-trioxide [12060-00-3], Melamine [108-78-1], Cobalt(II) nitrate hexahydrate [10026-22-9], TBBA [79-94-7], 1-Methyl-2-pyrrolidone [872-50-4], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], N,N-Dimethylacetamide [127-19-5], Lead [7439-92-1]
Electric Power Supply / Instruments - [antenna]	ANTENNA AMPLIFIER, CARD READER, ETC ANTENNA, ETC, ANTENNA	Lead-monoxide [1317-36-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead titanium zirconium oxide [12626-81-2], Diboron-trioxide [1303-86-2], 1-Propanol, 2,3-dibromo- [96-13-9], Melamine [108-78-1], Lead [7439-92-1]

Body, Interior / Exterior - [lock / handle]	LOCK, OUTER HANDLE, SIX POINT SOCKET SCREW, BRACKET, ACTUATOR, DOOR LOCK, EXT739, EXT743, EXT747, EXT745, EXT746, EXT749	Hexahydromethylphthalic-anhydride [25550-51-0], Triphenyl-phosphate [115-86-6], Melamine [108-78-1], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 1-Methyl-2-pyrrolidone [872-50-4], Diboron-trioxide [1303-86-2], Phenol, dimethyl-, phosphate (3:1) [25155-23-1], 2-Methylimidazole [693-98-1], C,C'-azodi(formamide) [123-77-3], Lead-monoxide [1317-36-8], Lead [7439-92-1]
Body, Interior / Exterior - [airbag]	ACCELEROMETER, FRONT SENSOR, AIRBAG, INFLATABLE KNEE BOLSTER, AIRBAG MODULE, DAWN, CONTROL UNIT, AIRBAG PASSENGER	Lead-monoxide [1317-36-8], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Electric Power Supply / Instruments - [radio equipment]	LOUDSPEAKER, TWEETER, MIDRANGE, AUDIO MODULE, CENTRE LOUDSPEAKER, WOOFER, MICROPHONE	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2], 4,4'-Isopropylidenediphenol [80-05-7], Lead-monoxide [1317-36-8], Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [anti-roll bar]	LINK FRONT ANTI-ROLL BAR, LINK ANTI-ROLL BAR	Diboron-trioxide [1303-86-2], Imidazolidine-2-thione [96-45-7]
Brake - [wheel brake]	BRAKE CALIPER, WEAR SENSOR, BRAKE CALIPER FRONT, AIR VENTING NIPPLE	Imidazolidine-2-thione [96-45-7], Cobalt(II) nitrate hexahydrate [10026-22-9], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]
Electric Power Supply / Instruments - [cable system high voltage]	CHARGE CABLE CORD, CHARGE CABLE, CABLE HARNESS, ADAPTER, FLANGE NUT, ACTUATOR	Octamethylcyclotetrasiloxane [556-67-2], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Melamine [108-78-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Cobalt-dinitrate [10141-05-6], Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [rim]	SENSOR, SPARE WHEEL 20", TYRE 265/45R21 108H XL, TYRE 295/40R21 111H XL, TYRE 295/35R22 108H XL, TYRE 265/40R22 106H XL, TYRE 295/35R22 111H HLXL, ADHESIVE BALANCE WEIGHT, VALVE, KEY, WHEEL BOLT	1,2-Dimethoxyethane [110-71-4], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], Triphenyl-phosphate [115-86-6], 2-Methylimidazole [693-98-1], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [glass, window / windscreen / roof]	REAR SCREEN, GLASS LAMINATED, QUARTER GLASS HARDENED, QUARTER GLASS LAMINATED, SEALING	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Bumetizole [3896-11-5], Diboron-trioxide [1303-86-2]

Wheel Suspension / Steering - [front suspension]	HUB, TRIPLESQUARE SOCKET SCREW	O,O,O-Triphenyl phosphorothioate [597-82-0], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [side door]	CARRIER PLATE, MOTOR WINDOW REGULATOR, DOOR MODULE LH FRT, DOOR MODULE LH REAR, DOOR MODULE RH FRT, DOOR MODULE RH REAR	O,O,O-Triphenyl phosphorothioate [597-82-0], Triphenyl-phosphate [115-86-6], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]
Electric Power Supply / Instruments - [cable system]	FUSE MODULE, CABLE HARNESS BUMPER, CABLE HARNESS, CABLE, ADAPTER HARNESS, CABLE FLOOR, FLANGE SCREW, FUSE BOX ASSY	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Octamethylcyclotetrasiloxane [556-67-2], Dodecamethylcyclohexasiloxane [540-97-6], Decamethylcyclopentasiloxane [541-02-6], Triphenyl-phosphate [115-86-6], Bumetrizole [3896-11-5], Glycols, polyethylene, mono(p-(1,1,3,3-tetramethylbutyl)phenyl) ether [9002-93-1], Cobalt-dichloride [7646-79-9], Lead [7439-92-1]
Engine - [accelerator control]	ACCELERATOR PEDAL	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-Methylimidazole [693-98-1], Lead [7439-92-1]
Electric Power Supply / Instruments - [cleaner]	WIPER APPARATUS, WASHER FLUID RESERVOIR, LEVEL SENSOR, DUAL PUMP, PUMP, WIPER ARM, REAR WIPER	Lead-monoxide [1317-36-8], O,O,O-Triphenyl phosphorothioate [597-82-0], Diboron-trioxide [1303-86-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], TBBA [79-94-7], C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1]
Electric Power Supply / Instruments - [battery and mounting parts]	FILTER, SERVICE LID, FUSE, CONNECTOR PLATE, CABLE HARNESS, BATTERY MODULE, PLATE, SERVICE LID HV BATTERY, FLANGE NUT, TOLERANCE COMPENSATOR, BATTERY, CONTACTOR, RELAY, BMS, RBMS	Octamethylcyclotetrasiloxane [556-67-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Melamine [108-78-1], Dodecamethylcyclohexasiloxane [540-97-6], Decamethylcyclopentasiloxane [541-02-6], 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) [29420-49-3], Cobalt-dinitrate [10141-05-6], Lead [7439-92-1]
Body, Interior / Exterior - [recovery / towing unit]	HARNESS, TOWING HOOK	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Imidazolidine-2-thione [96-45-7], Lead [7439-92-1]
Body, Interior / Exterior - [air conditioning]	PRESSURE HOSE, PIPE ASSEMBLY, GAS HOSE, CHILLER, PIPE AC, SENSOR, BOTTLE, EXPANSION VALVE, SENSOR PRESSURE TEMP, TEMPERATURE SENSOR, DAWN, ELECTRIC HEATER, WATER COOLED CONDENSER, AIR INLET HOUSING, GROMMET, STEPPING MOTOR, SUN SENSOR, FAN, POWER UNIT, BRACKET, ELECTRIC HEATER COOLANT, CLIMATE UNIT, HUMIDITY SENSOR, EL COMPRESSOR, LOW PRESSURE PIPE, AIR CONDITIONING, DISTRIBUTION HOUSING, FLANGE SCREW, AIR CLEANER, BRACKET SUBFRAME, AIR DUCT, SENSOR INTERIOR, CHANNEL SENSOR, VALVE	Dodecamethylcyclohexasiloxane [540-97-6], Decamethylcyclopentasiloxane [541-02-6], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Imidazolidine-2-thione [96-45-7], Melamine [108-78-1], 2-Methylimidazole [693-98-1], Lead-titanium-trioxide [12060-00-3], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bumetrizole [3896-11-5], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], TBBA [79-94-7], Octamethylcyclotetrasiloxane [556-67-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Cobalt-dichloride [7646-79-9], Lead [7439-92-1]

Engine - [cooling system]	FAN, PUMP, VALVE, GROMMET, CLIP, HOSE, HOSE LOWER, TEMPERATURE SENSOR	Lead-monoxide [1317-36-8], 2-Methylimidazole [693-98-1], O,O,O-Triphenyl phosphorothioate [597-82-0], Octamethylcyclotetrasiloxane [556-67-2], Dodecamethylcyclohexasiloxane [540-97-6], Decamethylcyclopentasiloxane [541-02-6], Diboron-trioxide [1303-86-2], Bumetizole [3896-11-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Body, Interior / Exterior - [outside / exterior trim]	RAILS, EMBLEM, LID, REFLEX, SEALING	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Dicyclohexyl-phthalate [84-61-7], Lead [7439-92-1]
Electric Power Supply / Instruments - [infotainment system]	DISPLAY, GRAPHIC HEAD UP DISPLAY, CAMERA	TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead-titanium-trioxide [12060-00-3], Melamine [108-78-1], Boric acid [10043-35-3], Triphenyl-phosphate [115-86-6], Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8], Silicic acid, lead salt [11120-22-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Dibutylbis(pentane-2,4-dionato-O,O')tin [22673-19-4], Lead [7439-92-1]
Power Transmission - [electrical axis drive]	ELECTRIC MOTOR, SERVICE KIT, O-RING, SEALING, SEALING RING, INVERTER, DRIVE SHAFT SEAL, TWIN DISC CLUTCH, FRONT AXLE, GASKET, REAR AXLE, FLANGE SCREW, INNER HOUSING, OUTER HOUSING, BRACKET, TRANSMISSION HOUSE	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], N,N-Dimethylacetamide [127-19-5], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Triphenyl-phosphate [115-86-6], O,O,O-Triphenyl phosphorothioate [597-82-0], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Lead-titanium-trioxide [12060-00-3], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt-dichloride [7646-79-9], Lead [7439-92-1]
Electric Power Supply / Instruments - [communication, mobile telephone]	BATTERY, WIRELESS CHARGE SYSTEM, CONTROL UNIT, PRINTED CIRCUIT BOARD	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], 1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4], Triphenyl-phosphate [115-86-6], 2-Ethoxyethanol [110-80-5], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], TBBA [79-94-7], Lead [7439-92-1]
Electric Power Supply / Instruments - [miscellaneous]	TELESCOPE, WASHER FLUID RESERVOIR, DUAL PUMP, PUMP	Lead-titanium-trioxide [12060-00-3], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead [7439-92-1]
Body, Interior / Exterior - [front fender]	FRONT FENDER, ANTIFLUTTER	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]

Body, Interior / Exterior - [upholstery]	B-PILLAR PANEL, DAWN, DOOR PANEL, C-PILLAR PANEL, CHARCOAL, SILL MOULDING, DAWN/CHARCOAL, MICROSWITCH, CARDAMOM, GRAB HANDLE DAWN, GRAB HANDLE CARDAMOM, LUGGAGE COVER, GRAB HANDLE CHARCOAL, TRIM MOULDING, BROWN ASH, CLIP HOUSING, SHIM, TURNED BIRC, LIGHT ASH	Melamine [108-78-1], C,C'-azodi(formamide) [123-77-3], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead-monoxide [1317-36-8], Bumetrizole [3896-11-5], Lead [7439-92-1]
Electric Power Supply / Instruments - [automatic monitoring / control]	UWB ANTENNA, CONTROL UNIT, RAIN SENSOR, SIREN, TRM, RFK SET	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead titanium zirconium oxide [12626-81-2], 1,2-Dimethoxyethane [110-71-4], TBBA [79-94-7], Lead [7439-92-1]
Body, Interior / Exterior - [outside mirrors]	HOSE, NOZZLE, REAR VIEW MIRROR OUTER, CAMERA, REAR VIEW MIRROR, MOTOR UNIT, WIRE HARNESS, DIRECTION INDICATOR, SEALING, GLASS	Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Bumetrizole [3896-11-5], Lead-monoxide [1317-36-8], Lead [7439-92-1]
Electric Power Supply / Instruments - [lighting]	REAR LAMP, CONTROL UNIT HCM, DIRECTION INDICATOR, HEADLAMP	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 4,4'-Isopropylidenediphenol [80-05-7], Lead [7439-92-1]
Body, Interior / Exterior - [interior equipment]	RETAINER, PANEL AIR OUTLET, AIR OUTLET, CUP HOLDER, WOOD, CUP SUPPORT, CHARCOAL SOLI, EC REAR VIEW MIRROR, LED MODULE	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Tris(nonylphenyl)phosphite [26523-78-4], Lead [7439-92-1]
Body, Interior / Exterior - [seat belt / other restraining systems]	SEAT BELT, HEIGHT ADJUSTMENT	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Silicic acid, lead salt [11120-22-2], Triphenyl-phosphate [115-86-6], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt(II) nitrate hexahydrate [10026-22-9], Melamine [108-78-1], Decamethyltetrasiloxane [141-62-8], Lead [7439-92-1]
Wheel Suspension / Steering - [steering gear / wheel / shaft / column]	STEERING COLUMN, SEALING FLOOR, STEERING GEAR, CONTROL UNIT, STEERING WHEEL, CHARCOAL/D	Phosphorothioic acid, O,O,O-triphenyl esters, tert-Bu derivs. [192268-65-8], O,O,O-Triphenyl phosphorothioate [597-82-0], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Diboron-trioxide [1303-86-2], Triphenyl-phosphate [115-86-6], TBBA [79-94-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]

Body, Interior / Exterior - [seats]	HARDBACK, DAWN, HEAD REST, WHITE, CHARCOAL, CARDAMOM, LUMBAR SUPPORT, HEATER, UPHOLSTERY, FOG MELANGE, ECU, LUMBAR SUPPORT 4-WAY, HEADREST, MULBERRY, VENTILATION, OUTER SECTION REAR, UNDERCARRIAGE, SEAT, FRAMEWORK	C,C'-azodi(formamide) [123-77-3], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Imidazolidine-2-thione [96-45-7], Melamine [108-78-1], Triphenyl-phosphate [115-86-6], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], O,O,O-Triphenyl phosphorothioate [597-82-0], Bumetrizole [3896-11-5], Lead [7439-92-1]
Body, Interior / Exterior - [exterior equipment]	BRACKET, SPOILER, EXT739, EXT743, STOP LAMP, EXT745, EXT746, ACTIVE SPOILER SHUTTER	Bumetrizole [3896-11-5], Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [roof]	BRACKET, ANTENNA, WELD SEALANT CURING, GLASS ROOF, GLASS COVER, CONTROL MODULE	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead-monoxide [1317-36-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], C,C'-azodi(formamide) [123-77-3], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Bumetrizole [3896-11-5], Lead-titanium-trioxide [12060-00-3], Lead [7439-92-1]
Electric Power Supply / Instruments - [electric drive system]	VOLTAGE CONVERTER, ONBOARD CHARGER	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Decamethylcyclopentasiloxane [541-02-6], Boric acid [10043-35-3], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7], 2-Methylimidazole [693-98-1], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Dodecamethylcyclhexasiloxane [540-97-6], Cobalt chloride [7791-13-1], Lead [7439-92-1]
Brake - [brake, anti lock (anti-skid)]	HYDRAULIC UNIT, LID, SENSOR	Lead titanium zirconium oxide [12626-81-2], Boric acid [10043-35-3], O,O,O-Triphenyl phosphorothioate [597-82-0], Cobalt(II) nitrate hexahydrate [10026-22-9], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], TBBA [79-94-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]
Body, Interior / Exterior - [bumper with mounting / damping]	CLIP	Bumetrizole [3896-11-5]
Body, Interior / Exterior - [climate unit]	CONTROL UNIT	Lead titanium zirconium oxide [12626-81-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1]
Electric Power Supply / Instruments - [electrical distribution box / fuse box]	CONTROL UNIT, BRACKET	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1]

Body, Interior / Exterior - [lid, cover plate]	COVER PANEL, LIDAR COVER GLASS	Tris(nonylphenyl)phosphite [26523-78-4], Diboron-trioxide [1303-86-2]
Frame / Springs / Damping / Wheels - [spring, leaf spring]	AIR SPRING FRONT, AIR SPRING REAR, SHOCK ABSORBER FRONT, TOPMOUNT, PRESSURE RETAIN VALVE, HOSE COUPLING	O,O,O-Triphenyl phosphorothioate [597-82-0], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 1-Methyl-2-pyrrolidone [872-50-4], Lead [7439-92-1]
Electric Power Supply / Instruments - [electric drive system, high voltage]	CONTROL UNIT, CELL VOLTAGE TEMP NODE, FLANGE NUT, CURRENT SENSOR, DETECTION UNIT	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Decamethylcyclopentasiloxane [541-02-6], Dodecamethylcyclohexasiloxane [540-97-6], Octamethylcyclotetrasiloxane [556-67-2], Lead-monoxide [1317-36-8], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], Cobalt-dinitrate [10141-05-6], Lead [7439-92-1]
Electric Power Supply / Instruments - [media, navigation and communication]	PRINTED CIRCUIT BOARD, CONTROL UNIT	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 4,4'-Isopropylidenediphenol [80-05-7], Lead-titanium-trioxide [12060-00-3], Melamine [108-78-1], Lead [7439-92-1]
Body, Interior / Exterior - [floor / frame section / wheel housing / firewall]	WELD SEALANT CURING, FLANGE SCREW	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt-dichloride [7646-79-9]
Body, Interior / Exterior - [body side]	WELD SEALANT CURING	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Electric Power Supply / Instruments - [horn]	HORN	Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [instruction / information plates]	SIX POINT SOCKET SCREW, NUMBER PLATE HOLDER	1-Methyl-2-pyrrolidone [872-50-4], Lead [7439-92-1]
Brake - [brake line with connections]	BRAKE PIPE FRONT, BRAKE PIPE, BRAKE PIPE REAR, BRAKE PIPE LEFT REAR, FILLER PIPE, BRAKE PIPE FRONT LH, RETAINER	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bumetrizole [3896-11-5], Lead [7439-92-1]
Body, Interior / Exterior - [tool / jack]	REPAIR KIT, COMPRESSOR, BOTTLE	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]

Electric Power Supply / Instruments - [vehicle computational units / gateway modules]	CONTROL UNIT, GATEWAY MODULE	2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], TBBA [79-94-7], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], Melamine [108-78-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 1-Methyl-2-pyrrolidone [872-50-4], Lead [7439-92-1]
Body, Interior / Exterior - [instrument / radio panel]	DECOR, LIGHT ASH, LIGHTING, TURNED BIRCH, BROWN ASH, LAMP, CONCEALING PANEL, GLOVE BOX, ACTUATOR, HINGE PIN	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [bonnet / cover with assembly parts]	SIDE PANEL, SEALING, COVER	Bumetrizole [3896-11-5], C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1]
Body, Interior / Exterior - [trunk lid / tailgate complete]	SPINDLE DRIVE, ANTIFLUTTER	Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Body, Interior / Exterior - [hood cover]	HOOD, ANTIFLUTTER	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Electric Power Supply / Instruments - [Lighting Interior areas]	OVERHEAD CONSOLE, READING LAMP, SENSOR, LIGHT GUIDE, LAMP, LED MODULE	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead titanium zirconium oxide [12626-81-2], Lead [7439-92-1]
Body, Interior / Exterior - [miscellaneous]	TRANSPORT PROTECTION	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Brake - [brake control]	BRAKE PEDAL, PEDAL UNIT	Lead [7439-92-1]
Engine - [cold zone / batterybox]	NVH WALL	Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [shock absorber]	SHOCK ABSORBER REAR, TOPMOUNT	Lead [7439-92-1]