

S60 MODEL YEAR 2026
Candidate List Substances Table

Released: 2025 week 35.

We hereby inform that almost all product areas contain lead (CAS No 7439-92-1), primarily as alloying elements in steel, aluminium and copper.

Localisation	Partnames	Substance/s
Body, Interior / Exterior - [outside / exterior trim]	GRILLE, EMBLEM, ANTENNA CAP, WHITE614, BLUE467, SILV477, BLACK487, GREY492, BROWN700, BLUE706, EXT707, EXT711, EXT714, EXT717, EXT719, CKDCOLOR, KSOCOLOR, SVART19S, RED612, EXT720, TAPE, EXT722, EXT721, EXT723, EXT621, EXT724, EXT725	C,C'-azodi(formamide) [123-77-3], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Triphenyl-phosphate [115-86-6]
Wheel Suspension / Steering - [axle member / link arm / suspension]	HUB, SUBFRAME FRONT, UPPER LINK ARM, TRIPLESQUARE SOCKET SCREW, LINK ARM, LOWER LINK ARM, BALL JOINT	O,O,O-Triphenyl phosphorothioate [597-82-0], Cobalt-dichloride [7646-79-9], Imidazolidine-2-thione [96-45-7], Diboron-trioxide [1303-86-2]
Wheel Suspension / Steering - [front suspension]	HUB, TRIPLESQUARE SOCKET SCREW	O,O,O-Triphenyl phosphorothioate [597-82-0], Diboron-trioxide [1303-86-2]
Electric Power Supply / Instruments - [radio equipment]	MICROPHONE, LOUDSPEAKER, SPEAKER MIDRANGE, AUDIO MODULE, SOUND MODULE, WOOFER, SUBWOOFER, TWEETER, CENTRE LOUDSPEAKER	Diboron-trioxide [1303-86-2], N,N-Dimethylacetamide [127-19-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], Melamine [108-78-1], TBBA [79-94-7], Triphenyl-phosphate [115-86-6], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Cobalt(II) nitrate hexahydrate [10026-22-9], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead [7439-92-1]
Electric Power Supply / Instruments - [lighting]	HEADLAMP, REAR LAMP, REAR LAMP TRUNK LID, READING LAMP, OVERHEAD CONSOLE LENS, CONTROL UNIT HCM, LIGHTING, LAMP LED, FOG LIGHT, STOP LAMP, LED MODULE	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], TBBA [79-94-7], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Melamine [108-78-1], Tris(2-methoxyethoxy)vinylsilane [1067-53-4], Dicyclohexyl-phthalate [84-61-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Bumetrizole [3896-11-5], Octamethylcyclotetrasiloxane [556-67-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Lead-titanium-trioxide [12060-00-3], Lead [7439-92-1]

Body, Interior / Exterior - [upholstery]	DOOR PANEL, ARM REST, BELT GUIDE, CHARCOAL, BLOND, TOP COVER, FOAM, LOUDSPEAKER GRILLE, CHARCO, CLIP HOUSING, SILL MOULDING	C,C'-azodi(formamide) [123-77-3], Triphenyl-phosphate [115-86-6], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Bumetrizole [3896-11-5], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Body, Interior / Exterior - [lock / handle]	OUTER HANDLE, WIRE, EXT743, LOCK, EXT745, EXT746, EXT744, DOOR LOCK, LOCK CYLINDER SET, KEY	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Bumetrizole [3896-11-5], Diboron-trioxide [1303-86-2], Melamine [108-78-1], Lead-monoxide [1317-36-8], Lead [7439-92-1]
Electric Power Supply / Instruments - [support systems]	SENSOR, CONTROL UNIT, CAMERA, RADAR, EXT743, EXT746, EXT744, EXT745, BOX	Lead-monoxide [1317-36-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Methylimidazole [693-98-1], Dicyclohexyl-phthalate [84-61-7], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], Lead titanium zirconium oxide [12626-81-2], TBBA [79-94-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Lead [7439-92-1]
Body, Interior / Exterior - [interior equipment]	PADDING, FRAMEWORK, JALUSIE, ARM REST, CARRIER, CUP HOLDER, EC REAR VIEW MIRROR, LIGHTING, LED MODULE, HINGE, SUN VISOR, CHARCOAL SOLID, CHARCOAL, BLOND, CARRIER ARM REST, DAMPER	C,C'-azodi(formamide) [123-77-3], TBBA [79-94-7], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], Tris(nonylphenyl)phosphite [26523-78-4], Diboron-trioxide [1303-86-2], Cobalt sulphate [10124-43-3], 4,4'-Isopropylidenediphenol [80-05-7], Bumetrizole [3896-11-5], Lead [7439-92-1]
Power Transmission - [front axle / rear axle / drive shaft]	AOC, SEALING RING, REAR AXLE, PUMP UNIT, FINAL DRIVE, RADIAL SEAL KIT, DRIVE SHAFT, BRACKET, BEARING ANCHORAGE, VIBRATION DAMPER	Triphenyl-phosphate [115-86-6], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead [7439-92-1]
Body, Interior / Exterior - [seats]	HEAD RESTRAINT, HARDBACK, UNDERCARRIAGE, UPHOLSTERY, ENGINE, HEATING PAD SEAT, LUMBAR SUPPORT, STS SENSOR, BACKREST FRAME, LUMBAR SUPPORT 4-WAY, HEATER, MASSAGE PUMP, SIX POINT SOCKET SCREW, ARM REST, FRAMEWORK, VENTILATION, FAN, COVER, CHARCOAL SOLID, AMBER, COULISSE, HATCH, CHARCOAL/BLOND, SLATE, SIDE BOLSTER, ENGINE TILT, CABLE HARNESS	Triphenyl-phosphate [115-86-6], C,C'-azodi(formamide) [123-77-3], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], N,N-Dimethylacetamide [127-19-5], Diboron-trioxide [1303-86-2], O,O,O-Triphenyl phosphorothioate [597-82-0], TBBA [79-94-7], Melamine [108-78-1], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Imidazolidine-2-thione [96-45-7], 1-Methyl-2-pyrrolidone [872-50-4], Bumetrizole [3896-11-5], Boric acid [10043-35-3], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3], Lead [7439-92-1]

Body, Interior / Exterior - [outside mirrors]	REAR VIEW MIRROR OUTER, REAR VIEW MIRROR, CAMERA, GLASS, MOTOR UNIT	Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], TBBA [79-94-7], 2-Methylimidazole [693-98-1], Dicyclohexyl-phthalate [84-61-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Cobalt-dinitrate [10141-05-6], Lead [7439-92-1]
Engine - [control systems]	AIR TEMP SENSOR, CONTROL UNIT, MASS AIR FLOW SENSOR, TEMP AND PRESSURE SENSOR, PRESSURE SENSOR	Lead-monoxide [1317-36-8], Silicic acid, lead salt [11120-22-2], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3], Lead [7439-92-1]
Body, Interior / Exterior - [recovery / towing unit]	TOWING HOOK, HARNESS	TBBA [79-94-7], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]
Power Transmission - [electrical axis drive]	EMC ASSEMBLY, INLET PIPE, OUTLET PIPE, O-RING, SEAL CAP, REAR AXLE, SEALING, TRANSMISSION, CABLE HARNESS, DRIVE SHAFT	Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Triphenyl-phosphate [115-86-6], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead-monoxide [1317-36-8], Sodium borate, pentahydrate [12179-04-3], Tris(nonylphenyl)phosphite [26523-78-4], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Engine - [inlet / exhaust systems]	EXHAUST SYSTEM, THROTTLE, HEAT SHIELD PLATE, INTAKE MANIFOLD	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1], Boric acid [10043-35-3]
Electric Power Supply / Instruments - [battery and mounting parts]	HEAT SHIELD, HEAT INSULATION PAD, MODULE, BATTERY, 48V BATTERY, CONTROL UNIT, INLET HOSE, OUTLET HOSE, SERVICE SWITCH, CURRENT SENSOR, BMS	Diboron-trioxide [1303-86-2], Melamine [108-78-1], Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8], Lead-monoxide [1317-36-8], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 1,3-Propanesultone [1120-71-4], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead titanium zirconium oxide [12626-81-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Boric acid [10043-35-3], 1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4], Octamethylcyclotetrasiloxane [556-67-2], 1-Propanol, 2,3-dibromo- [96-13-9], Lead-titanium-trioxide [12060-00-3], Decamethylcyclopentasiloxane [541-02-6], Dodecamethylcyclotetrasiloxane [540-97-6], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1]
Body, Interior / Exterior - [tank hatch]	PLASTIC MODULE	Triphenyl-phosphate [115-86-6], Lead [7439-92-1]

Engine - [cooling system]	HOSE TEMP SENSOR, PUMP, HOSE OUTLET, SET, RADIATOR HYBRID, HOSE INLET, HOSE, PUMP MODULE, EL WATER PUMP, COOLER, COMPLETE COOLER, PRESSURE SENSOR, CONDENSER, THREE-WAY VALVE, TEMPERATURE SENSOR, RADIATOR, CHARGE AIR COOLER, HEATER HOSE, TWO-WAY VALVE, VALVE, SEPARATOR, BRACKET, CLAMP BRACKET, PIPE, HOSE HEATER, HOSE MODULE, GASKET, O-RING, SIX POINT SOCKET SCREW, FLANGE SCREW, STRIKER PLATE, THERMOSTAT HOUSING, NIPPLE, WATER PUMP, PLASTIC PIPE	TBBA [79-94-7], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], 1-Methyl-2-pyrrolidone [872-50-4], Melamine [108-78-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Dodecamethylcyclotetrasiloxane [540-97-6], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Silicic acid, lead salt [11120-22-2], 4,4'-Isopropylidenediphenol [80-05-7], Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt-dichloride [7646-79-9], C,C'-azodi(formamide) [123-77-3]
Electric Power Supply / Instruments - [mobile data services]	CONTROL UNIT	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1], Lead [7439-92-1]
Body, Interior / Exterior - [instrument / radio panel]	IONIZER, GLOVE BOX, CONCEALING PANEL, INSTRUMENT PANEL, LAMP LED, PANEL NOZZLE, HINGE PIN	Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Lead [7439-92-1]
Body, Interior / Exterior - [air conditioning]	IONIZER, SUN SENSOR, EL COMPRESSOR, DISTRIBUTION HOUSING, ELECTRIC HEATER, PIPE ASSEMBLY, CLIMATE UNIT, FAN, EVAPORATOR HOUSING, AIR INLET, HUMIDITY SENSOR, AC-COMPRESSOR, SENSOR KIT, DEFROSTER, STEPPING MOTOR, CONTROL UNIT, FLANGE SCREW, DRAINAGE HOSE, AIR CLEANER, EXPANSION VALVE, SOLENOID CLUTCH, SENSOR, SENSOR INTERIOR, PROTECTIVE CAP, VALVE, CONTROL VALVE, CHANNEL SENSOR	Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Diboron-trioxide [1303-86-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead-titanium-trioxide [12060-00-3], 1-Propanol, 2,3-dibromo- [96-13-9], 2-Methylimidazole [693-98-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4], Tris(nonylphenyl)phosphite [26523-78-4], Melamine [108-78-1], Bumetrizole [3896-11-5], Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8], TBBA [79-94-7], Cobalt(II) nitrate hexahydrate [10026-22-9], Cobalt-dichloride [7646-79-9], Lead [7439-92-1]
Wheel Suspension / Steering - [steering gear / wheel / shaft / column]	STEERING COLUMN, STEERING COLUMN MANUAL, STEERING GEAR, STEERING WHEEL, STEERING WHEEL RIM, COVER PLUG, CHARCOAL SO, BLOND, SEALING FLOOR, STEERING WHEEL HARNESS	Phosphorothioic acid, O,O,O-triphenyl esters, tert-Bu derivs. [192268-65-8], Lead-monoxide [1317-36-8], O,O,O-Triphenyl phosphorothioate [597-82-0], Dicyclohexyl-phthalate [84-61-7], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]

Electric Power Supply / Instruments - [vehicle control system]	SWITCH PANEL, CONTROL UNIT DOOR, SWITCH, CUT-OFF SWITCH, USB POWER OUTLET, ECU, STALK MODULE, COMBI INSTRUMENT, HARDWARE, CONTROL PANEL POWER SEAT, LOCK BUTTON, LOCK BUTTON LED, SWITCH DOOR, SWITCH WINDOW LIFT, SWITCH MODULE, SWITCH STEERING WHEEL	Triphenyl-phosphate [115-86-6], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead titanium zirconium oxide [12626-81-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7], Boric acid [10043-35-3], Lead-titanium-trioxide [12060-00-3], Lead [7439-92-1]
Electric Power Supply / Instruments - [communication, mobile telephone]	CONTROL UNIT, BATTERY, WIRELESS CHARGE SYSTEM	Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Engine - [fuel / EVAP system]	FUEL PUMP MODULE, PUMP MODULE, JET PUMP AND LEVEL SENSOR, FILTER, LEAK DETECTION PUMP, ISOLATION VALVE, FILLER PIPE, PEM, HOSE, EVAP PURGE PUMP, CANISTER, EVAP-LINE ASSY, FUEL TANK, TANK WELDED, PURGE VALVE, PURGE VALVE ASSY, FUEL PRESSURE SENSOR, FUEL DISTRIBUTION PIPE, HIGH PRESSURE PUMP, INJECTOR, FUEL PUMP	Melamine [108-78-1], Lead-monoxide [1317-36-8], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Diboron-trioxide [1303-86-2], O,O,O-Triphenyl phosphorothioate [597-82-0], TBBA [79-94-7], Cobalt-dinitrate [10141-05-6], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1]
Electric Power Supply / Instruments - [cleaner]	FILLER PIPE, SEALING, WIPER APPARATUS, WASHER FLUID RESERVOIR, WIPER ARM, WIPER ARM DS, WIPER ARM PS, PUMP, WASHER PUMP	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Cobalt(II) nitrate hexahydrate [10026-22-9], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], Triphenyl-phosphate [115-86-6], TBBA [79-94-7], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead [7439-92-1]
Body, Interior / Exterior - [airbag]	SIDE AIR BAG, AIRBAG MODULE, CONTROL UNIT, ACCELEROMETER SENSOR, INFLATABLE CURTAIN	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], Lead-monoxide [1317-36-8], Lead [7439-92-1]
Body, Interior / Exterior - [floor / frame section / wheel housing / firewall]	FRONT SIDE MEMBER, WHEEL HOUSING, ADHESIVE, FLOOR PANEL, TOP COVER, REINFORCEMENT, TOP COVER PANEL REAR	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Electric Power Supply / Instruments - [cable system]	CABLE, CABLE HARNESS, CABLE FLOOR, FLANGE NUT, CABLE HARNESS WEM, FUSE BOX, CABLE DUCT, EJB, BRACKET, FUSE BOX ASSY	TBBA [79-94-7], Triphenyl-phosphate [115-86-6], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt-dinitrate [10141-05-6], Decamethylcyclotrasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Lead [7439-92-1]
Body, Interior / Exterior - [exterior equipment]	ACTIVE GRILLE SHUTTER, ACTIVE SPOILER SHUTTER	Diboron-trioxide [1303-86-2], Lead [7439-92-1]

Body, Interior / Exterior - [roof]	PANORAMA ROOF, FRAME, ADHESIVE ROOF HATCH, MOTOR, WELD SEALANT CURING, REAR SHELF	O,O,O-Triphenyl phosphorothioate [597-82-0], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Phosphorothioic acid, O,O,O-triphenyl esters, tert-Bu derivs. [192268-65-8], C,C'-azodi(formamide) [123-77-3], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Electric Power Supply / Instruments - [electric drive system]	VOLTAGE CONVERTER, INVERTER IEM, INVERTER IGM, ONBOARD CHARGER, STARTER MOTOR ALTERNATOR, PROTECTION HIGH VOLTAGE, BRACKET, SEALING, STARTER MOTOR, COOLANT PIPE, SENSOR	Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], 2-Methylimidazole [693-98-1], 4,4'-Isopropylidenediphenol [80-05-7], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Alkanes, C14-17, chloro [85535-85-9], Triphenyl-phosphate [115-86-6], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Lead [7439-92-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], N,N-Dimethylacetamide [127-19-5]
Brake - [wheel brake]	BRAKE CALIPER, HOUSING, EPB, BRAKE LINING, AIR VENTING NIPPLE, BLEEDER VALVE	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], O,O,O-Triphenyl phosphorothioate [597-82-0], 2-Methylimidazole [693-98-1], Diboron-trioxide [1303-86-2], Tris(nonylphenyl)phosphite [26523-78-4], Hexahydromethylphthalic-anhydride [25550-51-0], Dicyclohexyl-phthalate [84-61-7], Lead [7439-92-1]
Electric Power Supply / Instruments - [infotainment system]	GRAPHIC HEAD UP DISPLAY, PRINTED CIRCUIT BOARD, DISPLAY, USB HUB	Diboron-trioxide [1303-86-2], 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) [29420-49-3], Boric acid [10043-35-3], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 4,4'-Isopropylidenediphenol [80-05-7], Melamine [108-78-1], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Triphenyl-phosphate [115-86-6], Lead [7439-92-1]
Electric Power Supply / Instruments - [cable system high voltage]	CABLE CHARGE POINT HV, CABLE HARNESS, ADAPTER PLATE, CHARGE CABLE CORD, STRAIN RELIEF, CABLE DUCT, CABLE CHANNEL	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 4,4'-Sulfonyldiphenol [80-09-1], TBBA [79-94-7], Octamethylcyclotetrasiloxane [556-67-2], Lead [7439-92-1]
Electric Power Supply / Instruments - [vehicle computational units / gateway modules]	CONTROL UNIT	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1]

Body, Interior / Exterior - [glass, window / windscreen / roof]	REAR SCREEN, GLASS HARDENED, WINDSCREEN, QUARTER GLASS LAMINATED	Diboron-trioxide [1303-86-2], C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1]
Body, Interior / Exterior - [seat belt / other restraining systems]	BELT CATCH, SEAT BELT, BELT, BELT CATCH REAR, HEIGHT ADJUSTMENT	TBBA [79-94-7], Triphenyl-phosphate [115-86-6], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Melamine [108-78-1], Decamethyltetrasiloxane [141-62-8], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead-monoxide [1317-36-8], Cobalt(II) nitrate hexahydrate [10026-22-9], Lead [7439-92-1]
Power Transmission - [gearbox]	CONTROL UNIT, CABLE HARNESS, CONNECTOR, AUTOMATIC GEARBOX, OIL PUMP, GEARBOX, AIR VENT PIPE, FLANGE NUT, FLANGE SCREW, TEMPERATURE SENSOR, SPACER, VALVE BODY, SERVO COVER, TORQUE CONVERTER, CONTROL SYSTEM, ADAPTER, DIFFERENTIAL SPACER, LID	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], Lead-monoxide [1317-36-8], Nonylphenol [25154-52-3], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], 4,4'-Isopropylidenediphenol [80-05-7], 1-Methyl-2-pyrrolidone [872-50-4], O,O,O-Triphenyl phosphorothioate [597-82-0], TBBA [79-94-7], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Dioctyltin dilaurate [3648-18-8], Cobalt-dinitrate [10141-05-6], Cobalt-dichloride [7646-79-9], Lead-titanium-trioxide [12060-00-3], Silicic acid, lead salt [11120-22-2], Lead [7439-92-1]
Electric Power Supply / Instruments - [automatic monitoring / control]	SIREN, SENSOR, REMOTE KEY, RAIN SENSOR, TRM, CONTROL UNIT	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead titanium zirconium oxide [12626-81-2], 1,2-Dimethoxyethane [110-71-4], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead [7439-92-1]
Power Transmission - [gear lever carrier / gear selector controls]	GEAR LEVER CARRIER, ACTUATOR	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead [7439-92-1]
Power Transmission - [actuator, gear shift]	CONTROL UNIT	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], Silicic acid, lead salt [11120-22-2], Diboron-trioxide [1303-86-2], Lead [7439-92-1]

Brake - [brake line with connections]	BRAKE PIPE, BRAKE PIPE FRONT, RETAINER, BRAKE HOSE	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bumetrizole [3896-11-5], Lead [7439-92-1]
Engine - [engine / engine mounting]	ENGINE, ENGINE MOUNT, TORQUE ROD, TORQUE LINK BRACKET, ENGINE BRACKET	Bis(4-chlorophenyl) sulfon [80-07-9], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Lead titanium zirconium oxide [12626-81-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1], TBBA [79-94-7], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9]
Engine - [emission equipment]	LAMBDA SOND, PRESSURE SENSOR, VALVE, COOLER, ALUMINIUM, STAY	Diboron-trioxide [1303-86-2], TBBA [79-94-7], Lead-monoxide [1317-36-8], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1]
Engine - [fan]	FAN	Boric acid [10043-35-3], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead [7439-92-1]
Brake - [brake, anti lock (anti-skid)]	HYDRAULIC UNIT, SENSOR	Lead titanium zirconium oxide [12626-81-2], Boric acid [10043-35-3], O,O,O-Triphenyl phosphorothioate [597-82-0], Cobalt(II) nitrate hexahydrate [10026-22-9], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Lead [7439-92-1]
Electric Power Supply / Instruments - [electrical distribution box / fuse box]	CEM, ATTACHMENT	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [rim]	WHEEL, ADHESIVE BALANCE WEIGHT, VALVE, KEY, WHEEL BOLT	Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], 2-Methylimidazole [693-98-1], Diboron-trioxide [1303-86-2], Lead [7439-92-1]

Body, Interior / Exterior - [body side]	WELD SEALANT CURING	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Electric Power Supply / Instruments - [horn]	HORN	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead [7439-92-1]
Body, Interior / Exterior - [instruction / information plates]	SIX POINT SOCKET SCREW	1-Methyl-2-pyrrolidone [872-50-4]
Brake - [brake control]	PEDAL UNIT, BACK-UP BATTERY, AUXILIARY TELEMATIC, SENSOR	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], TBBA [79-94-7], N,N-Dimethylacetamide [127-19-5], Dioctyltin dilaurate [3648-18-8], Lead [7439-92-1]
Electric Power Supply / Instruments - [antenna]	ETC MODULE, ANTENNA AMPLIFIER, WAVE TRAP, GROUND SIDE COIL, ETC ON BOARD UNIT, ANTENNA	Lead-monoxide [1317-36-8], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Hexahydromethylphthalic-anhydride [25550-51-0], Lead titanium zirconium oxide [12626-81-2], 1-Propanol, 2,3-dibromo- [96-13-9], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Lead [7439-92-1]
Body, Interior / Exterior - [hood cover]	HINGE RELEASER, HOOD, ANTIFLUTTER, HINGE	Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]
Body, Interior / Exterior - [miscellaneous]	SOUND ABSORBER, TRANSPORT PROTECTION, SEALANT REPAIR, SEALING	Triphenyl-phosphate [115-86-6], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Dibutylbis(pentane-2,4-dionato-O,O')tin [22673-19-4], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Body, Interior / Exterior - [trunk lid / tailgate complete]	ANTIFLUTTER, HINGE	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]

Body, Interior / Exterior - [protective shields / flaps]	CLIP, HEAT SHIELD PLATE	Bumetrizole [3896-11-5], C,C'-azodi(formamide) [123-77-3]
Frame / Springs / Damping / Wheels - [anti-roll bar]	LINK ANTI-ROLL BAR, ANTI-ROLL BAR FRONT, ANTI-ROLL BAR REAR	Imidazolidine-2-thione [96-45-7], 2-Methylimidazole [693-98-1]
Power Transmission - [final drive]	SEALING, PT-UNIT, BRACKET	Triphenyl-phosphate [115-86-6], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead [7439-92-1]
Brake - [master cylinder / brake booster]	LID	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Engine - [intercooler / connection]	CHARGE AIR HOSE, CHARGE AIR PIPE, RESONATOR, CHARGE AIR COOLER	Boric acid [10043-35-3], Lead [7439-92-1]
Body, Interior / Exterior - [tool / jack]	JACK	Ethylenediamine [107-15-3]
Body, Interior / Exterior - [side door]	SEALING, BODY MOUNTED SEALING, DOOR MOUNTED SEALING, WINDOW LIFT, CARRIER PLATE	C,C'-azodi(formamide) [123-77-3], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Imidazolidine-2-thione [96-45-7], Lead [7439-92-1]
Engine - [accelerator control]	ACCELERATOR PEDAL	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead [7439-92-1]
Electric Power Supply / Instruments - [protection]	SENSOR FRONT, SENSOR REAR	TBBA [79-94-7], Lead [7439-92-1]
Body, Interior / Exterior - [bonnet / cover with assembly parts]	END FOAM, HOOD RELEASE CABLE, HOOD LOCK, HOOD LOCK CONTROL, COVER	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Imidazolidine-2-thione [96-45-7], Lead [7439-92-1]

Engine - [air cleaner]	BELLOWS, FRESH AIR PIPE, BOX	Bumetrizole [3896-11-5], Lead [7439-92-1]
Body, Interior / Exterior - [front fender]	SHIM	Lead [7439-92-1]
Engine - [miscellaneous / help device installation]	BRACKET, TENSIONER, SPLASH PROTECTION	Lead [7439-92-1]
Electric Power Supply / Instruments - [cable components]	RECEPTACLE HOUSING, CABLE DUCT	Lead [7439-92-1]
Engine - [cold zone / batterybox]	NVH PANEL	Lead [7439-92-1]
Engine - [ignition / spark plug]	IGNITION COIL, SPARK PLUG, GLOW PLUG	Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Engine - [lubricating and oil system]	GASKET, OIL PUMP, OIL LEVEL SENSOR, OIL FILTER, OIL PRESSURE SENSOR, OIL SUMP, SUCTION LINE, PISTON COOLING JET, VALVE, INLET PIPE, PISTON COOLING VALVE, WINDAGE TRAY, PLUG	Bis(4-chlorophenyl) sulfon [80-07-9], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Engine - [transmission]	GASKET, VVT-UNIT, TENSIONER, IDLER PULLEY, CAMSHAFT, SOLENOID, BALANCE SHAFT, BELT PROTECTOR, HOUSING, BELT COVER, VVT ACTUATOR, SLEEVE	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]
Engine - [supercharging]	TURBO CHARGER, O-RING, VACUUM RESERVOIR, VACUUM REGULATOR, BRACKET	N,N-Dimethylacetamide [127-19-5], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Lead [7439-92-1]
Engine - [distributor]	KNOCK SENSOR, CAMSHAFT POSITION SENSOR	Lead titanium zirconium oxide [12626-81-2], Lead-monoxide [1317-36-8], Lead [7439-92-1]
Engine - [cylinder block / head]	BEDPLATE, ENGINE BRACKET, VACUUM PUMP, CYLINDER BLOCK, TOP COVER, GUIDE SLEEVE, BEARING HOUSE CAM SHAFT, CYLINDER HEAD, CAP, CAM SHAFT COVER, CAMSHAFT CAP, HOUSING, LOCATING PIN	Lead [7439-92-1]
Engine - [crank mechanism]	DUAL MASS FLYWHEEL, NIPPLE, NON-RETURN VALVE	Lead [7439-92-1]