

S90L MODEL YEAR 2026
Candidate List Substances Table

Released: 2025 week 35.

We hereby inform that almost all product areas contain lead (CAS No 7439-92-1), primarily as alloying elements in steel, aluminium and copper.

Localisation	Partnames	Substance/s
Wheel Suspension / Steering - [axle member / link arm / suspension]	HUB, LOWER LINK ARM, SUBFRAME FRONT, UPPER LINK ARM, TRIPLESQUARE SOCKET SCREW, BALL JOINT	O,O,O-Triphenyl phosphorothioate [597-82-0], Imidazolidine-2-thione [96-45-7], Cobalt-dichloride [7646-79-9], Diboron-trioxide [1303-86-2]
Wheel Suspension / Steering - [front suspension]	HUB, TRIPLESQUARE SOCKET SCREW	O,O,O-Triphenyl phosphorothioate [597-82-0], Diboron-trioxide [1303-86-2]
Electric Power Supply / Instruments - [automatic monitoring / control]	CONTROL UNIT, SIREN, SENSOR, REMOTE KEY, RAIN SENSOR	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 1,2-Dimethoxyethane [110-71-4], Lead-titanium-trioxide [12060-00-3], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead [7439-92-1]
Electric Power Supply / Instruments - [radio equipment]	MICROPHONE, SPEAKER MIDRANGE, AUDIO MODULE, SOUND MODULE, SUBWOOFER, WOOFER, TWEETER, LOUDSPEAKER, CENTRE LOUDSPEAKER, AUD COVER	Diboron-trioxide [1303-86-2], N,N-Dimethylacetamide [127-19-5], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], Melamine [108-78-1], TBBA [79-94-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Triphenyl-phosphate [115-86-6], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Cobalt(II) nitrate hexahydrate [10026-22-9], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Body, Interior / Exterior - [upholstery]	DOOR PANEL, SILL MOULDING, FLOOR HATCH, TRIM MOULDING, LIGHT ASH, BROWN ASH, GREY ASH, MULBERRY/CHAR, GRAPH BLUE/CHA, SILL FRONT, LIGHTING, MOTOR SUN CURTAIN, ECU SIDE, LED MODULE, SUN CURTAIN, CLIP HOUSING, B-PILLAR PANEL, BLOND, C-PILLAR PANEL, CHARCOAL, A-PILLAR PANEL, LIGHT GUIDE	C,C'-azodi(formamide) [123-77-3], Diboron-trioxide [1303-86-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], TBBA [79-94-7], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Boric acid [10043-35-3], Imidazolidine-2-thione [96-45-7], Triphenyl-phosphate [115-86-6], O,O,O-Triphenyl phosphorothioate [597-82-0], Bumetrizole [3896-11-5], Lead [7439-92-1]

Power Transmission - [front axle / rear axle / drive shaft]	AOC, SEALING RING, PUMP UNIT, FINAL DRIVE, RADIAL SEAL KIT, REAR AXLE, VIBRATION DAMPER, BRACKET	Triphenyl-phosphate [115-86-6], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead [7439-92-1]
Body, Interior / Exterior - [interior equipment]	PADDING, ARM REST, CARRIER, EC REAR VIEW MIRROR, LIGHTING, LED MODULE, SIDE PANEL, CUP HOLDER, SUN VISOR, BLOND, CHARCOAL, CARRIER ARM REST, HINGE, FRAMEWORK, DAMPER	C,C'-azodi(formamide) [123-77-3], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Cobalt sulphate [10124-43-3], TBBA [79-94-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead [7439-92-1]
Electric Power Supply / Instruments - [support systems]	SENSOR, CONTROL UNIT, CAMERA, RADAR, EXT743, EXT746, EXT744, EXT745	Lead-monoxide [1317-36-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Methylimidazole [693-98-1], Dicyclohexyl-phthalate [84-61-7], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], TBBA [79-94-7], Lead titanium zirconium oxide [12626-81-2], Lead [7439-92-1]
Engine - [control systems]	AIR TEMP SENSOR, CONTROL UNIT, MASS AIR FLOW SENSOR, TEMP AND PRESSURE SENSOR	Lead-monoxide [1317-36-8], Silicic acid, lead salt [11120-22-2], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3], Lead [7439-92-1]
Power Transmission - [electrical axis drive]	EMC ASSEMBLY, INLET PIPE, OUTLET PIPE, O-RING, SEAL CAP, REAR AXLE, CABLE HARNESS, DRIVE SHAFT	Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Triphenyl-phosphate [115-86-6], O,O,O-Triphenyl phosphorothioate [597-82-0], Sodium borate, pentahydrate [12179-04-3], Tris(nonylphenyl)phosphite [26523-78-4], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Electric Power Supply / Instruments - [cable system]	CABLE HARNESS, CABLE HARNESS BUMPER, CABLE AUDIO, FLANGE NUT, CABLE, CABLE PAC, FUSE BOX, CABLE DUCT, BRACKET, CABLE INFOTAINMENT	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Triphenyl-phosphate [115-86-6], Dicyclohexyl-phthalate [84-61-7], Tris(nonylphenyl)phosphite [26523-78-4], TBBA [79-94-7], Cobalt-dinitrate [10141-05-6], Lead [7439-92-1]

Body, Interior / Exterior - [seats]	HARDBACK, UPHOLSTERY, UNDERCARRIAGE, HEAD RESTRAINT, ENGINE, HEATING PAD SEAT, LUMBAR SUPPORT, STS SENSOR, BACKREST FRAME, LUMBAR SUPPORT 4-WAY, HEATER, MASSAGE PUMP, CARDAMOM, ARM REST, LED MODULE, GRAPHITE BLUE, GRAPHITE R, HEAD REST, SIDE BOLSTER, GRAPHITE BLU, MULBERRY, ARMREST, STRUCTURE LOWER, HEAD RESTRAINT ASSEMBLY, VENTILATION, FAN, LOCK, STORAGE LID, COVER, CHARCOAL SOLID, AMBER, HATCH, CHARCOAL/BLOND, SLATE, ENGINE TILT, FRAMEWORK, CABLE HARNESS	C,C'-azodi(formamide) [123-77-3], Triphenyl-phosphate [115-86-6], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], N,N-Dimethylacetamide [127-19-5], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], O,O,O-Triphenyl phosphorothioate [597-82-0], TBBA [79-94-7], Melamine [108-78-1], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Imidazolidine-2-thione [96-45-7], Octamethylcyclotetrasiloxane [556-67-2], Bumetrizole [3896-11-5], Boric acid [10043-35-3], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead [7439-92-1]
Body, Interior / Exterior - [outside / exterior trim]	EMBLEM, GRILLE, ANTENNA CAP, WHITE614, BLUE467, SILV477, BLACK487, GREY492, BROWN700, BLUE706, EXT707, EXT711, EXT714, EXT717, EXT719, CKDCOLOR, KSOCOLOR, SVART19S, RED612, EXT720, TAPE, EXT722, EXT721, EXT723, EXT621, EXT724, EXT725	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], C,C'-azodi(formamide) [123-77-3], Triphenyl-phosphate [115-86-6]
Electric Power Supply / Instruments - [battery and mounting parts]	HEAT SHIELD, HEAT INSULATION PAD, MODULE, BATTERY, 48V BATTERY, CONTROL UNIT, INLET HOSE, OUTLET HOSE, SERVICE SWITCH, CURRENT SENSOR, BMS	Diboron-trioxide [1303-86-2], Melamine [108-78-1], Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8], Lead-monoxide [1317-36-8], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 1,3-Propanesultone [1120-71-4], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead titanium zirconium oxide [12626-81-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Boric acid [10043-35-3], 1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4], Octamethylcyclotetrasiloxane [556-67-2], 1-Propanol, 2,3-dibromo- [96-13-9], Lead-titanium-trioxide [12060-00-3], Decamethylcyclopentasiloxane [541-02-6], Dodecamethylcyclohexasiloxane [540-97-6], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1]
Engine - [cooling system]	HOSE TEMP SENSOR, PUMP, SET, RADIATOR HYBRID, HOSE OUTLET, HOSE, EL WATER PUMP, COOLER, COMPLETE COOLER, PRESSURE SENSOR, CONDENSER, THREE-WAY VALVE, TEMPERATURE SENSOR, BUSHING, RADIATOR, CHARGE AIR COOLER, HEATER HOSE, TWO-WAY VALVE, VALVE, HOSE MODULE, SEPARATOR, BRACKET, CLAMP BRACKET, PIPE, HOSE HEATER, HOSE INLET	TBBA [79-94-7], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], 1-Methyl-2-pyrrolidone [872-50-4], Melamine [108-78-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Dodecamethylcyclohexasiloxane [540-97-6], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Silicic acid, lead salt [11120-22-2], 4,4'-Isopropylidenediphenol [80-05-7], Lead [7439-92-1]

Body, Interior / Exterior - [outside mirrors]	REAR VIEW MIRROR, CAMERA, REAR VIEW MIRROR OUTER, GLASS, MOTOR UNIT	Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-Methylimidazole [693-98-1], Dicyclohexyl-phthalate [84-61-7], TBBA [79-94-7], Lead-monoxide [1317-36-8], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Cobalt-dinitrate [10141-05-6], Lead [7439-92-1]
Body, Interior / Exterior - [lock / handle]	OUTER HANDLE, LOCK, EXT746, EXT739, EXT745, E, EXT723, EXT731, EXT736, KSOCOLOR, CKDCOLOR, WIRE, DOOR LOCK, LOCK CYLINDER SET, KEY, BRACKET OUTER HANDLE, LOCK CYLINDER	TBBA [79-94-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Triphenyl-phosphate [115-86-6], Melamine [108-78-1], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Bumetrizole [3896-11-5], Lead [7439-92-1]
Electric Power Supply / Instruments - [lighting]	REAR LAMP, HEADLAMP, READING LAMP, OVERHEAD CONSOLE LENS, CONTROL UNIT HCM, STOP LAMP, LIGHTING, LAMP LED, LED MODULE, LIGHTNING INSTRUMENT PANEL, NUMBER PLATE LIGHTING, SEAL CAP, FOG LIGHT	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Silicic acid, lead salt [11120-22-2], 1-Methyl-2-pyrrolidone [872-50-4], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], TBBA [79-94-7], Dicyclohexyl-phthalate [84-61-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Bumetrizole [3896-11-5], Octamethylcyclotetrasiloxane [556-67-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1], Lead-titanium-trioxide [12060-00-3], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1]
Electric Power Supply / Instruments - [mobile data services]	CONTROL UNIT	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1], Lead [7439-92-1]

Body, Interior / Exterior - [air conditioning]	IONIZER, SUN SENSOR, DISTRIBUTION HOUSING, EL COMPRESSOR, ELECTRIC HEATER, PIPE ASSEMBLY, CLIMATE UNIT, FAN, EVAPORATOR HOUSING, NOZZLE, CHARCOAL SOLID, BLOND, HUMIDITY SENSOR, SENSOR KIT, DEFROSTER, STEPPING MOTOR, CONTROL UNIT, FLANGE SCREW, DRAINAGE HOSE, AIR CLEANER, EXPANSION VALVE, MAGNET CLUTCH, AC-COMPRESSOR, SENSOR, SENSOR INTERIOR, PROTECTIVE CAP, VALVE, CHANNEL SENSOR, CONTROL VALVE	Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Melamine [108-78-1], Bumetrizole [3896-11-5], Diboron-trioxide [1303-86-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead-titanium-trioxide [12060-00-3], 1-Propanol, 2,3-dibromo- [96-13-9], 2-Methylimidazole [693-98-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4], Tris(nonylphenyl)phosphite [26523-78-4], Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8], TBBA [79-94-7], Cobalt-dichloride [7646-79-9], 4,4'-Isopropylidenediphenol [80-05-7], Lead [7439-92-1]
Wheel Suspension / Steering - [steering gear / wheel / shaft / column]	STEERING COLUMN, STEERING COLUMN MANUAL, STEERING GEAR, STEERING WHEEL, STEERING WHEEL RIM, SEALING FLOOR, STEERING WHEEL HARNESS	Phosphorothioic acid, O,O,O-triphenyl esters, tert-Bu derivs. [192268-65-8], Lead-monoxide [1317-36-8], O,O,O-Triphenyl phosphorothioate [597-82-0], Dicyclohexyl-phthalate [84-61-7], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]
Engine - [fuel / EVAP system]	FUEL PUMP MODULE, PUMP MODULE, JET PUMP AND LEVEL SENSOR, FILTER, LEAK DETECTION PUMP, ISOLATION VALVE, FILLER PIPE, PEM, HOSE, EVAP PURGE PUMP, CANISTER, EVAP-LINE ASSY, FUEL TANK, TANK WELDED, PURGE VALVE, PURGE VALVE ASSY, FUEL PRESSURE SENSOR	Melamine [108-78-1], Lead-monoxide [1317-36-8], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Diboron-trioxide [1303-86-2], O,O,O-Triphenyl phosphorothioate [597-82-0], TBBA [79-94-7], Cobalt-dinitrate [10141-05-6], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1]
Electric Power Supply / Instruments - [communication, mobile telephone]	CONTROL UNIT, BATTERY, WIRELESS CHARGE SYSTEM, BACK-UP BATTERY, AUXILIARY TELEMATIC, ANTENNA	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Hexahydromethylphthalic-anhydride [25550-51-0], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], N,N-Dimethylacetamide [127-19-5], Dioctyltin dilaurate [3648-18-8], Lead [7439-92-1]
Electric Power Supply / Instruments - [vehicle control system]	CONTROL UNIT DOOR, SWITCH, CUT-OFF SWITCH, USB POWER OUTLET DUAL, ECU, SWITCH PANEL, STALK MODULE, SWITCH MODULE, COMBI INSTRUMENT, HARDWARE, CONTROL PANEL POWER SEAT, BUTTON, LOCK BUTTON, LOCK BUTTON LED, SWITCH DOOR, SWITCH STEERING WHEEL	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead titanium zirconium oxide [12626-81-2], Triphenyl-phosphate [115-86-6], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Melamine [108-78-1], 4,4'-Isopropylidenediphenol [80-05-7], Boric acid [10043-35-3], Lead-titanium-trioxide [12060-00-3], Lead [7439-92-1]

Body, Interior / Exterior - [airbag]	SIDE AIR BAG, AIRBAG MODULE, CONTROL UNIT, ACCELEROMETER SENSOR, PRESSURE SENSOR	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7], Lead [7439-92-1]
Electric Power Supply / Instruments - [cleaner]	WIPER UNIT, LEVEL SENSOR, WASHER FLUID RESERVOIR, HEADLAMP WIPER, PUMP, WASHER PUMP, WIPER ARM	O,O,O-Triphenyl phosphorothioate [597-82-0], Lead-monoxide [1317-36-8], TBBA [79-94-7], Triphenyl-phosphate [115-86-6], C,C'-azodi(formamide) [123-77-3], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], Lead titanium zirconium oxide [12626-81-2], Lead [7439-92-1]
Electric Power Supply / Instruments - [electric drive system]	VOLTAGE CONVERTER, INVERTER IEM, INVERTER IGM, ONBOARD CHARGER, STARTER MOTOR ALTERNATOR, PROTECTION HIGH VOLTAGE, BRACKET	Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], 2-Methylimidazole [693-98-1], 4,4'-Isopropylidenediphenol [80-05-7], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Alkanes, C14-17, chloro [85535-85-9], Triphenyl-phosphate [115-86-6], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Lead [7439-92-1]
Brake - [wheel brake]	BRAKE CALIPER, HOUSING, EPB, BRAKE LINING, AIR VENTING NIPPLE, BLEEDER VALVE	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], O,O,O-Triphenyl phosphorothioate [597-82-0], 2-Methylimidazole [693-98-1], Diboron-trioxide [1303-86-2], Tris(nonylphenyl)phosphite [26523-78-4], Hexahydromethylphthalic-anhydride [25550-51-0], Dicyclohexyl-phthalate [84-61-7], Lead [7439-92-1]
Electric Power Supply / Instruments - [infotainment system]	GRAPHIC HEAD UP DISPLAY, PRINTED CIRCUIT BOARD, DISPLAY, USB HUB	1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) [29420-49-3], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 4,4'-Isopropylidenediphenol [80-05-7], Melamine [108-78-1], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Boric acid [10043-35-3], Triphenyl-phosphate [115-86-6], Lead [7439-92-1]

Electric Power Supply / Instruments - [cable system high voltage]	CABLE CHARGE POINT HV, BRACKET, CHARGE CABLE CORD, CABLE HARNESS, STRAIN RELIEF, CABLE DUCT, CABLE CHANNEL	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 4,4'-Sulfonyldiphenol [80-09-1], TBBA [79-94-7], Octamethylcyclotetrasiloxane [556-67-2], Lead [7439-92-1]
Electric Power Supply / Instruments - [vehicle computational units / gateway modules]	CONTROL UNIT	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [glass, window / windscreen / roof]	WINDSCREEN, GLASS HARDENED, GLASS LAMINATED, MOULDING, REAR SCREEN	Diboron-trioxide [1303-86-2], C,C'-azodi(formamide) [123-77-3], Boric acid [10043-35-3], Lead [7439-92-1]
Body, Interior / Exterior - [seat belt / other restraining systems]	BELT CATCH, SEAT BELT, BELT, HEIGHT ADJUSTMENT, BELT CATCH REAR	TBBA [79-94-7], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt sulphate [10124-43-3], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead-monoxide [1317-36-8], Decamethyltetrasiloxane [141-62-8], Melamine [108-78-1], Cobalt-dinitrate [10141-05-6], Triphenyl-phosphate [115-86-6], Lead [7439-92-1]
Power Transmission - [gearbox]	CONTROL UNIT, CABLE HARNESS, CONNECTOR, AUTOMATIC GEARBOX, AIR VENT PIPE, FLANGE NUT, FLANGE SCREW, TORQUE CONVERTER, VALVE BODY, SERVO COVER, CONTROL SYSTEM, OIL PUMP, ADAPTER, DIFFERENTIAL SPACER, LID	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], Lead-monoxide [1317-36-8], Nonylphenol [25154-52-3], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], 4,4'-Isopropylidenediphenol [80-05-7], 1-Methyl-2-pyrrolidone [872-50-4], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Cobalt-dinitrate [10141-05-6], Cobalt-dichloride [7646-79-9], Lead-titanium-trioxide [12060-00-3], Silicic acid, lead salt [11120-22-2], Lead [7439-92-1]
Body, Interior / Exterior - [side door]	HEMMING ADHESIVE, SEALING, BODY MOUNTED SEALING, DOOR MOUNTED SEALING, WINDOW LIFT	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Imidazolidine-2-thione [96-45-7], C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1]

Power Transmission - [gear lever carrier / gear selector controls]	GEAR LEVER CARRIER, ACTUATOR	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead [7439-92-1]
Power Transmission - [actuator, gear shift]	CONTROL UNIT	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], Silicic acid, lead salt [11120-22-2], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Brake - [brake line with connections]	BRAKE PIPE, BRAKE PIPE FRONT, RETAINER	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bumetrizole [3896-11-5], Lead [7439-92-1]
Electric Power Supply / Instruments - [protection]	CONTROL UNIT, SENSOR FRONT, SENSOR REAR, ACCELEROMETER, ACCELEROMETER FRONT	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Lead [7439-92-1]
Engine - [emission equipment]	LAMBDA SOND, PRESSURE SENSOR, VALVE, COOLER, STAY, ALUMINIUM	Diboron-trioxide [1303-86-2], TBBA [79-94-7], Lead-monoxide [1317-36-8], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1]
Body, Interior / Exterior - [instrument / radio panel]	LIGHTING, IP, GLOVE BOX, CONCEALING PANEL, LAMP LED, PANEL NOZZLE, LIGHT ASH, LED MODULE, BROWN ASH, GREY ASH, CASSETTE, GLOVE BOX LID, CHARCOAL, BLOND, LIGHT GUIDE, COVER, ADAPTER, STORAGE BOX, HINGE PIN	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Bumetrizole [3896-11-5], TBBA [79-94-7], Lead [7439-92-1]
Engine - [fan]	FAN	Boric acid [10043-35-3], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead [7439-92-1]

Engine - [engine / engine mounting]	ENGINE, ENGINE MOUNT, TORQUE ROD, TORQUE LINK BRACKET, ENGINE BRACKET	Bis(4-chlorophenyl) sulfon [80-07-9], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Decamethylcyclotetrasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], TBBA [79-94-7], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Lead [7439-92-1]
Brake - [brake, anti lock (anti-skid)]	HYDRAULIC UNIT, SENSOR	Lead titanium zirconium oxide [12626-81-2], Boric acid [10043-35-3], O,O,O-Triphenyl phosphorothioate [597-82-0], Cobalt(II) nitrate hexahydrate [10026-22-9], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Lead [7439-92-1]
Electric Power Supply / Instruments - [electrical distribution box / fuse box]	CEM, ATTACHMENT	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [miscellaneous]	SEALING, TRANSPORT PROTECTION	C,C'-azodi(formamide) [123-77-3], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Frame / Springs / Damping / Wheels - [rim]	WHEEL 8, 5X20X47, 5, ADHESIVE BALANCE WEIGHT, TYRE 245/40R20 99W XL, VALVE	Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], 2-Methylimidazole [693-98-1], Triphenyl-phosphate [115-86-6], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [body side]	WELD SEALANT CURING	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Body, Interior / Exterior - [roof]	WELD SEALANT CURING, ADHESIVE ROOF HATCH, MOTOR, SEALING STRIP, GLASS PANEL, SEALING, PANORAMA ROOF	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], C,C'-azodi(formamide) [123-77-3], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [floor / frame section / wheel housing / firewall]	WELD SEALANT CURING, TOP COVER, REINFORCEMENT, SIDE MEMBER UPPER INNER, BRACE INNER, BRACE OUTER, BATTERY TRAY	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]

Electric Power Supply / Instruments - [horn]	HORN	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead [7439-92-1]
Body, Interior / Exterior - [instruction / information plates]	SIX POINT SOCKET SCREW, NUMBER PLATE HOLDER	1-Methyl-2-pyrrolidone [872-50-4], Lead [7439-92-1]
Body, Interior / Exterior - [bumper with mounting / damping]	SOFTNOSE, EXT707, EXT717, EXT723, EXT731, EXT736, EXT739, EXT740, EXT745, KSOCOLOR	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Electric Power Supply / Instruments - [antenna]	ETC MODULE, ANTENNA AMPLIFIER, WAVE TRAP, GROUND SIDE COIL, ETC ON BOARD UNIT	Lead-monoxide [1317-36-8], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Hexahydromethylphthalic-anhydride [25550-51-0], Lead [7439-92-1]
Body, Interior / Exterior - [bonnet / cover with assembly parts]	HOOD RELEASE CABLE, FOAM, HOOD LOCK, COVER, HOOD LOCK CONTROL	Imidazolidine-2-thione [96-45-7], C,C'-azodi(formamide) [123-77-3], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [anti-roll bar]	LINK FRONT ANTI-ROLL BAR, LINK ANTI-ROLL BAR, ANTI-ROLL BAR FRONT, ANTI-ROLL BAR REAR	Imidazolidine-2-thione [96-45-7], 2-Methylimidazole [693-98-1]
Body, Interior / Exterior - [trunk lid / tailgate complete]	ANTIFLUTTER, SPINDLE DRIVE, BUMPSTOP, HINGE	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], C,C'-azodi(formamide) [123-77-3], Imidazolidine-2-thione [96-45-7], Lead [7439-92-1]
Body, Interior / Exterior - [hood cover]	ANTIFLUTTER, FOAM, HOOD	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], C,C'-azodi(formamide) [123-77-3], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Body, Interior / Exterior - [front fender]	ANTIFLUTTER, SHIM	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]

Body, Interior / Exterior - [tank hatch]	ACTUATOR, PLASTIC MODULE	TBBA [79-94-7], Triphenyl-phosphate [115-86-6], Lead [7439-92-1]
Body, Interior / Exterior - [protective shields / flaps]	CLIP	Bumetizole [3896-11-5]
Power Transmission - [final drive]	SEALING, PT-UNIT, BRACKET	Triphenyl-phosphate [115-86-6], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead [7439-92-1]
Brake - [master cylinder / brake booster]	LID	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Frame / Springs / Damping / Wheels - [spring, leaf spring]	VALVE BLOCK, AIR SPRING REAR, COMPRESSOR, RESEVOIR, HOSE COUPLING	Decamethylcyclopentasiloxane [541-02-6], O,O,O-Triphenyl phosphorothioate [597-82-0], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Triphenyl-phosphate [115-86-6], Tris(nonylphenyl)phosphite [26523-78-4], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Engine - [intercooler / connection]	CHARGE AIR HOSE, CHARGE AIR PIPE, RESONATOR, CHARGE AIR COOLER	Boric acid [10043-35-3], Lead [7439-92-1]
Engine - [accelerator control]	ACCELERATOR PEDAL	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead [7439-92-1]
Engine - [air cleaner]	FRESH AIR PIPE, BOX	Lead [7439-92-1]
Brake - [brake control]	PEDAL UNIT, SENSOR	Lead [7439-92-1]
Engine - [miscellaneous / help device installation]	BRACKET, TENSIONER	Lead [7439-92-1]

Electric Power Supply / Instruments - [cable components]	CABLE DUCT	Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [shock absorber]	SHOCK ABSORBER, SHOCK ABSORBER FRONT	Lead [7439-92-1]
Engine - [cold zone / batterybox]	NVH PANEL	Lead [7439-92-1]