

S90 MODEL YEAR 2026
Candidate List Substances Table

Released: 2025 week 35.

We hereby inform that almost all product areas contain lead (CAS No 7439-92-1), primarily as alloying elements in steel, aluminium and copper.

Localisation	Partnames	Substance/s
Wheel Suspension / Steering - [axle member / link arm / suspension]	HUB, LOWER LINK ARM	O,O,O-Triphenyl phosphorothioate [597-82-0], Imidazolidine-2-thione [96-45-7]
Wheel Suspension / Steering - [front suspension]	HUB	O,O,O-Triphenyl phosphorothioate [597-82-0]
Electric Power Supply / Instruments - [radio equipment]	MICROPHONE, SPEAKER MIDRANGE, AUDIO MODULE, SOUND MODULE, SUBWOOFER, WOOFER, TWEETER, LOUDSPEAKER, CENTRE LOUDSPEAKER	Diboron-trioxide [1303-86-2], N,N-Dimethylacetamide [127-19-5], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], Melamine [108-78-1], TBBA [79-94-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Triphenyl-phosphate [115-86-6], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Cobalt(II) nitrate hexahydrate [10026-22-9], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Body, Interior / Exterior - [seats]	FRAMEWORK, HEAD RESTRAINT, UNDERCARRIAGE, ENGINE, UPHOLSTERY, HEATING PAD SEAT, LUMBAR SUPPORT, BACKREST FRAME, LUMBAR SUPPORT 4-WAY, MASSAGE PUMP, SIX POINT SOCKET SCREW, VENTILATION, FAN, COVER, CHARCOAL SOLID, AMBER, COULISSE, HARDBACK, HATCH, CHARCOAL/BLOND, SLATE, ENGINE TILT, CABLE HARNESS	Paraffin oils, chloro [85422-92-0], Triphenyl-phosphate [115-86-6], C,C'-azodi(formamide) [123-77-3], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2], O,O,O-Triphenyl phosphorothioate [597-82-0], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], TBBA [79-94-7], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Imidazolidine-2-thione [96-45-7], 1-Methyl-2-pyrrolidone [872-50-4], Bumetrizole [3896-11-5], Boric acid [10043-35-3], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], N,N-Dimethylacetamide [127-19-5], Lead [7439-92-1]

Body, Interior / Exterior - [upholstery]	DOOR PANEL, SILL MOULDING, WAISTRAIL, SILL FRONT, LIGHTING, CLIP HOUSING, B-PILLAR PANEL, BLOND, C-PILLAR PANEL, CHARCOAL, A-PILLAR PANEL	C,C'-azodi(formamide) [123-77-3], Diboron-trioxide [1303-86-2], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Bumetrizole [3896-11-5], Lead [7439-92-1]
Body, Interior / Exterior - [interior equipment]	PADDING, ARM REST, CARRIER, JALUSIE, EC REAR VIEW MIRROR, COURTESY HANDLE, SIDE PANEL, FRAMEWORK, SUN VISOR, BLOND, CHARCOAL, CARRIER ARM REST, DAMPER, HINGE	C,C'-azodi(formamide) [123-77-3], Tris(nonylphenyl)phosphite [26523-78-4], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Cobalt sulphate [10124-43-3], TBBA [79-94-7], Cobalt-dinitrate [10141-05-6], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead [7439-92-1]
Power Transmission - [front axle / rear axle / drive shaft]	AOC, SEALING RING, PUMP UNIT, FINAL DRIVE, RADIAL SEAL KIT, REAR AXLE, DRIVE SHAFT, BRACKET, VIBRATION DAMPER, BEARING ANCHORAGE	Triphenyl-phosphate [115-86-6], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead [7439-92-1]
Engine - [control systems]	AIR TEMP SENSOR, CONTROL UNIT, MASS AIR FLOW SENSOR, TEMP AND PRESSURE SENSOR, PRESSURE SENSOR	Lead-monoxide [1317-36-8], Silicic acid, lead salt [11120-22-2], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], Lead [7439-92-1]
Electric Power Supply / Instruments - [support systems]	CONTROL UNIT, CAMERA, RADAR	Lead-monoxide [1317-36-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Methylimidazole [693-98-1], Dicyclohexyl-phthalate [84-61-7], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Electric Power Supply / Instruments - [cable system]	CABLE HARNESS, CABLE, FLANGE NUT, CABLE HARNESS WEM, BRACKET, FUSE BOX ASSY, FUSE BOX	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], TBBA [79-94-7], Triphenyl-phosphate [115-86-6], Cobalt-dinitrate [10141-05-6], Lead [7439-92-1]

Body, Interior / Exterior - [air conditioning]	FUEL OPERATED HEATER, SUN SENSOR, EL COMPRESSOR, ELECTRIC HEATER, PIPE ASSEMBLY, HUMIDITY SENSOR, NOZZLE CHARCOAL SOLID, NOZZLE BLOND, FLANGE SCREW, DRAINAGE HOSE, AIR CLEANER, EXPANSION VALVE, MAGNET CLUTCH, AC-COMPRESSOR, PROTECTIVE CAP, VALVE, CHANNEL SENSOR, CONTROL VALVE	Refractory ceramic fibres [142844-00-6], 2-Methylimidazole [693-98-1], Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Diboron-trioxide [1303-86-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead-titanium-trioxide [12060-00-3], 1-Propanol, 2,3-dibromo- [96-13-9], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4], Tris(nonylphenyl)phosphite [26523-78-4], Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8], TBBA [79-94-7], Bumetrizole [3896-11-5], Cobalt-dichloride [7646-79-9], Melamine [108-78-1], 4,4'-Isopropylidenediphenol [80-05-7], Lead [7439-92-1]
Body, Interior / Exterior - [outside / exterior trim]	EMBLEM	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9]
Electric Power Supply / Instruments - [battery and mounting parts]	HEAT SHIELD, HEAT INSULATION PAD, MODULE, BATTERY, CONTROL UNIT, INLET HOSE, OUTLET HOSE, SERVICE SWITCH, CURRENT SENSOR	Diboron-trioxide [1303-86-2], Melamine [108-78-1], Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8], Lead-monoxide [1317-36-8], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Boric acid [10043-35-3], Decamethylcyclopentasiloxane [541-02-6], Dodecamethylcyclotetrasiloxane [540-97-6], Octamethylcyclotetrasiloxane [556-67-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1]
Engine - [cooling system]	HOSE TEMP SENSOR, PUMP, RADIATOR HYBRID, HOSE, EL WATER PUMP, TEMPERATURE SENSOR, BUSHING, THREE-WAY VALVE, HOSE OUTLET, HEATER HOSE, TWO-WAY VALVE, VALVE, HOSE MODULE, SEPARATOR, BRACKET, CLAMP BRACKET, PIPE, HOSE HEATER, HOSE INLET, GASKET, O-RING, SIX POINT SOCKET SCREW, FLANGE SCREW, STRIKER PLATE, THERMOSTAT HOUSING, NIPPLE, WATER PUMP, PLASTIC PIPE	TBBA [79-94-7], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], 1-Methyl-2-pyrrolidone [872-50-4], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Silicic acid, lead salt [11120-22-2], 4,4'-Isopropylidenediphenol [80-05-7], Melamine [108-78-1], Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt-dichloride [7646-79-9], C,C'-azodi(formamide) [123-77-3]

Electric Power Supply / Instruments - [mobile data services]	CONTROL UNIT	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1], Lead [7439-92-1]
Wheel Suspension / Steering - [steering gear / wheel / shaft / column]	STEERING COLUMN, STEERING COLUMN MANUAL, STEERING GEAR, STEERING WHEEL, STEERING WHEEL RIM, STEERING WHEEL HARNESS	Phosphorothioic acid, O,O,O-triphenyl esters, tert-Bu derivs. [192268-65-8], Lead-monoxide [1317-36-8], O,O,O-Triphenyl phosphorothioate [597-82-0], Dicyclohexyl-phthalate [84-61-7], Lead [7439-92-1]
Electric Power Supply / Instruments - [vehicle control system]	SWITCH PANEL, CONTROL UNIT DOOR, SWITCH, CUT-OFF SWITCH, USB POWER OUTLET, ECU, CONTROL PANEL POWER SEAT, LOCK BUTTON, LOCK BUTTON LED, SWITCH WINDOW LIFT, SWITCH DOOR, SWITCH MODULE, SWITCH STEERING WHEEL	Triphenyl-phosphate [115-86-6], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead titanium zirconium oxide [12626-81-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1]
Electric Power Supply / Instruments - [communication, mobile telephone]	CONTROL UNIT, BATTERY	Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Lead [7439-92-1]
Engine - [fuel / EVAP system]	FUEL PUMP MODULE, PUMP MODULE, JET PUMP AND LEVEL SENSOR, FILTER, ISOLATION VALVE, PEM, CANISTER, EVAP-LINE ASSY, FUEL TANK, TANK WELDED, PURGE VALVE, PURGE VALVE ASSY, FUEL PRESSURE SENSOR, FUEL DISTRIBUTION PIPE, HIGH PRESSURE PUMP, INJECTOR, FUEL PUMP	Melamine [108-78-1], Lead-monoxide [1317-36-8], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], TBBA [79-94-7], Cobalt-dinitrate [10141-05-6], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], C,C'-azodi(formamide) [123-77-3], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [airbag]	SIDE AIR BAG, AIRBAG MODULE, ACCELEROMETER SENSOR	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], TBBA [79-94-7], Lead [7439-92-1]
Electric Power Supply / Instruments - [cleaner]	WIPER UNIT, HEADLAMP WIPER, WIPER ARM	O,O,O-Triphenyl phosphorothioate [597-82-0], Lead-monoxide [1317-36-8], TBBA [79-94-7], Triphenyl-phosphate [115-86-6], Lead [7439-92-1]

Body, Interior / Exterior - [floor / frame section / wheel housing / firewall]	FRONT SIDE MEMBER, WHEEL HOUSING, WELD SEALANT CURING, ADHESIVE, FLOOR PANEL, TOP COVER, REINFORCEMENT, SIDE MEMBER UPPER INNER, BRACE INNER, BRACE OUTER, BATTERY TRAY	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Electric Power Supply / Instruments - [electric drive system]	VOLTAGE CONVERTER, INVERTER IEM, INVERTER IGM, STARTER MOTOR ALTERNATOR, PROTECTION HIGH VOLTAGE, BRACKET, SEALING, STARTER MOTOR, COOLANT PIPE, SENSOR	Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], 2-Methylimidazole [693-98-1], 4,4'-Isopropylidenediphenol [80-05-7], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Alkanes, C14-17, chloro [85535-85-9], Triphenyl-phosphate [115-86-6], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Lead [7439-92-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], N,N-Dimethylacetamide [127-19-5]
Brake - [wheel brake]	BRAKE CALIPER, EPB, AIR VENTING NIPPLE, BLEEDER VALVE	O,O,O-Triphenyl phosphorothioate [597-82-0], 2-Methylimidazole [693-98-1], Diboron-trioxide [1303-86-2], Hexahydromethylphthalic-anhydride [25550-51-0], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]
Electric Power Supply / Instruments - [infotainment system]	GRAPHIC HEAD UP DISPLAY, USB HUB	1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) [29420-49-3], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], Triphenyl-phosphate [115-86-6], Boric acid [10043-35-3], Lead [7439-92-1]
Electric Power Supply / Instruments - [vehicle computational units / gateway modules]	CONTROL UNIT	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [glass, window / windscreen / roof]	WINDSCREEN, GLASS HARDENED, GLASS LAMINATED	Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [seat belt / other restraining systems]	BELT CATCH, HEIGHT ADJUSTMENT, BELT CATCH REAR	TBBA [79-94-7], Lead [7439-92-1]

Engine - [inlet / exhaust systems]	EXHAUST SYSTEM, THROTTLE, HEAT SHIELD PLATE, INTAKE MANIFOLD	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1], Boric acid [10043-35-3]
Power Transmission - [gear lever carrier / gear selector controls]	GEAR LEVER CARRIER, ACTUATOR	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead [7439-92-1]
Power Transmission - [actuator, gear shift]	CONTROL UNIT	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], Silicic acid, lead salt [11120-22-2], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Brake - [brake line with connections]	BRAKE PIPE, BRAKE PIPE FRONT, RETAINER	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bumetrizole [3896-11-5], Lead [7439-92-1]
Electric Power Supply / Instruments - [protection]	CONTROL UNIT, SENSOR FRONT, SENSOR REAR, ACCELEROMETER, ACCELEROMETER FRONT	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Lead [7439-92-1]
Engine - [emission equipment]	LAMBDA SOND, PRESSURE SENSOR, VALVE, COOLER, ALUMINIUM, STAY	Diboron-trioxide [1303-86-2], TBBA [79-94-7], Lead-monoxide [1317-36-8], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1]
Electric Power Supply / Instruments - [automatic monitoring / control]	SENSOR, RAIN SENSOR	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead [7439-92-1]
Engine - [fan]	FAN, FAN LOW	Boric acid [10043-35-3], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead [7439-92-1]

Engine - [engine / engine mounting]	ENGINE, TORQUE ROD, TORQUE LINK BRACKET, ENGINE BRACKET, ENGINE MOUNT	Lead-monoxide [1317-36-8], Bis(4-chlorophenyl) sulfon [80-07-9], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], TBBA [79-94-7], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9]
Body, Interior / Exterior - [body side]	WELD SEALANT CURING	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Frame / Springs / Damping / Wheels - [anti-roll bar]	LINK FRONT ANTI-ROLL BAR, LINK ANTI-ROLL BAR, ANTI-ROLL BAR FRONT, ANTI-ROLL BAR REAR	Imidazolidine-2-thione [96-45-7], 2-Methylimidazole [693-98-1]
Body, Interior / Exterior - [miscellaneous]	TRANSPORT PROTECTION, SEALANT REPAIR	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Dibutylbis(pentane-2,4-dionato-O,O')tin [22673-19-4]
Body, Interior / Exterior - [hood cover]	ANTIFLUTTER, FOAM, HOOD	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], C,C'-azodi(formamide) [123-77-3], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Body, Interior / Exterior - [tank hatch]	ACTUATOR, PLASTIC MODULE	TBBA [79-94-7], Triphenyl-phosphate [115-86-6], Lead [7439-92-1]
Body, Interior / Exterior - [protective shields / flaps]	CLIP	Bumetrizole [3896-11-5]
Electric Power Supply / Instruments - [antenna]	ANTENNA AMPLIFIER, WAVE TRAP, GROUND SIDE COIL, ANTENNA	TBBA [79-94-7], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead titanium zirconium oxide [12626-81-2], 1-Propanol, 2,3-dibromo- [96-13-9], Melamine [108-78-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Lead [7439-92-1]

Power Transmission - [gearbox]	CABLE HARNESS, FLANGE NUT, FLANGE SCREW, AUTOMATIC GEARBOX, CONTROL UNIT, SERVO COVER, TORQUE CONVERTER, CONTROL SYSTEM, OIL PUMP, ADAPTER, DIFFERENTIAL SPACER, LID	Lead-monoxide [1317-36-8], Nonylphenol [25154-52-3], Cobalt-dinitrate [10141-05-6], Cobalt-dichloride [7646-79-9], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], Lead titanium zirconium oxide [12626-81-2], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], 1-Methyl-2-pyrrolidone [872-50-4], Silicic acid, lead salt [11120-22-2], Lead [7439-92-1]
Power Transmission - [final drive]	SEALING, PT-UNIT, BRACKET	Triphenyl-phosphate [115-86-6], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead [7439-92-1]
Brake - [master cylinder / brake booster]	LID	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Body, Interior / Exterior - [bonnet / cover with assembly parts]	FOAM, HOOD RELEASE CABLE, HOOD LOCK, COVER, HOOD LOCK CONTROL	C,C'-azodi(formamide) [123-77-3], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Imidazolidine-2-thione [96-45-7], Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [spring, leaf spring]	VALVE BLOCK, AIR SPRING REAR, COMPRESSOR, RESEVOIR, HOSE COUPLING	Decamethylcyclopentasiloxane [541-02-6], O,O,O-Triphenyl phosphorothioate [597-82-0], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Triphenyl-phosphate [115-86-6], Tris(nonylphenyl)phosphite [26523-78-4], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Engine - [intercooler / connection]	CHARGE AIR HOSE, CHARGE AIR PIPE, RESONATOR, CHARGE AIR COOLER	Boric acid [10043-35-3], Lead [7439-92-1]
Body, Interior / Exterior - [exterior equipment]	ACTIVE GRILLE SHUTTER, ACTIVE SPOILER SHUTTER	Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Engine - [accelerator control]	ACCELERATOR PEDAL	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead [7439-92-1]

Electric Power Supply / Instruments - [cable system high voltage]	CHARGE CABLE CORD, CABLE HARNESS, STRAIN RELIEF, CABLE DUCT	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Octamethylcyclotetrasiloxane [556-67-2], TBBA [79-94-7], Lead [7439-92-1]
Engine - [air cleaner]	BELLOWS, FRESH AIR PIPE, BOX	Bumetrizole [3896-11-5], Lead [7439-92-1]
Electric Power Supply / Instruments - [lighting]	FOG LIGHT	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead [7439-92- 1]
Body, Interior / Exterior - [lock / handle]	DOOR LOCK, LOCK CYLINDER SET, KEY, BRACKET OUTER HANDLE, LOCK CYLINDER	Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [shock absorber]	SHOCK ABSORBER FRONT, SHOCK ABSORBER	Lead [7439-92-1]
Body, Interior / Exterior - [front fender]	SHIM	Lead [7439-92-1]
Electric Power Supply / Instruments - [electrical distribution box / fuse box]	ATTACHMENT	Lead [7439-92-1]
Body, Interior / Exterior - [side door]	CARRIER PLATE	Lead [7439-92-1]
Brake - [brake control]	SENSOR, PEDAL UNIT	Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [rim]	KEY, WHEEL BOLT	Lead [7439-92-1]

Body, Interior / Exterior - [instrument / radio panel]	STORAGE BOX	Lead [7439-92-1]
Brake - [brake, anti lock (anti-skid)]	SENSOR	Lead [7439-92-1]
Engine - [miscellaneous / help device installation]	SPLASH PROTECTION, BRACKET	Lead [7439-92-1]
Engine - [cold zone / batterybox]	NVH PANEL	Lead [7439-92-1]
Engine - [ignition / spark plug]	IGNITION COIL, SPARK PLUG, GLOW PLUG	Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Engine - [lubricating and oil system]	GASKET, OIL PUMP, OIL LEVEL SENSOR, OIL FILTER, OIL PRESSURE SENSOR, OIL SUMP, SUCTION LINE, PISTON COOLING JET, VALVE, INLET PIPE, PISTON COOLING VALVE, WINDAGE TRAY, PLUG	Bis(4-chlorophenyl) sulfon [80-07-9], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Engine - [transmission]	GASKET, VVT-UNIT, TENSIONER, IDLER PULLEY, CAMSHAFT, SOLENOID, BALANCE SHAFT, BELT PROTECTOR, HOUSING, BELT COVER, VVT ACTUATOR, SLEEVE	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]
Engine - [supercharging]	TURBO CHARGER, O-RING, VACUUM RESERVOIR, VACUUM REGULATOR, BRACKET	N,N-Dimethylacetamide [127-19-5], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Lead [7439-92-1]
Engine - [distributor]	KNOCK SENSOR, CAMSHAFT POSITION SENSOR	Lead titanium zirconium oxide [12626-81-2], Lead-monoxide [1317-36-8], Lead [7439-92-1]
Engine - [cylinder block / head]	BEDPLATE, ENGINE BRACKET, VACUUM PUMP, CYLINDER BLOCK, TOP COVER, GUIDE SLEEVE, BEARING HOUSE CAM SHAFT, CYLINDER HEAD, CAP, CAM SHAFT COVER, CAMSHAFT CAP, HOUSING, LOCATING PIN	Lead [7439-92-1]
Engine - [crank mechanism]	DUAL MASS FLYWHEEL, NIPPLE, NON-RETURN VALVE	Lead [7439-92-1]