

V90 MODEL YEAR 2026
Candidate List Substances Table

Released: 2025 week 35.

We hereby inform that almost all product areas contain lead (CAS No 7439-92-1), primarily as alloying elements in steel, aluminium and copper.

Localisation	Partnames	Substance/s
Wheel Suspension / Steering - [axle member / link arm / suspension]	HUB, LOWER LINK ARM, UPPER LINK ARM, TRIPLESQUARE SOCKET SCREW, BALL JOINT	O,O,O-Triphenyl phosphorothioate [597-82-0], Imidazolidine-2-thione [96-45-7], Diboron-trioxide [1303-86-2]
Wheel Suspension / Steering - [front suspension]	HUB, TRIPLESQUARE SOCKET SCREW	O,O,O-Triphenyl phosphorothioate [597-82-0], Diboron-trioxide [1303-86-2]
Electric Power Supply / Instruments - [automatic monitoring / control]	CONTROL UNIT, SIREN, SENSOR, REMOTE KEY, RAIN SENSOR, TRM	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead titanium zirconium oxide [12626-81-2], 1,2-Dimethoxyethane [110-71-4], Lead-titanium-trioxide [12060-00-3], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead [7439-92-1]
Electric Power Supply / Instruments - [radio equipment]	MICROPHONE, SPEAKER MIDRANGE, AUDIO MODULE, SOUND MODULE, SUBWOOFER, WOOFER, TWEETER, LOUDSPEAKER, CENTRE LOUDSPEAKER, BRACKET	Diboron-trioxide [1303-86-2], N,N-Dimethylacetamide [127-19-5], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], Melamine [108-78-1], TBBA [79-94-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Triphenyl-phosphate [115-86-6], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Cobalt(II) nitrate hexahydrate [10026-22-9], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Body, Interior / Exterior - [seats]	FRAMEWORK, HEAD RESTRAINT, UPHOLSTERY, UNDERCARRIAGE, ENGINE, HEATING PAD SEAT, LUMBAR SUPPORT, LOCK, CHARCOAL SOLID, STS SENSOR, BACKREST FRAME, LUMBAR SUPPORT 4-WAY, HEATER, MASSAGE PUMP, SIX POINT SOCKET SCREW, ARM REST, VENTILATION, SIDE BOLSTER, FAN, COVER, AMBER, COULISSE, HARDBACK, HATCH, CHARCOAL/BLOND, SLATE, BLOND, ENGINE TILT, CABLE HARNESS	Paraffin oils, chloro [85422-92-0], Triphenyl-phosphate [115-86-6], C,C'-azodi(formamide) [123-77-3], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2], O,O,O-Triphenyl phosphorothioate [597-82-0], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], TBBA [79-94-7], Melamine [108-78-1], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Imidazolidine-2-thione [96-45-7], 1-Methyl-2-pyrrolidone [872-50-4], N,N-Dimethylacetamide [127-19-5], Bumetrizole [3896-11-5], Boric acid [10043-35-3], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3], Lead [7439-92-1]

Body, Interior / Exterior - [upholstery]	DOOR PANEL, SILL MOULDING, WAISTRAIL, LAMP LED, SIDE PANEL, SILL FRONT, LIGHTING, GUIDE RAIL, PANEL, CLIP HOUSING, HEADLINING, BELT GUIDE, LUGGAGE COVER, B-PILLAR PANEL, BLOND, C-PILLAR PANEL, CHARCOAL, A-PILLAR PANEL	C,C'-azodi(formamide) [123-77-3], Diboron-trioxide [1303-86-2], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Triphenyl-phosphate [115-86-6], TBBA [79-94-7], Bumetrizole [3896-11-5], Melamine [108-78-1], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead [7439-92-1]
Body, Interior / Exterior - [interior equipment]	PADDING, ARM REST, FRAMEWORK, CARRIER, JALUSIE, EC REAR VIEW MIRROR, COURTESY HANDLE, LIGHTING, LED MODULE, CUP HOLDER, AIR OUTLET, SIDE PANEL, SUN VISOR, CHARCOAL, BLOND, CARRIER ARM REST, DAMPER, HINGE	C,C'-azodi(formamide) [123-77-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Tris(nonylphenyl)phosphite [26523-78-4], Diboron-trioxide [1303-86-2], Cobalt sulphate [10124-43-3], TBBA [79-94-7], Cobalt-dinitrate [10141-05-6], Bumetrizole [3896-11-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Power Transmission - [front axle / rear axle / drive shaft]	AOC, SEALING RING, PUMP UNIT, FINAL DRIVE, RADIAL SEAL KIT, REAR AXLE, DRIVE SHAFT, BRACKET, VIBRATION DAMPER, BEARING ANCHORAGE	Triphenyl-phosphate [115-86-6], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead [7439-92-1]
Electric Power Supply / Instruments - [support systems]	SENSOR, CONTROL UNIT, CAMERA, RADAR, EXT743, EXT746, EXT744, EXT745	Lead-monoxide [1317-36-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Methylimidazole [693-98-1], Dicyclohexyl-phthalate [84-61-7], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Lead [7439-92-1]
Engine - [control systems]	AIR TEMP SENSOR, CONTROL UNIT, MASS AIR FLOW SENSOR, TEMP AND PRESSURE SENSOR, PRESSURE SENSOR	Lead-monoxide [1317-36-8], Silicic acid, lead salt [11120-22-2], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], Lead [7439-92-1]
Electric Power Supply / Instruments - [cable system]	CABLE HARNESS, CABLE FLOOR, CABLE, FLANGE NUT, CABLE HARNESS WEM, FUSE BOX, CABLE DUCT, BRACKET, EJB, FUSE BOX ASSY, CABLE INFOTAINMENT	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Triphenyl-phosphate [115-86-6], TBBA [79-94-7], Cobalt-dinitrate [10141-05-6], Lead [7439-92-1]

Body, Interior / Exterior - [air conditioning]	FUEL OPERATED HEATER, SUN SENSOR, EL COMPRESSOR, DISTRIBUTION HOUSING, ELECTRIC HEATER, PIPE ASSEMBLY, CLIMATE UNIT, FAN, EVAPORATOR HOUSING, AIR INLET, HUMIDITY SENSOR, SENSOR KIT, DEFROSTER, STEPPING MOTOR, NOZZLE CHARCOAL SOLID, NOZZLE BLOND, CONTROL UNIT, FLANGE SCREW, DRAINAGE HOSE, AIR CLEANER, EXPANSION VALVE, MAGNET CLUTCH, AC-COMPRESSOR, SENSOR, SENSOR INTERIOR, PROTECTIVE CAP, VALVE, CHANNEL SENSOR, CONTROL VALVE, FUEL PUMP	Refractory ceramic fibres [142844-00-6], 2-Methylimidazole [693-98-1], Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Diboron-trioxide [1303-86-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead-titanium-trioxide [12060-00-3], 1-Propanol, 2,3-dibromo- [96-13-9], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4], Tris(nonylphenyl)phosphite [26523-78-4], Melamine [108-78-1], Bumetrizole [3896-11-5], Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8], TBBA [79-94-7], Cobalt-dichloride [7646-79-9], 4,4'-Isopropylidenediphenol [80-05-7], Lead [7439-92-1]
Body, Interior / Exterior - [outside / exterior trim]	EMBLEM, ANTENNA CAP, WHITE614, BLUE467, SILV477, BLACK487, GREY492, BROWN700, BLUE706, EXT707, EXT711, EXT714, EXT717, EXT719, CKDCOLOR, KSOCOLOR, SVART19S, RED612, EXT720, TAPE, EXT722, EXT721, EXT723, EXT621, EXT724, EXT725	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Triphenyl-phosphate [115-86-6]
Electric Power Supply / Instruments - [battery and mounting parts]	HEAT SHIELD, HEAT INSULATION PAD, MODULE, BATTERY, 48V BATTERY, CONTROL UNIT, INLET HOSE, OUTLET HOSE, SERVICE SWITCH, CURRENT SENSOR, BMS	Diboron-trioxide [1303-86-2], Melamine [108-78-1], Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8], Lead-monoxide [1317-36-8], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Boric acid [10043-35-3], 1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Octamethylcyclotetrasiloxane [556-67-2], 1-Propanol, 2,3-dibromo- [96-13-9], Lead-titanium-trioxide [12060-00-3], Decamethylcyclopentasiloxane [541-02-6], Dodecamethylcyclohexasiloxane [540-97-6], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1]
Engine - [cooling system]	HOSE TEMP SENSOR, PUMP, SET, RADIATOR HYBRID, HOSE, EL WATER PUMP, PRESSURE SENSOR, CONDENSER, COOLER, THREE-WAY VALVE, TEMPERATURE SENSOR, BUSHING, HOSE OUTLET, HEATER HOSE, TWO-WAY VALVE, VALVE, HOSE MODULE, HOSE INLET, SEPARATOR, BRACKET, CLAMP BRACKET, PIPE, HOSE HEATER, GASKET, O-RING, SIX POINT SOCKET SCREW, FLANGE SCREW, STRIKER PLATE, THERMOSTAT HOUSING, NIPPLE, WATER PUMP, PLASTIC PIPE	TBBA [79-94-7], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], 1-Methyl-2-pyrrolidone [872-50-4], Melamine [108-78-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Dodecamethylcyclohexasiloxane [540-97-6], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Silicic acid, lead salt [11120-22-2], 4,4'-Isopropylidenediphenol [80-05-7], Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt-dichloride [7646-79-9], C,C'-azodi(formamide) [123-77-3]

Body, Interior / Exterior - [outside mirrors]	REAR VIEW MIRROR, CAMERA, REAR VIEW MIRROR OUTER, GLASS, MOTOR UNIT	Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-Methylimidazole [693-98-1], Dicyclohexyl-phthalate [84-61-7], Lead-monoxide [1317-36-8], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], TBBA [79-94-7], Cobalt-dinitrate [10141-05-6], Lead [7439-92-1]
Body, Interior / Exterior - [side door]	SIDE DOOR, HEMMING ADHESIVE, CARRIER PLATE, WINDOW LIFT	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Body, Interior / Exterior - [lock / handle]	OUTER HANDLE, HANDLE, LOCK, LOCK WITH ANTI THEFT COVE, EXT746, EXT739, EXT745, DOOR LOCK, LOCK CYLINDER SET, KEY, BRACKET OUTER HANDLE, LOCK CYLINDER	TBBA [79-94-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Triphenyl-phosphate [115-86-6], Melamine [108-78-1], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Hexahydromethylphthalic-anhydride [25550-51-0], Lead [7439-92-1]
Electric Power Supply / Instruments - [mobile data services]	CONTROL UNIT	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1], Lead [7439-92-1]
Wheel Suspension / Steering - [steering gear / wheel / shaft / column]	STEERING COLUMN, STEERING GEAR, STEERING WHEEL, STEERING WHEEL RIM, SEALING FLOOR, STEERING WHEEL HARNESS	Phosphorothioic acid, O,O,O-triphenyl esters, tert-Bu derivs. [192268-65-8], Lead-monoxide [1317-36-8], O,O,O-Triphenyl phosphorothioate [597-82-0], Dicyclohexyl-phthalate [84-61-7], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]
Electric Power Supply / Instruments - [vehicle control system]	SWITCH PANEL, CONTROL UNIT DOOR, SWITCH, CUT-OFF SWITCH, USB POWER OUTLET, ECU, STALK MODULE, COMBI INSTRUMENT, HARDWARE, CONTROL PANEL POWER SEAT, BUTTON, LOCK BUTTON, LOCK BUTTON LED, SWITCH WINDOW LIFT, SWITCH DOOR, SWITCH MODULE, SWITCH STEERING WHEEL	Triphenyl-phosphate [115-86-6], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead titanium zirconium oxide [12626-81-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7], Boric acid [10043-35-3], Lead-titanium-trioxide [12060-00-3], Lead [7439-92-1]

Electric Power Supply / Instruments - [communication, mobile telephone]	CONTROL UNIT, BATTERY, WIRELESS CHARGE SYSTEM	Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Engine - [fuel / EVAP system]	FUEL PUMP MODULE, PUMP MODULE, JET PUMP AND LEVEL SENSOR, FILTER, ISOLATION VALVE, FILLER PIPE, PEM, HOSE, CANISTER, EVAP-LINE ASSY, FUEL TANK, TANK WELDED, PURGE VALVE, PURGE VALVE ASSY, FUEL PRESSURE SENSOR, FUEL DISTRIBUTION PIPE, HIGH PRESSURE PUMP, INJECTOR, FUEL PUMP	Melamine [108-78-1], Lead-monoxide [1317-36-8], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], TBBA [79-94-7], Cobalt-dinitrate [10141-05-6], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], C,C'-azodi(formamide) [123-77-3], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [airbag]	SIDE AIR BAG, AIRBAG MODULE, CONTROL UNIT, ACCELEROMETER SENSOR, PRESSURE SENSOR	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7], Lead-monoxide [1317-36-8], Lead [7439-92-1]
Electric Power Supply / Instruments - [cleaner]	WIPER UNIT, WASHER FLUID RESERVOIR, LEVEL SENSOR, HEADLAMP WIPER, PUMP, DUAL PUMP, REAR WIPER, WIPER ARM	O,O,O-Triphenyl phosphorothioate [597-82-0], Lead-monoxide [1317-36-8], TBBA [79-94-7], Triphenyl-phosphate [115-86-6], C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1]
Power Transmission - [electrical axis drive]	INLET PIPE, OUTLET PIPE, O-RING, SEAL CAP, REAR AXLE, CABLE HARNESS	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Triphenyl-phosphate [115-86-6], O,O,O-Triphenyl phosphorothioate [597-82-0], Sodium borate, pentahydrate [12179-04-3], Tris(nonylphenyl)phosphite [26523-78-4], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [floor / frame section / wheel housing / firewall]	FRONT SIDE MEMBER, WHEEL HOUSING, WELD SEALANT CURING, ADHESIVE, FLOOR PANEL, BUMPER BEAM, TOP COVER, REINFORCEMENT, SIDE MEMBER UPPER INNER, BRACE INNER, BRACE OUTER, BATTERY TRAY, CRASH BOX	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Body, Interior / Exterior - [recovery / towing unit]	TOWING HOOK, HARNESS	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]

Electric Power Supply / Instruments - [lighting]	READING LAMP, OVERHEAD CONSOLE LENS, CONTROL UNIT HCM, HEADLAMP, LIGHTING, LIGHTNING INSTRUMENT PANEL, LAMP LED, LED MODULE, REAR LAMP, STOP LAMP, FOG LIGHT	Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Dicyclohexyl-phthalate [84-61-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Bumetizole [3896-11-5], Octamethylcyclotetrasiloxane [556-67-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1], Lead-titanium-trioxide [12060-00-3], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 1-Methyl-2-pyrrolidone [872-50-4], Lead [7439-92-1]
Electric Power Supply / Instruments - [electric drive system]	VOLTAGE CONVERTER, INVERTER IEM, INVERTER IGM, ONBOARD CHARGER, STARTER MOTOR ALTERNATOR, PROTECTION HIGH VOLTAGE, BRACKET, SEALING, STARTER MOTOR, COOLANT PIPE, SENSOR	Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], 2-Methylimidazole [693-98-1], 4,4'-Isopropylidenediphenol [80-05-7], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Alkanes, C14-17, chloro [85535-85-9], Triphenyl-phosphate [115-86-6], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Lead [7439-92-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], N,N-Dimethylacetamide [127-19-5]
Brake - [wheel brake]	BRAKE CALIPER, HOUSING, EPB, AIR VENTING NIPPLE, BLEEDER VALVE	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], O,O,O-Triphenyl phosphorothioate [597-82-0], 2-Methylimidazole [693-98-1], Diboron-trioxide [1303-86-2], Tris(nonylphenyl)phosphite [26523-78-4], Hexahydromethylphthalic-anhydride [25550-51-0], Lead [7439-92-1]
Electric Power Supply / Instruments - [infotainment system]	GRAPHIC HEAD UP DISPLAY, PRINTED CIRCUIT BOARD, DISPLAY, USB HUB	1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) [29420-49-3], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], Triphenyl-phosphate [115-86-6], Boric acid [10043-35-3], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 4,4'-Isopropylidenediphenol [80-05-7], Melamine [108-78-1], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1]

Body, Interior / Exterior - [roof]	GLASS PANEL, WELD SEALANT CURING, PANORAMA ROOF, ADHESIVE ROOF HATCH, MOTOR, FRAME	Tris(nonylphenyl)phosphite [26523-78-4], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Triphenyl-phosphate [115-86-6], C,C'-azodi(formamide) [123-77-3], Lead-monoxide [1317-36-8], Phosphorothioic acid, O,O,O-triphenyl esters, tert-Bu derivs. [192268-65-8], Lead [7439-92-1]
Electric Power Supply / Instruments - [vehicle computational units / gateway modules]	CONTROL UNIT	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [glass, window / windscreen / roof]	WINDSCREEN, GLASS HARDENED, GLASS LAMINATED, REAR SCREEN, QUARTER GLASS HARDENED, QUARTER GLASS LAMINATED	Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [seat belt / other restraining systems]	BELT CATCH, SEAT BELT, BELT, HEIGHT ADJUSTMENT, BELT CATCH REAR	TBBA [79-94-7], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt sulphate [10124-43-3], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead-monoxide [1317-36-8], Melamine [108-78-1], Cobalt-dinitrate [10141-05-6], Triphenyl-phosphate [115-86-6], Decamethyltetrasiloxane [141-62-8], Lead [7439-92-1]
Engine - [inlet / exhaust systems]	EXHAUST SYSTEM, THROTTLE, HEAT SHIELD PLATE, INTAKE MANIFOLD	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1], Boric acid [10043-35-3]
Power Transmission - [gearbox]	CONTROL UNIT, CABLE HARNESS, CONNECTOR, AUTOMATIC GEARBOX, FLANGE NUT, FLANGE SCREW, TORQUE CONVERTER, VALVE BODY, SERVO COVER, CONTROL SYSTEM, OIL PUMP, ADAPTER, DIFFERENTIAL SPACER, LID	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], Lead-monoxide [1317-36-8], Nonylphenol [25154-52-3], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], 4,4'-Isopropylidenediphenol [80-05-7], 1-Methyl-2-pyrrolidone [872-50-4], Cobalt-dinitrate [10141-05-6], Cobalt-dichloride [7646-79-9], Lead-titanium-trioxide [12060-00-3], Silicic acid, lead salt [11120-22-2], Lead [7439-92-1]
Power Transmission - [gear lever carrier / gear selector controls]	GEAR LEVER CARRIER, ACTUATOR	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead [7439-92-1]

Power Transmission - [actuator, gear shift]	CONTROL UNIT	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], Silicic acid, lead salt [11120-22-2], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Brake - [brake line with connections]	BRAKE PIPE, BRAKE PIPE FRONT, RETAINER	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bumetrizole [3896-11-5], Lead [7439-92-1]
Electric Power Supply / Instruments - [protection]	CONTROL UNIT, SENSOR FRONT, SENSOR REAR, ACCELEROMETER, ACCELEROMETER FRONT	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Lead [7439-92-1]
Engine - [emission equipment]	LAMBDA SOND, PRESSURE SENSOR, VALVE, COOLER, ALUMINIUM, STAY	Diboron-trioxide [1303-86-2], TBBA [79-94-7], Lead-monoxide [1317-36-8], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1]
Brake - [brake, anti lock (anti-skid)]	HYDRAULIC UNIT, SENSOR	Lead titanium zirconium oxide [12626-81-2], Boric acid [10043-35-3], O,O,O-Triphenyl phosphorothioate [597-82-0], Cobalt(II) nitrate hexahydrate [10026-22-9], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Lead [7439-92-1]
Electric Power Supply / Instruments - [electrical distribution box / fuse box]	CEM, ATTACHMENT	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Engine - [fan]	FAN, FAN LOW	Boric acid [10043-35-3], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead [7439-92-1]
Engine - [engine / engine mounting]	ENGINE, ENGINE MOUNT, TORQUE ROD, TORQUE LINK BRACKET, ENGINE BRACKET	Bis(4-chlorophenyl) sulfon [80-07-9], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Lead titanium zirconium oxide [12626-81-2], Lead [7439-92-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]

Body, Interior / Exterior - [body side]	WELD SEALANT CURING	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Electric Power Supply / Instruments - [cable system high voltage]	CABLE HARNESS, CABLE CHARGE POINT HV, BRACKET, CHARGE CABLE CORD, STRAIN RELIEF, CABLE DUCT, CABLE CHANNEL	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 4,4'-Sulfonyldiphenol [80-09-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Octamethylcyclotetrasiloxane [556-67-2], Lead [7439-92-1]
Electric Power Supply / Instruments - [horn]	HORN	Lead-monoxide [1317-36-8], Lead [7439-92-1]
Body, Interior / Exterior - [instruction / information plates]	SIX POINT SOCKET SCREW	1-Methyl-2-pyrrolidone [872-50-4]
Body, Interior / Exterior - [instrument / radio panel]	GLOVE BOX, CONCEALING PANEL, LAMP LED, STORAGE BOX, HINGE PIN	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], 2-Methyl-1-(4- methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead [7439-92-1]
Body, Interior / Exterior - [front fender]	FRONT FENDER, ANTIFLUTTER, SHIM	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [anti-roll bar]	LINK FRONT ANTI-ROLL BAR, LINK ANTI-ROLL BAR, ANTI-ROLL BAR FRONT, ANTI-ROLL BAR REAR	Imidazolidine-2-thione [96-45-7], 2-Methylimidazole [693-98-1]
Body, Interior / Exterior - [miscellaneous]	TRANSPORT PROTECTION, SEALANT REPAIR, ABSORBER	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Dibutylbis(pentane-2,4-dionato- O,O')tin [22673-19-4], Triphenyl-phosphate [115-86-6]
Body, Interior / Exterior - [hood cover]	ANTIFLUTTER, FOAM, HOOD	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], C,C'-azodi(formamide) [123-77-3], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Body, Interior / Exterior - [tank hatch]	ACTUATOR, PLASTIC MODULE	TBBA [79-94-7], Triphenyl-phosphate [115-86-6], Lead [7439-92-1]

Body, Interior / Exterior - [protective shields / flaps]	CLIP	Bumetrizole [3896-11-5]
Electric Power Supply / Instruments - [antenna]	ANTENNA AMPLIFIER, ANTENNA	TBBA [79-94-7], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead titanium zirconium oxide [12626-81-2], 1-Propanol, 2,3-dibromo- [96-13-9], Melamine [108-78-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Lead [7439-92-1]
Power Transmission - [final drive]	SEALING, PT-UNIT, BRACKET	Triphenyl-phosphate [115-86-6], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead [7439-92-1]
Brake - [master cylinder / brake booster]	LID	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Body, Interior / Exterior - [bonnet / cover with assembly parts]	FOAM, HOOD RELEASE CABLE, HOOD LOCK, COVER, HOOD LOCK CONTROL	C,C'-azodi(formamide) [123-77-3], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Imidazolidine-2-thione [96-45-7], Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [spring, leaf spring]	VALVE BLOCK, AIR SPRING REAR, COMPRESSOR, RESEVOIR, HOSE COUPLING	Decamethylcyclopentasiloxane [541-02-6], O,O,O-Triphenyl phosphorothioate [597-82-0], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Triphenyl-phosphate [115-86-6], Tris(nonylphenyl)phosphite [26523-78-4], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Engine - [intercooler / connection]	CHARGE AIR HOSE, CHARGE AIR PIPE, RESONATOR, CHARGE AIR COOLER	Boric acid [10043-35-3], Lead [7439-92-1]
Body, Interior / Exterior - [exterior equipment]	ACTIVE GRILLE SHUTTER, ACTIVE SPOILER SHUTTER	Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [tool / jack]	JACK	Ethylenediamine [107-15-3]

Body, Interior / Exterior - [trunk lid / tailgate complete]	SPINDLE DRIVE, REAR DOOR	TBBA [79-94-7], Triphenyl-phosphate [115-86-6], Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8], Lead [7439-92-1]
Engine - [accelerator control]	ACCELERATOR PEDAL	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [rim]	TYRE 245/40R20 99W XL, VALVE, KEY, WHEEL BOLT	Triphenyl-phosphate [115-86-6], Lead [7439-92-1]
Engine - [air cleaner]	BELLOWS, FRESH AIR PIPE, BOX	Bumetrizole [3896-11-5], Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [shock absorber]	SHOCK ABSORBER FRONT, SHOCK ABSORBER REAR, SHOCK ABSORBER	Lead [7439-92-1]
Brake - [brake control]	PEDAL UNIT, SENSOR	Lead [7439-92-1]
Engine - [miscellaneous / help device installation]	BRACKET, TENSIONER, SPLASH PROTECTION	Lead [7439-92-1]
Engine - [cold zone / batterybox]	NVH PANEL	Lead [7439-92-1]
Engine - [ignition / spark plug]	IGNITION COIL, SPARK PLUG, GLOW PLUG	Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Engine - [lubricating and oil system]	GASKET, OIL PUMP, OIL LEVEL SENSOR, OIL FILTER, OIL PRESSURE SENSOR, OIL SUMP, SUCTION LINE, PISTON COOLING JET, VALVE, INLET PIPE, PISTON COOLING VALVE, WINDAGE TRAY, PLUG	Bis(4-chlorophenyl) sulfon [80-07-9], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Diboron-trioxide [1303-86-2], Lead [7439-92-1]

Engine - [transmission]	GASKET, VVT-UNIT, TENSIONER, IDLER PULLEY, CAMSHAFT, SOLENOID, BALANCE SHAFT, BELT PROTECTOR, HOUSING, BELT COVER, VVT ACTUATOR, SLEEVE	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]
Engine - [supercharging]	TURBO CHARGER, O-RING, VACUUM RESERVOIR, VACUUM REGULATOR, BRACKET	N,N-Dimethylacetamide [127-19-5], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Lead [7439-92-1]
Engine - [distributor]	KNOCK SENSOR, CAMSHAFT POSITION SENSOR	Lead titanium zirconium oxide [12626-81-2], Lead-monoxide [1317-36-8], Lead [7439-92-1]
Engine - [cylinder block / head]	BEDPLATE, ENGINE BRACKET, VACUUM PUMP, CYLINDER BLOCK, TOP COVER, GUIDE SLEEVE, BEARING HOUSE CAM SHAFT, CYLINDER HEAD, CAP, CAM SHAFT COVER, CAMSHAFT CAP, HOUSING, LOCATING PIN	Lead [7439-92-1]
Engine - [crank mechanism]	DUAL MASS FLYWHEEL, NIPPLE, NON-RETURN VALVE	Lead [7439-92-1]