

XC40 MODEL YEAR 2026
Candidate List Substances Table

Released: 2025 week 35.

We hereby inform that almost all product areas contain lead (CAS No 7439-92-1), primarily as alloying elements in steel, aluminium and copper.

Localisation	Partnames	Substance/s
Electric Power Supply / Instruments - [cable system]	CABLE FLOOR, CABLE HARNESS, CABLE, CABLE IP, CABLE HARNESS BUMPER, CABLE HARNESS TAILGATE, ADAPTER CABLE, BRACKET, FUSE BOX HOUSING, BRACKET CJB	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Triphenyl-phosphate [115-86-6], Bumetrizole [3896-11-5], Lead [7439-92-1]
Wheel Suspension / Steering - [axle member / link arm / suspension]	HUB, TRIPLESQUARE SOCKET SCREW, WHEEL HUB, BUSHING, SUBFRAME, SUBFRAME REAR	O,O,O-Triphenyl phosphorothioate [597-82-0], Diboron-trioxide [1303-86-2], Triphenyl-phosphate [115-86-6], Lead [7439-92-1]
Wheel Suspension / Steering - [front suspension]	HUB, TRIPLESQUARE SOCKET SCREW, WHEEL HUB	O,O,O-Triphenyl phosphorothioate [597-82-0], Diboron-trioxide [1303-86-2], Triphenyl-phosphate [115-86-6]
Electric Power Supply / Instruments - [support systems]	SENSOR, CONTROL UNIT, CAMERA, RADAR, EXT743, EXT747, EXT746, EXT744, EXT745, EXT748	Lead-monoxide [1317-36-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Dodecamethylcyclohexasiloxane [540-97-6], Diboron-trioxide [1303-86-2], 2-Methylimidazole [693-98-1], Dicyclohexyl-phthalate [84-61-7], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Lead-titanium-trioxide [12060-00-3], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], TBBA [79-94-7], Lead titanium zirconium oxide [12626-81-2], Lead [7439-92-1]
Electric Power Supply / Instruments - [radio equipment]	MICROPHONE, AUDIO MODULE, SOUND MODULE, TWEETER, SUBWOOFER, WOOFER	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Triphenyl-phosphate [115-86-6], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Cobalt(II) nitrate hexahydrate [10026-22-9], Imidazolidine-2-thione [96-45-7], Lead [7439-92-1]
Body, Interior / Exterior - [upholstery]	DOOR PANEL, HEADLINING, BRACKET SUPPORT, CLIP HOUSING, SILL MOULDING, BELT GUIDE, CHARCOAL, SHIM	Triphenyl-phosphate [115-86-6], C,C'-azodi(formamide) [123-77-3], Diboron-trioxide [1303-86-2], Bumetrizole [3896-11-5], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead [7439-92-1]

Body, Interior / Exterior - [side door]	CARRIER, SEALING, BELT MOULDING	O,O,O-Triphenyl phosphorothioate [597-82-0], Imidazolidine-2-thione [96-45-7], Bumetrizole [3896-11-5], Lead [7439-92-1]
Body, Interior / Exterior - [lock / handle]	OUTER HANDLE, EXT743, LOCK, EXT745, EXT746, EXT744, WIRE, DOOR LOCK, LOCK CYLINDER SET, KEY	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Diboron-trioxide [1303-86-2], Triphenyl-phosphate [115-86-6], Melamine [108-78-1], Hexahydromethylphthalic-anhydride [25550-51-0], Bumetrizole [3896-11-5], Lead [7439-92-1]
Body, Interior / Exterior - [seats]	HEAD RESTRAINT, UPHOLSTERY, ARM REST, FOG, LUMBAR SUPPORT, REAR SEAT, FRONT SEAT, FRONT SEAT CUSHION EXTENS, FRONT SEAT BACKREST, GREY LH, GREY RH, UNDERCARRIAGE, SIX POINT SOCKET SCREW, HEAD RESTRAINT GREY, COVER, CHARCOAL SOLID, AMBER, HATCH, BACKREST FRAME, ENGINE, LATCH BEZEL, CHARCOAL SOLI, CABLE HARNESS, ECU, FRAMEWORK	Triphenyl-phosphate [115-86-6], C,C'-azodi(formamide) [123-77-3], Melamine [108-78-1], Hexahydromethylphthalic-anhydride [25550-51-0], Phenol, dimethyl-, phosphate (3:1) [25155-23-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 1-Methyl-2-pyrrolidone [872-50-4], Bumetrizole [3896-11-5], O,O,O-Triphenyl phosphorothioate [597-82-0], Sodium borate, decahydrate [1303-96-4], Acrylamide [79-06-1], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], N,N-Dimethylacetamide [127-19-5], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1]
Body, Interior / Exterior - [air conditioning]	AIR INLET, CHILLER BRACKET, FUEL OPERATED HEATER, IONIZER, SUN SENSOR, PRESSURE HOSE, SUCTION HOSE, LIQUID HOSE, CONDENSER, WATER CONDENSER, PIPE ASSEMBLY, CHILLER, CLIMATE UNIT, BLOCK WATER CONDENSER, ELECTRICAL HEATER, EL COMPRESSOR, PRESSURE SENSOR, BLOCK, HUMIDITY SENSOR, AC-COMPRESSOR, FILTER INSERT, CONTROL UNIT FAN, SOLENOID CLUTCH, RUBBER BUSHING, SENSOR PRESSURE TEMP, MAIN BRACKET, BLOCK BRACKET, HARNESS, KIT RETAINER HOSE, SENSOR, PROTECTIVE CAP, SENSOR EVAPORATOR, SENSOR HEX, SENSOR AQS, TXV, VALVE, SHUT-OFF VALVE, CONTROL VALVE, FUEL PUMP, CHANNEL SENSOR, FAN HOUSING	Lead-monoxide [1317-36-8], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Bumetrizole [3896-11-5], Lead titanium zirconium oxide [12626-81-2], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Decamethylcyclotetrasiloxane [541-02-6], Melamine [108-78-1], Diboron-trioxide [1303-86-2], Octamethylcyclotetrasiloxane [556-67-2], Dodecamethylcyclotetrasiloxane [540-97-6], C,C'-azodi(formamide) [123-77-3], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7], Cobalt(II) nitrate hexahydrate [10026-22-9], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Body, Interior / Exterior - [instrument / radio panel]	DECOR DIAMOND CUT, DECOR WOOD, LIGHTNING INSTRUMENT PANEL, PANEL NOZZLE, FRAME, DECOR SPINNAKER, LED MODULE, DIM COOLING, INSTRUMENT PANEL, HINGE PIN, GLOVE BOX	TBBA [79-94-7], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Tris(nonylphenyl)phosphite [26523-78-4], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1]

Engine - [inlet / exhaust systems]	EXHAUST SYSTEM, ACTUATOR, THROTTLE, HEAT SHIELD PLATE, INTAKE MANIFOLD	Lead-monoxide [1317-36-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1], Boric acid [10043-35-3], Diboron-trioxide [1303-86-2]
Electric Power Supply / Instruments - [vehicle control system]	ECU, CONTROL UNIT DOOR, ECU MODULE SEAT HEATING, SWITCH DOOR, CONTROL PANEL 12W, SWITCH, SWITCH PANEL, CUT-OFF SWITCH, USB POWER OUTLET, STALK MODULE, COMBI INSTRUMENT, HARDWARE, SWITCH WINDOW LIFT, LOCK BUTTON, BUTTON, SWITCH CRUISE CONTROL	Lead titanium zirconium oxide [12626-81-2], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], TBBA [79-94-7], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7], Triphenyl-phosphate [115-86-6], Boric acid [10043-35-3], Lead-titanium-trioxide [12060-00-3], Lead [7439-92-1]
Engine - [control systems]	AIR TEMP SENSOR, CONTROL UNIT, MASS AIR FLOW SENSOR, PRESSURE SENSOR	Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Silicic acid, lead salt [11120-22-2], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Brake - [brake control]	BRAKE LIGHT SWITCH	Triphenyl-phosphate [115-86-6], Lead [7439-92-1]
Engine - [cooling system]	FAN, HOSE MODULE, HOSE, COOLING MODULE, CONDENSER, PUMP, 4WAY VALVE, ELECTRIC WATER PUMP, WATER PUMP, HOSE RADIATOR QC, VALVE, THREE-WAY VALVE, COOLER, EXPANSION TANK, SET, PLUG, TWO-WAY VALVE, PIPE, HOSE OUTLET, RETURN PIPE, TEMPERATURE SENSOR, BRACKET, CLAMP BRACKET, GASKET, O-RING, SIX POINT SOCKET SCREW, FLANGE SCREW, STRIKER PLATE, THERMOSTAT HOUSING, NIPPLE, PLASTIC PIPE	O,O,O-Triphenyl phosphorothioate [597-82-0], TBBA [79-94-7], Melamine [108-78-1], Lead titanium zirconium oxide [12626-81-2], Lead-monoxide [1317-36-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Diboron-trioxide [1303-86-2], Silicic acid, lead salt [11120-22-2], 1-Methyl-2-pyrrolidone [872-50-4], 4,4'-Isopropylidenediphenol [80-05-7], Lead [7439-92-1], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt-dichloride [7646-79-9], C,C'-azodi(formamide) [123-77-3]
Body, Interior / Exterior - [outside / exterior trim]	EMBLEM, GRILLE, ANTENNA CAP, WHITE614, BLUE467, SILV477, BLACK487, GREY492, BROWN700, BLUE706, EXT707, EXT711, EXT714, EXT717, EXT719, CKDCOLOR, KSOCOLOR, SVART19S, RED612, EXT720, TAPE, EXT722, EXT721, EXT723, EXT621, EXT724, EXT725	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], C,C'-azodi(formamide) [123-77-3], Triphenyl-phosphate [115-86-6]

Body, Interior / Exterior - [outside mirrors]	REAR VIEW MIRROR, CAMERA, REAR VIEW MIRROR OUTER, MOTOR UNIT, GLASS	Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-Methylimidazole [693-98-1], Dicyclohexyl-phthalate [84-61-7], Lead-monoxide [1317-36-8], TBBA [79-94-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Cobalt-dinitrate [10141-05-6], Lead [7439-92-1]
Power Transmission - [propeller shaft]	PROPELLER SHAFT, CROSSMEMBER	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]
Electric Power Supply / Instruments - [cable system high voltage]	CHARGE CABLE CORD, CHARGE CABLE, CABLE HARNESS, CABLE CHARGE POINT HV, CABLE HARNESS ENGINE, CABLE HARNESS HV, ADAPTER, BRACKET, STRAIN RELIEF, CABLE DUCT, CHANNEL	Octamethylcyclotetrasiloxane [556-67-2], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Melamine [108-78-1], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Lead [7439-92-1]
Body, Interior / Exterior - [trunk lid / tailgate complete]	TAILGATE, SPINDLE DRIVE, ANTIFLUTTER	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], O,O,O-Triphenyl phosphorothioate [597-82-0], Bumetrizole [3896-11-5], Melamine [108-78-1], Triphenyl-phosphate [115-86-6], Lead [7439-92-1]
Brake - [wheel brake]	BRAKE LINING, BRAKE CALIPER, HOUSING, EPB, MOTOR UNIT, DUST COVER, AIR VENTING NIPPLE, BLEEDER VALVE	Dicyclohexyl-phthalate [84-61-7], Tris(nonylphenyl)phosphite [26523-78-4], Diboron-trioxide [1303-86-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], O,O,O-Triphenyl phosphorothioate [597-82-0], 2-Methylimidazole [693-98-1], Hexahydromethylphthalic-anhydride [25550-51-0], Lead [7439-92-1]
Wheel Suspension / Steering - [steering gear / wheel / shaft / column]	SEALING FLOOR LHD, SEALING FLOOR RHD, STEERING COLUMN LOCK, STEERING COLUMN MANUAL, STEERING GEAR, COVER PLUG, CHARCOAL SO, STEERING WHEEL	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], O,O,O-Triphenyl phosphorothioate [597-82-0], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Dodecamethylcyclohexasiloxane [540-97-6], Diboron-trioxide [1303-86-2], TBBA [79-94-7], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead [7439-92-1]
Electric Power Supply / Instruments - [mobile data services]	CONTROL UNIT	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1], Lead [7439-92-1]

Power Transmission - [front axle / rear axle / drive shaft]	AOC, REAR AXLE, SEALING RING, PUMP UNIT, FINAL DRIVE, RADIAL SEAL KIT, BRACKET, BEARING ANCHORAGE	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], O,O,O-Triphenyl phosphorothioate [597-82-0], Triphenyl-phosphate [115-86-6], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Lead [7439-92-1]
Electric Power Supply / Instruments - [communication, mobile telephone]	CONTROL UNIT, BATTERY, WIRELESS CHARGE SYSTEM	Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1]
Electric Power Supply / Instruments - [lighting]	HEADLAMP, READING LAMP, OVERHEAD CONSOLE LENS, CONTROL UNIT HCM, REAR LAMP, LIGHTING, LAMP LED, LED MODULE, FOG LIGHT	Diboron-trioxide [1303-86-2], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Dicyclohexyl-phthalate [84-61-7], Lead-monoxide [1317-36-8], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], TBBA [79-94-7], Bumetrizole [3896-11-5], Octamethylcyclotetrasiloxane [556-67-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1], Lead-titanium-trioxide [12060-00-3], Lead [7439-92-1]
Body, Interior / Exterior - [interior equipment]	ARM REST, EC REAR VIEW MIRROR, DAWN, SUN VISOR, CHARCOAL SOLID, CHARCOAL, BLOND, AIR OUTLET, BRACKET, CUP HOLDER, REAR BRACKET	C,C'-azodi(formamide) [123-77-3], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Cobalt sulphate [10124-43-3], TBBA [79-94-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Tris(nonylphenyl)phosphite [26523-78-4], Lead [7439-92-1]
Power Transmission - [final drive]	PT-UNIT, SEALING, BRACKET	Triphenyl-phosphate [115-86-6], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead [7439-92-1]
Engine - [fuel / EVAP system]	FUEL PUMP, FEED LINE FUEL, FUEL LINE ASSY, LEAK DETECTION PUMP, EVAP PURGE PUMP, FILTER, PEM, BRACKET, AIR FILTER, FOAM PAD, CLIP, FUEL TANK, TANK WELDED, PURGE VALVE, PURGE LINE ASSY, FUEL PRESSURE SENSOR, FUEL DISTRIBUTION PIPE, HIGH PRESSURE PUMP, INJECTOR	Lead-monoxide [1317-36-8], Melamine [108-78-1], Bumetrizole [3896-11-5], Diboron-trioxide [1303-86-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], O,O,O-Triphenyl phosphorothioate [597-82-0], TBBA [79-94-7], Tris(nonylphenyl)phosphite [26523-78-4], C,C'-azodi(formamide) [123-77-3], Boric acid [10043-35-3], Lead [7439-92-1]

Electric Power Supply / Instruments - [cleaner]	WIPER APPARATUS, SEALING, WASHER FLUID RESERVOIR, LEVEL SENSOR, REAR WIPER, WIPER ARM, PUMP, WASHER PUMP, DUAL PUMP	Lead-monoxide [1317-36-8], O,O,O-Triphenyl phosphorothioate [597-82-0], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1]
Body, Interior / Exterior - [exterior equipment]	SPOILER, STOP LAMP, EXT743, EXT745, EXT746, GRILLE SHUTTER, ACTIVE SPOILER SHUTTER	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-ethylhexyl 10-ethyl-4,4-dioctyl-7-oxo-8-oxa-3,5-dithia-4-stannatetradecanoate [15571-58-1], 4,4'-Isopropylidenediphenol [80-05-7], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1], Lead [7439-92-1]
Electric Power Supply / Instruments - [automatic monitoring / control]	RAIN SENSOR, SIREN, SENSOR, REMOTE KEY, CONTROL UNIT, TRM	Lead-monoxide [1317-36-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead titanium zirconium oxide [12626-81-2], 1,2-Dimethoxyethane [110-71-4], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], Lead [7439-92-1]
Engine - [fan]	FAN	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], 2-Methylimidazole [693-98-1], 4,4'-Isopropylidenediphenol [80-05-7], O,O,O-Triphenyl phosphorothioate [597-82-0], 1-Methyl-2-pyrrolidone [872-50-4], Lead [7439-92-1]
Body, Interior / Exterior - [seat belt / other restraining systems]	BELT, SEAT BELT, HEIGHT ADJUSTMENT, BELT CATCH	Triphenyl-phosphate [115-86-6], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], TBBA [79-94-7], Cobalt(II) nitrate hexahydrate [10026-22-9], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead-monoxide [1317-36-8], Melamine [108-78-1], Decamethyltetrasiloxane [141-62-8], Lead [7439-92-1]
Body, Interior / Exterior - [roof]	PANORAMA ROOF, FRAME, ADHESIVE ROOF HATCH, MOTOR	O,O,O-Triphenyl phosphorothioate [597-82-0], Diboron-trioxide [1303-86-2], Phosphorothioic acid, O,O,O-triphenyl esters, tert-Bu derivs. [192268-65-8], C,C'-azodi(formamide) [123-77-3], TBBA [79-94-7], Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [rim]	ADHESIVE BALANCE WEIGHT, WHEEL 7, 5X19X50, 5, WHEEL 8, 5X19X56, VALVE, KEY, WHEEL BOLT	Diboron-trioxide [1303-86-2], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], 2-Methylimidazole [693-98-1], Lead [7439-92-1]

Electric Power Supply / Instruments - [battery and mounting parts]	HOUSING, PLUG, BUSBAR, BATTERY MODULE, CURRENT SENSOR, SERVICE LID, BARRIER RIGHT, BARRIER LEFT, 48V BATTERY, BATTERY DISCONNECT UNIT, LID, RAIL INLET, RAIL, SWITCH, CONNECTOR, TEMP SENSOR, BATTERY, BMS	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Dodecamethylcyclotetrasiloxane [540-97-6], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Triphenyl-phosphate [115-86-6], Lead-monoxide [1317-36-8], 1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4], 1-Propanol, 2,3-dibromo- [96-13-9], Lead-titanium-trioxide [12060-00-3], Alkanes, C14-17, chloro [85535-85-9], Lead [7439-92-1]
Electric Power Supply / Instruments - [electric drive system]	VOLTAGE CONVERTER, FUSE, ONBOARD CHARGER, STARTER MOTOR ALTERNATOR, INVERTER TRANSDUCER, BRACKET, SEALING, STARTER MOTOR, COOLANT PIPE, SENSOR	Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], 2-Methylimidazole [693-98-1], Melamine [108-78-1], N,N-Dimethylacetamide [127-19-5], 1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Terphenyl, hydrogenated [61788-32-7], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Triphenyl-phosphate [115-86-6], Lead [7439-92-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Electric Power Supply / Instruments - [antenna]	ANTENNA AMPLIFIER, ETC MODULE, BLUETOOTH ANTENNA, WAVE TRAP, GROUND SIDE COIL, ETC ON BOARD UNIT, ANTENNA	Lead-monoxide [1317-36-8], Melamine [108-78-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2], TBBA [79-94-7], 4,4'-Isopropylidenediphenol [80-05-7], Hexahydromethylphthalic-anhydride [25550-51-0], Lead titanium zirconium oxide [12626-81-2], 1-Propanol, 2,3-dibromo- [96-13-9], Lead [7439-92-1]
Electric Power Supply / Instruments - [vehicle computational units / gateway modules]	CONTROL UNIT	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1]

Power Transmission - [electrical axis drive]	O-RING, SEALING, SEALING RING, DRIVE SHAFT SEAL, INVERTER, GASKET, DRIVE SHAFT, ELECTRIC MOTOR, REAR AXLE, FRONT AXLE, FLANGE SCREW, INNER HOUSING, OUTER HOUSING, BRACKET, TRANSMISSION HOUSE	Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Triphenyl-phosphate [115-86-6], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead-monoxide [1317-36-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], Sodium borate, pentahydrate [12179-04-3], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], N,N-Dimethylacetamide [127-19-5], Melamine [108-78-1], Cobalt-dichloride [7646-79-9], Lead [7439-92-1]
Body, Interior / Exterior - [glass, window / windscreen / roof]	WINDSCREEN, QUARTER GLASS DOOR HARDENED, REAR SCREEN, GLASS HARDENED	C,C'-azodi(formamide) [123-77-3], Bumetrizole [3896-11-5], Diboron-trioxide [1303-86-2], 1-Methyl-2-pyrrolidone [872-50-4], Lead [7439-92-1]
Power Transmission - [gearbox]	CONTROL UNIT, CABLE HARNESS, CONNECTOR, AUTOMATIC GEARBOX, OIL PUMP, GEARBOX, AIR VENT PIPE, TEMPERATURE SENSOR, SPACER, VALVE BODY	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], Lead-monoxide [1317-36-8], Nonylphenol [25154-52-3], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], 4,4'-Isopropylidenediphenol [80-05-7], 1-Methyl-2-pyrrolidone [872-50-4], O,O,O-Triphenyl phosphorothioate [597-82-0], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Dioctyltin dilaurate [3648-18-8], Lead [7439-92-1]
Body, Interior / Exterior - [airbag]	CONTROL UNIT, AIRBAG MODULE, ACCELEROMETER SENSOR, AIRBAG	Lead-monoxide [1317-36-8], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Refractory ceramic fibres [142844-00-6], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]
Body, Interior / Exterior - [hood cover]	HOOD, ANTIFLUTTER	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Power Transmission - [gear lever carrier / gear selector controls]	GEAR LEVER CARRIER	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead [7439-92-1]
Brake - [brake line with connections]	BRAKE PIPE, BRAKE PIPE FRONT, BRAKE PIPE REAR, BRAKE PIPE ENGINE COMPART, RETAINER, CLIP, BRAKE HOSE REAR	Bumetrizole [3896-11-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]

Electric Power Supply / Instruments - [infotainment system]	PRINTED CIRCUIT BOARD, DISPLAY, USB HUB	Lead-monoxide [1317-36-8], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 4,4'-Isopropylidenediphenol [80-05-7], Diboron-trioxide [1303-86-2], Melamine [108-78-1], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Boric acid [10043-35-3], Triphenyl-phosphate [115-86-6], Lead [7439-92-1]
Engine - [engine / engine mounting]	ENGINE, BRACKET ENGINE MOUNT, BRACKET, TORQUE ROD, TORQUE ROD LOWER, ENGINE MOUNT, GEARBOX ATTACHMENT, TORQUE LINK BRACKET	Bis(4-chlorophenyl) sulfon [80-07-9], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Lead titanium zirconium oxide [12626-81-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1], TBBA [79-94-7], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9]
Electric Power Supply / Instruments - [electric drive system, high voltage]	BATTERY CONTROL UNIT, CELL VOLTAGE TEMP NODE	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Dodecamethylcyclohexasiloxane [540-97-6], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Lead-monoxide [1317-36-8], Melamine [108-78-1], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Engine - [emission equipment]	LAMBDA SOND, ALUMINIUM, STAY	Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Brake - [brake, anti lock (anti-skid)]	HYDRAULIC UNIT MKC1, SENSOR	Lead titanium zirconium oxide [12626-81-2], Boric acid [10043-35-3], O,O,O-Triphenyl phosphorothioate [597-82-0], Cobalt(II) nitrate hexahydrate [10026-22-9], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Lead [7439-92-1]
Electric Power Supply / Instruments - [electrical distribution box / fuse box]	CEM	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [tool / jack]	JACK, COMPRESSOR, BOTTLE	Ethylenediamine [107-15-3], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]
Body, Interior / Exterior - [floor / frame section / wheel housing / firewall]	WELD SEALANT CURING, ADHESIVE, WELD NUT, CARRIER	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Boric acid [10043-35-3], Lead [7439-92-1]

Electric Power Supply / Instruments - [horn]	HORN	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [bonnet / cover with assembly parts]	HOOD LOCK, COVER	4-Nonylphenol, branched [84852-15-3], Lead [7439-92-1]
Body, Interior / Exterior - [climate unit]	CONTROL UNIT	Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Electric Power Supply / Instruments - [protection]	LEVEL SENSOR FRONT, LEVEL SENSOR REAR, SENSOR	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead-monoxide [1317-36-8], Lead [7439-92-1]
Body, Interior / Exterior - [miscellaneous]	TRANSPORT PROTECTION, SEALANT REPAIR	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Dibutylbis(pentane-2,4-dionato-O,O')tin [22673-19-4]
Electric Power Supply / Instruments - [cable components]	BRACKET, DISCONNECTOR POWER, DIODE, FUSE BOX, BOTTOM PART, CHANNEL, FUSE BOX HOUSING, FRAME ASSY, STRAIN RELIEF, CABLE DUCT, RECEPTACLE HOUSING, ADAPTER PLATE	TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Brake - [master cylinder / brake booster]	LID	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Frame / Springs / Damping / Wheels - [anti-roll bar]	LINK ANTI-ROLL BAR	Imidazolidine-2-thione [96-45-7]
Body, Interior / Exterior - [protective shields / flaps]	ENGINE UNDERSHIELD	Triphenyl-phosphate [115-86-6]
Body, Interior / Exterior - [instruction / information plates]	NUMBER PLATE HOLDER	Lead [7439-92-1]

Body, Interior / Exterior - [recovery / towing unit]	TOWING HOOK, HARNESS	Lead [7439-92-1]
Engine - [intercooler / connection]	CHARGE AIR PIPE	Lead [7439-92-1]
Engine - [miscellaneous / help device installation]	BRACKET, TENSIONER, SPLASH PROTECTION	Lead [7439-92-1]
Body, Interior / Exterior - [tank hatch]	PLASTIC MODULE	Lead [7439-92-1]
Engine - [ignition / spark plug]	IGNITION COIL, SPARK PLUG, GLOW PLUG	Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Engine - [lubricating and oil system]	GASKET, OIL PUMP, OIL LEVEL SENSOR, OIL FILTER, OIL PRESSURE SENSOR, OIL SUMP, SUCTION LINE, PISTON COOLING JET, VALVE, INLET PIPE, PISTON COOLING VALVE, WINDAGE TRAY, PLUG	Bis(4-chlorophenyl) sulfon [80-07-9], TBBA [79-94-7], Lead-titanium-trioxide [12060-00- 3], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Engine - [transmission]	GASKET, VVT-UNIT, TENSIONER, IDLER PULLEY, CAMSHAFT, SOLENOID, BALANCE SHAFT, BELT PROTECTOR, HOUSING, BELT COVER, VVT ACTUATOR, SLEEVE	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]
Engine - [supercharging]	TURBO CHARGER, O-RING, VACUUM RESERVOIR, VACUUM REGULATOR, BRACKET	N,N-Dimethylacetamide [127-19-5], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Lead [7439-92-1]
Engine - [distributor]	KNOCK SENSOR, CAMSHAFT POSITION SENSOR	Lead titanium zirconium oxide [12626-81-2], Lead-monoxide [1317-36-8], Lead [7439-92- 1]
Engine - [cylinder block / head]	BEDPLATE, ENGINE BRACKET, VACUUM PUMP, CYLINDER BLOCK, TOP COVER, GUIDE SLEEVE, BEARING HOUSE CAM SHAFT, CYLINDER HEAD, CAP, CAM SHAFT COVER, CAMSHAFT CAP, HOUSING, LOCATING PIN	Lead [7439-92-1]
Engine - [crank mechanism]	DUAL MASS FLYWHEEL, NIPPLE, NON-RETURN VALVE	Lead [7439-92-1]