

XC60 MODEL YEAR 2026
Candidate List Substances Table

We hereby inform that almost all product areas contain lead (CAS No 7439-92-1), primarily as alloying elements in steel, aluminium and copper.

Released: 2025 week 35.

Localisation	Partnames	Substance/s
Wheel Suspension / Steering - [axle member / link arm / suspension]	HUB, LOWER LINK ARM, SUBFRAME FRONT, UPPER LINK ARM, TRIPLESQUARE SOCKET SCREW, CONTROL ARM	O,O,O-Triphenyl phosphorothioate [597-82-0], Imidazolidine-2-thione [96-45-7], Cobalt-dichloride [7646-79-9], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Wheel Suspension / Steering - [front suspension]	HUB, TRIPLESQUARE SOCKET SCREW	O,O,O-Triphenyl phosphorothioate [597-82-0], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [front fender]	SENSOR, EXT743, EXT747, EXT746, EXT745, EXT744, EXT748, ANTIFLUTTER, FRONT FENDER, SHIM	Lead-monoxide [1317-36-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Electric Power Supply / Instruments - [support systems]	SENSOR, CONTROL UNIT, CAMERA, RADAR, EXT743, EXT747, EXT746, EXT744, EXT745, EXT748, BOX	Lead-monoxide [1317-36-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Dodecamethylcyclotetrasiloxane [540-97-6], Diboron-trioxide [1303-86-2], 2-Methylimidazole [693-98-1], Dicyclohexyl-phthalate [84-61-7], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Lead-titanium-trioxide [12060-00-3], Lead titanium zirconium oxide [12626-81-2], TBBA [79-94-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Lead [7439-92-1]
Electric Power Supply / Instruments - [radio equipment]	MICROPHONE, LOUDSPEAKER, SPEAKER MIDRANGE, AUDIO MODULE, SOUND MODULE, WOOFER, SUBWOOFER, TWEETER, CENTRE LOUDSPEAKER, BRACKET	Diboron-trioxide [1303-86-2], N,N-Dimethylacetamide [127-19-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], Melamine [108-78-1], TBBA [79-94-7], Triphenyl-phosphate [115-86-6], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Cobalt(II) nitrate hexahydrate [10026-22-9], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead [7439-92-1]

Body, Interior / Exterior - [seats]	FRAMEWORK, HEAD RESTRAINT, UPHOLSTERY, HARDBACK, UNDERCARRIAGE, ENGINE, HEATING PAD SEAT, LUMBAR SUPPORT, LOCK, CHARCOAL SOLID, STS SENSOR, BACKREST FRAME, LUMBAR SUPPORT 4-WAY, HEATER, MASSAGE PUMP, SIX POINT SOCKET SCREW, GRAPHITE, GRAPHITE BLUE, CARDAMOM, GRAPH BLUE, SIDE BOLSTER, ARM REST, TEXTILE, WHITE, VINYL, VENTILATION, FAN, COVER, AMBER, COULISSE, HATCH, CHARCOAL/BLOND, SLATE, BLOND, ENGINE TILT, CABLE HARNESS, HARNESS	Paraffin oils, chloro [85422-92-0], Triphenyl-phosphate [115-86-6], C,C'-azodi(formamide) [123-77-3], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], N,N-Dimethylacetamide [127-19-5], Glutaral [111-30-8], Diboron-trioxide [1303-86-2], O,O,O-Triphenyl phosphorothioate [597-82-0], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], TBBA [79-94-7], Melamine [108-78-1], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Imidazolidine-2-thione [96-45-7], 1-Methyl-2-pyrrolidone [872-50-4], Bumetrizole [3896-11-5], Boric acid [10043-35-3], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3], Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [shock absorber]	SHOCK ABSORBER, SHOCK ABSORBER FRONT, SHOCK ABSORBER REAR, TOPMOUNT	Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Power Transmission - [front axle / rear axle / drive shaft]	AOC, SEALING RING, REAR AXLE, PUMP UNIT, FINAL DRIVE, RADIAL SEAL KIT, DRIVE SHAFT, BRACKET, VIBRATION DAMPER, BEARING ANCHORAGE	Triphenyl-phosphate [115-86-6], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], O,O,O-Triphenyl phosphorothioate [597-82-0], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Brake - [wheel brake]	BRAKE CALIPER, HOUSING, EPB, BRAKE LINING, AIR VENTING NIPPLE, BLEEDER VALVE	Decamethylcyclopentasiloxane [541-02-6], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], O,O,O-Triphenyl phosphorothioate [597-82-0], 2-Methylimidazole [693-98-1], Diboron-trioxide [1303-86-2], Tris(nonylphenyl)phosphite [26523-78-4], Hexahydromethylphthalic-anhydride [25550-51-0], Dicyclohexyl-phthalate [84-61-7], Lead [7439-92-1]
Body, Interior / Exterior - [interior equipment]	JALUSIE, ARM REST, CUP HOLDER, EC REAR VIEW MIRROR, WHITE DRIFTWOOD, CARDAMOM, RUBBER MAT, NATURAL DRIFTWOOD, HINGE, SUN VISOR, CHARCOAL SOLID, CHARCOAL, BLOND, LIGHTING, LED MODULE, DAMPER	C,C'-azodi(formamide) [123-77-3], TBBA [79-94-7], Tris(nonylphenyl)phosphite [26523-78-4], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Cobalt sulphate [10124-43-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Bumetrizole [3896-11-5], 4,4'-Isopropylidenediphenol [80-05-7], Lead [7439-92-1]
Engine - [control systems]	AIR TEMP SENSOR, CONTROL UNIT, MASS AIR FLOW SENSOR, TEMP AND PRESSURE SENSOR, PRESSURE SENSOR	Lead-monoxide [1317-36-8], Silicic acid, lead salt [11120-22-2], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3], Lead [7439-92-1]

Electric Power Supply / Instruments - [lighting]	REAR LAMP, READING LAMP, HEADLAMP, OVERHEAD CONSOLE LENS, CONTROL UNIT HCM, FOG LIGHT, LIGHTING, STOP LAMP, LAMP LED, LED MODULE	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Melamine [108-78-1], Dicyclohexyl-phthalate [84-61-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], TBBA [79-94-7], Bumetrizole [3896-11-5], Octamethylcyclotetrasiloxane [556-67-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Lead-titanium-trioxide [12060-00-3], 1-Propanol, 2,3-dibromo- [96-13-9], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]
Power Transmission - [electrical axis drive]	EMC ASSEMBLY, INLET PIPE, OUTLET PIPE, O-RING, SEAL CAP, REAR AXLE, SEALING, TRANSMISSION, CABLE HARNESS, DRIVE SHAFT	Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Triphenyl-phosphate [115-86-6], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead-monoxide [1317-36-8], Sodium borate, pentahydrate [12179-04-3], Tris(nonylphenyl)phosphite [26523-78-4], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Electric Power Supply / Instruments - [cable system]	CABLE HARNESS, CABLE FLOOR, CABLE, FLANGE NUT, CABLE HARNESS WEM, CABLE HARNESS TAILGATE, FUSE BOX, CABLE DUCT, EJB, FUSE BOX ASSY, CABLE INFOTAINMENT	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Triphenyl-phosphate [115-86-6], TBBA [79-94-7], Cobalt-dinitrate [10141-05-6], Lead [7439-92-1]
Electric Power Supply / Instruments - [cleaner]	REAR WIPER MOTOR, FILLER PIPE, SEALING, NOZZLE, WIPER APPARATUS, WASHER FLUID RESERVOIR, WIPER ARM AND BLADE DS, WIPER ARM AND BLADE, WIPER ARM PS, WIPER ARM AND BLADE PS, WIPER ARM DS, PUMP, DUAL PUMP	Lead-monoxide [1317-36-8], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Bumetrizole [3896-11-5], TBBA [79-94-7], O,O,O-Triphenyl phosphorothioate [597-82-0], Triphenyl-phosphate [115-86-6], Cobalt(II) nitrate hexahydrate [10026-22-9], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], Lead [7439-92-1]
Body, Interior / Exterior - [glass, window / windscreen / roof]	QUARTER GLASS LAMINATED, REAR SCREEN, GLASS HARDENED, GLASS LAMINATED, WINDSCREEN, QUARTER GLASS HARDENED	Diboron-trioxide [1303-86-2], Bumetrizole [3896-11-5], Lead [7439-92-1]

Body, Interior / Exterior - [air conditioning]	FUEL OPERATED HEATER, IONIZER, SUN SENSOR, DRAINAGE HOSE, EL COMPRESSOR, DISTRIBUTION HOUSING, ELECTRIC HEATER, PIPE ASSEMBLY, CLIMATE UNIT, FAN, EVAPORATOR HOUSING, AIR INLET, HUMIDITY SENSOR, AC-COMPRESSOR, SENSOR KIT, DEFROSTER, STEPPING MOTOR, CONTROL UNIT, FLANGE SCREW, AIR CLEANER, EXPANSION VALVE, SOLENOID CLUTCH, SENSOR, SENSOR INTERIOR, PROTECTIVE CAP, VALVE, CONTROL VALVE, CHANNEL SENSOR, FUEL PUMP	Refractory ceramic fibres [142844-00-6], 2-Methylimidazole [693-98-1], Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], 1-Propanol, 2,3-dibromo- [96-13-9], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4], Tris(nonylphenyl)phosphite [26523-78-4], Melamine [108-78-1], Bumetrizole [3896-11-5], Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8], TBBA [79-94-7], Cobalt(II) nitrate hexahydrate [10026-22-9], Cobalt-dichloride [7646-79-9], Lead [7439-92-1]
Body, Interior / Exterior - [outside / exterior trim]	EMBLEM, GRILLE, ANTENNA CAP, WHITE614, BLUE467, SILV477, BLACK487, GREY492, BROWN700, BLUE706, EXT707, EXT711, EXT714, EXT717, EXT719, CKDCOLOR, KSOCOLOR, SVART19S, RED612, EXT720, TAPE, EXT722, EXT721, EXT723, EXT621, EXT724, EXT725	2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], C,C'-azodi(formamide) [123-77-3], Triphenyl-phosphate [115-86-6]
Electric Power Supply / Instruments - [battery and mounting parts]	HEAT SHIELD, HEAT INSULATION PAD, MODULE, BATTERY, 48V BATTERY, CONTROL UNIT, INLET HOSE, OUTLET HOSE, SERVICE SWITCH, CURRENT SENSOR, BMS	Diboron-trioxide [1303-86-2], Melamine [108-78-1], Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8], Lead-monoxide [1317-36-8], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Boric acid [10043-35-3], 1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Octamethylcyclotetrasiloxane [556-67-2], 1-Propanol, 2,3-dibromo- [96-13-9], Lead-titanium-trioxide [12060-00-3], Decamethylcyclopentasiloxane [541-02-6], Dodecamethylcyclohexasiloxane [540-97-6], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1]
Body, Interior / Exterior - [side door]	DOOR MOUNTED SEALING, SPLITLINE SEAL, CARRIER PLATE, SIDE DOOR, HEMMING ADHESIVE, BELT MOULDING, WINDOW LIFT	C,C'-azodi(formamide) [123-77-3], Imidazolidine-2-thione [96-45-7], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Dodecamethylcyclohexasiloxane [540-97-6], O,O,O-Triphenyl phosphorothioate [597-82-0], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bumetrizole [3896-11-5], Lead [7439-92-1]

Engine - [cooling system]	HOSE TEMP SENSOR, PUMP, SET, RADIATOR HYBRID, HOSE OUTLET, HOSE, EL WATER PUMP, COOLER, COMPLETE COOLER, PRESSURE SENSOR, CONDENSER, THREE-WAY VALVE, TEMPERATURE SENSOR, BUSHING, RADIATOR, CHARGE AIR COOLER, HOSE COLD ZONE, TWO-WAY VALVE, VALVE, HOSE MODULE, HOSE INLET, SEPARATOR, BRACKET, CLAMP BRACKET, HEATER HOSE, PIPE, HOSE HEATER, GASKET, O-RING, SIX POINT SOCKET SCREW, FLANGE SCREW, STRIKER PLATE, THERMOSTAT HOUSING, NIPPLE, WATER PUMP, PLASTIC PIPE	TBBA [79-94-7], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], 1-Methyl-2-pyrrolidone [872-50-4], Melamine [108-78-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Dodecamethylcyclotetrasiloxane [540-97-6], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Silicic acid, lead salt [11120-22-2], 4,4'-Isopropylidenediphenol [80-05-7], Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt-dichloride [7646-79-9], C,C'-azodi(formamide) [123-77-3]
Body, Interior / Exterior - [recovery / towing unit]	TOWING HOOK, HARNESS	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]
Body, Interior / Exterior - [lock / handle]	OUTER HANDLE, WIRE, WIRE DOOR OPENER, HANDLE, LOCK, LOCK WITH ANTI THEFT COVE, EXT746, EXT739, EXT745, E, EXT723, EXT731, EXT736, KSOCOLOR, CKDCOLOR, DOOR LOCK, LOCK CYLINDER SET, KEY, BRACKET OUTER HANDLE, LOCK CYLINDER	TBBA [79-94-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Bumetrizole [3896-11-5], Triphenyl-phosphate [115-86-6], Melamine [108-78-1], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Lead [7439-92-1]
Engine - [inlet / exhaust systems]	EXHAUST SYSTEM, THROTTLE, HEAT SHIELD PLATE, INTAKE MANIFOLD	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1], Boric acid [10043-35-3]
Electric Power Supply / Instruments - [mobile data services]	CONTROL UNIT	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1], Lead [7439-92-1]
Wheel Suspension / Steering - [steering gear / wheel / shaft / column]	STEERING COLUMN, STEERING GEAR, STEERING WHEEL, STEERING WHEEL RIM, SEALING FLOOR, STEERING WHEEL HARNESS	Phosphorothioic acid, O,O,O-triphenyl esters, tert-Bu derivs. [192268-65-8], Lead-monoxide [1317-36-8], O,O,O-Triphenyl phosphorothioate [597-82-0], Dicyclohexyl-phthalate [84-61-7], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]

Electric Power Supply / Instruments - [vehicle control system]	SWITCH PANEL, CONTROL UNIT DOOR, SWITCH, CUT-OFF SWITCH, USB POWER OUTLET, ECU, STALK MODULE, SWITCH MODULE, COMBI INSTRUMENT, HARDWARE, CONTROL PANEL POWER SEAT, LOCK BUTTON, BUTTON, LOCK BUTTON LED, SWITCH DOOR, SWITCH WINDOW LIFT, SWITCH STEERING WHEEL	Triphenyl-phosphate [115-86-6], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead titanium zirconium oxide [12626-81-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Melamine [108-78-1], 4,4'-Isopropylidenediphenol [80-05-7], Boric acid [10043-35-3], Lead-titanium-trioxide [12060-00-3], Lead [7439-92-1]
Electric Power Supply / Instruments - [communication, mobile telephone]	CONTROL UNIT, BATTERY, WIRELESS CHARGE SYSTEM, BACK-UP BATTERY, AUXILIARY TELEMATIC, ANTENNA	Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], N,N-Dimethylacetamide [127-19-5], Dioctyltin dilaurate [3648-18-8], Lead [7439-92-1]
Engine - [fuel / EVAP system]	FUEL PUMP MODULE, PUMP MODULE, JET PUMP AND LEVEL SENSOR, FILTER, LEAK DETECTION PUMP, ISOLATION VALVE, FILLER PIPE, PEM, HOSE, EVAP PURGE PUMP, CANISTER, EVAP-LINE ASSY, FUEL TANK, TANK WELDED, PURGE VALVE, PURGE VALVE ASSY, FUEL PRESSURE SENSOR, FUEL DISTRIBUTION PIPE, HIGH PRESSURE PUMP, INJECTOR, FUEL PUMP	Melamine [108-78-1], Lead-monoxide [1317-36-8], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Diboron-trioxide [1303-86-2], O,O,O-Triphenyl phosphorothioate [597-82-0], TBBA [79-94-7], Cobalt-dinitrate [10141-05-6], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1]
Body, Interior / Exterior - [airbag]	SIDE AIR BAG, AIRBAG MODULE, CONTROL UNIT, ACCELEROMETER SENSOR, INFLATABLE CURTAIN, PRESSURE SENSOR	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7], Lead [7439-92-1]
Body, Interior / Exterior - [floor / frame section / wheel housing / firewall]	FRONT SIDE MEMBER, WHEEL HOUSING, ADHESIVE, FLOOR PANEL, TOP COVER, BRACE OUTER, BRACE, SIDE MEMBER, BACK PANEL, SIDE MEMBER UPPER INNER	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Body, Interior / Exterior - [upholstery]	DOOR PANEL, SIDE PANEL, DOOR FRAME BOW, GRAPH BLUE/CHA, LAMP LED, LUGGAGE COVER, CLIP HOUSING	C,C'-azodi(formamide) [123-77-3], TBBA [79-94-7], N,N-Dimethylacetamide [127-19-5], 4-Nonylphenol, branched [84852-15-3], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Bumetizole [3896-11-5], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead [7439-92-1]
Body, Interior / Exterior - [exterior equipment]	ACTIVE GRILLE SHUTTER, ACTIVE SPOILER SHUTTER	Diboron-trioxide [1303-86-2], Lead [7439-92-1]

Body, Interior / Exterior - [outside mirrors]	REAR VIEW MIRROR OUTER, CAMERA, REAR VIEW MIRROR, MOTOR UNIT, DIRECTION INDICATOR, TEMPERATURE SENSOR, GLASS, REAR VIEW MIRROR CASING	Lead-monoxide [1317-36-8], Octamethylcyclotetrasiloxane [556-67-2], Diboron-trioxide [1303-86-2], Dicyclohexyl-phthalate [84-61-7], Tris(nonylphenyl)phosphite [26523-78-4], 2-Methylimidazole [693-98-1], TBBA [79-94-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 4,4'-Isopropylidenediphenol [80-05-7], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Melamine [108-78-1], Lead [7439-92-1]
Body, Interior / Exterior - [hood cover]	HOOD, ANTIFLUTTER	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Electric Power Supply / Instruments - [electric drive system]	VOLTAGE CONVERTER, INVERTER IEM, INVERTER IGM, ONBOARD CHARGER, STARTER MOTOR ALTERNATOR, CHARGE POINT, PROTECTION HIGH VOLTAGE, BRACKET, SEALING, STARTER MOTOR, COOLANT PIPE, SENSOR	Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], 2-Methylimidazole [693-98-1], 4,4'-Isopropylidenediphenol [80-05-7], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Alkanes, C14-17, chloro [85535-85-9], Triphenyl-phosphate [115-86-6], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Lead [7439-92-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], N,N-Dimethylacetamide [127-19-5]
Electric Power Supply / Instruments - [infotainment system]	GRAPHIC HEAD UP DISPLAY, PRINTED CIRCUIT BOARD, DISPLAY, USB HUB	Diboron-trioxide [1303-86-2], 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) [29420-49-3], Boric acid [10043-35-3], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 4,4'-Isopropylidenediphenol [80-05-7], Melamine [108-78-1], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Triphenyl-phosphate [115-86-6], Lead [7439-92-1]
Electric Power Supply / Instruments - [cable system high voltage]	CABLE CHARGE POINT HV, CABLE HARNESS, BRACKET, CHARGE CABLE CORD, STRAIN RELIEF, CABLE DUCT, CABLE CHANNEL	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 4,4'-Sulfonyldiphenol [80-09-1], TBBA [79-94-7], Octamethylcyclotetrasiloxane [556-67-2], Lead [7439-92-1]
Body, Interior / Exterior - [roof]	GLASS PANEL, PANORAMA ROOF, ADHESIVE ROOF HATCH, MOTOR, SEALING, SEALING STRIP, FRAME, ROOF HATCH	Tris(nonylphenyl)phosphite [26523-78-4], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Triphenyl-phosphate [115-86-6], C,C'-azodi(formamide) [123-77-3], Lead-monoxide [1317-36-8], Phosphorothioic acid, O,O,O-triphenyl esters, tert-Bu derivs. [192268-65-8], Lead [7439-92-1]

Electric Power Supply / Instruments - [vehicle computational units / gateway modules]	CONTROL UNIT	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [rim]	TYRE 255/40R21 102V, TYRE 265/35R22 102V XL, TYRE 255/40R21 102V XL, WHEEL 7, 5X19X50, 5, WHEEL 8, 5X21X49, WHEEL 9X22X43, TYRE 255/40R21 102V M+S, ADHESIVE BALANCE WEIGHT, TYRE 265/35R22, TYRE 255/40R21, VALVE, KEY, WHEEL BOLT	Triphenyl-phosphate [115-86-6], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], 2-Methylimidazole [693-98-1], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [trunk lid / tailgate complete]	SPINDLE DRIVE, REAR DOOR, EXT739, EXT745, EXT746	Bumetrizole [3896-11-5], O,O,O-Triphenyl phosphorothioate [597-82-0], Melamine [108-78-1], Lead [7439-92-1]
Body, Interior / Exterior - [seat belt / other restraining systems]	BELT CATCH, SEAT BELT, BELT, HEIGHT ADJUSTMENT, LOAD NET	TBBA [79-94-7], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead-monoxide [1317-36-8], Cobalt sulphate [10124-43-3], Cobalt-dinitrate [10141-05-6], Cobalt(II) nitrate hexahydrate [10026-22-9], Decamethyltetrasiloxane [141-62-8], Melamine [108-78-1], Triphenyl-phosphate [115-86-6], Lead [7439-92-1]
Power Transmission - [gearbox]	CONTROL UNIT, CABLE HARNESS, CONNECTOR, AUTOMATIC GEARBOX, AIR VENT PIPE, FLANGE NUT, FLANGE SCREW, TORQUE CONVERTER, VALVE BODY, SERVO COVER, CONTROL SYSTEM, OIL PUMP, ADAPTER, DIFFERENTIAL SPACER, LID	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], Lead-monoxide [1317-36-8], Nonylphenol [25154-52-3], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], 4,4'-Isopropylidenediphenol [80-05-7], 1-Methyl-2-pyrrolidone [872-50-4], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Cobalt-dinitrate [10141-05-6], Cobalt-dichloride [7646-79-9], Lead-titanium-trioxide [12060-00-3], Silicic acid, lead salt [11120-22-2], Lead [7439-92-1]
Electric Power Supply / Instruments - [automatic monitoring / control]	SIREN, SENSOR, REMOTE KEY, RAIN SENSOR, CONTROL UNIT, TRM	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead titanium zirconium oxide [12626-81-2], 1,2-Dimethoxyethane [110-71-4], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead [7439-92-1]
Power Transmission - [gear lever carrier / gear selector controls]	GEAR LEVER CARRIER, ACTUATOR	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead [7439-92-1]

Power Transmission - [actuator, gear shift]	CONTROL UNIT	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], Silicic acid, lead salt [11120-22-2], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [instrument / radio panel]	DASHBOARD, GLOVE BOX, ADAPTER BRACKET, CONCEALING PANEL, LAMP LED, HINGE PIN	Tris(nonylphenyl)phosphite [26523-78-4], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], TBBA [79-94-7], Lead [7439-92-1]
Brake - [brake line with connections]	BRAKE PIPE, BRAKE PIPE FRONT, BRAKE PIPE REAR, RETAINER, BRAKE HOSE	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bumetizole [3896-11-5], Lead [7439-92-1]
Electric Power Supply / Instruments - [protection]	CONTROL UNIT, SENSOR FRONT, ACCELEROMETER, ACCELEROMETER FRONT, SENSOR REAR	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Lead [7439-92-1]
Engine - [engine / engine mounting]	ENGINE, ENGINE MOUNT, TORQUE ROD, TORQUE LINK BRACKET, ENGINE BRACKET	Bis(4-chlorophenyl) sulfon [80-07-9], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], TBBA [79-94-7], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Lead-titanium-trioxide [12060-00-3], Lead [7439-92-1]
Engine - [emission equipment]	LAMBDA SOND, PRESSURE SENSOR, VALVE, COOLER, ALUMINIUM, STAY	Diboron-trioxide [1303-86-2], TBBA [79-94-7], Lead-monoxide [1317-36-8], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1]
Engine - [fan]	FAN, FAN LOW	Boric acid [10043-35-3], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead [7439-92-1]
Brake - [brake, anti lock (anti- skid)]	HYDRAULIC UNIT, SENSOR	Lead titanium zirconium oxide [12626-81-2], Boric acid [10043-35-3], O,O,O-Triphenyl phosphorothioate [597-82-0], Cobalt(II) nitrate hexahydrate [10026-22-9], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Lead [7439-92-1]

Electric Power Supply / Instruments - [electrical distribution box / fuse box]	CEM, ATTACHMENT	Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Electric Power Supply / Instruments - [horn]	HORN	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead [7439-92-1]
Body, Interior / Exterior - [instruction / information plates]	SIX POINT SOCKET SCREW	1-Methyl-2-pyrrolidone [872-50-4]
Electric Power Supply / Instruments - [antenna]	ETC MODULE, ANTENNA AMPLIFIER, ETC ON BOARD UNIT, ANTENNA	Lead-monoxide [1317-36-8], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Hexahydromethylphthalic-anhydride [25550-51-0], Lead titanium zirconium oxide [12626-81-2], 1-Propanol, 2,3-dibromo- [96-13-9], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Lead [7439-92-1]
Engine - [air cleaner]	BELLOWS, FRESH AIR PIPE, BOX	Bumetrizole [3896-11-5], Lead [7439-92-1]
Electric Power Supply / Instruments - [cable components]	RECEPTACLE HOUSING, PRINTED CIRCUIT BOARD, DISCONNECTOR POWER, GROMMET, SPLICE, STRAIN RELIEF, CABLE DUCT, UNLOADING CABLE, FUSE BOX, EJB, CABLE, CABLE CHANNEL, BATTERY TERMINAL, FUSE BOX ASSY, FUSE BOX REAR, RETAINER, CHANNEL, AIR HOSE	Dodecamethylcyclotetrasiloxane [540-97-6], Decamethylcyclotetrasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [anti-roll bar]	LINK FRONT ANTI-ROLL BAR, LINK ANTI-ROLL BAR, ANTI-ROLL BAR FRONT, ANTI-ROLL BAR REAR	Imidazolidine-2-thione [96-45-7], 2-Methylimidazole [693-98-1]
Body, Interior / Exterior - [miscellaneous]	TRANSPORT PROTECTION, SEALANT REPAIR, ABSORBER, SEALING, INSULATION	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Dibutylbis(pentane-2,4-dionato-O,O')tin [22673-19-4], Triphenyl-phosphate [115-86-6], C,C'-azodi(formamide) [123-77-3], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Body, Interior / Exterior - [protective shields / flaps]	CLIP	Bumetrizole [3896-11-5]

Power Transmission - [final drive]	SEALING, PT-UNIT, BRACKET	Triphenyl-phosphate [115-86-6], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead [7439-92-1]
Brake - [master cylinder / brake booster]	LID	Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]
Engine - [intercooler / connection]	CHARGE AIR HOSE, CHARGE AIR PIPE, RESONATOR, CHARGE AIR COOLER	Boric acid [10043-35-3], Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [spring, leaf spring]	VALVE BLOCK, AIR SPRING FRONT, COMPRESSOR, RESEVOIR, HOSE COUPLING, AIR HOSE BUNDLE, CONNECTOR, T-CONNECTION, AIR SPRING REAR, SHOCK ABSORBER FRONT, TOPMOUNT	Decamethylcyclopentasiloxane [541-02-6], O,O,O-Triphenyl phosphorothioate [597-82-0], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Triphenyl-phosphate [115-86-6], Tris(nonylphenyl)phosphite [26523-78-4], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Body, Interior / Exterior - [bonnet / cover with assembly parts]	HOOD RELEASE CABLE, FOAM, HOOD LOCK, COVER, HOOD LOCK CONTROL	Imidazolidine-2-thione [96-45-7], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1]
Engine - [accelerator control]	ACCELERATOR PEDAL	Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead [7439-92-1]
Body, Interior / Exterior - [tank hatch]	PLASTIC MODULE	Triphenyl-phosphate [115-86-6], TBBA [79-94-7], Lead [7439-92-1]
Brake - [brake control]	SENSOR, PEDAL UNIT	Lead [7439-92-1]
Engine - [miscellaneous / help device installation]	BRACKET, TENSIONER, SPLASH PROTECTION	Lead [7439-92-1]
Engine - [cold zone / batterybox]	NVH PANEL	Lead [7439-92-1]
Engine - [ignition / spark plug]	IGNITION COIL, SPARK PLUG, GLOW PLUG	Diboron-trioxide [1303-86-2], Lead [7439-92-1]

Engine - [lubricating and oil system]	GASKET, OIL PUMP, OIL LEVEL SENSOR, OIL FILTER, OIL PRESSURE SENSOR, OIL SUMP, SUCTION LINE, PISTON COOLING JET, VALVE, INLET PIPE, PISTON COOLING VALVE, WINDAGE TRAY, PLUG	Bis(4-chlorophenyl) sulfon [80-07-9], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Engine - [transmission]	GASKET, VVT-UNIT, TENSIONER, IDLER PULLEY, CAMSHAFT, SOLENOID, BALANCE SHAFT, BELT PROTECTOR, HOUSING, BELT COVER, VVT ACTUATOR, SLEEVE	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]
Engine - [supercharging]	TURBO CHARGER, O-RING, VACUUM RESERVOIR, VACUUM REGULATOR, BRACKET	N,N-Dimethylacetamide [127-19-5], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Lead [7439-92-1]
Engine - [distributor]	KNOCK SENSOR, CAMSHAFT POSITION SENSOR	Lead titanium zirconium oxide [12626-81-2], Lead-monoxide [1317-36-8], Lead [7439-92-1]
Engine - [cylinder block / head]	BEDPLATE, ENGINE BRACKET, VACUUM PUMP, CYLINDER BLOCK, TOP COVER, GUIDE SLEEVE, BEARING HOUSE CAM SHAFT, CYLINDER HEAD, CAP, CAM SHAFT COVER, CAMSHAFT CAP, HOUSING, LOCATING PIN	Lead [7439-92-1]
Engine - [crank mechanism]	DUAL MASS FLYWHEEL, NIPPLE, NON-RETURN VALVE	Lead [7439-92-1]