

**V90CC MODEL YEAR 2024**  
**Candidate List Substances Table**

We hereby inform that almost all product areas contain lead (CAS No 7439-92-1), primarily as alloying elements in steel, aluminium and copper.

Released: 2023 week 17

| Localisation   | Partnames  | Substance/s  |
|--|--|--|
| Engine - [cooling system]  | PUMP, TWO-WAY VALVE, VALVE, HOSE TEMP SENSOR, HOSE OUTLET, HOSE MODULE, TWIN CLIP, WATER PUMP, COOLER, SET, CONDENSER, RADIATOR, CHARGE AIR COOLER, TEMPERATURE SENSOR, THREE-WAY VALVE, BRACKET, CLAMP BRACKET, HOSE, RETAINER, HEATER HOSE, PIPE, COMPLETE COOLER, PRESSURE SENSOR, HOSE HEATER, HOSE INLET, OUTLET HOSE, THERMOSTAT HOUSING, O-RING, NIPPLE, INLET PIPE, PLASTIC PIPE, COVER, SIX POINT SOCKET SCREW, MODULE WATER PUMP, BRACKET TEMP SENSOR, STRIKER PLATE | TBBA [79-94-7], Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Decamethylcyclopentasiloxane [541-02-6], Melamine [108-78-1], Lead titanium zirconium oxide [12626-81-2], 1-Methyl-2-pyrrolidone [872-50-4], Silicic acid, lead salt [11120-22-2], 4,4'-Isopropylidenediphenol [80-05-7], Octamethylcyclotetrasiloxane [556-67-2], Lead(II,IV)-oxide [1314-41-6], C,C'-azodi(formamide) [123-77-3]   |
| Body, Interior / Exterior - [lock / handle]                          | DOOR LOCK, LOCK WITH ANTI THEFT COVE, LOCK, OUTER HANDLE, LOCK CYLINDER SET, KEY, BRACKET OUTER HANDLE, HANDLE, LOCK CYLINDER  | Lead [7439-92-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Hexahydromethylphthalic-anhydride [25550-51-0], Melamine [108-78-1], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9]  |
| Wheel Suspension / Steering [steering gear / wheel / shaft / column] | STEERING WHEEL, STEERING WHEEL RIM, STEERING COLUMN LOCK, STEERING GEAR, STEERING WHEEL HARNESS, STEERING COLUMN   | Dicyclohexyl-phthalate [84-61-7], Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2]   |
| Electric Power Supply / Instruments - [radio equipment]              | MICROPHONE, SPEAKER MIDRANGE, AUDIO MODULE, BRACKET, SUBWOOFER, WOOFER, LOUDSPEAKER, CENTRE LOUDSPEAKER  | Diboron-trioxide [1303-86-2], Lead [7439-92-1], N,N-Dimethylacetamide [127-19-5], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], Melamine [108-78-1], TBBA [79-94-7], Cobalt(II) nitrate hexahydrate [10026-22-9], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]  |
| Body, Interior / Exterior - [air conditioning]                       | CLIMATE UNIT, FUEL OPERATED HEATER, IONIZER, SUN SENSOR, SENSOR, PROTECTIVE CAP, VALVE, HUMIDITY SENSOR, SENSOR KIT, DEFROSTER, STEPPING MOTOR, FAN, CONTROL UNIT, PIPE ASSEMBLY, AIR CLEANER, AIR INLET, VALVE CAP, CHANNEL SENSOR, CONTROL VALVE, MAGNET CLUTCH, AC-COMPRESSOR, SENSOR INTERIOR, FUEL PUMP   | TBBA [79-94-7], 2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol [3864-99-1], Lead [7439-92-1], Refractory ceramic fibres [142844-00-6], 2-Methylimidazole [693-98-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 4,4'-Isopropylidenediphenol [80-05-7], Tris(nonylphenyl)phosphite [26523-78-4], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Octamethylcyclotetrasiloxane [556-67-2], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9] |
| Engine - [fan]   | FAN, FAN LOW   | 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Lead [7439-92-1], TBBA [79-94-7], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2]  |

|  |   |   |
|--|---|---|
| Body, Interior / Exterior - [seats]                            | FRAMEWORK, HEAD RESTRAINT, UPHOLSTERY, HARDBACK, UNDERCARRIAGE, ARM REST, ENGINE TILT, ENGINE, HEATING PAD SEAT, VENTILATION, LUMBAR SUPPORT, STS SENSOR, MASSAGE UNIT, BACKREST FRAME, SIDE BOLSTER, HEATER, CABLE HARNESS, SIX POINT SOCKET SCREW, FRAME, FAN, LUMBAR SUPPORT 4-WAY | C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], N,N-Dimethylacetamide [127-19-5], TBBA [79-94-7], Melamine [108-78-1], Boric acid [10043-35-3], Imidazolidine-2-thione [96-45-7], Phenol, dimethyl-, phosphate (3:1) [25155-23-1], Diboron-trioxide [1303-86-2], 1-Methyl-2-pyrrolidone [872-50-4], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3], Glutaral [111-30-8] |
| Body, Interior / Exterior - [upholstery]                       | DOOR PANEL, SILL MOULDING, WAISTRAIL, LIGHTING, LAMP LED, SILL FRONT, RUBBER MAT, GUIDE RAIL, SIDE PANEL, FLOOR HATCH, PANEL, TRUNK FLOOR SUPPORT, HEADLINING, BELT GUIDE   | C,C'-azodi(formamide) [123-77-3], Diboron-trioxide [1303-86-2], Lead [7439-92-1], TBBA [79-94-7], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1], Melamine [108-78-1]   |
| Body, Interior / Exterior - [interior equipment]               | PADDING, ARM REST, JALUSIE, CUP HOLDER, EC REAR VIEW MIRROR, COURTESY HANDLE, DAMPER, HINGE, SIDE PANEL, LIGHTING, LED MODULE, FRAMEWORK  | C,C'-azodi(formamide) [123-77-3], Tris(nonylphenyl)phosphite [26523-78-4], Lead [7439-92-1], TBBA [79-94-7], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Cobalt sulphate [10124-43-3], Cobalt-dinitrate [10141-05-6], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]   |
| Power Transmission - [front axle / rear axle / drive shaft]    | AOC, PUMP UNIT, DRIVE SHAFT, VIBRATION DAMPER, BRACKET, REAR AXLE, FINAL DRIVE, BEARING ANCHORAGE, FLANGE SCREW   | Lead [7439-92-1], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Cobalt-dichloride [7646-79-9]   |
| Electric Power Supply / Instruments - [vehicle control system] | SWITCH PANEL, CONTROL UNIT DOOR, BUTTON, ECU, STALK MODULE, HARDWARE, SWITCH, LOCK BUTTON, LOCK BUTTON LED, COMBI INSTRUMENT, CUT-OFF SWITCH, USB POWER OUTLET, SWITCH WINDOW LIFT, GEAR SHIFT PADDLE, CONTROL PANEL POWER SEAT, SWITCH DOOR, SWITCH MODULE, SWITCH STEERING WHEEL    | Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], TBBA [79-94-7], 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride [19438-60-9], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Boric acid [10043-35-3], 4,4'-Isopropylidenediphenol [80-05-7]   |
| Electric Power Supply / Instruments - [infotainment system]    | DISPLAY, GRAPHIC HEAD UP DISPLAY, CONTROL UNIT, USB HUB, PRINTED CIRCUIT BOARD  | Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], TBBA [79-94-7], Melamine [108-78-1], Lead-titanium-trioxide [12060-00-3], 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonfluoro-, potassium salt (1:1) [29420-49-3], Boric acid [10043-35-3], Silicic acid, lead salt [11120-22-2]  |
| Body, Interior / Exterior - [front fender]                     | SHIM, FRONT FENDER  | Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]   |
| Engine - [control systems]                                     | TEMP AND PRESSURE SENSOR, AIR TEMP SENSOR, CONTROL UNIT, MASS AIR FLOW SENSOR, PRESSURE SENSOR  | Lead [7439-92-1], Hexahydromethylphthalic-anhydride [25550-51-0], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Silicic acid, lead salt [11120-22-2], Lead titanium zirconium oxide [12626-81-2]   |

|  |  |  |
|--|--|--|
| Electric Power Supply / Instruments - [support systems]                | SENSOR, CONTROL UNIT, CAMERA, RADAR  | Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-Methylimidazole [693-98-1], TBBA [79-94-7], Dicyclohexyl-phthalate [84-61-7], Lead-titanium-trioxide [12060-00-3], Lead titanium zirconium oxide [12626-81-2], 1-Propanol, 2,3-dibromo- [96-13-9], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6]   |
| Brake - [brake, anti lock (anti-skid)]                                 | HYDRAULIC UNIT, SENSOR   | Lead [7439-92-1], Lead titanium zirconium oxide [12626-81-2], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3]   |
| Electric Power Supply / Instruments - [battery and mounting parts]     | BMS, BATTERY, SWITCH, BATTERY 48V  | Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead titanium zirconium oxide [12626-81-2], 1,3-Propanesultone [1120-71-4], Octamethylcyclotetrasiloxane [556-67-2], 1-Propanol, 2,3-dibromo- [96-13-9], Lead-titanium-trioxide [12060-00-3]   |
| Electric Power Supply / Instruments - [lighting]                       | CONTROL UNIT HCM, HEADLAMP, OVERHEAD CONSOLE LENS, READING LAMP, LIGHTING, LIGHTNING INSTRUMENT PANEL, LED MODULE, STOP LAMP, LAMP LED, REAR LAMP, FOG LIGHT                             | Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], TBBA [79-94-7], 1-Methyl-2-pyrrolidone [872-50-4], Dicyclohexyl-phthalate [84-61-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Octamethylcyclotetrasiloxane [556-67-2], Silicic acid, lead salt [11120-22-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Melamine [108-78-1], Lead-titanium-trioxide [12060-00-3] |
| Engine - [selective catalytic reduction]                               | CONTROL UNIT, SENSOR, PUMP MODULE, BRACKET, TANK, CONTROL MODULE   | Lead [7439-92-1], Nonylphenol [25154-52-3], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead titanium zirconium oxide [12626-81-2], Octamethylcyclotetrasiloxane [556-67-2], Silicic acid, lead salt [11120-22-2]  |
| Electric Power Supply / Instruments - [cable system]                   | CABLE, CABLE HARNESS, CABLE FLOOR, CABLE HARNESS WEM, CABLE DUCT, BRACKET, FLANGE NUT, DISCONNECTOR POWER, FUSE BOX ASSY, CABLE PAC, FUSE BOX, PRINTED CIRCUIT BOARD, CABLE INFOTAINMENT | Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Tris(nonylphenyl)phosphite [26523-78-4], TBBA [79-94-7], Dicyclohexyl-phthalate [84-61-7], Cobalt-dinitrate [10141-05-6], Diboron-trioxide [1303-86-2], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], 4,4'-Isopropylidenediphenol [80-05-7]   |
| Power Transmission - [gear lever carrier / gear selector controls]     | GEAR LEVER CARRIER   | Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]  |
| Electric Power Supply / Instruments - [automatic monitoring / control] | SIREN, RAIN SENSOR, CONTROL UNIT, REMOTE KEY, SENSOR   | Lead [7439-92-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead(II,IV)-oxide [1314-41-6], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], 1,2-Dimethoxyethane [110-71-4], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7]   |
| Brake - [brake line with connections]                                  | BRAKE PIPE, BRAKE PIPE FRONT, BRAKE PIPE REAR  | Lead [7439-92-1]   |

|   |   |   |
|---|---|---|
| Engine - [engine / engine mounting]   | ENGINE MOUNT, TORQUE ROD, TORQUE LINK BRACKET, ENGINE BRACKET   | Lead [7439-92-1]  |
| Body, Interior / Exterior - [bonnet / cover with assembly parts]                      | HOOD LOCK, COVER, FOAM, HOOD RELEASE CABLE, HOOD LOCK CONTROL   | Lead [7439-92-1], C,C'-azodi(formamide) [123-77-3], 2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol [3864-99-1], Imidazolidine-2-thione [96-45-7]   |
| Electric Power Supply / Instruments - [vehicle computational units / gateway modules] | CONTROL UNIT  | Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8]   |
| Power Transmission - [gearbox]  | TORQUE CONVERTER, AUTOMATIC GEARBOX, CONTROL UNIT, VALVE BODY, CABLE HARNESS, CONNECTOR                   | Lead [7439-92-1], Lead-monoxide [1317-36-8], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], Diboron-trioxide [1303-86-2], Nonylphenol [25154-52-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7], 1-Methyl-2-pyrrolidone [872-50-4], Lead titanium zirconium oxide [12626-81-2]   |
| Body, Interior / Exterior - [glass, window / windscreen / roof]                       | WINDSCREEN, GLASS HARDENED, GLASS LAMINATED, REAR SCREEN, QUARTER GLASS HARDENED, QUARTER GLASS LAMINATED | Diboron-trioxide [1303-86-2], Lead [7439-92-1]  |
| Body, Interior / Exterior - [side door]   | SIDE DOOR, WINDOW LIFT, HEMMING ADHESIVE, CARRIER PLATE, BODY MOUNTED SEALING, DOOR MOUNTED SEALING       | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1], Imidazolidine-2-thione [96-45-7], C,C'-azodi(formamide) [123-77-3]   |
| Body, Interior / Exterior - [recovery / towing unit]                                  | TOWING HOOK, TRM, HARNESS   | Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], Lead-monoxide [1317-36-8], TBBA [79-94-7]  |
| Electric Power Supply / Instruments - [mobile data services]                          | CONTROL UNIT  | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1]  |
| Electric Power Supply / Instruments - [electric drive system]                         | VOLTAGE CONVERTER, STARTER MOTOR ALTERNATOR, COOLANT PIPE, SENSOR, STARTER MOTOR, BRACKET                 | Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Dicyclohexyl-phthalate [84-61-7], N,N-Dimethylacetamide [127-19-5]  |
| Body, Interior / Exterior - [roof]  | PANORAMA ROOF, GLASS PANEL, WELD SEALANT CURING, ADHESIVE ROOF HATCH, MOTOR                               | Lead [7439-92-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Tris(nonylphenyl)phosphite [26523-78-4], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], C,C'-azodi(formamide) [123-77-3], Lead-monoxide [1317-36-8]   |
| Electric Power Supply / Instruments - [communication, mobile telephone]               | CONTROL UNIT, WIRELESS CHARGE SYSTEM, BATTERY, PRINTED CIRCUIT BOARD                                      | Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1] |

|  |  |   |
|--|--|---|
| Engine - [fuel / EVAP system]  | FUEL PUMP MODULE, PURGE VALVE, LEAK DETECTION PUMP, PURGE VALVE ASSY, CANISTER, FUEL PRESSURE SENSOR, HOSE, FUEL FILTER, FUEL TANK, TANK WELDED, HIGH PRESSURE PUMP, FUEL DISTRIBUTION PIPE, FUEL PUMP, DELIVERY PIPE, INJECTOR, INJECTION VALVE | Lead-monoxide [1317-36-8], Lead [7439-92-1], Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], TBBA [79-94-7], Cobalt-dinitrate [10141-05-6], C,C'-azodi(formamide) [123-77-3]   |
| Body, Interior / Exterior - [seat belt / other restraining systems]            | HEIGHT ADJUSTMENT, BELT CATCH, SEAT BELT, LOAD NET, BELT CATCH REAR, BELT  | Lead [7439-92-1], TBBA [79-94-7], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]   |
| Electric Power Supply / Instruments - [cleaner]                                | WIPER UNIT, WASHER FLUID RESERVOIR, REAR WIPER, HEADLAMP WIPER, PUMP, DUAL PUMP, WIPER ARM   | Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2]   |
| Body, Interior / Exterior - [floor / frame section / wheel housing / firewall] | BUMPER BEAM, FRONT SIDE MEMBER, WHEEL HOUSING, WELD SEALANT CURING, ADHESIVE, TOP COVER, REINFORCEMENT, SIDE MEMBER UPPER INNER, BRACE INNER, BRACE OUTER, CRASH BOX REINFORCEMENT, FLOOR PANEL, BATTERY TRAY, CRASH BOX                         | Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]   |
| Engine - [emission equipment]  | COOLER, PRESSURE SENSOR, VALVE, TEMPERATURE SENSOR EGT, TEMPERATURE SENSOR   | Lead [7439-92-1], TBBA [79-94-7], Lead-monoxide [1317-36-8], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2]   |
| Engine - [intercooler / connection]  | CHARGE AIR COOLER, CHARGE AIR HOSE, CHARGE AIR PIPE, RESONATOR   | Lead [7439-92-1], Boric acid [10043-35-3]   |
| Body, Interior / Exterior - [trunk lid / tailgate complete]                    | REAR DOOR, SPINDLE DRIVE   | Lead [7439-92-1], TBBA [79-94-7], Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8]   |
| Wheel Suspension / Steering - [axle member / link arm / suspension]            | LOWER LINK ARM, SUBFRAME FRONT, UPPER LINK ARM   | Imidazolidine-2-thione [96-45-7], Cobalt-dichloride [7646-79-9], Lead [7439-92-1]   |
| Body, Interior / Exterior - [outside mirrors]                                  | CAMERA, REAR VIEW MIRROR OUTER, REAR VIEW MIRROR, MOTOR UNIT, DIRECTION INDICATOR, TEMPERATURE SENSOR, GLASS, REAR VIEW MIRROR CASING  | Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1], Dicyclohexyl-phthalate [84-61-7], Octamethylcyclotetrasiloxane [556-67-2], 2-Methylimidazole [693-98-1], Phenol, dimethyl-, phosphate (3:1) [25155-23-1], Lead titanium zirconium oxide [12626-81-2], TBBA [79-94-7], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Melamine [108-78-1], Tris(nonylphenyl)phosphite [26523-78-4] |
| Engine - [inlet / exhaust systems]   | TAILPIPE, THROTTLE, EXHAUST SYSTEM, HEAT SHIELD PLATE, INTAKE MANIFOLD   | Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 4,4'-Isopropylidenediphenol [80-05-7], Boric acid [10043-35-3], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]   |

|  |   |   |
|--|---|---|
| Brake - [wheel brake]  | BRAKE CALIPER, AIR VENTING NIPPLE, EPB, BLEEDER VALVE, HOUSING                        | Lead [7439-92-1], 2-Methylimidazole [693-98-1], Tris(nonylphenyl)phosphite [26523-78-4], Hexahydromethylphthalic-anhydride [25550-51-0]   |
| Electric Power Supply / Instruments - [protection]                             | SENSOR FRONT, SENSOR REAR, CONTROL UNIT, ACCELEROMETER FRONT                          | Lead [7439-92-1], TBBA [79-94-7]  |
| Body, Interior / Exterior - [airbag]   | AIRBAG MODULE, ACCELEROMETER SENSOR, CONTROL UNIT                                     | 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], Lead [7439-92-1], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3]  |
| Body, Interior / Exterior - [instruction / information plates]                 | DECAL SRS, NUMBER PLATE HOLDER, SIX POINT SOCKET SCREW                                | 2-ethylhexyl 10-ethyl-4,4-dioctyl-7-oxo-8-oxa-3,5-dithia-4-stannatetradecanoate [15571-58-1], Imidazolidine-2-thione [96-45-7], 1-Methyl-2-pyrrolidone [872-50-4]   |
| Body, Interior / Exterior - [body side]  | WELD SEALANT CURING, ADHESIVE   | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]   |
| Frame / Springs / Damping / Wheels - [rim]                                     | KEY, WHEEL BOLT   | Lead [7439-92-1]  |
| Frame / Springs / Damping / Wheels - [anti-roll bar]                           | LINK FRONT ANTI-ROLL BAR, LINK ANTI-ROLL BAR, ANTI-ROLL BAR REAR, ANTI-ROLL BAR FRONT | Imidazolidine-2-thione [96-45-7], 2-Methylimidazole [693-98-1]  |
| Body, Interior / Exterior - [miscellaneous]                                    | TRANSPORT PROTECTION, SEALANT REPAIR, SEALING, SOUND INSULATION                       | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Dibutylbis(pentane-2,4-dionato-O,O')tin [22673-19-4], C,C'-azodi(formamide) [123-77-3], Diboron-trioxide [1303-86-2]   |
| Brake - [brake control]  | SENSOR, PEDAL UNIT  | Lead [7439-92-1]  |
| Electric Power Supply / Instruments - [antenna]                                | ANTENNA AMPLIFIER, ETC ON BOARD UNIT, ANTENNA, ETC MODULE                             | TBBA [79-94-7], Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead titanium zirconium oxide [12626-81-2], 1-Propanol, 2,3-dibromo- [96-13-9], Melamine [108-78-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1] |
| Body, Interior / Exterior - [tank hatch]                                       | ACTUATOR, PLASTIC MODULE  | Lead [7439-92-1]  |
| Body, Interior / Exterior - [instrument / radio panel]                         | STORAGE BOX, HINGE PIN, LAMP LED, CONCEALING PANEL, GLOVE BOX                         | Lead [7439-92-1], TBBA [79-94-7]  |
| Electric Power Supply / Instruments - [electrical distribution box / fuse box] | ATTACHMENT, CEM   | Lead [7439-92-1]  |

|   |  |  |
|---|--|--|
| Frame / Springs / Damping / Wheels - [spring, leaf spring]        | RESEVOIR, HOSE COUPLING, VALVE BLOCK, AIR SPRING REAR, TOPMOUNT, COMPRESSOR  | Lead [7439-92-1], Decamethylcyclopentasiloxane [541-02-6], Tris(nonylphenyl)phosphite [26523-78-4]   |
| Electric Power Supply / Instruments - [horn]                      | HORN   | Lead [7439-92-1], Diboron-trioxide [1303-86-2]   |
| Body, Interior / Exterior - [exterior equipment]                  | ACTIVE GRILLE SHUTTER, ACTIVE SPOILER SHUTTER  | Diboron-trioxide [1303-86-2], Lead [7439-92-1]   |
| Electric Power Supply / Instruments - [starting system]           | STARTER MOTOR  | Lead [7439-92-1]   |
| Body, Interior / Exterior - [hood cover]                          | FOAM, HOOD   | C,C'-azodi(formamide) [123-77-3], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]  |
| Engine - [accelerator control]                                    | ACCELERATOR PEDAL  | Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-monoxide [1317-36-8]  |
| Engine - [miscellaneous / help device installation]               | SPLASH PROTECTION, BRACKET, TENSIONER, GUIDE SLEEVE  | Lead [7439-92-1]   |
| Power Transmission - [final drive]                                | BRACKET, PT-UNIT   | Lead [7439-92-1]   |
| Frame / Springs / Damping / Wheels - [shock absorber]             | SHOCK ABSORBER FRONT, TOPMOUNT, SHOCK ABSORBER, SHOCK ABSORBER REAR  | Lead [7439-92-1]   |
| Electric Power Supply / Instruments - [cable system high voltage] | CHARGE CABLE CORD  | Lead [7439-92-1], Melamine [108-78-1], Octamethylcyclotetrasiloxane [556-67-2], Lead-monoxide [1317-36-8]  |
| Engine - [cold zone / batterybox]                                 | NVH PANEL  | Lead [7439-92-1]   |
| Engine - [supercharging]  | SLEEVE, PIPE COMPRESSOR, TURBO CHARGER, OIL DRAINING PIPE, COMPRESSOR, O-RING, STAY COMPRESSOR, SUPERCHARGER, THROTTLE, VACUUM RESERVOIR, VACUUM REGULATOR, BYPASS HOUSING, COMPRESSOR PIPE, BRACKET, MP TURBO, INLET PIPE | Lead [7439-92-1], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], N,N-Dimethylacetamide [127-19-5], Melamine [108-78-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Dicyclohexyl-phthalate [84-61-7], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Lead-monoxide [1317-36-8] |
| Engine - [transmission]   | TENSIONER, CAMSHAFT, IDLER PULLEY, BALANCE SHAFT, SOLENOID, BELT PROTECTOR, HOUSING, BELT COVER, VVT ACTUATOR, SLEEVE  | Lead [7439-92-1]   |

|                                       |   |   |
|---------------------------------------|---|---|
| Engine - [lubricating and oil system] | OIL SUMP, SUCTION LINE, OIL PUMP, VALVE, INLET PIPE, PISTON COOLING VALVE, WINDAGE TRAY, OIL LEVEL SENSOR, PISTON COOLING JET, OIL FILTER, PLUG, OIL PRESSURE SENSOR  | Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7], Diboron-trioxide [1303-86-2]                   |
| Engine - [cylinder block / head]      | CYLINDER HEAD, BEDPLATE, ENGINE BRACKET, VACUUM PUMP, CYLINDER BLOCK, TOP COVER, GUIDE SLEEVE, BEARING HOUSE CAM SHAFT, CAP, CAM SHAFT COVER, PROTECTING CASING, CAMSHAFT CAP, HOUSING, CAM SHAFT HOUSING, LOCATING PIN | Lead [7439-92-1]  |
| Engine - [distributor]                | CRANKSHAFT POS SENSOR, CAMSHAFT POSITION SENSOR, BRACKET, KNOCK SENSOR  | Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2] |
| Engine - [crank mechanism]            | DUAL MASS FLYWHEEL, NIPPLE, NON-RETURN VALVE  | Lead [7439-92-1]  |
| Engine - [ignition / spark plug]      | GLOW PLUG, IGNITION COIL, SPARK PLUG, CONTROL UNIT  | Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8]   |
| Engine - [air cleaner]                | RESONATOR, HOSE MODULE  | Lead [7439-92-1]  |