

**V60 MODEL YEAR 2024
Candidate List Substances Table**

We hereby inform that almost all product areas contain lead (CAS No 7439-92-1), primarily as alloying elements in steel, aluminium and copper.

Released: 2023 week 41.

Localisation	Partnames	Substance/s
Engine - [cooling system]	PUMP, HEATER HOSE, TWO-WAY VALVE, VALVE, HOSE TEMP SENSOR, HOSE OUTLET, HOSE MODULE, TWIN CLIP, PUMP MODULE, WATER PUMP, COOLER, CONDENSER, SET, RADIATOR HYBRID, HOSE, HOSE INLET, EL WATER PUMP, COMPLETE COOLER, PRESSURE SENSOR, TEMPERATURE SENSOR, RADIATOR, CHARGE AIR COOLER, SEPARATOR, BRACKET, THREE-WAY VALVE, CLAMP BRACKET, RETAINER, PIPE, HOSE HEATER, OUTLET HOSE, THERMOSTAT HOUSING, O-RING, NIPPLE, PLASTIC PIPE, GASKET, INLET PIPE, COVER, SIX POINT SOCKET SCREW, MODULE WATER PUMP, BRACKET TEMP SENSOR, STRIKER PLATE	TBBA [79-94-7], Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], 1-Methyl-2-pyrrolidone [872-50-4], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Decamethylcyclotetrasiloxane [541-02-6], Melamine [108-78-1], Silicic acid, lead salt [11120-22-2], 4,4'-Isopropylidenediphenol [80-05-7], Octamethylcyclotetrasiloxane [556-67-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead(II,IV)-oxide [1314-4-1-6], C,C'-azodi(formamide) [123-77-3]
Body, Interior / Exterior - [outside / exterior trim]	GRILLE	C,C'-azodi(formamide) [123-77-3]
Body, Interior / Exterior - [air conditioning]	EL COMPRESSOR, CLIMATE UNIT, PIPE ASSEMBLY, FUEL OPERATED HEATER, IONIZER, SUN SENSOR, SENSOR, ELECTRIC HEATER, PROTECTIVE CAP, VALVE, HUMIDITY SENSOR, SENSOR KIT, DEFROSTER, STEPPING MOTOR, FAN, EXPANSION VALVE, CHILLER, CONTROL UNIT, SOLENOID CLUTCH, AC-COMPRESSOR, FLANGE SCREW, AIR CLEANER, AIR INLET, VALVE CAP, CONTROL VALVE, CHANNEL SENSOR, SENSOR INTERIOR, FUEL PUMP	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], TBBA [79-94-7], 2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol [3864-99-1], Refractory ceramic fibres [142844-00-6], 2-Methylimidazole [693-98-1], Lead-titanium-trioxide [12060-00-3], 1-Propanol, 2,3-dibromo- [96-13-9], Tris(nonylphenyl)phosphite [26523-78-4], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8], Melamine [108-78-1], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Cobalt(II) nitrate hexahydrate [10026-22-9], Cobalt-dichloride [7646-79-9], Octamethylcyclotetrasiloxane [556-67-2]
Body, Interior / Exterior - [lock / handle]	DOOR LOCK, LOCK, OUTER HANDLE, LOCK CYLINDER SET, EXT743, KEY, WIRE	Lead [7439-92-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Melamine [108-78-1], Hexahydromethylphthalic-anhydride [25550-51-0], 2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol [3864-99-1]
Wheel Suspension / Steering [steering gear / wheel / shaft / column]	STEERING WHEEL, STEERING WHEEL RIM, STEERING COLUMN LOCK, STEERING COLUMN, STEERING GEAR, STEERING WHEEL HARNESS	Dicyclohexyl-phthalate [84-61-7], Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], TBBA [79-94-7], Diboron-trioxide [1303-86-2]

Engine - [inlet / exhaust systems]	ACTUATOR, EXHAUST SYSTEM, THROTTLE, HEAT SHIELD PLATE, INTAKE MANIFOLD	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 4,4'-Isopropylidenediphenol [80-05-7], Boric acid [10043-35-3], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
Electric Power Supply / Instruments - [vehicle control system]	HARDWARE, SWITCH PANEL, STALK MODULE, CONTROL UNIT DOOR, BUTTON, ECU, SWITCH, COMBI INSTRUMENT, CUT-OFF SWITCH, USB POWER OUTLET, GEAR SHIFT PADDLE, CONTROL PANEL POWER SEAT, SWITCH DOOR, SWITCH WINDOW LIFT, SWITCH MODULE, SWITCH STEERING WHEEL	Lead [7439-92-1], 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride [19438-60-9], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Boric acid [10043-35-3], TBBA [79-94-7], 4,4'-Isopropylidenediphenol [80-05-7], Lead titanium zirconium oxide [12626-81-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-titanium-trioxide [12060-00-3]
Electric Power Supply / Instruments - [radio equipment]	MICROPHONE, LOUDSPEAKER, SPEAKER MIDRANGE, AUDIO MODULE, SOUND MODULE, WOOFER, SUBWOOFER, CENTRE LOUDSPEAKER	Diboron-trioxide [1303-86-2], Lead [7439-92-1], N,N-Dimethylacetamide [127-19-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], Melamine [108-78-1], TBBA [79-94-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Cobalt(II) nitrate hexahydrate [10026-22-9]
Electric Power Supply / Instruments - [support systems]	SENSOR, CONTROL UNIT, CAMERA, BOX, RADAR	Lead-monoxide [1317-36-8], Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], 2-Methylimidazole [693-98-1], Dicyclohexyl-phthalate [84-61-7], Lead-titanium-trioxide [12060-00-3], Decamethylcyclotetrasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Lead titanium zirconium oxide [12626-81-2], 1-Propanol, 2,3-dibromo- [96-13-9]
Engine - [fan]	FAN	1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Lead [7439-92-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Boric acid [10043-35-3]
Body, Interior / Exterior - [glass, window / windscreen / roof]	WINDSCREEN, REAR SCREEN, GLASS HARDENED	Lead [7439-92-1], Diboron-trioxide [1303-86-2]
Electric Power Supply / Instruments - [lighting]	OVERHEAD CONSOLE LENS, CONTROL UNIT HCM, HEADLAMP, READING LAMP, LIGHTING, LAMP LED, REAR LAMP REAR DOOR, REAR LAMP, FOG LIGHT, LED MODULE	Lead [7439-92-1], TBBA [79-94-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Melamine [108-78-1], Dicyclohexyl-phthalate [84-61-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Octamethylcyclotetrasiloxane [556-67-2], Lead-titanium-trioxide [12060-00-3]

Body, Interior / Exterior - [interior equipment]	PADDING, FRAMEWORK, JALUSIE, ARM REST, CARRIER, EC REAR VIEW MIRROR, DAMPER, LIGHTING, RUBBER MAT, LED MODULE, HINGE, SIDE PANEL, CUP HOLDER, CARRIER ARM REST	C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1], TBBA [79-94-7], Tris(nonylphenyl)phosphite [26523-78-4], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Cobalt sulphate [10124-43-3], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1], Alkanes, C14-17, chloro [85535-85-9], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7]
Electric Power Supply / Instruments - [horn]	HORN	Lead [7439-92-1], Diboron-trioxide [1303-86-2]
Power Transmission - [front axle / rear axle / drive shaft]	AOC, PUMP UNIT, CABLE HARNESS, DRIVE SHAFT, REAR AXLE, FEEDER PUMP KIT, BEARING ANCHORAGE, VIBRATION DAMPER, BRACKET, FINAL DRIVE, FLANGE SCREW	Lead [7439-92-1], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Melamine [108-78-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Sodium borate, pentahydrate [12179-04-3], Tris(nonylphenyl)phosphite [26523-78-4], Lead-monoxide [1317-36-8], Cobalt-dichloride [7646-79-9]
Engine - [air cleaner]	FRESH AIR PIPE, HOSE FRESH AIR PIPE, BOX, RESONATOR, HOSE MODULE	Lead [7439-92-1]
Engine - [fuel / EVAP system]	PURGE VALVE ASSY, PURGE VALVE, FUEL PUMP MODULE, PUMP MODULE, JET PUMP AND LEVEL SENSOR, EVAP PURGE PUMP, LEAK DETECTION PUMP, ISOLATION VALVE, CANISTER, FUEL PRESSURE SENSOR, HOSE, FUEL FILTER, FUEL TANK, TANK WELDED, HIGH PRESSURE PUMP, FUEL DISTRIBUTION PIPE, INJECTOR, FUEL PUMP, DELIVERY PIPE, INJECTION VALVE	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Melamine [108-78-1], TBBA [79-94-7], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt-dinitrate [10141-05-6], C,C'-azodi(formamide) [123-77-3]
Body, Interior / Exterior - [upholstery]	DOOR PANEL, SWITCH, LOCK BUTTON, LOCK BUTTON LED, ARM REST, LAMP LED, SIDE PANEL	C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1], TBBA [79-94-7], N,N-Dimethylacetamide [127-19-5]
Body, Interior / Exterior - [seats]	HEAD RESTRAINT, UPHOLSTERY, SIDE BOLSTER, HARDBACK, UNDERCARRIAGE, ARM REST, ENGINE TILT, ENGINE, HEATING PAD SEAT, VENTILATION, LUMBAR SUPPORT, STS SENSOR, FRAMEWORK, MASSAGE UNIT, BACKREST FRAME, CABLE HARNESS, SIX POINT SOCKET SCREW, FRAME, FAN, LUMBAR SUPPORT 4-WAY, HEATER	C,C'-azodi(formamide) [123-77-3], Melamine [108-78-1], Lead [7439-92-1], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], TBBA [79-94-7], Boric acid [10043-35-3], Imidazolidine-2-thione [96-45-7], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], Diboron-trioxide [1303-86-2], 1-Methyl-2-pyrrolidone [872-50-4], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3], Glutaral [111-30-8], N,N-Dimethylacetamide [127-19-5]
Body, Interior / Exterior - [front fender]	SHIM	Lead [7439-92-1]

Engine - [control systems]	TEMP AND PRESSURE SENSOR, AIR TEMP SENSOR, CONTROL UNIT, PRESSURE SENSOR, MASS AIR FLOW SENSOR	Lead [7439-92-1], Hexahydromethylphthalic-anhydride [25550-51-0], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Silicic acid, lead salt [11120-22-2], Dicyclohexyl-phthalate [84-61-7], Acrylamide [79-06-1], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3]
Electric Power Supply / Instruments - [cable system high voltage]	STRAIN RELIEF, CABLE HARNESS, CABLE CHARGE POINT HV, CABLE DUCT, ADAPTER PLATE, CHARGE CABLE CORD, CABLE CHANNEL, CHARGE CABLE	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], TBBA [79-94-7], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Octamethylcyclotetrasiloxane [556-67-2], Melamine [108-78-1]
Brake - [brake, anti lock (anti-skid)]	HYDRAULIC UNIT, SENSOR	Lead [7439-92-1], Lead titanium zirconium oxide [12626-81-2], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
Electric Power Supply / Instruments - [battery and mounting parts]	BMS, CURRENT SENSOR, BATTERY, FILTER BOARD ASSY, MODULE, SWITCH, CONTROL UNIT, BATTERY 48V, 48V BATTERY, COVER, HEAT INSULATION PAD, SERVICE SWITCH, INLET HOSE, OUTLET HOSE, FILTER BOARD, HEAT SHIELD	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead titanium zirconium oxide [12626-81-2], 1,3-Propanesultone [1120-71-4], Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8], Melamine [108-78-1], Boric acid [10043-35-3], Octamethylcyclotetrasiloxane [556-67-2], 1-Propanol, 2,3-dibromo- [96-13-9], Lead-titanium-trioxide [12060-00-3], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1]
Body, Interior / Exterior - [outside mirrors]	REAR VIEW MIRROR OUTER, REAR VIEW MIRROR, CAMERA, GLASS, MOTOR UNIT	Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], Dicyclohexyl-phthalate [84-61-7], TBBA [79-94-7], 2-Methylimidazole [693-98-1], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Cobalt-dinitrate [10141-05-6]
Engine - [selective catalytic reduction]	CONTROL UNIT, PUMP MODULE, SENSOR, BRACKET, TANK, CONTROL MODULE	Lead [7439-92-1], Nonylphenol [25154-52-3], Lead-titanium-trioxide [12060-00-3], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Decamethylcyclopentasiloxane [541-02-6], Dodecamethylcyclohexasiloxane [540-97-6], TBBA [79-94-7], Lead titanium zirconium oxide [12626-81-2], Octamethylcyclotetrasiloxane [556-67-2], Silicic acid, lead salt [11120-22-2]
Electric Power Supply / Instruments - [cleaner]	WIPER ARM, REAR WIPER MOTOR, WASHER FLUID RESERVOIR, WIPER APPARATUS, WIPER ARM DS, WIPER ARM PS, PUMP, DUAL PUMP	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Cobalt(II) nitrate hexahydrate [10026-22-9], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2]
Power Transmission - [electrical axis drive]	CABLE HARNESS, REAR AXLE, TRANSMISSION HOUSE, PLUG, PLANET CARRIER	Lead [7439-92-1], Sodium borate, pentahydrate [12179-04-3], Tris(nonylphenyl)phosphite [26523-78-4], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8]
Body, Interior / Exterior - [recovery / towing unit]	TOWING HOOK, TRM, HARNESS	TBBA [79-94-7], Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3]

Power Transmission - [gear lever carrier / gear selector controls]	GEAR LEVER CARRIER, BRACKET, GEAR LEVER KNOB, GEAR SHIFT CABLE, INSERT, HOUSING, ACTUATOR	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1], 4,4'-Isopropylidenediphenol [80-05-7], Lead-titanium-trioxide [12060-00-3], Lead titanium zirconium oxide [12626-81-2], TBBA [79-94-7]
Electric Power Supply / Instruments - [automatic monitoring / control]	SIREN, RAIN SENSOR, CONTROL UNIT, REMOTE KEY, TRM, SENSOR	Lead-monoxide [1317-36-8], Lead [7439-92-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Diboron-trioxide [1303-86-2], Lead(II,IV)-oxide [1314-41-6], Lead titanium zirconium oxide [12626-81-2], 1,2-Dimethoxyethane [110-71-4], Lead-titanium-trioxide [12060-00-3], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], TBBA [79-94-7]
Electric Power Supply / Instruments - [antenna]	BLUETOOTH ANTENNA, ANTENNA AMPLIFIER, MAM ANTENNA MODULE, ANTENNA, ETC ON BOARD UNIT, ETC MODULE	Lead [7439-92-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], Lead titanium zirconium oxide [12626-81-2], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 1-Propanol, 2,3-dibromo- [96-13-9], Melamine [108-78-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1]
Brake - [brake line with connections]	BRAKE PIPE, BRAKE PIPE FRONT, BRAKE HOSE, BRAKE PIPE REAR	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
Engine - [engine / engine mounting]	ENGINE MOUNT, TORQUE ROD, TORQUE LINK BRACKET, ENGINE BRACKET, FRONT AXLE, ELECTRIC MOTOR, REAR AXLE, INNER HOUSING, OUTER HOUSING, BRACKET, O-RING, STRAIN RELIEF, CABLE HARNESS	Lead [7439-92-1], Lead-monoxide [1317-36-8], N,N-Dimethylacetamide [127-19-5], Decamethylcyclotrasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Cobalt-dichloride [7646-79-9], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
Body, Interior / Exterior - [bonnet / cover with assembly parts]	HOOD LOCK, HOOD LOCK CONTROL, HOOD RELEASE CABLE, COVER	Lead [7439-92-1], Imidazolidine-2-thione [96-45-7]
Body, Interior / Exterior - [side door]	SIDE DOOR, CARRIER PLATE, WINDOW LIFT	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Engine - [intercooler / connection]	CHARGE AIR PIPE, CHARGE AIR COOLER, CHARGE AIR HOSE, RESONATOR	Lead [7439-92-1], Boric acid [10043-35-3]
Electric Power Supply / Instruments - [vehicle computational units / gateway modules]	CONTROL UNIT	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8]

Power Transmission - [gearbox]	TORQUE CONVERTER, GEARBOX, SPACER, AUTOMATIC GEARBOX, CONTROL UNIT, VALVE BODY, CABLE HARNESS, CONNECTOR, SERVO COVER, CONTROL SYSTEM, OIL PUMP, ADAPTER, FLANGE NUT, DIFFERENTIAL SPACER, LID, FLANGE SCREW, TEMPERATURE SENSOR	Lead [7439-92-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], Dioctyltin dilaurate [3648-18-8], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], Nonylphenol [25154-52-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7], 1-Methyl-2-pyrrolidone [872-50-4], Lead-titanium-trioxide [12060-00-3], Cobalt-dinitrate [10141-05-6], Cobalt-dichloride [7646-79-9], 2-Methylimidazole [693-98-1], Silicic acid, lead salt [11120-22-2]
Electric Power Supply / Instruments - [cable system]	CABLE, CABLE HARNESS, CABLE HARNESS WEM, CABLE FLOOR, CABLE DUCT, EJB, FLANGE NUT, FUSE BOX, FUSE BOX ASSY, BRACKET, CABLE PAC, CABLE TELE, CABLE INFOTAINMENT, PRINTED CIRCUIT BOARD	Lead [7439-92-1], TBBA [79-94-7], Tris(nonylphenyl)phosphite [26523-78-4], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Cobalt-dinitrate [10141-05-6], Paraffin oils, chloro [85422-92-0], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Dicyclohexyl-phthalate [84-61-7], 4,4'-Isopropylidenediphenol [80-05-7]
Body, Interior / Exterior - [floor / frame section / wheel housing / firewall]	WHEEL HOUSING, FRONT SIDE MEMBER, ADHESIVE, TOP COVER, REINFORCEMENT, TOP COVER PANEL REAR, BATTERY BOX, FLOOR PANEL	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Electric Power Supply / Instruments - [mobile data services]	CONTROL UNIT, BOX	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methylimidazole [693-98-1], Melamine [108-78-1]
Electric Power Supply / Instruments - [electric drive system]	VOLTAGE CONVERTER, INVERTER IEM, STARTER MOTOR ALTERNATOR, ONBOARD CHARGER, INVERTER IGM, PROTECTION HIGH VOLTAGE, BRACKET, COOLANT PIPE, SENSOR, STARTER MOTOR, INVERTER, FLANGE SCREW	Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], Lead titanium zirconium oxide [12626-81-2], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Dicyclohexyl-phthalate [84-61-7], 4,4'-Isopropylidenediphenol [80-05-7], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Alkanes, C14-17, chloro [85535-85-9], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], N,N-Dimethylacetamide [127-19-5], Cobalt-dichloride [7646-79-9]
Body, Interior / Exterior - [roof]	PANORAMA ROOF, GLASS PANEL, WELD SEALANT CURING, ADHESIVE ROOF HATCH, MOTOR	Lead [7439-92-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Tris(nonylphenyl)phosphite [26523-78-4], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], C,C'-azodi(formamide) [123-77-3], Lead-monoxide [1317-36-8]

Electric Power Supply / Instruments - [communication, mobile telephone]	CONTROL UNIT, WIRELESS CHARGE SYSTEM, BATTERY, PRINTED CIRCUIT BOARD	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Electric Power Supply / Instruments - [alternator]	ALTERNATOR 210A, REGULATOR LIN	Lead [7439-92-1], TBBA [79-94-7]
Body, Interior / Exterior - [exterior equipment]	SPOILER, ACTIVE GRILLE SHUTTER, ACTIVE SPOILER SHUTTER	Lead [7439-92-1], C,C'-azodi(formamide) [123-77-3], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [seat belt / other restraining systems]	HEIGHT ADJUSTMENT, BELT CATCH, BELT, BELT CATCH REAR, SEAT BELT	Lead [7439-92-1], TBBA [79-94-7], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt-dinitrate [10141-05-6], Cobalt(II) nitrate hexahydrate [10026-22-9], Lead-monoxide [1317-36-8]
Body, Interior / Exterior - [miscellaneous]	ABSORBER, TRANSPORT PROTECTION, SEALANT REPAIR, SOUND INSULATION	Tris(nonylphenyl)phosphite [26523-78-4], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Dibutylbis(pentane-2,4-dionato-O,O')tin [22673-19-4], Diboron-trioxide [1303-86-2]
Wheel Suspension / Steering - [axle member / link arm / suspension]	LOWER LINK ARM, UPPER LINK ARM, BALL JOINT	Imidazolidine-2-thione [96-45-7]
Body, Interior / Exterior - [trunk lid / tailgate complete]	TAILGATE, SPINDLE DRIVE, ANTIFLUTTER	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Engine - [emission equipment]	COOLER, ALUMINIUM, LAMBDA SOND, STAY, PRESSURE SENSOR, VALVE, TEMPERATURE SENSOR EGT, TEMPERATURE SENSOR	Lead [7439-92-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Lead-monoxide [1317-36-8], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
Electric Power Supply / Instruments - [infotainment system]	CONTROL UNIT, USB HUB, GRAPHIC HEAD UP DISPLAY, DISPLAY, PRINTED CIRCUIT BOARD, TV TUNER	Lead-monoxide [1317-36-8], Lead [7439-92-1], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 4,4'-Isopropylidenediphenol [80-05-7], Diboron-trioxide [1303-86-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], TBBA [79-94-7], Melamine [108-78-1], Lead-titanium-trioxide [12060-00-3], 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonfluoro-, potassium salt (1:1) [29420-49-3], Boric acid [10043-35-3], Lead titanium zirconium oxide [12626-81-2]
Brake - [wheel brake]	BRAKE CALIPER, HOUSING, AIR VENTING NIPPLE, EPB, BRAKE LINING, BLEEDER VALVE, BRAKE DISC	Lead [7439-92-1], 2-Methylimidazole [693-98-1], Tris(nonylphenyl)phosphite [26523-78-4], Hexahydromethylphthalic-anhydride [25550-51-0], Dicyclohexyl-phthalate [84-61-7]
Body, Interior / Exterior - [instrument / radio panel]	INSTRUMENT PANEL, LAMP LED, CONCEALING PANEL, HINGE PIN, GLOVE BOX	Lead [7439-92-1], TBBA [79-94-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2]

Electric Power Supply / Instruments - [protection]	SENSOR REAR, SENSOR FRONT	Lead [7439-92-1], TBBA [79-94-7]
Body, Interior / Exterior - [airbag]	CONTROL UNIT SRS, AIRBAG MODULE, CONTROL UNIT, INFLATABLE CURTAIN	Lead-monoxide [1317-36-8], Lead [7439-92-1], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9]
Electric Power Supply / Instruments - [electrical distribution box / fuse box]	CEM, ATTACHMENT	Lead-monoxide [1317-36-8], Lead [7439-92-1], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [instruction / information plates]	DECAL SRS, NUMBER PLATE HOLDER, SIX POINT SOCKET SCREW	2-ethylhexyl 10-ethyl-4,4-dioctyl-7-oxo-8-oxa-3,5-dithia-4-stannatetradecanoate [15571-58-1], Imidazolidine-2-thione [96-45-7], 1-Methyl-2-pyrrolidone [872-50-4]
Power Transmission - [actuator, gear shift]	CONTROL UNIT	Lead [7439-92-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], Silicic acid, lead salt [11120-22-2], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [body side]	WELD SEALANT CURING, ADHESIVE, REINFORCEMENT	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [rim]	KEY, WHEEL BOLT, WHEEL, ADHESIVE BALANCE WEIGHT	Lead [7439-92-1], 2-Methylimidazole [693-98-1], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [hood cover]	ANTIFLUTTER, HOOD, HINGE RELEASER	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1], Diboron-trioxide [1303-86-2]
Brake - [brake control]	SENSOR, PEDAL UNIT	Lead [7439-92-1]
Frame / Springs / Damping / Wheels - [anti-roll bar]	LINK ANTI-ROLL BAR, ANTI-ROLL BAR FRONT, ANTI-ROLL BAR REAR	Imidazolidine-2-thione [96-45-7], 2-Methylimidazole [693-98-1]
Electric Power Supply / Instruments - [starting system]	STARTER MOTOR	Lead [7439-92-1], Ethylenediamine [107-15-3], Diboron-trioxide [1303-86-2]
Electric Power Supply / Instruments - [cable components]	RECEPTACLE HOUSING, CABLE DUCT	Lead [7439-92-1]
Brake - [master cylinder / brake booster]	SHELL, BRAKE FLUID RESERVOIR, ACTUATION UNIT, MASTER CYLINDER	Lead [7439-92-1], TBBA [79-94-7]
Engine - [miscellaneous / help device installation]	BRACKET, SPLASH PROTECTION, TENSIONER, GUIDE SLEEVE	Lead [7439-92-1]
Body, Interior / Exterior - [tool / jack]	JACK	Ethylenediamine [107-15-3]

Power Transmission - [final drive]	BRACKET, PT-UNIT	Lead [7439-92-1]
Engine - [accelerator control]	ACCELERATOR PEDAL	Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-monoxide [1317-36-8]
Body, Interior / Exterior - [tank hatch]	PLASTIC MODULE	Lead [7439-92-1], TBBA [79-94-7]
Body, Interior / Exterior - [protective shields / flaps]	HEAT SHIELD PLATE	C,C'-azodi(formamide) [123-77-3]
Engine - [cold zone / batterybox]	NVH PANEL	Lead [7439-92-1]
Engine - [supercharging]	SLEEVE, PIPE COMPRESSOR, TURBO CHARGER, OIL DRAINING PIPE, COMPRESSOR, O-RING, STAY COMPRESSOR, SUPERCHARGER, THROTTLE, VACUUM RESERVOIR, VACUUM REGULATOR, BYPASS HOUSING, COMPRESSOR PIPE, BRACKET, MP TURBO, INLET PIPE	Lead [7439-92-1], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], N,N-Dimethylacetamide [127-19-5], Melamine [108-78-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Lead-monoxide [1317-36-8], Dicyclohexyl-phthalate [84-61-7]
Engine - [transmission]	TENSIONER, CAMSHAFT, IDLER PULLEY, HOUSING, SOLENOID, GASKET, BALANCE SHAFT, BELT PROTECTOR, BELT COVER, VVT ACTUATOR, SLEEVE	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Engine - [lubricating and oil system]	OIL SUMP, SUCTION LINE, OIL PUMP, PISTON COOLING JET, GASKET, VALVE, INLET PIPE, PISTON COOLING VALVE, WINDAGE TRAY, OIL LEVEL SENSOR, OIL FILTER, PLUG, OIL PRESSURE SENSOR	Lead [7439-92-1], Bis(4-chlorophenyl) sulfon [80-07-9], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7], Diboron-trioxide [1303-86-2]
Engine - [cylinder block / head]	CYLINDER HEAD, BEDPLATE, ENGINE BRACKET, VACUUM PUMP, CYLINDER BLOCK, TOP COVER, GUIDE SLEEVE, BEARING HOUSE CAM SHAFT, CAP, CAM SHAFT COVER, PROTECTING CASING, CAMSHAFT CAP, HOUSING, CAM SHAFT HOUSING, LOCATING PIN	Lead [7439-92-1]
Engine - [distributor]	CRANKSHAFT POS SENSOR, CAMSHAFT POSITION SENSOR, BRACKET, KNOCK SENSOR	Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2]
Engine - [crank mechanism]	DUAL MASS FLYWHEEL, NIPPLE, NON-RETURN VALVE	Lead [7439-92-1]
Engine - [ignition / spark plug]	GLOW PLUG, IGNITION COIL, SPARK PLUG, CONTROL UNIT	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8]