

**XC60 MODEL YEAR 2024  
Candidate List Substances Table**

We hereby inform that almost all product areas contain lead (CAS No 7439-92-1), primarily as alloying elements in steel, aluminium and copper.

Released: 2023 week 41.

Localisation	Partnames	Substance/s
Body, Interior / Exterior - [interior equipment]	JALUSIE, ARM REST, CUP HOLDER, EC REAR VIEW MIRROR, DAMPER, LIGHTING, HINGE, LED MODULE	C,C'-azodi(formamide) [123-77-3], TBBA [79-94-7], Tris(nonylphenyl)phosphite [26523-78-4], Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Cobalt sulphate [10124-43-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7]
Engine - [cooling system]	PUMP, HOSE COLD ZONE, TWO-WAY VALVE, VALVE, HOSE TEMP SENSOR, HOSE OUTLET, HOSE MODULE, TWIN CLIP, WATER PUMP, COOLER, CONDENSER, SET, RADIATOR HYBRID, HOSE, EL WATER PUMP, COMPLETE COOLER, PRESSURE SENSOR, TEMPERATURE SENSOR, RADIATOR, CHARGE AIR COOLER, SEPARATOR, BRACKET, THREE-WAY VALVE, CLAMP BRACKET, RETAINER, HEATER HOSE, PIPE, HOSE HEATER, HOSE INLET, OUTLET HOSE, THERMOSTAT HOUSING, O-RING, NIPPLE, PLASTIC PIPE, GASKET, INLET PIPE, COVER, SIX POINT SOCKET SCREW, MODULE WATER PUMP, BRACKET TEMP SENSOR, STRIKER PLATE	TBBA [79-94-7], Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], 1-Methyl-2-pyrrolidone [872-50-4], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Decamethylcyclopentasiloxane [541-02-6], Melamine [108-78-1], Silicic acid, lead salt [11120-22-2], 4,4'-Isopropylidenediphenol [80-05-7], Octamethylcyclotetrasiloxane [556-67-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead(II,IV)-oxide [1314-41-6], C,C'-azodi(formamide) [123-77-3]
Body, Interior / Exterior - [air conditioning]	EL COMPRESSOR, CLIMATE UNIT, PIPE ASSEMBLY, FUEL OPERATED HEATER, IONIZER, SUN SENSOR, SENSOR, ELECTRIC HEATER, PROTECTIVE CAP, HUMIDITY SENSOR, SENSOR KIT, DEFROSTER, STEPPING MOTOR, FAN, EXPANSION VALVE, CHILLER, CONTROL UNIT, SOLENOID CLUTCH, AC-COMPRESSOR, FLANGE SCREW, AIR CLEANER, AIR INLET, VALVE, VALVE CAP, CONTROL VALVE, CHANNEL SENSOR, SENSOR INTERIOR, FUEL PUMP	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], TBBA [79-94-7], 2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol [3864-99-1], Refractory ceramic fibres [142844-00-6], 2-Methylimidazole [693-98-1], Lead-titanium-trioxide [12060-00-3], 1-Propanol, 2,3-dibromo- [96-13-9], Tris(nonylphenyl)phosphite [26523-78-4], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8], Melamine [108-78-1], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Cobalt(II) nitrate hexahydrate [10026-22-9], Cobalt-dichloride [7646-79-9], Octamethylcyclotetrasiloxane [556-67-2]
Body, Interior / Exterior - [front fender]	SENSOR, SHIM, EXT743, ANTIFLUTTER, FRONT FENDER	Lead-monoxide [1317-36-8], Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]

Electric Power Supply / Instruments - [support systems]	SENSOR, CONTROL UNIT, CAMERA, BOX, RADAR, EXT743	Lead-monoxide [1317-36-8], Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Diboron-trioxide [1303-86-2], 2-Methylimidazole [693-98-1], TBBA [79-94-7], Dicyclohexyl-phthalate [84-61-7], Lead-titanium-trioxide [12060-00-3], Decamethylcyclotetrasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Lead titanium zirconium oxide [12626-81-2], 1-Propanol, 2,3-dibromo- [96-13-9]
Frame / Springs / Damping / Wheels - [shock absorber]	SHOCK ABSORBER FRONT, SHOCK ABSORBER, SHOCK ABSORBER REAR, TOPMOUNT	Lead [7439-92-1], Diboron-trioxide [1303-86-2]
Electric Power Supply / Instruments - [battery and mounting parts]	BATTERY, BMS, CURRENT SENSOR, FILTER BOARD ASSY, MODULE, SWITCH, CONTROL UNIT, 48V BATTERY, COVER, HEAT INSULATION PAD, SERVICE SWITCH, INLET HOSE, OUTLET HOSE, FILTER BOARD, HEAT SHIELD	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead titanium zirconium oxide [12626-81-2], 1,3-Propanesultone [1120-71-4], Bis(2-(2-methoxyethoxy)ethyl)ether [143-24-8], Melamine [108-78-1], Boric acid [10043-35-3], Octamethylcyclotetrasiloxane [556-67-2], 1-Propanol, 2,3-dibromo- [96-13-9], Lead-titanium-trioxide [12060-00-3], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1]
Body, Interior / Exterior - [lock / handle]	DOOR LOCK, LOCK WITH ANTI THEFT COVE, LOCK, OUTER HANDLE, CAMERA, HANDLE, LOCK CYLINDER SET, KEY, BRACKET OUTER HANDLE, LOCK CYLINDER, WIRE	Lead [7439-92-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-Methylimidazole [693-98-1], Dicyclohexyl-phthalate [84-61-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Melamine [108-78-1], Lead titanium zirconium oxide [12626-81-2], Hexahydromethylphthalic-anhydride [25550-51-0], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], 2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)phenol [3864-99-1]
Wheel Suspension / Steering [steering gear / wheel / shaft / column]	STEERING WHEEL, STEERING WHEEL RIM, STEERING COLUMN LOCK, STEERING COLUMN, STEERING GEAR, STEERING WHEEL HARNESS	Dicyclohexyl-phthalate [84-61-7], Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], TBBA [79-94-7], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [upholstery]	DOOR PANEL, SIDE PANEL, LAMP LED	C,C'-azodi(formamide) [123-77-3], TBBA [79-94-7], N,N-Dimethylacetamide [127-19-5]
Electric Power Supply / Instruments - [radio equipment]	MICROPHONE, LOUDSPEAKER, SPEAKER MIDRANGE, AUDIO MODULE, SOUND MODULE, BRACKET, WOOFER, SUBWOOFER, CENTRE LOUDSPEAKER	Diboron-trioxide [1303-86-2], Lead [7439-92-1], N,N-Dimethylacetamide [127-19-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], Melamine [108-78-1], TBBA [79-94-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Cobalt(II) nitrate hexahydrate [10026-22-9]

Engine - [fan]	FAN, FAN LOW	1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Lead [7439-92-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Boric acid [10043-35-3]
Body, Interior / Exterior - [seats]	FRAMEWORK, HEAD RESTRAINT, UPHOLSTERY, HARDBACK, UNDERCARRIAGE, ARM REST, ENGINE TILT, ENGINE, HEATING PAD SEAT, VENTILATION, LUMBAR SUPPORT, STS SENSOR, MASSAGE UNIT, BACKREST FRAME, TEXTILE, WHITE, VINYL, CUP HOLDER, HEATER, CABLE HARNESS, SIX POINT SOCKET SCREW, FRAME, FAN, LUMBAR SUPPORT 4-WAY, SIDE BOLSTER, HARNESS	Paraffin oils, chloro [85422-92-0], C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Glutaral [111-30-8], N,N-Dimethylacetamide [127-19-5], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], TBBA [79-94-7], Melamine [108-78-1], Boric acid [10043-35-3], Imidazolidine-2-thione [96-45-7], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], Diboron-trioxide [1303-86-2], 1-Methyl-2-pyrrolidone [872-50-4], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3]
Power Transmission - [electrical axis drive]	DRIVE SHAFT, CABLE HARNESS, EMC ASSEMBLY, REAR AXLE, TRANSMISSION HOUSE, PLUG, PLANET CARRIER	Lead [7439-92-1], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Sodium borate, pentahydrate [12179-04-3], Tris(nonylphenyl)phosphite [26523-78-4], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2]
Power Transmission - [front axle / rear axle / drive shaft]	DRIVE SHAFT, AOC, PUMP UNIT, CABLE HARNESS, EMC ASSEMBLY, REAR AXLE, BRACKET, FEEDER PUMP KIT, VIBRATION DAMPER, FINAL DRIVE, BEARING ANCHORAGE, FLANGE SCREW	Lead [7439-92-1], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Melamine [108-78-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Sodium borate, pentahydrate [12179-04-3], Tris(nonylphenyl)phosphite [26523-78-4], Lead-monoxide [1317-36-8], Cobalt-dichloride [7646-79-9]
Engine - [air cleaner]	FRESH AIR PIPE, BOX, RESONATOR, HOSE MODULE	Lead [7439-92-1]
Engine - [fuel / EVAP system]	PURGE VALVE ASSY, FUEL PUMP MODULE, PUMP MODULE, JET PUMP AND LEVEL SENSOR, EVAP PURGE PUMP, PURGE VALVE, LEAK DETECTION PUMP, ISOLATION VALVE, CANISTER, FUEL PRESSURE SENSOR, HOSE, FUEL FILTER, FUEL TANK, TANK WELDED, HIGH PRESSURE PUMP, FUEL DISTRIBUTION PIPE, INJECTOR, FUEL PUMP, DELIVERY PIPE, INJECTION VALVE	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Melamine [108-78-1], TBBA [79-94-7], 6,6'-Di-tert-butyl-2,2'-methylene-di-p-cresol [119-47-1], Cobalt-dinitrate [10141-05-6]
Brake - [wheel brake]	BRAKE CALIPER, HOUSING, AIR VENTING NIPPLE, EPB, BLEEDER VALVE, BRAKE LINING	Decamethylcyclopentasiloxane [541-02-6], Lead [7439-92-1], 2-Methylimidazole [693-98-1], Tris(nonylphenyl)phosphite [26523-78-4], Hexahydromethylphthalic-anhydride [25550-51-0], Dicyclohexyl-phthalate [84-61-7]

Electric Power Supply / Instruments - [vehicle control system]	SWITCH PANEL, STALK MODULE, CONTROL UNIT DOOR, LOCK BUTTON, SWITCH, BUTTON, ECU, HARDWARE, LOCK BUTTON LED, COMBI INSTRUMENT, CUT-OFF SWITCH, USB POWER OUTLET, SWITCH MODULE, GEAR SHIFT PADDLE, CONTROL PANEL POWER SEAT, SWITCH DOOR, SWITCH WINDOW LIFT, SWITCH STEERING WHEEL	Lead [7439-92-1], TBBA [79-94-7], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], 4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride [19438-60-9], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Boric acid [10043-35-3], 4,4'-Isopropylidenediphenol [80-05-7], Lead-titanium-trioxide [12060-00-3]
Engine - [control systems]	TEMP AND PRESSURE SENSOR, AIR TEMP SENSOR, CONTROL UNIT, MASS AIR FLOW SENSOR, PRESSURE SENSOR	Lead [7439-92-1], Hexahydromethylphthalic-anhydride [25550-51-0], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Silicic acid, lead salt [11120-22-2], Dicyclohexyl-phthalate [84-61-7], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3]
Electric Power Supply / Instruments - [cable system high voltage]	STRAIN RELIEF, CABLE CHARGE POINT HV, CABLE HARNESS, BRACKET, CABLE DUCT, CHARGE CABLE CORD, CABLE CHANNEL, CHARGE CABLE	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], TBBA [79-94-7], Octamethylcyclotetrasiloxane [556-67-2], Melamine [108-78-1]
Electric Power Supply / Instruments - [cable components]	STRAIN RELIEF, CABLE DUCT, FUSE BOX, RECEPTACLE HOUSING, UNLOADING CABLE, PRINTED CIRCUIT BOARD, EJB, DISCONNECTOR POWER, CABLE, CABLE CHANNEL, BATTERY TERMINAL, FUSE BOX ASSY, SPLICE, FUSE BOX REAR, RETAINER, CHANNEL, AIR HOSE	Lead [7439-92-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Octamethylcyclotetrasiloxane [556-67-2]
Brake - [brake, anti lock (anti-skid)]	HYDRAULIC UNIT, SENSOR	Lead [7439-92-1], Lead titanium zirconium oxide [12626-81-2], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
Electric Power Supply / Instruments - [lighting]	CONTROL UNIT HCM, REAR LAMP, HEADLAMP, OVERHEAD CONSOLE LENS, READING LAMP, FOG LIGHT, LIGHTING, STOP LAMP, LAMP LED, LED MODULE	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Melamine [108-78-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Octamethylcyclotetrasiloxane [556-67-2], Dicyclohexyl-phthalate [84-61-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-titanium-trioxide [12060-00-3], 1-Propanol, 2,3-dibromo- [96-13-9]
Electric Power Supply / Instruments - [cleaner]	WIPER ARM AND BLADE DS, WIPER ARM AND BLADE PS, WIPER ARM AND BLADE, REAR WIPER MOTOR, WIPER APPARATUS, WASHER FLUID RESERVOIR, WIPER ARM DS, WIPER ARM PS, PUMP, DUAL PUMP	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Cobalt(II) nitrate hexahydrate [10026-22-9], Lead titanium zirconium oxide [12626-81-2]
Engine - [selective catalytic reduction]	CONTROL UNIT, PUMP MODULE, SENSOR, BRACKET, TANK, CONTROL MODULE	Lead [7439-92-1], Nonylphenol [25154-52-3], Lead-titanium-trioxide [12060-00-3], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Decamethylcyclopentasiloxane [541-02-6], Dodecamethylcyclohexasiloxane [540-97-6], TBBA [79-94-7], Lead titanium zirconium oxide [12626-81-2], Octamethylcyclotetrasiloxane [556-67-2], Silicic acid, lead salt [11120-22-2]

Electric Power Supply / Instruments - [cable system]	CABLE HARNESS, CABLE, CABLE FLOOR, CABLE HARNESS WEM, CABLE HARNESS BUMPER, CABLE HARNESS TAILGATE, FUSE BOX, CABLE DUCT, EJB, FLANGE NUT, FUSE BOX ASSY, PRINTED CIRCUIT BOARD, CABLE AUDIO, CABLE LOCKING DEVICE, CABLE PAC, CABLE INFOTAINMENT	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], TBBA [79-94-7], Dicyclohexyl-phthalate [84-61-7], Cobalt-dinitrate [10141-05-6], Paraffin oils, chloro [85422-92-0], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], 4,4'-Isopropylidenediphenol [80-05-7]
Electric Power Supply / Instruments - [automatic monitoring / control]	SIREN, RAIN SENSOR, CONTROL UNIT, REMOTE KEY, TRM, SENSOR	Lead-monoxide [1317-36-8], Lead [7439-92-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Diboron-trioxide [1303-86-2], Lead(II,IV)-oxide [1314-41-6], Lead titanium zirconium oxide [12626-81-2], 1,2-Dimethoxyethane [110-71-4], Lead-titanium-trioxide [12060-00-3], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], TBBA [79-94-7]
Power Transmission - [gear lever carrier / gear selector controls]	GEAR LEVER CARRIER, BRACKET, GEAR LEVER KNOB, INSERT, HOUSING, ACTUATOR	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1], 4,4'-Isopropylidenediphenol [80-05-7], Lead-titanium-trioxide [12060-00-3], Lead titanium zirconium oxide [12626-81-2], TBBA [79-94-7]
Body, Interior / Exterior - [glass, window / windscreen / roof]	QUARTER GLASS LAMINATED, REAR SCREEN, WINDSCREEN, GLASS HARDENED, GLASS LAMINATED, QUARTER GLASS HARDENED	Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Brake - [brake line with connections]	BRAKE PIPE, BRAKE PIPE FRONT, BRAKE PIPE REAR, BRAKE HOSE	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Engine - [engine / engine mounting]	ENGINE MOUNT, TORQUE ROD, TORQUE LINK BRACKET, ENGINE BRACKET, FRONT AXLE, ELECTRIC MOTOR, REAR AXLE, INNER HOUSING, OUTER HOUSING, BRACKET, O-RING, STRAIN RELIEF, CABLE HARNESS	Lead [7439-92-1], Lead-monoxide [1317-36-8], N,N-Dimethylacetamide [127-19-5], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Cobalt-dichloride [7646-79-9], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
Body, Interior / Exterior - [floor / frame section / wheel housing / firewall]	WHEEL HOUSING, FRONT SIDE MEMBER, ADHESIVE, TOP COVER, BRACE OUTER, BRACE, SIDE MEMBER, FLOOR PANEL, BACK PANEL, SIDE MEMBER UPPER INNER, BATTERY BOX	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Body, Interior / Exterior - [bonnet / cover with assembly parts]	HOOD LOCK, COVER, HOOD RELEASE CABLE, FOAM, HOOD LOCK CONTROL	Lead [7439-92-1], Imidazolidine-2-thione [96-45-7], C,C'-azodi(formamide) [123-77-3]
Electric Power Supply / Instruments - [vehicle computational units / gateway modules]	CONTROL UNIT	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8]

Power Transmission - [gearbox]	TORQUE CONVERTER, AUTOMATIC GEARBOX, CONTROL UNIT, VALVE BODY, CABLE HARNESS, CONNECTOR, SERVO COVER, CONTROL SYSTEM, OIL PUMP, ADAPTER, FLANGE NUT, DIFFERENTIAL SPACER, LID, FLANGE SCREW	Lead [7439-92-1], Lead-monoxide [1317-36-8], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], Diboron-trioxide [1303-86-2], Nonylphenol [25154-52-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7], 1-Methyl-2-pyrrolidone [872-50-4], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3], Cobalt-dinitrate [10141-05-6], Cobalt-dichloride [7646-79-9], Silicic acid, lead salt [11120-22-2]
Body, Interior / Exterior - [side door]	BODY MOUNTED SEALING, DOOR MOUNTED SEALING, SPLITLINE SEAL, WINDOW LIFT, CARRIER PLATE, SIDE DOOR, HEMMING ADHESIVE	C,C'-azodi(formamide) [123-77-3], Imidazolidine-2-thione [96-45-7], Dodecamethylcyclohexasiloxane [540-97-6], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Body, Interior / Exterior - [recovery / towing unit]	TOWING HOOK, TRM, HARNESS	Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7]
Engine - [inlet / exhaust systems]	EXHAUST SYSTEM, TAILPIPE, THROTTLE, HEAT SHIELD PLATE, INTAKE MANIFOLD	Lead-monoxide [1317-36-8], Lead [7439-92-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], 4,4'-Isopropylidenediphenol [80-05-7], Boric acid [10043-35-3], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
Electric Power Supply / Instruments - [mobile data services]	CONTROL UNIT	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1]
Body, Interior / Exterior - [trunk lid / tailgate complete]	SPINDLE DRIVE, REAR DOOR	Lead [7439-92-1]
Electric Power Supply / Instruments - [electric drive system]	VOLTAGE CONVERTER, INVERTER IEM, STARTER MOTOR ALTERNATOR, ONBOARD CHARGER, INVERTER IGM, CHARGE POINT, PROTECTION HIGH VOLTAGE, BRACKET, COOLANT PIPE, SENSOR, STARTER MOTOR, INVERTER, FLANGE SCREW	Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], Lead titanium zirconium oxide [12626-81-2], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Dicyclohexylphthalate [84-61-7], 4,4'-Isopropylidenediphenol [80-05-7], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Alkanes, C14-17, chloro [85535-85-9], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], N,N-Dimethylacetamide [127-19-5], Cobalt-dichloride [7646-79-9]
Body, Interior / Exterior - [roof]	PANORAMA ROOF, GLASS PANEL, ROOF HATCH, ADHESIVE ROOF HATCH, ADHESIVE, MOTOR, SEALING, SEALING STRIP	Lead [7439-92-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Tris(nonylphenyl)phosphite [26523-78-4], C,C'-azodi(formamide) [123-77-3], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead-monoxide [1317-36-8]

Electric Power Supply / Instruments - [communication, mobile telephone]	CONTROL UNIT, WIRELESS CHARGE SYSTEM, BATTERY, ANTENNA, BACK-UP BATTERY, AUXILIARY TELEMATIC, PRINTED CIRCUIT BOARD	Lead [7439-92-1], Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], N,N-Dimethylacetamide [127-19-5], Dioctyltin dilaurate [3648-18-8]
Body, Interior / Exterior - [seat belt / other restraining systems]	HEIGHT ADJUSTMENT, BELT CATCH, BELT, SEAT BELT	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt(II) nitrate hexahydrate [10026-22-9], Cobalt-dinitrate [10141-05-6], TBBA [79-94-7], Lead-monoxide [1317-36-8], Cobalt sulphate [10124-43-3]
Wheel Suspension / Steering - [axle member / link arm / suspension]	LOWER LINK ARM, SUBFRAME FRONT, UPPER LINK ARM	Imidazolidine-2-thione [96-45-7], Cobalt-dichloride [7646-79-9], Lead [7439-92-1]
Engine - [emission equipment]	COOLER, PRESSURE SENSOR, ALUMINIUM, LAMBDA SOND, STAY, VALVE, TEMPERATURE SENSOR EGT, TEMPERATURE SENSOR	Lead [7439-92-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Lead-monoxide [1317-36-8], Melamine [108-78-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
Engine - [intercooler / connection]	CHARGE AIR COOLER, CHARGE AIR PIPE, CHARGE AIR HOSE, RESONATOR	Lead [7439-92-1], Boric acid [10043-35-3]
Electric Power Supply / Instruments - [infotainment system]	CONTROL UNIT, GRAPHIC HEAD UP DISPLAY, USB HUB, DISPLAY, PRINTED CIRCUIT BOARD	Lead-monoxide [1317-36-8], Lead [7439-92-1], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 4,4'-Isopropylidenediphenol [80-05-7], Diboron-trioxide [1303-86-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], TBBA [79-94-7], Melamine [108-78-1], Lead-titanium-trioxide [12060-00-3], 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonfluoro-, potassium salt (1:1) [29420-49-3], Boric acid [10043-35-3], Lead titanium zirconium oxide [12626-81-2]
Body, Interior / Exterior - [tank hatch]	PLASTIC MODULE	Lead [7439-92-1], TBBA [79-94-7]
Body, Interior / Exterior - [exterior equipment]	ACTIVE GRILLE SHUTTER, ACTIVE SPOILER SHUTTER	Diboron-trioxide [1303-86-2], Lead [7439-92-1]
Body, Interior / Exterior - [outside mirrors]	REAR VIEW MIRROR OUTER, CAMERA, REAR VIEW MIRROR, MOTOR UNIT, DIRECTION INDICATOR, TEMPERATURE SENSOR, GLASS, REAR VIEW MIRROR CASING	Lead [7439-92-1], Lead-monoxide [1317-36-8], Octamethylcyclotetrasiloxane [556-67-2], Diboron-trioxide [1303-86-2], Dicyclohexyl-phthalate [84-61-7], Tris(nonylphenyl)phosphite [26523-78-4], 2-Methylimidazole [693-98-1], TBBA [79-94-7], Phenol, dimethyl-, phosphate (3:1) [25155-23-1], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Lead titanium zirconium oxide [12626-81-2], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], 4,4'-Isopropylidenediphenol [80-05-7], Melamine [108-78-1]

Body, Interior / Exterior - [hood cover]	HOOD, ANTIFLUTTER	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
Electric Power Supply / Instruments - [protection]	SENSOR REAR, CONTROL UNIT, SENSOR FRONT, ACCELEROMETER, ACCELEROMETER FRONT	Lead [7439-92-1], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], TBBA [79-94-7]
Body, Interior / Exterior - [airbag]	AIRBAG MODULE, CONTROL UNIT, ACCELEROMETER SENSOR, INFLATABLE CURTAIN	4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7], Lead-monoxide [1317-36-8]
Electric Power Supply / Instruments - [electrical distribution box / fuse box]	CEM, ATTACHMENT	Lead-monoxide [1317-36-8], Lead [7439-92-1], Diboron-trioxide [1303-86-2]
Body, Interior / Exterior - [instruction / information plates]	DECAL SRS, NUMBER PLATE HOLDER, SIX POINT SOCKET SCREW	2-ethylhexyl 10-ethyl-4,4-dioctyl-7-oxo-8-oxa-3,5-dithia-4-stannatetradecanoate [15571-58-1], Imidazolidine-2-thione [96-45-7], 1-Methyl-2-pyrrolidone [872-50-4]
Body, Interior / Exterior - [outside / exterior trim]	GRILLE	C,C'-azodi(formamide) [123-77-3]
Power Transmission - [actuator, gear shift]	CONTROL UNIT	Lead [7439-92-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], Silicic acid, lead salt [11120-22-2], Diboron-trioxide [1303-86-2]
Power Transmission - [final drive]	BRACKET, PT-UNIT	Lead [7439-92-1]
Body, Interior / Exterior - [instrument / radio panel]	DASHBOARD, HINGE PIN, LAMP LED, ADAPTER BRACKET, GLOVE BOX, CONCEALING PANEL	Lead [7439-92-1], Tris(nonylphenyl)phosphite [26523-78-4], TBBA [79-94-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2]
Frame / Springs / Damping / Wheels - [rim]	KEY, WHEEL BOLT, ADHESIVE BALANCE WEIGHT	Lead [7439-92-1], 2-Methylimidazole [693-98-1], Diboron-trioxide [1303-86-2]
Frame / Springs / Damping / Wheels - [anti-roll bar]	LINK FRONT ANTI-ROLL BAR, LINK ANTI-ROLL BAR, ANTI-ROLL BAR FRONT, ANTI-ROLL BAR REAR	Imidazolidine-2-thione [96-45-7], 2-Methylimidazole [693-98-1]
Body, Interior / Exterior - [miscellaneous]	TRANSPORT PROTECTION, SEALANT REPAIR, SEALING, SOUND INSULATION	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Dibutylbis(pentane-2,4-dionato-O,O')tin [22673-19-4], C,C'-azodi(formamide) [123-77-3], Diboron-trioxide [1303-86-2]
Brake - [brake control]	SENSOR, PEDAL UNIT	Lead [7439-92-1]



Electric Power Supply / Instruments - [antenna]	ANTENNA AMPLIFIER, ETC ON BOARD UNIT, ANTENNA, ETC MODULE	TBBA [79-94-7], Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead titanium zirconium oxide [12626-81-2], 1-Propanol, 2,3-dibromo- [96-13-9], Melamine [108-78-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1]
Electric Power Supply / Instruments - [alternator]	REGULATOR LIN, ALTERNATOR 210A	Lead [7439-92-1]
Electric Power Supply / Instruments - [starting system]	STARTER MOTOR	Lead [7439-92-1], Ethylenediamine [107-15-3]
Frame / Springs / Damping / Wheels - [spring, leaf spring]	AIR HOSE BUNDLE, CONNECTOR, HOSE COUPLING, VALVE BLOCK, RESEVOIR, T-CONNECTION, AIR SPRING REAR, SHOCK ABSORBER FRONT, AIR SPRING FRONT, TOPMOUNT, COMPRESSOR	Lead [7439-92-1], Decamethylcyclopentasiloxane [541-02-6], Tris(nonylphenyl)phosphite [26523-78-4]
Body, Interior / Exterior - [bumper with mounting / damping]	NUMBER PLATE HOLDER	Imidazolidine-2-thione [96-45-7]
Engine - [miscellaneous / help device installation]	BRACKET, SPLASH PROTECTION, TENSIONER, GUIDE SLEEVE	Lead [7439-92-1]
Electric Power Supply / Instruments - [horn]	HORN	Lead [7439-92-1], Diboron-trioxide [1303-86-2]
Brake - [vacuum pump / tank / line / valve]	VACUUM HOSE	C,C'-azodi(formamide) [123-77-3]
Engine - [accelerator control]	ACCELERATOR PEDAL	Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-monoxide [1317-36-8]
Engine - [cold zone / batterybox]	NVH PANEL	Lead [7439-92-1]
Engine - [supercharging]	SLEEVE, PIPE COMPRESSOR, TURBO CHARGER, OIL DRAINING PIPE, COMPRESSOR, O-RING, STAY COMPRESSOR, SUPERCHARGER, THROTTLE, VACUUM RESERVOIR, VACUUM REGULATOR, BYPASS HOUSING, COMPRESSOR PIPE, BRACKET, MP TURBO, INLET PIPE	Lead [7439-92-1], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], N,N-Dimethylacetamide [127-19-5], Melamine [108-78-1], TBBA [79-94-7], Diboron-trioxide [1303-86-2], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9], Lead-monoxide [1317-36-8], Dicyclohexyl-phthalate [84-61-7]
Engine - [transmission]	TENSIONER, CAMSHAFT, IDLER PULLEY, HOUSING, SOLENOID, GASKET, BALANCE SHAFT, BELT PROTECTOR, BELT COVER, VVT ACTUATOR, SLEEVE	Lead [7439-92-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]

Engine - [lubricating and oil system]	OIL SUMP, SUCTION LINE, OIL PUMP, PISTON COOLING JET, GASKET, VALVE, INLET PIPE, PISTON COOLING VALVE, WINDAGE TRAY, OIL LEVEL SENSOR, OIL FILTER, PLUG, OIL PRESSURE SENSOR	Lead [7439-92-1], Bis(4-chlorophenyl) sulfon [80-07-9], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7], Diboron-trioxide [1303-86-2]
Engine - [cylinder block / head]	CYLINDER HEAD, BEDPLATE, ENGINE BRACKET, VACUUM PUMP, CYLINDER BLOCK, TOP COVER, GUIDE SLEEVE, BEARING HOUSE CAM SHAFT, CAP, CAM SHAFT COVER, PROTECTING CASING, CAMSHAFT CAP, HOUSING, CAM SHAFT HOUSING, LOCATING PIN	Lead [7439-92-1]
Engine - [distributor]	CRANKSHAFT POS SENSOR, CAMSHAFT POSITION SENSOR, BRACKET, KNOCK SENSOR	Diboron-trioxide [1303-86-2], Lead [7439-92-1], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2]
Engine - [crank mechanism]	DUAL MASS FLYWHEEL, NIPPLE, NON-RETURN VALVE	Lead [7439-92-1]
Engine - [ignition / spark plug]	GLOW PLUG, IGNITION COIL, SPARK PLUG, CONTROL UNIT	Lead [7439-92-1], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8]