

**V60CC MODEL YEAR 2026**  
**Candidate List Substances Table**

Released: 2025 week 35.

We hereby inform that almost all product areas contain lead (CAS No 7439-92-1), primarily as alloying elements in steel, aluminium and copper.

| Localisation                                                           | Partnames                                                                                                     | Substance/s                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |
|------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Wheel Suspension / Steering<br>- [front suspension]                    | HUB, TRIPLESQUARE SOCKET SCREW                                                                                | O,O,O-Triphenyl phosphorothioate [597-82-0], Diboron-trioxide [1303-86-2]                                                                                                                                                                                                                                                                                                                                                                                                                                   |
| Wheel Suspension / Steering<br>- [axle member / link arm / suspension] | HUB, LOWER LINK ARM, UPPER LINK ARM, TRIPLESQUARE SOCKET SCREW                                                | O,O,O-Triphenyl phosphorothioate [597-82-0], Imidazolidine-2-thione [96-45-7], Diboron-trioxide [1303-86-2], Lead [7439-92-1]                                                                                                                                                                                                                                                                                                                                                                               |
| Electric Power Supply / Instruments - [automatic monitoring / control] | CONTROL UNIT, SIREN, SENSOR, REMOTE KEY, RAIN SENSOR                                                          | Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead titanium zirconium oxide [12626-81-2], 1,2-Dimethoxyethane [110-71-4], Lead-titanium-trioxide [12060-00-3], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead [7439-92-1]                                                                                                                                                                                |
| Electric Power Supply / Instruments - [radio equipment]                | MICROPHONE, LOUDSPEAKER, SPEAKER MIDRANGE, AUDIO MODULE, WOOFER, SUBWOOFER, TWEETER, CENTRE LOUDSPEAKER       | Diboron-trioxide [1303-86-2], N,N-Dimethylacetamide [127-19-5], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], Melamine [108-78-1], TBBA [79-94-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Cobalt(II) nitrate hexahydrate [10026-22-9], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead [7439-92-1] |
| Body, Interior / Exterior - [lock / handle]                            | OUTER HANDLE, WIRE, EXT743, LOCK, EXT745, EXT746, EXT744, DOOR LOCK, LOCK CYLINDER SET, ANTI THEFT COVER, KEY | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Bumetrizole [3896-11-5], Diboron-trioxide [1303-86-2], Triphenyl-phosphate [115-86-6], Melamine [108-78-1], Hexahydromethylphthalic-anhydride [25550-51-0], Lead [7439-92-1]                                                                                                                                                                                |

|                                                             |                                                                                                                                                                                                                                                                                                                                                                   |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |
|-------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Electric Power Supply / Instruments - [support systems]     | SENSOR, CONTROL UNIT, CAMERA, RADAR, EXT743, EXT746, EXT744, EXT745, BOX                                                                                                                                                                                                                                                                                          | Lead-monoxide [1317-36-8], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Methylimidazole [693-98-1], Dicyclohexyl-phthalate [84-61-7], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], Lead titanium zirconium oxide [12626-81-2], TBBA [79-94-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Lead [7439-92-1]                                                                                                                                                                                                                                                                                                                                                                                             |
| Power Transmission - [front axle / rear axle / drive shaft] | AOC, SEALING RING, REAR AXLE, PUMP UNIT, FINAL DRIVE, RADIAL SEAL KIT, DRIVE SHAFT, BRACKET, VIBRATION DAMPER, BEARING ANCHORAGE                                                                                                                                                                                                                                  | Triphenyl-phosphate [115-86-6], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead [7439-92-1]                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |
| Body, Interior / Exterior - [seats]                         | HEAD RESTRAINT, UPHOLSTERY, SIDE BOLSTER, HARDBACK, UNDERCARRIAGE, ENGINE, HEATING PAD SEAT, LUMBAR SUPPORT, LOCK, CHARCOAL SOLID, STS SENSOR, BACKREST FRAME, LUMBAR SUPPORT 4-WAY, HEATER, MASSAGE PUMP, SIX POINT SOCKET SCREW, ARM REST, VENTILATION, FAN, COVER, AMBER, COULISSE, HATCH, CHARCOAL/BLOND, SLATE, BLOND, ENGINE TILT, FRAMEWORK, CABLE HARNESS | Triphenyl-phosphate [115-86-6], C,C'-azodi(formamide) [123-77-3], Melamine [108-78-1], Lead-monoxide [1317-36-8], 4,4'-Isopropylidenediphenol [80-05-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2], O,O,O-Triphenyl phosphorothioate [597-82-0], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], TBBA [79-94-7], Benzene-1,2,4-tricarboxylic acid 1,2-anhydride [552-30-7], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Imidazolidine-2-thione [96-45-7], 1-Methyl-2-pyrrolidone [872-50-4], Bumetrizole [3896-11-5], Boric acid [10043-35-3], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3], N,N-Dimethylacetamide [127-19-5], Lead [7439-92-1] |
| Body, Interior / Exterior - [upholstery]                    | DOOR PANEL, ARM REST, SIDE PANEL, LUGGAGE COVER, LAMP LED, CLIP HOUSING, SWITCH, LOCK BUTTON, LOCK BUTTON LED                                                                                                                                                                                                                                                     | C,C'-azodi(formamide) [123-77-3], Triphenyl-phosphate [115-86-6], N,N-Dimethylacetamide [127-19-5], Bumetrizole [3896-11-5], TBBA [79-94-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1]                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |
| Body, Interior / Exterior - [outside mirrors]               | REAR VIEW MIRROR OUTER, REAR VIEW MIRROR, CAMERA, GLASS, MOTOR UNIT                                                                                                                                                                                                                                                                                               | TBBA [79-94-7], Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], 2-Methylimidazole [693-98-1], Dicyclohexyl-phthalate [84-61-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], Cobalt-dinitrate [10141-05-6], Lead [7439-92-1]                                                                                                                                                                                                                                                                                                                                                                                                                                                          |

|                                                          |                                                                                                                                                                                                                                                                                                                                |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |
|----------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Body, Interior / Exterior -<br>[interior equipment]      | JALUSIE, ARM REST, EC REAR VIEW MIRROR, LIGHTING, HINGE, CUP HOLDER, SUN VISOR, CHARCOAL SOLID, CHARCOAL, BLOND, LED MODULE, DAMPER                                                                                                                                                                                            | C,C'-azodi(formamide) [123-77-3], Tris(nonylphenyl)phosphite [26523-78-4], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Cobalt sulphate [10124-43-3], TBBA [79-94-7], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7], Lead [7439-92-1]                                                                                                                                                                                                                                                                                                  |
| Engine - [control systems]                               | AIR TEMP SENSOR, CONTROL UNIT, MASS AIR FLOW SENSOR, TEMP AND PRESSURE SENSOR, PRESSURE SENSOR                                                                                                                                                                                                                                 | Lead-monoxide [1317-36-8], Silicic acid, lead salt [11120-22-2], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], Lead-titanium-trioxide [12060-00-3], Lead [7439-92-1]                                                                                                                                                                                                                                                                                                                                                                                                                  |
| Electric Power Supply /<br>Instruments - [cleaner]       | REAR WIPER MOTOR, FILLER PIPE, SEALING, WIPER APPARATUS, WASHER FLUID RESERVOIR, WIPER ARM, WIPER ARM DS, WIPER ARM PS, PUMP, DUAL PUMP                                                                                                                                                                                        | Lead-monoxide [1317-36-8], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Cobalt(II) nitrate hexahydrate [10026-22-9], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], Triphenyl-phosphate [115-86-6], TBBA [79-94-7], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead [7439-92-1]                                                                                                                                                                                                                                                                                               |
| Engine - [inlet / exhaust<br>systems]                    | EXHAUST SYSTEM, THROTTLE, HEAT SHIELD PLATE, INTAKE MANIFOLD                                                                                                                                                                                                                                                                   | Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1], Boric acid [10043-35-3]                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |
| Body, Interior / Exterior -<br>[outside / exterior trim] | EMBLEM, ANTENNA CAP, WHITE614, BLUE467, SILV477, BLACK487, GREY492, BROWN700, BLUE706, EXT707, EXT711, EXT714, EXT717, EXT719, CKDCOLOR, KSOCOLOR, SVART19S, RED612, EXT720, TAPE, EXT722, EXT721, EXT723, EXT621, EXT724, EXT725                                                                                              | 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Triphenyl-phosphate [115-86-6]                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |
| Engine - [cooling system]                                | HOSE TEMP SENSOR, SET, PUMP, COMPLETE COOLER, PRESSURE SENSOR, CONDENSER, COOLER, THREE-WAY VALVE, HOSE OUTLET, TWO-WAY VALVE, VALVE, TEMPERATURE SENSOR, BRACKET, CLAMP BRACKET, PIPE, HOSE MODULE, GASKET, O-RING, SIX POINT SOCKET SCREW, FLANGE SCREW, STRIKER PLATE, THERMOSTAT HOUSING, NIPPLE, WATER PUMP, PLASTIC PIPE | TBBA [79-94-7], Melamine [108-78-1], Lead titanium zirconium oxide [12626-81-2], Lead-monoxide [1317-36-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Diboron-trioxide [1303-86-2], Silicic acid, lead salt [11120-22-2], 1-Methyl-2-pyrrolidone [872-50-4], 4,4'-Isopropylidenediphenol [80-05-7], Lead [7439-92-1], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt-dichloride [7646-79-9], C,C'-azodi(formamide) [123-77-3] |

|                                                                              |                                                                                                                                                                                                                                                                                                                                             |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |
|------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Body, Interior / Exterior -<br>[side door]                                   | CARRIER PLATE, WINDOW LIFT                                                                                                                                                                                                                                                                                                                  | O,O,O-Triphenyl phosphorothioate [597-82-0], Lead [7439-92-1]                                                                                                                                                                                                                                                                                                                                                                                                                          |
| Electric Power Supply /<br>Instruments - [mobile data<br>services]           | CONTROL UNIT                                                                                                                                                                                                                                                                                                                                | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1], Lead [7439-92-1]                                                                                                                                                                                                           |
| Body, Interior / Exterior -<br>[glass, window / windscreen<br>/ roof]        | QUARTER GLASS LAMINATED, REAR SCREEN, QUARTER GLASS<br>HARDENED, GLASS HARDENED, WINDSCREEN                                                                                                                                                                                                                                                 | Bumetrizole [3896-11-5], Diboron-trioxide [1303-86-2], Lead [7439-92-1]                                                                                                                                                                                                                                                                                                                                                                                                                |
| Body, Interior / Exterior -<br>[instrument / radio panel]                    | IONIZER, GLOVE BOX, CONCEALING PANEL, INSTRUMENT PANEL,<br>LAMP LED, PANEL NOZZLE, HINGE PIN                                                                                                                                                                                                                                                | Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Lead [7439-92-1]                                                                                                                                                                                                                                              |
| Body, Interior / Exterior - [air<br>conditioning]                            | IONIZER, SUN SENSOR, DISTRIBUTION HOUSING, CLIMATE UNIT,<br>FAN, EVAPORATOR HOUSING, AIR INLET, HUMIDITY SENSOR, AC-<br>COMPRESSOR, SENSOR KIT, DEFROSTER, STEPPING MOTOR,<br>CONTROL UNIT, DRAINAGE HOSE, AIR CLEANER, SOLENOID CLUTCH,<br>SENSOR, SENSOR INTERIOR, PROTECTIVE CAP, PIPE ASSEMBLY,<br>VALVE, CONTROL VALVE, CHANNEL SENSOR | Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Melamine [108-78-1], Bumetrizole [3896-11-5], TBBA [79-94-7], Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead-titanium-trioxide [12060-00-3], Cobalt(II) nitrate hexahydrate [10026-22-9], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead [7439-92-1] |
| Wheel Suspension / Steering<br>- [steering gear / wheel /<br>shaft / column] | STEERING COLUMN, STEERING COLUMN MANUAL, STEERING GEAR,<br>STEERING WHEEL, STEERING WHEEL RIM, COVER PLUG, CHARCOAL<br>SO, BLOND, SEALING FLOOR, STEERING WHEEL HARNESS                                                                                                                                                                     | Phosphorothioic acid, O,O,O-triphenyl esters, tert-Bu derivs. [192268-65-8], Lead-monoxide [1317-36-8], O,O,O-Triphenyl phosphorothioate [597-82-0], Dicyclohexyl-phthalate [84-61-7], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]                                                                                                                                                   |
| Electric Power Supply /<br>Instruments - [vehicle control<br>system]         | SWITCH PANEL, CONTROL UNIT DOOR, SWITCH, CUT-OFF SWITCH,<br>USB POWER OUTLET, ECU, STALK MODULE, COMBI INSTRUMENT,<br>HARDWARE, CONTROL PANEL POWER SEAT, BUTTON, SWITCH<br>DOOR, SWITCH WINDOW LIFT, SWITCH MODULE, SWITCH<br>STEERING WHEEL                                                                                               | Triphenyl-phosphate [115-86-6], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead titanium zirconium oxide [12626-81-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], 4,4'-Isopropylidenediphenol [80-05-7], Boric acid [10043-35-3], Lead-titanium-trioxide [12060-00-3], Lead [7439-92-1]                                                                                                                                      |

|                                                                                |                                                                                                                                                                                                                               |                                                                                                                                                                                                                                                                                                           |
|--------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Electric Power Supply / Instruments - [communication, mobile telephone]        | CONTROL UNIT, BATTERY, WIRELESS CHARGE SYSTEM                                                                                                                                                                                 | Lead-monoxide [1317-36-8], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], Hexahydromethylphthalic-anhydride [25550-51-0], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1] |
| Engine - [fuel / EVAP system]                                                  | FUEL PUMP MODULE, FILTER, LEAK DETECTION PUMP, FILLER PIPE, PEM, HOSE, CANISTER, FUEL TANK, TANK WELDED, PURGE VALVE, PURGE VALVE ASSY, FUEL PRESSURE SENSOR, FUEL DISTRIBUTION PIPE, HIGH PRESSURE PUMP, INJECTOR, FUEL PUMP | Melamine [108-78-1], Lead-monoxide [1317-36-8], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Cobalt-dinitrate [10141-05-6], C,C'-azodi(formamide) [123-77-3], Lead [7439-92-1]                                                                       |
| Body, Interior / Exterior - [exterior equipment]                               | SPOILER, ACTIVE GRILLE SHUTTER, STOP LAMP, EXT746, EXT745, ACTIVE SPOILER SHUTTER                                                                                                                                             | C,C'-azodi(formamide) [123-77-3], Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead [7439-92-1]                                                                                                                                                                                               |
| Body, Interior / Exterior - [airbag]                                           | SIDE AIR BAG, AIRBAG MODULE, CONTROL UNIT, ACCELEROMETER SENSOR, INFLATABLE CURTAIN                                                                                                                                           | Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], Lead-monoxide [1317-36-8], Lead [7439-92-1]                                                                                                                                                            |
| Body, Interior / Exterior - [miscellaneous]                                    | ABSORBER, SOUND ABSORBER, TRANSPORT PROTECTION, SEALANT REPAIR, SEALING                                                                                                                                                       | Tris(nonylphenyl)phosphite [26523-78-4], Triphenyl-phosphate [115-86-6], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Dibutylbis(pentane-2,4-dionato-O,O')tin [22673-19-4], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]                                                                |
| Body, Interior / Exterior - [trunk lid / tailgate complete]                    | TAILGATE, SPINDLE DRIVE, ANTIFLUTTER                                                                                                                                                                                          | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], O,O,O-Triphenyl phosphorothioate [597-82-0], Bumetrizole [3896-11-5], Lead [7439-92-1]                                                                                                                                                           |
| Body, Interior / Exterior - [floor / frame section / wheel housing / firewall] | FRONT SIDE MEMBER, WHEEL HOUSING, ADHESIVE, FLOOR PANEL, TOP COVER, REINFORCEMENT, TOP COVER PANEL REAR                                                                                                                       | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]                                                                                                                                                                                                                                 |

|                                                               |                                                                                                                                            |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |
|---------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Electric Power Supply / Instruments - [cable system]          | CABLE FLOOR, CABLE, CABLE HARNESS, FLANGE NUT, CABLE HARNESS WEM, FUSE BOX, BRACKET, CABLE DUCT, FUSE BOX ASSY                             | Triphenyl-phosphate [115-86-6], TBBA [79-94-7], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Cobalt-dinitrate [10141-05-6], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Lead [7439-92-1]                                                                                                                                                                                                                                                                                                                                                  |
| Electric Power Supply / Instruments - [lighting]              | READING LAMP, OVERHEAD CONSOLE LENS, CONTROL UNIT HCM, HEADLAMP, LIGHTING, LAMP LED, REAR LAMP REAR DOOR, REAR LAMP, FOG LIGHT, LED MODULE | Lead-monoxide [1317-36-8], 2-(2H-Benzotriazol-2-yl)-4-(1,1,3,3-tetramethylbutyl)phenol [3147-75-9], Dicyclohexyl-phthalate [84-61-7], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Bumetrizole [3896-11-5], Octamethylcyclotetrasiloxane [556-67-2], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Melamine [108-78-1], Lead-titanium-trioxide [12060-00-3], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1] |
| Electric Power Supply / Instruments - [electric drive system] | VOLTAGE CONVERTER, STARTER MOTOR ALTERNATOR, SEALING, STARTER MOTOR, COOLANT PIPE, SENSOR                                                  | Lead-monoxide [1317-36-8], TBBA [79-94-7], Diboron-trioxide [1303-86-2], Lead-titanium-trioxide [12060-00-3], 2-Methylimidazole [693-98-1], 1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9], Lead [7439-92-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], N,N-Dimethylacetamide [127-19-5]                                                                                                                                                                                                                                                            |
| Brake - [wheel brake]                                         | BRAKE CALIPER, HOUSING, EPB, BRAKE LINING, AIR VENTING NIPPLE, BLEEDER VALVE                                                               | O,O,O-Triphenyl phosphorothioate [597-82-0], 2-Methylimidazole [693-98-1], Diboron-trioxide [1303-86-2], Tris(nonylphenyl)phosphite [26523-78-4], Hexahydromethylphthalic-anhydride [25550-51-0], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Dicyclohexyl-phthalate [84-61-7], Lead [7439-92-1]                                                                                                                                                                                                                                                                                    |
| Electric Power Supply / Instruments - [infotainment system]   | GRAPHIC HEAD UP DISPLAY, PRINTED CIRCUIT BOARD, DISPLAY, USB HUB                                                                           | Diboron-trioxide [1303-86-2], 1-Butanesulfonic acid, 1,1,2,2,3,3,4,4,4-nonafluoro-, potassium salt (1:1) [29420-49-3], Boric acid [10043-35-3], Lead-monoxide [1317-36-8], Lead titanium zirconium oxide [12626-81-2], Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 4,4'-Isopropylidenediphenol [80-05-7], Melamine [108-78-1], Lead-titanium-trioxide [12060-00-3], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Triphenyl-phosphate [115-86-6], Lead [7439-92-1]                                                                               |

|                                                                                       |                                                                                      |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |
|---------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Body, Interior / Exterior - [roof]                                                    | GLASS PANEL, WELD SEALANT CURING, PANORAMA ROOF, MOTOR, FRAME                        | Tris(nonylphenyl)phosphite [26523-78-4], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Triphenyl-phosphate [115-86-6], Lead-monoxide [1317-36-8], Phosphorothioic acid, O,O,O-triphenyl esters, tert-Bu derivs. [192268-65-8], Lead [7439-92-1]                                                                                                                                                                                            |
| Electric Power Supply / Instruments - [vehicle computational units / gateway modules] | CONTROL UNIT                                                                         | Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1]                                                                                                                                                                                                                                                                                                                                                                                                                           |
| Body, Interior / Exterior - [seat belt / other restraining systems]                   | BELT CATCH, BELT, BELT CATCH REAR, SEAT BELT, HEIGHT ADJUSTMENT                      | TBBA [79-94-7], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Decamethyltetrasiloxane [141-62-8], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead-monoxide [1317-36-8], Triphenyl-phosphate [115-86-6], Lead [7439-92-1]                                                                                                                                                                                                                                                               |
| Power Transmission - [gearbox]                                                        | CONTROL UNIT, CABLE HARNESS, CONNECTOR, AUTOMATIC GEARBOX, AIR VENT PIPE, VALVE BODY | 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], Lead-monoxide [1317-36-8], Nonylphenol [25154-52-3], 4-(1,1,3,3-Tetramethylbutyl)phenol [140-66-9], 4,4'-Isopropylidenediphenol [80-05-7], 1-Methyl-2-pyrrolidone [872-50-4], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]                                                                                                 |
| Electric Power Supply / Instruments - [battery and mounting parts]                    | BATTERY, 48V BATTERY, BMS                                                            | Diphenyl(2,4,6-trimethylbenzoyl)phosphine oxide [75980-60-8], 1,3-Propanesultone [1120-71-4], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead titanium zirconium oxide [12626-81-2], 1-Butanone, 2-(dimethylamino)-2-((4-methylphenyl)methyl)-1-(4-(4-morpholinyl)phenyl)- [119344-86-4], Octamethylcyclotetrasiloxane [556-67-2], 1-Propanol, 2,3-dibromo- [96-13-9], Lead-titanium-trioxide [12060-00-3], Lead [7439-92-1] |
| Power Transmission - [gear lever carrier / gear selector controls]                    | GEAR LEVER CARRIER                                                                   | Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead [7439-92-1]                                                                                                                                                                                                                                                                                                                                                                                                                           |

|                                                                                |                                                                       |                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |
|--------------------------------------------------------------------------------|-----------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Brake - [brake line with connections]                                          | BRAKE PIPE, BRAKE PIPE FRONT, RETAINER                                | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bumetrizole [3896-11-5], Lead [7439-92-1]                                                                                                                                                                                                                                                                                                                                                                     |
| Engine - [emission equipment]                                                  | LAMBDA SOND, PRESSURE SENSOR                                          | Diboron-trioxide [1303-86-2], TBBA [79-94-7], Lead-monoxide [1317-36-8]                                                                                                                                                                                                                                                                                                                                                                                                |
| Brake - [brake, anti lock (anti-skid)]                                         | HYDRAULIC UNIT, SENSOR                                                | Lead titanium zirconium oxide [12626-81-2], Boric acid [10043-35-3], O,O,O-Triphenyl phosphorothioate [597-82-0], Cobalt(II) nitrate hexahydrate [10026-22-9], Lead-monoxide [1317-36-8], Lead-titanium-trioxide [12060-00-3], Diboron-trioxide [1303-86-2], TBBA [79-94-7], Lead [7439-92-1]                                                                                                                                                                          |
| Electric Power Supply / Instruments - [electrical distribution box / fuse box] | CEM, ATTACHMENT                                                       | Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead [7439-92-1]                                                                                                                                                                                                                                                                                                                                                                                              |
| Engine - [engine / engine mounting]                                            | ENGINE, ENGINE MOUNT, TORQUE ROD, TORQUE LINK BRACKET, ENGINE BRACKET | Bis(4-chlorophenyl) sulfon [80-07-9], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], Lead titanium zirconium oxide [12626-81-2], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Octamethylcyclotetrasiloxane [556-67-2], Decamethylcyclopentasiloxane [541-02-6], Lead [7439-92-1], Lead-titanium-trioxide [12060-00-3], TBBA [79-94-7], 1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9] |
| Body, Interior / Exterior - [body side]                                        | WELD SEALANT CURING, REINFORCEMENT                                    | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Lead [7439-92-1]                                                                                                                                                                                                                                                                                                                                                                                              |
| Electric Power Supply / Instruments - [horn]                                   | HORN                                                                  | Lead-monoxide [1317-36-8], Lead [7439-92-1]                                                                                                                                                                                                                                                                                                                                                                                                                            |
| Body, Interior / Exterior - [instruction / information plates]                 | SIX POINT SOCKET SCREW                                                | 1-Methyl-2-pyrrolidone [872-50-4]                                                                                                                                                                                                                                                                                                                                                                                                                                      |

|                                                             |                                                                                          |                                                                                                                                                                                                                                                                                                                                                                                             |
|-------------------------------------------------------------|------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Body, Interior / Exterior -<br>[hood cover]                 | HINGE RELEASER, HOOD, ANTIFLUTTER, HINGE                                                 | Diboron-trioxide [1303-86-2], 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]                                                                                                                                                                                                                                 |
| Frame / Springs / Damping /<br>Wheels - [anti-roll bar]     | LINK FRONT ANTI-ROLL BAR, LINK ANTI-ROLL BAR, ANTI-ROLL BAR<br>FRONT, ANTI-ROLL BAR REAR | Imidazolidine-2-thione [96-45-7], 2-Methylimidazole [693-98-1]                                                                                                                                                                                                                                                                                                                              |
| Body, Interior / Exterior -<br>[protective shields / flaps] | CLIP, HEAT SHIELD PLATE                                                                  | Bumetrizole [3896-11-5], C,C'-azodi(formamide) [123-77-3]                                                                                                                                                                                                                                                                                                                                   |
| Electric Power Supply /<br>Instruments - [antenna]          | ANTENNA AMPLIFIER, WAVE TRAP, GROUND SIDE COIL, ANTENNA                                  | TBBA [79-94-7], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead-monoxide [1317-36-8], Diboron-trioxide [1303-86-2], 2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5], Lead titanium zirconium oxide [12626-81-2], 1-Propanol, 2,3-dibromo- [96-13-9], Melamine [108-78-1], 2-Benzyl-2-dimethylamino-4-morpholinobutyrophenone [119313-12-1], Lead [7439-92-1] |
| Power Transmission - [final<br>drive]                       | SEALING, PT-UNIT, BRACKET                                                                | Triphenyl-phosphate [115-86-6], O,O,O-Triphenyl phosphorothioate [597-82-0], Lead [7439-92-1]                                                                                                                                                                                                                                                                                               |
| Brake - [master cylinder /<br>brake booster]                | LID                                                                                      | Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3]                                                                                                                                                                                                                                                                                                                                          |
| Engine - [accelerator control]                              | ACCELERATOR PEDAL                                                                        | Diboron-trioxide [1303-86-2], Lead-monoxide [1317-36-8], Lead [7439-92-1]                                                                                                                                                                                                                                                                                                                   |
| Electric Power Supply /<br>Instruments - [protection]       | SENSOR FRONT, SENSOR REAR                                                                | TBBA [79-94-7], Lead [7439-92-1]                                                                                                                                                                                                                                                                                                                                                            |
| Body, Interior / Exterior -<br>[tank hatch]                 | PLASTIC MODULE                                                                           | Triphenyl-phosphate [115-86-6], Lead [7439-92-1]                                                                                                                                                                                                                                                                                                                                            |

|                                                                        |                                                                      |                                                                                                           |
|------------------------------------------------------------------------|----------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------|
| Body, Interior / Exterior -<br>[bonnet / cover with<br>assembly parts] | END FOAM, HOOD RELEASE CABLE, HOOD LOCK, HOOD LOCK<br>CONTROL, COVER | Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Imidazolidine-2-thione [96-45-7], Lead<br>[7439-92-1] |
| Engine - [fan]                                                         | FAN                                                                  | O,O,O-Triphenyl phosphorothioate [597-82-0], Lead [7439-92-1]                                             |
| Frame / Springs / Damping /<br>Wheels - [rim]                          | TYRE 245/40R20 99W XL, VALVE, KEY, WHEEL BOLT                        | Triphenyl-phosphate [115-86-6], Lead [7439-92-1]                                                          |
| Engine - [air cleaner]                                                 | BELLOWS, BOX                                                         | Bumetrizole [3896-11-5], Lead [7439-92-1]                                                                 |
| Body, Interior / Exterior -<br>[front fender]                          | SHIM                                                                 | Lead [7439-92-1]                                                                                          |
| Brake - [brake control]                                                | PEDAL UNIT, SENSOR                                                   | Lead [7439-92-1]                                                                                          |
| Engine - [miscellaneous /<br>help device installation]                 | BRACKET, TENSIONER, SPLASH PROTECTION                                | Lead [7439-92-1]                                                                                          |
| Body, Interior / Exterior -<br>[window lift]                           | ANTI-THEFT BRACKET                                                   | Lead [7439-92-1]                                                                                          |
| Electric Power Supply /<br>Instruments - [cable<br>components]         | RECEPTACLE HOUSING, CABLE DUCT                                       | Lead [7439-92-1]                                                                                          |
| Body, Interior / Exterior -<br>[recovery / towing unit]                | HARNESS, TOWING HOOK                                                 | Lead [7439-92-1]                                                                                          |

|                                       |                                                                                                                                                                                   |                                                                                                                                                                                               |
|---------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Engine - [intercooler / connection]   | CHARGE AIR PIPE                                                                                                                                                                   | Lead [7439-92-1]                                                                                                                                                                              |
| Engine - [cold zone / batterybox]     | NVH PANEL                                                                                                                                                                         | Lead [7439-92-1]                                                                                                                                                                              |
| Engine - [ignition / spark plug]      | IGNITION COIL, SPARK PLUG, GLOW PLUG                                                                                                                                              | Diboron-trioxide [1303-86-2], Lead [7439-92-1]                                                                                                                                                |
| Engine - [lubricating and oil system] | GASKET, OIL PUMP, OIL LEVEL SENSOR, OIL FILTER, OIL PRESSURE SENSOR, OIL SUMP, SUCTION LINE, PISTON COOLING JET, VALVE, INLET PIPE, PISTON COOLING VALVE, WINDAGE TRAY, PLUG      | Bis(4-chlorophenyl) sulfon [80-07-9], TBBA [79-94-7], Lead-titanium-trioxide [12060-00-3], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Diboron-trioxide [1303-86-2], Lead [7439-92-1] |
| Engine - [transmission]               | GASKET, VVT-UNIT, TENSIONER, IDLER PULLEY, CAMSHAFT, SOLENOID, BALANCE SHAFT, BELT PROTECTOR, HOUSING, BELT COVER, VVT ACTUATOR, SLEEVE                                           | 6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1], Bis(alpha,alpha-dimethylbenzyl) peroxide [80-43-3], Lead [7439-92-1]                                                                 |
| Engine - [supercharging]              | TURBO CHARGER, O-RING, VACUUM RESERVOIR, VACUUM REGULATOR, BRACKET                                                                                                                | N,N-Dimethylacetamide [127-19-5], Decamethylcyclopentasiloxane [541-02-6], Octamethylcyclotetrasiloxane [556-67-2], Lead [7439-92-1]                                                          |
| Engine - [distributor]                | KNOCK SENSOR, CAMSHAFT POSITION SENSOR                                                                                                                                            | Lead titanium zirconium oxide [12626-81-2], Lead-monoxide [1317-36-8], Lead [7439-92-1]                                                                                                       |
| Engine - [cylinder block / head]      | BEDPLATE, ENGINE BRACKET, VACUUM PUMP, CYLINDER BLOCK, TOP COVER, GUIDE SLEEVE, BEARING HOUSE CAM SHAFT, CYLINDER HEAD, CAP, CAM SHAFT COVER, CAMSHAFT CAP, HOUSING, LOCATING PIN | Lead [7439-92-1]                                                                                                                                                                              |
| Engine - [crank mechanism]            | DUAL MASS FLYWHEEL, NIPPLE, NON-RETURN VALVE                                                                                                                                      | Lead [7439-92-1]                                                                                                                                                                              |